MITEL GOVERNMENT SYSTEMS GROUP PRICE LIST

EFFECTIVE: September 10, 2000





DISCLAIMER

Please be advised that this "Downloaded" version of the Price List may not have the most up-to-date prices. Please refer to the Mitel "On-Line" Price List for daily updated product pricing.

Mitel hereby grants Government End User the right to use the Price List contained herein ("soft copy" format) for internal purposes only and is in no way meant to influence the resale price of products contained herein.

Mitel reserves the right to make changes without notice, in the design, format and content as it deems necessary or desirable and disclaims responsibility and all liability for any typographical, formatting, and/or category errors and/or omissions.



| TERMS AND CONDITIONS | 1-2 |
|---|------|
| U.S. PRODUCT WARRANTY | 1-28 |
| CHANGE SUMMARY | 2-1 |
| NEW PART NUMBERS | 2-1 |
| PRICE DECREASES | 2-4 |
| PRICE INCREASES | 2-4 |
| PART NUMBERS REMOVED | 2-4 |
| PART DESCRIPTION CHANGES | 2-6 |
| PART NOTE CHANGES | 2-7 |
| SX-2000 LIGHT | 3-1 |
| SYSTEMS - SX-2000 LIGHT | 3-1 |
| SYSTEM SOFTWARE | 3-4 |
| HARDWARE | 3-5 |
| SOFTWARE OPTIONS | 3-6 |
| APPLICATIONS | 3-15 |
| ACD AGENTS | 3-15 |
| ISDN BRI KITS | 3-16 |
| ISDN NODES/CARDS | 3-18 |
| ISDN SOFTWARE OPTIONS | 3-21 |
| ISDN SPARES | 3-24 |
| CARDS | 3-25 |
| CONSOLES | 3-27 |
| SPARE COMPONENTS | 3-27 |
| R2 NODES/CARDS | 3-29 |
| PROGRAM: SX-2000 NETW ORKING PACKAGES | 3-30 |
| R2 SPARES | 3-30 |
| PROGRAM: SX-2000 SOFTWARE MIGRATION | 3-33 |
| PROGRAM: SX-2000 HARDWARE UPGRADE | 3-36 |
| SX-2000 SOFTWARE UPGRADES | 3-38 |
| SS7000 CONSOLE FOR SX-2000 | 3-38 |
| OPS MANAGER SYSTEMS | 3-39 |
| OPS MANAGER SOFTWARE | 3-39 |
| OPS MANAGER OPTIONS | 3-40 |
| SX-2000 MANAGEMENT OPTIONS | 3-40 |
| MSDN NETWORK RESOURCE DIMENSIONS | 3-41 |
| OPS MANAGER UPGRADES | 3-42 |
| SX-2000 MANAGEMENT OPTION UPGRADES | 3-42 |
| SX-2000 MGMT LAN CONNECTIVITY KITS FOR UNIX | 3-42 |
| OPS MANAGER SPARES FOR WINDOWS NT | 3-43 |
| OPS MANAGER SPARES FOR UNIX | 3-43 |



| SX-200 | 3-45 |
|--|------|
| SX-200 EL STANDARD PACKAGES | 3-45 |
| SX-200 EL VERTICAL MARKET PACKAGES | 3-45 |
| SX-200 ML STANDARD PACKAGES | 3-46 |
| SX-200 ML VERTICAL MARKET PACKAGES | 3-48 |
| CARDS | 3-49 |
| SPARE COMPONENTS | 3-50 |
| CONSOLES | 3-51 |
| SX-200 VERTICAL MARKET SYSTEM SOFTWARE | 3-51 |
| SX-200 MAXIMUM USER DEVICES | 3-55 |
| SX-200 SOFTW ARE OPTIONS | 3-56 |
| ACD AGENTS (SX-200 ML/EL) | 3-57 |
| TAPI SERVICE PROVIDER (SX200 ML/EL) | 3-57 |
| SX-200 SOFTW ARE - LIGHT | 3-58 |
| ISDN NODES/CARDS | 3-59 |
| ISDN SOFTWARE OPTIONS | 3-61 |
| ISDN SPARES | 3-64 |
| PROGRAM: SX-200 ML/EL UPGRADES | 3-65 |
| SX-200 SOFTWARE UPGRADES | 3-74 |
| SX-200 LIGHT | 3-74 |
| SS7000 CONSOLE FOR SX-200 | 3-74 |
| SX-200 ML/EL | 3-74 |
| MITEL INN SOLUTIONS | 3-76 |
| HARDWARE | 3-76 |
| SOFTWARE | 3-77 |



| MITEL MESSAGING SOLUTIONS | 3-82 |
|---|-------|
| MITEL EXPRESS MESSENGER | 3-82 |
| MITEL EXPRESS MESSENGER SOFTWARE | 3-83 |
| NUPOINT MESSENGER (70) SYSTEMS | 3-83 |
| NUPOINT MESSENGER (70) BASE SOFTWARE | 3-86 |
| NUPOINT MESSENGER (70) SW INTEGRATION KITS | 3-86 |
| NUPOINT MESSENGER (70) OPTIONAL SOFTW ARE | 3-86 |
| NUPOINT MESSENGER (70) HARDWARE | 3-87 |
| NUPOINT MESSENGER (70) HARDWARE SPARES | 3-90 |
| NUPOINT MESSENGER (70) UPGRADES | 3-90 |
| NUPOINT MESSENGER (70) BUNDLED APPLICATIONS | 3-91 |
| NUPOINT MESSENGER (120R) BASE SOFTWARE | 3-91 |
| NUPOINT MESSENGER(120R) SW INTEGRATION KITS | 3-92 |
| NUPOINT MESSENGER (120R) HARDWARE | 3-92 |
| NUPOINT MESSENGER (120R) UPGRADES | 3-92 |
| NUPOINT MESSENGER (120R) BUNDLED APPLICATIONS | 3-92 |
| NUPOINT MESSENGER (120S) BASE SOFTWARE | 3-93 |
| NUPOINT MESSENGER (120S) SW INTEGRATION KITS | 3-93 |
| NUPOINT MESSENGER (120S) HARDWARE | 3-94 |
| NUPOINT MESSENGER (120S) UPGRADES | 3-94 |
| NUPOINT MESSENGER (120S) BUNDLED APPLICATIONS | 3-94 |
| NUPOINT MESSENGER (640) BASE SOFTWARE | 3-95 |
| NUPOINT MESSENGER (640) SW INTEGRATION KITS | 3-95 |
| NUPOINT MESSENGER (640) HARDW ARE | 3-95 |
| NUPOINT MESSENGER (640) UPGRADES | 3-95 |
| NUPOINT MESSENGER (640) BUNDLED APPLICATIONS | 3-96 |
| MITEL MAIL 6.1B | 3-96 |
| MITEL MAIL 6.1B HARDWARE | 3-98 |
| MITEL ONEPOINT MESSENGER SYSTEM HARDWARE | 3-99 |
| MITEL ONEPOINT MESSENGER INTEGRATION | 3-99 |
| MITEL ONEPOINT MESSENGER SYSTEM SOFTWARE | 3-99 |
| PROGRAM: NUPOINT MESSENGER PRICE PROMOTION | 3-101 |
| REMOTE ACCESS | 3-102 |
| XPRESSOFFICE BUNDLES | 3-102 |
| XPRESSOFFICE COMPONENTS | 3-104 |
| XPRESSW AY RLAN BUNDLES | 3-107 |
| XPRESSW AY RLAN CHASSIS COMPONENTS | 3-107 |
| XPRESSW AY RLAN MODULES | 3-108 |
| XPRESSWAY RLAN PBX EXTENSION PRODUCTS | 3-108 |
| XPRESSWAY RLAN SYSTEM CONTROLLERS | 3-110 |
| XPRESSSTACK PRODUCTS | 3-111 |
| HARDWARE | 3-111 |
| MISCELLANEOUS CABLES AND ACCESSORIES | 3-112 |



| SX-50 | 3-113 |
|---|-------|
| SYSTEMS | 3-113 |
| HARDWARE | 3-113 |
| SOFTWARE | 3-113 |
| SPARE COMPONENTS | 3-113 |
| SX-50 SOFTWARE UPGRADES | 3-115 |
| SX-50 | 3-115 |
| DESKTOP DEVICES | 3-116 |
| SUPERSET 4000 SERIES | 3-116 |
| SUPERSET 4000 SERIES - SPARE PARTS | 3-116 |
| SUPERSET 400 SERIES | 3-117 |
| SUPERSET 400 SERIES - SPARE PARTS | 3-117 |
| SUPERSET 400/4000 SERIES - SPARE PARTS | 3-118 |
| SUPERSET 4001 | 3-118 |
| SUPERSET 4015 | 3-118 |
| SUPERSET 4025 | 3-118 |
| SUPERSET 4090 | 3-118 |
| SUPERSET 4125 | 3-119 |
| SUPERSET 4150 | 3-120 |
| PERIPHERALS - HEADSETS | 3-121 |
| PERIPHERALS - PKM MODULES | 3-121 |
| PERIPHERALS - EXPANSION MODULES | 3-122 |
| SPARE COMPONENTS | 3-123 |
| PROGRAM: SUPERSET 4090 PRICE PROMOTION | 3-123 |
| SPEAK@EASE | 3-125 |
| SOFTWARE | 3-125 |
| IMPRESA APPLICATIONS | 3-126 |
| CUSTOMER INTERACTION SERVERS | 3-126 |
| IMPRESA CUSTOMER INTERACTION SUITES | 3-127 |
| IMPRESA INTELLIGENT MEDIA ROUTER | 3-127 |
| IMPRESA AGENT DESKTOP | 3-128 |
| IMPRESA SCREEN POP | 3-128 |
| IMPRESA AGENT DESKTOP LICENSES | 3-129 |
| IMPRESA SCREEN POP CLIENT LICENSES | 3-129 |
| IMPRESA INTELLIGENT MEDIA ROUTER LICENSES | 3-130 |
| IMPRESA SPARES | 3-130 |
| CTI APPLICATIONS | 3-131 |
| FASTCALL | 3-131 |
| PHONEWARE NT | 3-131 |
| ENABLING TECHNOLOGIES | 3-133 |
| TALK TO TAPI | 3-133 |
| MITAI | 3-133 |



| PRAIRIEFYRE ACD REPORTING SYSTEMS | 3-134 |
|---|-------|
| SX-200 prairieFyre CyberACD | 3-134 |
| SX-200 prairieFyre CyberACD VT-100 | 3-134 |
| SX-200 prairieFyre CyberACD SQL | 3-134 |
| SX-2000 prairieFyre CyberACD | 3-134 |
| SX-2000 prairieFyre CyberACD SQL | 3-134 |
| SX-200 & SX-2000 prairieFyre HARDWARE | 3-135 |
| TASKE REL.7 ACD REPORTING SYSTEMS | 3-136 |
| SX-2000 TASKE REL.7 ACD AGENT TOOLBOX | 3-136 |
| SX-2000 TASKE REL.7 SUPERVISOR CLIENT | 3-136 |
| SX-2000 TASKE REL.7 VOICE TOOLBOX | 3-136 |
| SX-2000 TASKE REL.7 CALL CENTER COSTING | 3-136 |
| SX-2000 TASKE REL.7 DESKTOP SIGN | 3-136 |
| SX-200 & SX-2000 TASKE HARDWARE | 3-137 |
| TASKE REL.5 ACD REPORTING SYSTEMS | 3-138 |
| SX-200 REL.5 STANDALONE | 3-138 |
| SX-200 & SX-2000 TASKE HARDWARE | 3-138 |
| PROFESSIONAL SERVICES | 3-139 |
| BILLING SERVICES | 3-139 |
| MISCELLANEOUS | 3-140 |
| MISCELLANEOUS INSTALLATION | 3-140 |
| PRODUCT SUPPORT | 3-141 |
| TECHNICAL CREDITS | 3-141 |
| LITERATURE PRODUCTS | 3-142 |
| VOICE PROCESSING LITERATURE | 3-142 |
| OTHER | 3-143 |
| OTHER | 3-143 |
| INDEX | 4-1 |



INFORMATION FOR ORDERING OFFICES

SPECIAL NOTICE TO AGENCIES:

Small Business Participation

SBA strongly supports the participation of small business concerns in the Federal Supply Schedules Program. To enhance Small Business Participation SBA policy allows agencies to include in their procurement base and goals, the dollar value of orders expected to be placed against the Federal Supply Schedules, and to report accomplishments against these goals.

For orders exceeding the micropurchase threshold, FAR 8.404 requires agencies to consider the catalogs/pricelists of at least three schedule contractors or consider reasonably available information by using the GSA Advantage!™ on-line shopping service (www.fss.gsa.gov). The catalogs/pricelists, GSA Advantage!™ and the Federal Supply Service Home Page (www.fss.gsa.gov) contain information on a broad array of products and services offered by small business concerns.

This information should be used as a tool to assist ordering activities in meeting or exceeding established small business goals. It should also be used as a tool to assist in including small, small disadvantaged, and women-owned small businesses among those considered when selecting pricelists for a best value determination.

For orders exceeding the micropurchase threshold, customers are to give preference to small business concerns when two or more items at the same delivered price will satisfy their requirement.

1. Geographic Scope of Contract:

Sales area is limited to the 48 contiguous states and the District of Columbia, Alaska, Hawaii and Puerto Rico.

2. Contractor's Ordering Address and Payment Information:

Ordering Address: Mitel, Inc. – Government Systems Group 205 Van Buren Street Suite 400 Herndon, VA 20170-5336

Payment Address: Mitel, Inc. Department 771129 PO Box 77000 Detroit, MI 48277-1129



Contractors are required to accept the Government purchase card for payments equal to or less than the micro-purchase threshold for oral or written delivery orders. Government purchase cards **will** be acceptable for payment above the micro-purchase threshold. In addition, bank account information for wire transfer payments will be shown on the invoice.

The following telephone number(s) can be used by ordering agencies to obtain technical and/or ordering assistance:

(703)318-7020

3. LIABILITY FOR INJURY OR DAMAGE

The Contractor shall not be liable for any injury to Government personnel or damage to Government property arising from the use of equipment maintained by the Contractor, unless such injury or damage is due to the fault or negligence of the Contractor.

4. Statistical Data for Government Ordering Office Completion of Standard Form 279:

Block 9: <u>G.</u> Order/Modification Under Federal Schedule Block 16: Data Universal Numbering System (DUNS)

Number: 03-869-7942

Block 30: Type of Contractor – C. Large Business

- A. Small Disadvantaged Business
- B. Other Small Business
- C. Large Business
- G. Other Nonprofit Organization
- (1) Foreign Contractor

REVISION – AMENDMENT #3

Block 31: Woman-Owned Small Business - No

Block 36: Contractor's Taxpayer Identification Number (TIN): 59-1855-641

- **4a**. CAGE Code: <u>5R478</u>
- **4b.** Contractor **has** registered with the Central Contractor Registration Database.

5. FOB Destination

Prices quoted in Net U.S. Dollars e. and o.e.



DELIVERY SCHEDULE

a. TIME OF DELIVERY: The Contractor shall deliver to destination within the number of calendar days after receipt of order (ARO), as set forth below:

| SPECIAL ITEM NUMBER | DELIVERY TIME (Days ARO) |
|---------------------|--------------------------|
| <u>132-8</u> | 30 days ARO |
| <u>132-33</u> | 30 days ARO |

Expedited delivery is available for all Mitel items utilizing Federal Express. Expedited Delivery is available for all Mitel items utilizing Federal Express. In order to take advantage of this expedited delivery, please do the following:

- a) Fax to 613/591-2308 (Mitel US Order Desk) a listing, by Mitel part number and quantity, those Mitel items you wish to have delivered via Fed Ex
- b) Within 48 hours, Mitel US Order Desk will fax back to requesting agency, a copy of the Government provided listing with the FedEx cost noted
- c) Place this cost as the last line item on the Government purchase order and forward to Mitel for processing.
- b. URGENT REQUIREMENTS: When the Federal Supply Schedule contract delivery period does not meet the bona fide urgent delivery requirements of an ordering agency, agencies are encouraged, if time permits, to contact the Contractor for the purpose of obtaining accelerated delivery. The Contractor shall reply to the inquiry within 3 workdays after receipt. (Telephonic replies shall be confirmed by the Contractor in writing.) If the Contractor offers an accelerated delivery time acceptable to the ordering agency, any order(s) placed pursuant to the agreed upon accelerated delivery time frame shall be delivered within this shorter delivery time and in accordance with all other terms and conditions of the contract.

REVISION – AMENDMENT #2

- 7. Discounts: Prices shown are NET Prices; Basic Discounts have been deducted.
 - a. Prompt Payment: 0% 30 days from receipt of invoice or date of acceptance, whichever is later.
 - b. Quantity None
 - c. Dollar Volume Any single GSA contract order over \$200,000.00 will receive an additional 4% discount.
 - d. Government Educational Institutions
 - e. Other

8. Trade Agreements Act of 1979, as amended:

All items are U.S. made end products, designated country end products, Caribbean Basin country end products, Canadian end products, or Mexican end products as defined in the Trade Agreements Act of 1979, as amended.

Prices quoted in Net U.S. Dollars e. and o.e.

MITEL

TERMS AND CONDITIONS

9. Statement Concerning Availability of Export Packing:

Packaging for export can be provided by Mitel on an open market basis upon customer request.

10. Small Requirements: The minimum dollar value of orders to be issued is \$50.00

See C.10, ORDER LIMITATIONS, paragraph (a) Minimum Order.

- 11. Maximum Order: (All dollar amounts are exclusive of any discount for prompt payment.)
 - a. Special Item Number 132-3 Leasing of Equipment

The maximum dollar value per order for all leased equipment will be \$500,000.

- b. Special Item Number 132-8 Purchase of Equipment The maximum dollar value per order for all purchased equipment will be \$500,000.
- c. Special Item Number 132-12 Repair Parts/Spare Parts
 The maximum dollar value per order for all repair parts/spare parts will be \$10,000.
- d. Special Item Number 132-32 Term Software Licenses
 The maximum dollar value per order for all term software licenses will be \$50,000 or \$500,000.
- e. Special Item Number 132-33 Perpetual Software Licenses
 The maximum dollar value per order for all perpetual software licenses will be \$50,000 or \$500,000.
- f. Special Item Number 132-50 Training Courses
 The maximum dollar value per order for all training courses will be \$25,000.
- g. Special Item Number 132-51 Information Technology (IT) Professional Services The maximum dollar value per order for all IT Professional services will be \$500,000.
- h. Special Item Number 132-52 Electronic Commerce (EC) Services The maximum dollar value per order for all EC services will be \$500,000.
- i. Special Item Number 132-53 Telecommunication Transmission Services The maximum dollar value per order for all Telecommunication Transmission services will be \$500,000.

Note: Maximum Orders do not apply to Special Item Numbers 132-12 Maintenance and Repair Service (except for Repair Parts/Spare Parts) or 132-34 Maintenance of Software.

Prices quoted in Net U.S. Dollars e. and o.e.

Effective: September 10, 2000

Page 1-4



12. USE OF FEDERAL SUPPLY SERVICE INFORMATION TECHNOLOGY SCHEDULE CONTRACTS. In accordance with FAR 8.404:

[NOTE: Special ordering procedures have been established for Special Item Numbers (SINs) 132-51 IT Professional Services and 132-52 EC Services; refer to the terms and conditions for those SINs.1

REVISION – AMENDMENT #3

Orders placed pursuant to a Multiple Award Schedule (MAS), using the procedures in FAR 8.404, are considered to be issued pursuant to full and open competition. Therefore, when placing orders under Federal Supply Schedules, ordering offices need not seek further competition, synopsize the requirement, make a separate determination of fair and reasonable pricing, or consider small business set-asides in accordance with subpart 19.5. GSA has already determined the prices of items under schedule contracts to be fair and reasonable. By placing an order against a schedule using the procedures outlined below, the ordering office has concluded that the order represents the best value and results in the lowest overall cost alternative (considering price, special features, administrative costs, etc.) to meet the Government's needs.

- a. Orders placed at or below the micro-purchase threshold. Ordering offices can place orders at or below the micro-purchase threshold with any Federal Supply Schedule Contractor.
- b. Orders exceeding the micro-purchase threshold but not exceeding the maximum order threshold. Orders should be placed with the Schedule Contractor that can provide the supply or service that represents the best value. Before placing an order, ordering offices should consider reasonably available information about the supply or service offered under MAS contracts by using the "GSA Advantage!" on-line shopping service, or by reviewing the catalogs/pricelists of at least three Schedule Contractors and selecting the delivery and other options available under the schedule that meets the agency's needs. In selecting the supply or service representing the best value, the ordering office may consider--
- (1) Special features of the supply or service that are required in effective program performance and that are not provided by a comparable supply or service;
 - (2) Trade-in considerations;
 - (3) Probable life of the item selected as compared with that of a comparable

item;

- (4) Warranty considerations:
- (5) Maintenance availability;
- (6) Past performance; and
- (7) Environmental and energy efficiency considerations.

MITEL

TERMS AND CONDITIONS

- c. Orders exceeding the maximum order threshold. Each schedule contract has an established maximum order threshold. This threshold represents the point where it is advantageous for the ordering office to seek a price reduction. In addition to following the procedures in paragraph b, above, and before placing an order that exceeds the maximum order threshold, ordering offices shall--
- (1) Review additional Schedule Contractors' catalogs/pricelists or use the "GSA Advantage!" on-line shopping service;
- (2) Based upon the initial evaluation, generally seek price reductions from the Schedule Contractor(s) appearing to provide the best value (considering price and other factors); and
- (3) After price reductions have been sought, place the order with the Schedule Contractor that provides the best value and results in the lowest overall cost alternative. If further price reductions are not offered, an order may still be placed, if the ordering office determines that it is appropriate.

NOTE: For orders exceeding the maximum order threshold, the Contractor may:

- (1) Offer a new lower price for this requirement (the Price Reductions clause is not applicable to orders placed over the maximum order in FAR 52.216-19 Order Limitations);
 - (2) Offer the lowest price available under the contract; or
- (3) Decline the order (orders must be returned in accordance with FAR 52.216-19).
- d. Blanket purchase agreements (BPAs). The establishment of Federal Supply Schedule BPAs is permitted when following the ordering procedures in FAR 8.404. All schedule contracts contain BPA provisions. Ordering offices may use BPAs to establish accounts with Contractors to fill recurring requirements. BPAs should address the frequency of ordering and invoicing, discounts, and delivery locations and times.
- **e. Price reductions.** In addition to the circumstances outlined in paragraph c, above, there may be instances when ordering offices will find it advantageous to request a price reduction. For example, when the ordering office finds a schedule supply or service elsewhere at a lower price or when a BPA is being established to fill recurring requirements, requesting a price reduction could be advantageous. The potential volume of orders under these agreements, regardless of the size of the individual order, may offer the ordering office the opportunity to secure greater discounts. Schedule Contractors are not required to pass on to all schedule users a price reduction extended only to an individual agency for a specific order.
- **f. Small business.** For orders exceeding the micro-purchase threshold, ordering offices should give preference to the items of small business concerns when two or more items at the same delivered price will satisfy the requirement.
- **g. Documentation.** Orders should be documented, at a minimum, by identifying the Contractor the item was purchased from, the item purchased, and the amount paid. If an agency requirement in excess of the micro-purchase threshold is defined so as to require a particular brand name, product, or feature of a product peculiar to one manufacturer, thereby precluding consideration of a product manufactured by another company, the ordering office shall include an explanation in the file as to why the particular brand name, product, or feature is essential to satisfy the agency's needs.



13. FEDERAL INFORMATION TECHNOLOGY/TELECOMMUNICATION STANDARDS REQUIREMENTS:

Federal departments and agencies acquiring products from this Schedule must comply with the provisions of the Federal Standards Program, as appropriate (reference: NIST Federal Standards Index). Inquiries to determine whether or not specific products listed herein comply with Federal Information Processing Standards (FIPS) or Federal Telecommunication Standards (FED-STDS), which are cited by ordering offices, shall be responded to promptly by the Contractor.

- 13.1 FEDERAL INFORMATION PROCESSING STANDARDS PUBLICATIONS (FIPS PUBS): Information Technology products under this Schedule that do not conform to Federal Information Processing Standards (FIPS) should not be acquired unless a waiver has been granted in accordance with the applicable "FIPS Publication." Federal Information Processing Standards Publications (FIPS PUBS) are issued by the U.S. Department of Commerce, National Institute of Standards and Technology (NIST), pursuant to National Security Act. Information concerning their availability and applicability should be obtained from the National Technical Information Service (NTIS), 5285 Port Royal Road, Springfield, Virginia 22161. FIPS PUBS include voluntary standards when these are adopted for Federal use. Individual orders for FIPS PUBS should be referred to the NTIS Sales Office, and orders for subscription service should be referred to the NTIS Subscription Officer, both at the above address, or telephone number (703) 487-4650.
- 13.2 FEDERAL TELECOMMUNICATION STANDARDS (FED-STDS): Telecommunication products under this Schedule that do not conform to Federal Telecommunication Standards (FED-STDS) should not be acquired unless a waiver has been granted in accordance with the applicable "FED-STD." Federal Telecommunication Standards are issued by the U.S. Department of Commerce, National Institute of Standards and Technology (NIST), pursuant to National Security Act. Ordering information and information concerning the availability of FED-STDS should be obtained from the GSA, Federal Supply Service, Specification Section, 470 East L'Enfant Plaza, Suite 8100, SW, Washington, DC 20407, telephone number (202)619-8925. Please include a self-addressed mailing label when requesting information by mail. Information concerning their applicability can be obtained by writing or calling the U.S. Department of Commerce, National Institute of Standards and Technology, Gaithersburg, MD 20899, telephone number (301)975-2833.
- **SECURITY REQUIREMENTS.** In the event security requirements are necessary, the ordering activities may incorporate, in their delivery orders, a security clause in accordance with current laws, regulations, and individual agency policy; however, the burden of administering the security requirements shall be with the ordering agency. If any costs are incurred as a result of the inclusion of security requirements, such costs will not exceed ten percent (10%) or \$100,000, of the total dollar value of the order, whichever is lessor.
- **15. CONTRACT ADMINISTRATION FOR ORDERING OFFICES:** Any ordering office, with respect to any one or more delivery orders placed by it under this contract, may exercise the same rights of termination as might the GSA Contracting Officer under provisions of FAR 52.212-4, paragraphs (I) Termination for the Government's convenience, and (m) Termination for Cause (See C.1.)

₩MITEL

TERMS AND CONDITIONS

16. GSA Advantage!

GSA *Advantage*! is an on-line, interactive electronic information and ordering system that provides on-line access to vendors' schedule prices with ordering information. GSA *Advantage*! will allow the user to perform various searches across all contracts including, but not limited to:

- (1) Manufacturer;
- (2) Manufacturer's Part Number; and
- (3) Product categories.

Agencies can browse GSA Advantage! by accessing the Internet World Wide Web utilizing a browser (ex.: NetScape). The Internet address is http://www.fss.gsa.gov/.

17. PURCHASE OF INCIDENTAL, NON-SCHEDULE ITEMS

For administrative convenience, open market (non-contract) items may be added to a Federal Supply Schedule Blanket Purchase Agreement (BPA) or an individual order, provided that the items are clearly labeled as such on the order, all applicable regulations have been followed, and price reasonableness has been determined by the ordering activity for the open market (non-contract) items.

18. CONTRACTOR COMMITMENTS, WARRANTIES AND REPRESENTATIONS

- a. For the purpose of this contract, commitments, warranties and representations include, in addition to those agreed to for the entire schedule contract:
 - (1) Time of delivery/installation quotations for individual orders;
- (2) Technical representations and/or warranties of products concerning performance, total system performance and/or configuration, physical, design and/or functional characteristics and capabilities of a product/equipment/ service/software package submitted in response to requirements which result in orders under this schedule contract.
- (3) Any representations and/or warranties concerning the products made in any literature, description, drawings and/or specifications furnished by the Contractor.
 - The above is not intended to incumpus items not currently covered by the GSA Schedule contract.

19. OVERSEAS ACTIVITIES

The terms and conditions of this contract shall apply to all orders for installation, maintenance and repair of equipment in areas listed in the pricelist outside the 48 contiguous states and the District of Columbia, except as indicated below:

Upon request of the Contractor, the Government may provide the Contractor with logistics support, as available, in accordance with all applicable Government regulations. Such Government support will be provided on a reimbursable basis, and will only be provided to the Contractor's technical personnel whose services are exclusively required for the fulfillment of the terms and conditions of this contract.



20. YEAR 2000 WARRANTY—COMMERCIAL SUPPLY ITEMS

- (a) As used in this clause, "Year 2000 compliant" means, with respect to information technology, that the information technology accurately processes date/time data (including, but not limited to, calculating, comparing and sequencing) from, into, and between the twentieth and twenty-first centuries, and the years 1999 and 2000, and leap year calculations, to the extent that other information technology used in combination with the information technology being acquired, properly exchanges date/time data with it.
- (b) The Contractor shall warrant that each hardware, software, and firmware product delivered under this contract shall be able to accurately process date time data (including, but not limited to, calculating, comparing, and sequencing) from, into, and between the twentieth and twenty-first centuries, including leap year calculations, when used in accordance with the product documentation provided by the Contractor, provided that all products (e.g. hardware, software, firmware) used in combination with products properly exchange date time data with it. If the contract requires that specific listed products must perform as a system in accordance with the foregoing warranty, then that warranty shall apply to those products as a system. The duration of this warranty and the remedies available under this warranty shall include repair or replacement of any product whose non-

compliance is discovered and made known to the Contractor in

REVISION – AMENDMENT #2

writing within ninety (90) days after acceptance (installation is considered acceptance). The Contractor may offer an extended warranty to the Government to include repair or replacement of any product whose non-compliance is discovered and made known to the Contractor in writing at any time prior to June 1, 2000, or for a period of 6 months following acceptance (installation is considered acceptance) whichever is later. Nothing in this warranty shall be construed to limit any rights or remedies the Government may otherwise have under this contract with respect to defects other than Year 2000 performance.

21. BLANKET PURCHASE AGREEMENTS (BPAs)

Federal Acquisition Regulation (FAR) 13.201(a) defines Blanket Purchase Agreements (BPAs) as "...a simplified method of filling anticipated repetitive needs for supplies or services by establishing 'charge accounts' with qualified sources of supply." The use of Blanket Purchase Agreements under the Federal Supply Schedule Program is authorized in accordance with FAR 13.202(c)(3), which reads, in part, as follows:

"BPAs may be established with Federal Supply Schedule Contractors, if not inconsistent with the terms of the applicable schedule contract."

Prices quoted in Net U.S. Dollars e. and o.e.



Federal Supply Schedule contracts contain BPA provisions to enable schedule users to maximize their administrative and purchasing savings. This feature permits schedule users to set up "accounts" with Schedule Contractors to fill recurring requirements. These accounts establish a period for the BPA and generally address issues such as the frequency of ordering and invoicing, authorized callers, discounts, delivery locations and times. Agencies may qualify for the best quantity/volume discounts available under the contract, based on the potential volume of business that may be generated through such an agreement, regardless of the size of the individual orders. In addition, agencies may be able to secure a discount higher than that available in the contract based on the aggregate volume of business possible under a BPA. Finally, Contractors may be open to a progressive type of discounting where the discount would increase once the sales accumulated under the BPA reach certain prescribed levels. Use of a BPA may be particularly useful with the new Maximum Order feature. See the Suggested Format, contained in this Schedule Pricelist, for customers to consider when using this purchasing tool.

REVISION – AMENDMENT #2

22. CONTRACTOR TEAM ARRANGEMENTS

Federal Supply Schedule Contractors may use "Contractor Team Arrangements" (see FAR 9.6) to provide solutions when responding to a customer agency requirements. The policy and procedures outlined in this part will provide more flexibility and allow innovative acquisition methoc when using the Federal Supply Schedules. See the additional information regarding Contractor Team Arrangements in this Schedule Pricelist.

₩MITEL

TERMS AND CONDITIONS

TERMS AND CONDITIONS APPLICABLE TO PURCHASE OF GENERAL PURPOSE COMMERCIAL INFORMATION TECHNOLOGY EQUIPMENT (SPECIAL ITEM NUMBER 132-8)

1. MATERIAL AND WORKMANSHIP

All equipment furnished hereunder must satisfactorily perform the function for which it is intended.

2. ORDER

Written orders, EDI orders (GSA Advantage! and FACNET), credit card orders, and orders placed under blanket purchase agreements (BPA) agreements shall be the basis for purchase in accordance with the provisions of this contract. If time of delivery extends beyond the expiration date of the contract, the Contractor will be obligated to meet the delivery and installation date specified in the original order.

For credit card orders and BPAs, telephone orders are permissible.

3. TRANSPORTATION OF EQUIPMENT

FOB DESTINATION. Prices cover equipment delivery to destination, for any location within the geographic scope of this contract.

4. INSTALLATION AND TECHNICAL SERVICES

NOTE: Mitel equipment is self-installable.

- a. **INSTALLATION**. When the equipment provided under this contract is not normally self-installable, the Contractor's technical personnel shall be available to the Government, at the Government's location, to install the equipment and to train Government personnel in the use and maintenance of the equipment. The charges, if any, for such services are listed below, or in the price schedule:
- b. **OPERATING AND MAINTENANCE MANUALS**. Mitel shall furnish the Government with one (1) copy of all operating and maintenance manuals relating to the software being purchased/installed.

5. INSPECTION/ACCEPTANCE

The Contractor shall only tender for acceptance those items that conform to the requirements of this contract. The Government reserves the right to inspect or test any equipment that has been tendered for acceptance. The Government may require repair or replacement of nonconforming equipment at no increase in contract price. The Government must exercise its post acceptance rights (1) within a reasonable time after the defect was discovered or should have been discovered; and (2) before any substantial change occurs in the condition of the item, unless the change is due to the defect in the item.

6. WARRANTY

a. Unless specified otherwise in this contract, the Contractor's standard commercial warranty as stated in the contract's commercial pricelist will apply to this contract.



7. PURCHASE PRICE FOR ORDERED EQUIPMENT

The purchase price that the Government will be charged will be the Government purchase price in effect at the time of order placement, or the Government purchase price in effect on the installation date (or delivery date when installation is not applicable), whichever is less.

8. RESPONSIBILITIES OF THE CONTRACTOR

The Contractor shall comply with all laws, ordinances, and regulations (Federal, State, City or otherwise) covering work of this character, and shall include all costs, if any, of such compliance in the prices quoted in this offer.

9. TRADE-IN OF INFORMATION TECHNOLOGY EQUIPMENT

When an agency determines that Information Technology equipment will be replaced, the agency shall follow the contracting policies and procedures in the Federal Acquisition Regulation (FAR), the policies and procedures regarding disposition of information technology excess personal property in the Federal Property Management Regulations (FPMR) (41 CFR 101-43.6), and the policies and procedures on exchange/sale contained in the FPMR (41 CFR part 101-46).

TERMS AND CONDITIONS APPLICABLE TO MAINTENANCE, REPAIR SERVICE AND REPAIR PARTS/SPARE PARTS FOR GOVERNMENT-OWNED GENERAL PURPOSE COMMERCIAL INFORMATION TECHNOLOGY EQUIPMENT (AFTER EXPIRATION OF GUARANTEE/WARRANTY PROVISIONS AND/OR WHEN REQUIRED SERVICE IS NOT COVERED BY GUARANTEE/WARRANTY PROVISIONS) AND FOR LEASED EQUIPMENT (SPECIAL ITEM NUMBER 132-12)

MITEL

TERMS AND CONDITIONS

1. SERVICE AREAS

- a. The maintenance and repair service rates listed herein are applicable to any Government location within a N/A mile radius of the Contractor's service points. If any additional charge is to apply because of the greater distance from the Contractor's service locations, the mileage rate or other distance factor shall be stated in paragraphs 7.d and 8.d of this Special Item Number 132-12.
- b. When repair services cannot be performed at the Government installation site, the repair services will be performed at the Contractor's plant(s) listed below:

Mitel, Inc. 120 Chimney Point Drive Ogdensburg, NY 13669-2292

2. MAINTENANCE ORDER

- a. Agencies may use written orders, EDI orders, credit card orders, or BPAs, for ordering maintenance under this contract. The Contractor shall confirm orders within fifteen (15) calendar days from the date of receipt, except that confirmation of orders shall be considered automatic for renewals for maintenance (Special Item Number 132-12). Automatic acceptance of order renewals for maintenance service shall apply for machines which may have been discontinued from use for temporary periods of time not longer than 120 calendar days. If the order is not confirmed by the Contractor as prescribed by this paragraph, the order shall be considered to be confirmed by the Contractor.
- b. The Contractor shall honor orders for maintenance for the duration of the contract period or a lessor period of time, for the equipment shown in the pricelist. Maintenance service shall commence on a mutually agreed upon date, which will be written into the maintenance order. Maintenance orders shall <u>not</u> be made effective before the expiration of any applicable maintenance and parts guarantee/warranty period associated with the purchase of equipment. Orders for maintenance service shall not extend beyond the end of the contract period.
- c. Maintenance may be discontinued by the Government on thirty (30) calendar days written notice, or shorter notice when agreed to by the Contractor; such notice to become effective thirty (30) calendar days from the date on the notification. However, the Government may extend the original discontinuance date upon written notice to the Contractor, provided that such notice is furnished at least ten (10) calendar days prior to the original discontinuance date.
- d. Annual Funding. When annually appropriated funds are cited on a maintenance order, the period of maintenance shall automatically expire on September 30th of the contract period, or at the end of the contract period, whichever occurs first. Renewal of a maintenance order citing the new appropriation shall be required, if maintenance is to continue during any remainder of the contract period.
- e. Cross-year Funding Within Contract Period. Where an ordering office's specific appropriation authority provides for funds in excess of a 12 month, fiscal year period, the ordering office may place an order under this schedule contract for a period up to the expiration of the contract period, notwithstanding the intervening fiscal years.

Prices quoted in Net U.S. Dollars e. and o.e.

MITEL

TERMS AND CONDITIONS

f. Ordering offices should notify the Contractor in writing thirty (30) calendar days prior to the expiration of maintenance service, if maintenance is to be terminated at that time. Orders for continued maintenance will be required if maintenance is to be continued during the subsequent period.

3. REPAIR SERVICE AND REPAIR PARTS/SPARE PARTS ORDERS

- a. Agencies may use written orders, EDI orders, credit card orders, blanket purchase agreements (BPAs), or small order procedures for ordering repair service and/or repair parts/spare parts under this contract. Orders for repair service shall not extend beyond the end of the contract period.
- b. When repair service is ordered, only one chargeable repairman shall be dispatched to perform repair service, unless the ordering office agrees, in advance, that additional repair personnel are required to effect repairs.

4. LOSS OR DAMAGE

When the Contractor removes equipment to his establishment for repairs, the Contractor shall be responsible for any damage or loss, from the time the equipment is removed from the Government installation, until the equipment is returned to such installation.

SCOPE

- a. The Contractor shall provide maintenance for all equipment listed herein, as requested by the Government agency during the contract term. Repair service and repair parts/spare parts shall apply exclusively to the equipment types/models within the scope of this Information Technology Schedule.
- b. Equipment placed under maintenance service shall be in good operating condition.
- (1) In order to determine that the equipment is in good operating condition, the equipment shall be subject to inspection by the Contractor, without charge to the Government.
- (2) Costs of any repairs performed for the purpose of placing the equipment in good operating condition shall be borne by the Contractor, if the equipment was under the Contractor's guarantee/warranty or maintenance responsibility prior to the effective date of the maintenance order.
- (3) If the equipment was not under the Contractor's responsibility, the costs necessary to place the equipment in proper operating condition are to be borne by the Government, in accordance with the provisions of Special Item Number 132-12 (or outside the scope of this contract).

6. RESPONSIBILITIES OF THE GOVERNMENT

a. Government personnel shall not perform maintenance or attempt repairs to equipment while such equipment is under the purview of a maintenance order, unless agreed to by the Contractor.



b. Subject to security regulations, the Government shall permit access to the equipment which is to be maintained or repaired.

7. RESPONSIBILITIES OF THE CONTRACTOR

For equipment not covered by a maintenance contract or warranty, the Contractor's repair service personnel shall complete repairs as soon as possible after notification by the Government that service is required. Within the service areas, this repair service should normally be done within 4 hours after notification.

8. MAINTENANCE RATE PROVISIONS

a. The Contractor shall bear all costs of maintenance, including labor, parts, and such other expenses as are necessary to keep the equipment in good operating condition, provided that the required repairs are not occasioned by fault or negligence of the Government.

b. REGULAR HOURS

The basic monthly rate for each make and model of equipment shall entitle the Government to maintenance service during a mutually agreed upon nine (9) hour principal period of maintenance, Monday through Friday, exclusive of holidays observed at the Government location.

c. AFTER HOURS

Should the Government require that maintenance be performed outside of Regular Hours, charges for such maintenance, if any, will be specified in the pricelist. Periods of less than one hour will be prorated to the nearest quarter hour.

d. TRAVEL AND TRANSPORTATION

If any charge is to apply, over and above the regular maintenance rates, because of the distance between the Government location and the Contractor's service area, the charge will be:

Not Applicable e. QUANTITY DISCOUNTS

Quantity discounts from listed maintenance service rates for multiple equipment owned and/or leased by a Government agency are indicated below:

| Quantity Range | | <u>Discounts</u> |
|----------------|-------|------------------|
| N/A | Units | % |
| N/A | Units | % |
| N/A | Units | % |

MITEL.

TERMS AND CONDITIONS

9. REPAIR SERVICE RATE PROVISIONS

- a. CHARGES. Charges for repair service will include the labor charge, computed at the rates set forth below, for the time during which repairmen are actually engaged in work, and, when applicable, the charge for travel or transportation.
- b. MULTIPLE MACHINES. When repairs are ordered by a Government agency on two or more machines located in one or more buildings within walking distance of each other, the charges will be computed from the time the repairman commences work on the first machine, until the work is completed on the last machine. The time required to go from one machine to another, or from one building to another, will be considered actual work performance, and chargeable to the Government, provided the time consumed in going between machines (or buildings) is reasonable.

c. TRAVEL OR TRANSPORTATION

(1) AT THE CONTRACTOR'S SHOP

- (a) When equipment is returned to the Contractor's shop for adjustments or repairs which are not covered by the guarantee/warranty provision, the cost of transportation, packing, etc., from the Government location to the Contractor's plant, and return to the Government location, shall be borne by the Government.
- (b) The Government should not return defective equipment to the Contractor for adjustments and repairs or replacement without his prior consultation and instruction. (2) AT THE GOVERNMENT LOCATION (Within Established Service Areas)

When equipment is repaired at the Government location, and repair service rates are established for service areas or zones, the listed rates are applicable to any Government location within such service areas or zones. No extra charge, time, or expense will be allowed for travel or transportation of repairmen or machines to or from the Government office; such overhead is included in the repair service rates listed.

- (3) AT THE GOVERNMENT LOCATION (Outside Established Service Areas)
- (a) The repair service rates listed for subparagraph (2) above apply, except that a travel charge of N/A per mile for repairmen will apply to the round-trip distance between the geographic limits of the applicable service area and the Government location. Such charge will apply as an additional charge, but it will be limited to one round trip for each request that is made by the ordering activity for repair service, regardless of whether repairs are performed at the Government location or at the Contractor's shop.
- (b) When the overall travel charge computed at the above mileage rate is unreasonable (considering the time required for travel, actual and necessary transportation costs, and the allowable Government per diem rate for each night the repairman is required to remain overnight at the Government location), the Government shall have the option of reimbursing the Contractor for actual costs, provided that the actual costs are reasonable and allowable. The Contractor shall furnish the Government with a report of travel performed and related expenses incurred. The report shall include departure and arrival dates, times, and the applicable mode of travel.

₩MITEL

TERMS AND CONDITIONS

d. LABOR RATES

(1) REGULAR HOURS

The Regular Hours repair service rates listed herein shall entitle the Government to repair service during the period 8:00 a.m. to 5:00 p.m., Monday through Friday, exclusive of holidays observed at the Government location. There shall be no additional charge for repair service which was requested during Regular Hours, but performed outside the Regular Hours defined above, at the convenience of the Contractor.

(2) AFTER HOURS

When the Government requires that repair service be performed outside the Regular Hours defined above, except Sundays and Holidays observed at the Government location, the After Hours repair service rates listed herein shall apply. The Regular Hours rates defined above shall apply when repair service is requested during Regular Hours, but performed After Hours at the convenience of the Contractor.

(3) SUNDAYS AND HOLIDAYS

When the Government requires that repair service be performed on Sundays and Holidays observed at the Government location, the Sundays and Holidays repair service rates listed herein shall apply. When repair service is requested to be performed during Regular Hours and/or After Hours, but is performed at the convenience of the Contractor on Sundays or Holidays observed at the Government location, the Regular Hours and/or After Hours repair service rates, as applicable, shall apply.

| ppiicabie, si iaii appiy. | | | | |
|---|----------------------------|---|---------------------------|----------------------------------|
| REPAIR SERVICE RA | ATES | | | |
| Location | Minimu m Charge * | Regular Hours Per Hour ** | After Hours Per Hour** | Sundays and Holidays Per Hour |
| Contractor's Shop | N/A | See Repair Pricelist which follows new parts | N/A | N/A |
| Government Location (within established service areas) | N/A | N/A | N/A | N/A |
| Government Location (outside established service areas) | N/A | N/A | N/A | N/A |

^{*}MINIMUM CHARGES INCLUDE FULL HOURS ON THE JOB.

^{**}FRACTIONAL HOURS, AT THE END OF THE JOB, WILL BE PRORATED TO THE NEAREST QUARTER HOUR.

MITEL.

TERMS AND CONDITIONS

10. REPAIR PARTS/SPARE PARTS RATE PROVISIONS

All parts, furnished as spares or as repair parts in connection with the repair of equipment, unless otherwise indicated in this pricelist, shall be new, standard parts manufactured by the equipment manufacturer. All parts shall be furnished at prices indicated in the Contractor's commercial pricelist dated 05/10/00, at a discount of 10% from such listed prices.

11. GUARANTEE/WARRANTY—REPAIR SERVICE AND REPAIR PARTS/SPARE PARTS

a. REPAIR SERVICE

All repair work will be guaranteed/warranted for a period of two years.

b. REPAIR PARTS/SPARE PARTS

All parts, furnished either as spares or repairs parts will be guaranteed/warranted for a period two years.

12. INVOICES AND PAYMENTS

- a. Maintenance Service
- (1) Invoices for maintenance service shall be submitted by the Contractor on a quarterly or monthly basis, after the completion of such period. Maintenance charges must be paid in arrears (31 U.S.C. 3324). PROMPT PAYMENT DISCOUNT, IF APPLICABLE, SHALL BE SHOWN ON THE INVOICE.
- (2) Payment for maintenance service of less than one month's duration shall be prorated at 1/30th of the monthly rate for each calendar day.
 - b. Repair Service and Repair Parts/Spare Parts

Invoices for repair service and parts shall be submitted by the Contractor as soon as possible after completion of work. Payment under blanket purchase agreements will be made quarterly or monthly, except where cash payment procedures are used. Invoices shall be submitted separately to each Government office ordering services under the contract. The cost of repair parts shall be shown as a separate item on the invoice, and shall be priced in accordance with paragraph #10, above. PROMPT PAYMENT DISCOUNT, IF APPLICABLE, SHALL BE SHOWN ON THE INVOICE.

MITEL

TERMS AND CONDITIONS

TERMS AND CONDITIONS APPLICABLE TO
TERM SOFTWARE LICENSES (SPECIAL ITEM NUMBER 132-32),
PERPETUAL SOFTWARE LICENSES (SPECIAL ITEM NUMBER 132-33) AND
MAINTENANCE (SPECIAL ITEM NUMBER 132-34) OF GENERAL PURPOSE
COMMERCIAL INFORMATION TECHNOLOGY SOFTWARE

1. INSPECTION/ACCEPTANCE

The Contractor shall only tender for acceptance those items that conform to the requirements of this contract. The Government reserves the right to inspect or test any software that has been tendered for acceptance. The Government may require repair or replacement of nonconforming software at no increase in contract price. The Government must exercise its post acceptance rights (1) within a reasonable time after the defect was discovered or should have been discovered; and (2) before any substantial change occurs in the condition of the software, unless the change is due to the defect in the software.

2. GUARANTEE/WARRANTY

 Unless specified otherwise in this contract, the Contractor's standard commercial guarantee/warranty as stated in the contract's commercial pricelist will apply to this contract.

3. TECHNICAL SERVICES

The Contractor, without additional charge to the Government, shall provide a hot line technical support number 1-800-561-0860 for the purpose of providing user assistance and guidance in the implementation of the software. The technical support number is available from 8:30 am to 6:00 pm Eastern Standard Time.

4. SOFTWARE MAINTENANCE

a. Software maintenance service shall include the following:

See Mitel Product Warranty statement

b. Invoices for maintenance service shall be submitted by the Contractor on a quarterly or monthly basis, after the completion of such period. Maintenance charges must be paid in arrears (31 U.S.C. 3324). PROMPT PAYMENT DISCOUNT, IF APPLICABLE, SHALL BE SHOWN ON THE INVOICE.

5. PERIODS OF TERM LICENSES (132-32) AND MAINTENANCE (132-34)

- a. The Contractor shall honor orders for periods for the duration of the contract period or a lessor period of time.
- b. Term licenses and/or maintenance may be discontinued by the Government on thirty (30) calendar days written notice to the Contractor.
- c. Annual Funding. When annually appropriated funds are cited on an order for term licenses and/or maintenance, the period of the term licenses and/or maintenance shall automatically expire on September 30 of the contract period, or at the end of the contract period, whichever occurs first. Renewal of the term licenses and/or maintenance orders citing the new appropriation shall be required, if the term licenses and/or maintenance is to be continued during any remainder of the contract period.



- d. Cross-Year Funding Within Contract Period. Where an ordering office's specific appropriation authority provides for funds in excess of a 12 month (fiscal year) period, the ordering office may place an order under this schedule contract for a period up to the expiration of the contract period, notwithstanding the intervening fiscal years.
- e. Ordering offices should notify the Contractor in writing thirty (30) calendar days prior to the expiration of an order, if the term licenses and/or maintenance is to be terminated at that time. Orders for the continuation of term licenses and/or maintenance will be required if the term licenses and/or maintenance is to be continued during the subsequent period.

6. UTILIZATION LIMITATIONS - (132-32, 132-33, AND 132-34)

- a. Software acquisition is limited to commercial computer software defined in FAR Part2.101.
- b. When acquired by the Government, commercial computer software and related documentation so legend shall be subject to the following:
- (1) Title to and ownership of the software and documentation shall remain with the Contractor, unless otherwise specified.
- (2) Software licenses are by site and by agency. An agency is defined as a cabinet level or independent agency. The software may be used by any subdivision of the agency (service, bureau, division, command, etc.) that has access to the site the software is placed at, even if the subdivision did not participate in the acquisition of the software. Further, the software may be used on a sharing basis where multiple agencies have joint projects that can be satisfied by the use of the software placed at one agency's site. This would allow other agencies access to one agency's database. For Government public domain databases, user agencies and third parties may use the computer program to enter, retrieve, analyze and present data. The user agency will take appropriate action by instruction, agreement, or otherwise, to protect the Contractor's proprietary property with any third parties that are permitted access to the computer programs and documentation in connection with the user agency's permitted use of the computer programs and documentation. For purposes of this section, all such permitted third parties shall be deemed agents of the user agency.

REVISION – AMENDMENT #1

(3) Except as is provided in paragraph 8.b(2) above, the Government shall not provide or otherwise make available the software or documentation, or any portion thereof, in any form, to any third party without the prior written approval of the Contractor. Third parties do not include prime Contractors, subcontractors and agents of the government who have the Government's permission to use the licensed software and documentation at the facility, and who have agreed to use the licensed software and documentation only in accordance with these restrictions. This provision does not limit the right of the Government to use software, documentation, or information therein, which the Government may already have or obtains without restrictions.



- (4) The Government shall have the right to use the computer software and documentation with the computer for which it is acquired at any other facility to which that computer may be transferred, or in cases of disaster recovery, the Government has the right to transfer the software to another site if the Government site for which it is acquired is deemed to be unsafe for Government personnel; to use the computer software and documentation with a backup computer when the primary computer is inoperative; to copy computer programs for safekeeping (archives) or backup purposes; to transfer a copy of the software to another site for purposes of benchmarking new hardware and/or software; and to modify the software and documentation or combine it with other software, provided that the unmodified portions shall remain subject to these restrictions.
- (5) "Commercial Computer Software" may be marked with the Contractor's standard commercial restricted rights legend, but the schedule contract and schedule pricelist, including this clause, "Utilization Limitations" are the only governing terms and conditions, and shall take precedence and supersede any different or additional terms and conditions included in the standard commercial legend.

7. SOFTWARE CONVERSIONS - (132-32 AND 132-33)

Full monetary credit will be allowed to the Government when conversion from one version of the software to another is made as the result of a change in operating system, or from one computer system to another. Under a perpetual license (132-33), the purchase price of the new software shall be reduced by the amount that was paid to purchase the earlier version. Under a term license (132-32), conversion credits which accrued while the earlier version was under a term license shall carry forward and remain available as conversion credits which may be applied towards the perpetual license price of the new version.

8. DESCRIPTIONS AND EQUIPMENT COMPATIBILITY

The Contractor shall include, in the schedule pricelist, a complete description of each software product and a list of equipment on which the software can be used. Also, included shall be a brief, introductory explanation of the modules and documentation which are offered.

USA COMMITMENT TO PROMOTE SMALL BUSINESS PARTICIPATION PROCUREMENT PROGRAMS

PREAMBLE

Mitel, Inc. provides commercial products and services to the Federal Government. We are committed to promoting participation of small, small disadvantaged and women-owned small businesses in our contracts. We pledge to provide opportunities to the small business community through reselling opportunities, mentor-protégé programs, joint ventures, teaming arrangements, and subcontracting.



COMMITMENT

To actively seek and partner with small businesses.

To identify, qualify, mentor and develop small, small disadvantaged and women-owned small businesses by purchasing from these businesses whenever practical.

To develop and promote company policy initiatives that demonstrate our support for awarding contracts and subcontracts to small business concerns.

To undertake significant efforts to determine the potential of small, small disadvantaged and women-owned small business to supply products and services to our company.

To insure procurement opportunities are designed to permit the maximum possible participation of small, small disadvantaged, and women-owned small businesses.

To attend business opportunity workshops, minority business enterprise seminars, trade fairs, procurement conferences, etc., to identify and increase small businesses with whom to partner.

To publicize in our marketing publications our interest in meeting small businesses that may be interested in subcontracting opportunities.

We signify our commitment to work in partnership with small, small disadvantaged and womenowned small businesses to promote and increase their participation in Federal Government contracts. To accelerate potential opportunities please contact Glenda Paquin. Phone: (613-592-2122), Glenda Paquin@Mitel.com, , FAX: (613-592-1284).



BEST VALUE BLANKET PURCHASE AGREEMENT FEDERAL SUPPLY SCHEDULE (Insert Customer Name)

| In the spirit of the Federal Ac (Agency) and (Con | | g Act a cooperative agreement to further reduce the |
|--|--|--|
| administrative costs of acqui (GSA) Federal Supply Sche | | s from the General Services Administration |
| search for sources; the deve | lopment of technical c nts are permitted with | contracting and open market costs such as: documents, solicitations and the evaluation of Federal Supply Schedule Contractors in FAR) 9.6. |
| repetitive, individual purchas | es from the schedule | work, and save time by eliminating the need for contract. The end result is to create a works better and costs less. |
| Signatures | | |
| AGENCY | DATE DATE | CONTRACTOR |
| | | BPA NUMBER |



(CUSTOMER NAME) BLANKET PURCHASE AGREEMENT

| Pursuant to GSA Federal Supply Schedule Co Agreements, the Contractor agrees to the follo (BPA) EXCLUSIVELY WITH (Ordering Agency | |
|---|---|
| (1) The following contract items can be ordere BPA are subject to the terms and conditions of | ed under this BPA. All orders placed against this the contract, except as noted below: |
| MODEL NUMBER/PART NUMBER | *SPECIAL BPA DISCOUNT/PRICE |
| (2) Delivery: | |
| DESTINATION | DELIVERY SCHEDULE/DATES |
| (3) The Government estimates, but does not gethis agreement will be | guarantee, that the volume of purchases through |
| (4) This BPA does not obligate any funds. | |
| (5) This BPA expires onearlier. (6) The following office(s) is hereby au | or at the end of the contract period, whichever is thorized to place orders under this BPA: |
| OFFICE | POINT OF CONTACT |
| | |
| (7) Orders will be placed against this BPA via | Electronic Data Interchange (EDI), FAX, or paper. |
| (8) Unless otherwise agreed to, all deliveries utickets or sales slips that must contain the follows: | under this BPA must be accompanied by delivery wing information as a minimum: |
| (a) Name of Contractor; | |
| (b) Contract Number; | |
| (c) BPA Number; | |
| (d) Model Number or National Stock N | Number (NSN); |
| (e) Purchase Order Number; | |
| (f) Date of Purchase; | |
| | n of Each Item (unit prices and extensions need not utomated systems; provided, that the invoice is |
| (h) Date of Shipment. | |



- 9) The requirements of a proper invoice are specified in the Federal Supply Schedule contract. Invoices will be submitted to the address specified within the purchase order transmission issued against this BPA.
- (10) The terms and conditions included in this BPA apply to all purchases made pursuant to it. In the event of an inconsistency between the provisions of this BPA and the Contractor's invoice, the provisions of this BPA will take precedence.

BASIC GUIDELINES FOR USING "CONTRACTOR TEAM ARRANGEMENTS"

Federal Supply Schedule Contractors may use "Contractor Team Arrangements" (see FAR 9.6) to provide solutions when responding to a customer agency requirements.

These Team Arrangements can be included under a Blanket Purchase Agreement (BPA). BPAs are permitted under all Federal Supply Schedule contracts.

Orders under a Team Arrangement are subject to <u>terms and conditions</u> or the Federal Supply Schedule Contract.

Participation in a Team Arrangement is limited to Federal Supply Schedule Contractors.

Customers should refer to FAR 9.6 for specific details on Team Arrangements.

Here is a general outline on how it works:

- (1) The customer identifies their requirements.
- (2) Federal Supply Schedule Contractors may individually meet the customers needs, or -
- (3) Federal Supply Schedule Contractors may individually submit a Schedules "Team Solution" to meet the customer's requirement.
- (4) Customers make a best value selection.



U.S. PRODUCT WARRANTY

- a. Mitel warrants that its private branch exchange (PBX) PRODUCTS (as well as Mitel Mail®), except the firmware and software program components thereof, will, if delivered by Customer to the end-user in undamaged condition, be free from defects in material and workmanship under normal use and service for a period of either fifteen (15) months from the date of shipment by Mitel to Customer or twelve (12) months from the date Customer cuts over the PRODUCT whichever is sooner.
- b. Mitel likewise warrants that the software and firmware program components of such pbx PRODUCTS, to the extent such are utilized to provide an operating system or an embedded application ("inside the skins") for a Mitel pbx telecommunications system, will perform for the same period of time, substantially in conformity with the Mitel provided technical documentation (functional and operating specifications) that Mitel publishes regarding same (end-user reference and operating manuals and guides relating to the program). The software and firmware media will nevertheless be warranted as stated in subparagraph a., above.
- c. Mitel likewise warrants that the software and firmware program components of its PRODUCTS, to the extent such are utilized to provide an external (peripheral) operating system or an external (peripheral) application for a Mitel pbx or for a Mitel computer telephony integration telecommunications system, will perform for a period of either one hundred twenty (120) days from the date of shipment or ninety (90) days from the date Customer cuts over the PRODUCT, whichever is sooner. The software and firmware media will nevertheless be warranted as stated in subparagraph a), above.
- d. MITEL DOES NOT, HOWEVER, WARRANT THAT THE FUNCTIONS CONTAINED IN THE SOFTWARE AND FIRMWARE PROGRAMS AS DESCRIBED IN SUBPARAGRAPHS b) AND c) ABOVE, WILL SATISFY CUSTOMER'S PARTICULAR PURPOSE AND/OR REQUIREMENTS OR THAT THE OPERATION OF THE PROGRAM WILL BE UNINTERRUPTED OR ERROR FREE.
- e. Notwithstanding anything hereinabove to the contrary, any third-party developed and manufactured software or firmware that is not branded by Mitel as a Mitel PRODUCT and/or is included with a PRODUCT in an unmodified condition under license from a third-party (e.g., TASKE programs, a Microsoft program or Novell program) carries just the warranty of the Licensor which Mitel will pass through to the Customer. SUCH A NON-MITEL PROGRAM IS NOT SEPARATELY WARRANTED BY MITEL WITH THE SOLE EXCEPTION OF PHONEWARE AND FASTCALL WHICH ARE WARRANTED AS PER SUBPARAGRAPH c) above.
- f. Mitel shall incur no liability under this warranty and this warranty is voidable by Mitel (a) if the PRODUCT is used other than under normal use, with certified repair and maintenance service and under proper environmental conditions, (b) if the PRODUCT is subject to abuse, misuse, neglect, flooding, fire, lightning, power surges or "dirty" power, third-party error or omission, acts of God, damage or accident, (c) if the PRODUCT is modified or altered (unless expressly authorized in writing by Mitel), (d) if the PRODUCT is installed or used in combination or in assembly with products not supplied or authorized by Mitel and/or which are not compatible with or are of inferior quality, design or performance to Mitel or Mitel supplied PRODUCTS so as to cause a diminution or degradation in functionality, (e) if there is a failure to follow specific restrictions in operating instructions. Or (f) if payment for PRODUCT has not been timely made.



- g. The sole obligation of Mitel and the exclusive remedy and recourse of Customer under this warranty, or any other legal obligation, with respect to PRODUCT, including hardware, firmware, and software media, is for Mitel, at its election, to either repair and/or replace the allegedly defective PRODUCT or component(s) thereof and return (prepaid) same (if necessary), or grant a reimbursement credit with respect to the PRODUCT or component. With regard to a software program design defect, however, to the extent it prevents the program from providing specified functionality and/or operating as intended by Mitel, is service affecting, and prevents beneficial use of the product, Mitel does undertake to use its best efforts to devise a suitable corrective solution to the problem within a reasonable period of time; should said action, however, not substantially resolve the problem, then Mitel reserves the right to incorporate such solution in a new release ("stream") of software. The above, with regard to a software design defect, likewise, constitutes the sole obligation of Mitel and exclusive remedy of Customer hereunder with respect to PRODUCT.
- h. The responsibility of Mitel to honor the express limited warranty stated above also shall be predicated on receiving timely written notice of the alleged defect(s) with as much specificity as is known within thirty (30) calendar days of the malfunction or by the expiration of the warranty period (plus thirty [30] calendar days), whichever occurs first. Mitel shall further have the right to inspect and test the PRODUCT to determine, in its reasonable discretion, if the alleged malfunction is actually due to defects in material or workmanship. Unless waived by Mitel, Customer agrees to return (prepaid) the allegedly defective PRODUCT or component to Mitel for inspection and/or testing, and, if appropriate, for repair and/or replacement.
- i. THE ABOVE EXPRESS LIMITED WARRANTY IS IN LIEU OF ALL OTHER WARRANTIES, EXPRESS OR IMPLIED, FROM MITEL (INCLUDING ITS PARENT) AND THERE ARE NO OTHER WARRANTIES WHICH EXTEND BEYOND THE FACE OF THIS WARRANTY. ALL OTHER WARRANTIES WHATSOEVER, INCLUDING THE IMPLIED WARRANTY OF MERCHANTABILITY AND THE IMPLIED WARRANTY OF FITNESS FOR A PARTICULAR PURPOSE RELATING TO USE OR PERFORMANCE OF THE PRODUCT, INCLUDING ITS PARTS, ARE HEREBY EXCLUDED AND DISCLAIMED.
- j. IN NO EVENT SHALL MITEL (INCLUDING ITS PARENT) UNDER ANY CIRCUMSTANCES, BE LIABLE FOR NOR SHALL CUSTOMER (DIRECTLY OR INDIRECTLY) BE ENTITLED TO ANY SPECIAL, CONSEQUENTIAL, INCIDENTAL, INDIRECT, PUNITIVE OR EXEMPLARY DAMAGES AS A RESULT OF THE SALE OR LEASE OF PRODUCT, INCLUDING BUT NOT LIMITED TO FAILURE TO TIMELY DELIVER THE PRODUCT OR FAILURE OF PRODUCT TO ACHIEVE CERTAIN FUNCTIONALITY, OR ARISING OUT OF THE USE OR INABILITY TO USE THE PRODUCT, IN WHOLE OR IN PART AND INCLUDING BUT NOT LIMITED TO LOSS OF PROFIT, LOSS OF USE, DAMAGE TO BUSINESS OR DAMAGE TO BUSINESS RELATIONS. MITEL SHALL NOT BE LIABLE FOR PERSONAL INJURY OR PROPERTY DAMAGE UNLESS CAUSED SOLELY BY MITEL'S NEGLIGENCE.

U.S. PRODUCT WARRANTY



CONDITIONS CONCERNING USE OF MITEL SOFTWARE

- a. Customer receives no right to use any Mitel Software except by the grant of an express written license from Mitel as delineated in the underlying Agreement. Customer agrees to use the Mitel Software only in conjunction with the Mitel PRODUCTS with which it is intended to operate. Customer agrees that all Mitel Software shall be treated as the exclusive property of Mitel or its suppliers, as appropriate, and a proprietary trade secret of Mitel or its suppliers, as appropriate. Customer shall take those steps as may be necessary to hold the Mitel Software in confidence for the benefit of Mitel or its suppliers, as appropriate. Customer shall not provide or make the Mitel Software available to any person other than its employees on a "need to know" basis and shall issue adequate instructions to those persons necessary to satisfy Customer's obligations under this provision.
- b. Customer shall not execute, use, copy, alter or modify the Mitel Software (except for making a back-up copy) or take any action inconsistent with the exclusive ownership interest of Mitel or its suppliers, as appropriate, in the Mitel Software. Customer shall not decompile, reverse assemble, analyze or otherwise examine for reverse engineering purposes the Mitel Software, in whole or in part, or any firmware implementation of the Mitel Software. Customer may not sublicense the Mitel Software, in whole in or part, without first assuring that its sublicensee agrees, in writing, to adhere to the terms hereof. Customer may only use the Mitel Software in conjunction with the Mitel equipment configuration on which the Mitel Software may be executed and at the originally installed site without obtaining written permission otherwise from Mitel. Upon termination of this license, Customer shall deliver to Mitel all material supplied by Mitel pertaining to the license.
- c. During the term of this Agreement, and when not in default or breach hereunder, Customer shall have the right to sublicense the Mitel Software to its customers subject to the terms hereof and only for the operation by its customers of associated Mitel PRODUCTS. Customer agrees to take prompt steps to terminate any sub-license granted hereunder by Customer under direction from Mitel if its customer fails to comply with the terms of such sub-license and does not cure such failure within ten (10) days written notice from Customer.

TOLL FRAUD DISCLAIMER/WARNING

Mitel disclaims any express or implied warranty that its equipment is technically immune from or prevents fraudulent intrusions into and/or unauthorized use of the system (including its interconnection to the long distance network). Customer is hereby warned that fraudulent use of the system, including but not limited to DISA, auto-attendant, voice mail, 800, 888, 900, and 10XXX/10XXXXX service, is possible, and Customer agrees to warn its customers of such. Mitel also warns Customer that while telecommunications systems are not immune from toll fraud by an intervening criminal act, that Mitel has published a Technical Service Bulletin entitled "PABX-CDE Programming Pertaining to Unauthorized Toll Calling Access", which, if its recommendations are properly followed, will help minimize the threat of fraudulent intrusion into the system for the purpose of gaining access to a long distance line.

INVASION OF PRIVACY DISCLAIMER/WARNING

Mitel hereby disclaims any express or implied warranty that its equipment is technically immune from or prevents unlawful and/or unauthorized utilization that may result in invasion of one's right to privacy. Mitel hereby warns Customer that such is possible, and Customer agrees to warn its customers of such.

Prices quoted in Net U.S. Dollars
e. and o.e.

Page 1-28

₩MITEL

U.S. PRODUCT WARRANTY

LOSS OR THEFT OF DATA

Mitel hereby disclaims any express or implied warranty that its equipment is technically immune from or prevents improper, unlawful and/or unauthorized utilization that may result in the loss of or theft of electronic data. Mitel hereby warns Customer that such is possible, and Customer agrees to warn its customers of such.

- b. The Contractor warrants and implies that the items delivered hereunder are merchantable and fit for use for the particular purpose described in this contract.
- c. Limitation of Liability. Except as otherwise provided by an express or implied warranty, the Contractor will not be liable to the Government for consequential damages resulting from any defect or deficiencies in accepted items.
- d. If inspection and repair of defective equipment under this warranty will be performed at the Contractor's plant, the address is as follows:

Mitel, Inc. 120 Chimney Point Drive Ogdensburg, NY 13669-2292





| PART NUMBER | DESCRIPTION |
|--------------|-------------|
| FAN I NUMBEN | DESCRIFTION |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

CHANGE SUMMARY NEW PART NUMBERS

| | PR | |
|--|----|--|
| | | |
| | | |

| NEW 50000180 | \$2,116.20 | NPM 90HR Upgrade from 6.0 to 7.0 System - Model 70 |
|-------------------------|------------|--|
| NEW 50000181 | \$5,104.90 | NPM 210HR Upgrade from 6.0 to 7.0 System - Model 70 |
| NEW 50000402 | \$1,916.17 | SUPERSET 4025 DK GREY - 12 PACK |
| NEW 50000403 | \$1,916.17 | SUPERSET 4025 LT GREY - 12 PACK |
| NEW 52000060 | \$2,299.00 | Upgrade SX-200D 456 Port G1002-5 Basic to SX-200EL |
| ^{NEW} 52000061 | \$1,699.00 | Upgrade SX-200L LW16 Basic to SX-200ML |
| NEW 52000062 | \$1,399.00 | Upgrade SX-200ML to SX-200EL w/MCC III ELx |
| NEW 52000063 | \$2,099.00 | Upgrade SX-200D 480 Port G1003-5 ACD to SX-200 EL |
| ^{NEW} 52000064 | \$1,699.00 | Upgrade SX-200L LW16 ENH 72 Port to SX-200 ML |
| NEW 52000065 | \$2,099.00 | Upgrade SX-200D 480 Port G1004-5 BSC+MAI to SX-200 EL |
| NEW 52000066 | \$1,929.00 | Upgrade SX-200L LW16 ENH 144 Port to SX-200 EL |
| NEW 52000067 | \$2,299.00 | Upgrade SX-200D 456 Port G1004-5 BSC+MAI to SX-200EL |
| NEW 52000068 | \$1,929.00 | Upgrade SX-200L LW15 to SX-200EL |
| NEW 52000069 | \$2,899.00 | Upgrade SX-200D 672 LW15 or G1003-4 ACD to SX-200EL |
| NEW 52000070 | \$2,899.00 | Upgrade SX-200D 672 Port LW15 or G1003-4BSC to SX-200EL |
| NEW 52000071 | \$2,699.00 | Upgrade SX-200D 336 Port LW15 or G1001-4 Basic to SX-200EL |
| NEW 52000072 | \$1,929.00 | Upgrade SX-200L LW15 MAI to SX-200EL |
| NEW 52000073 | \$1,929.00 | Upgrade SX-200L LW16 ACD 144 Port to SX-200EL |
| NEW 52000074 | \$1,929.00 | Upgrade SX-200L LW16 Basic 672 Port to SX-200EL |
| NEW 52000075 | \$1,929.00 | Upgrade SX-200L LW15 ACD to SX-200EL |



| PART NUMBER | DESCRIPTION |
|-------------|-------------|
|-------------|-------------|

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

NEW PART NUMBERS (Continued)

| | NETTRIOL | |
|-------------------------|------------|--|
| ^{NEW} 52000076 | \$2,699.00 | Upgrade SX-200D 336 Port LW15 or G1003-4 ACD to SX-200EL |
| NEW 52000077 | \$1,929.00 | Upgrade SX-200L LW16 ENH 672 Port to SX-200EL |
| NEW 52000078 | \$1,399.00 | Upgrade SX-200EL w/MCC III EL to SX-200EL w/MCC III ELx |
| NEW 52000079 | \$1,929.00 | Upgrade SX-200L LW16 ACD 672 Port to SX-200EL |
| NEW 52000080 | \$1,699.00 | Upgrade SX-200L LW16 ACD 72 Port to SX-200ML |
| NEW 52000081 | \$1,929.00 | Upgrade SX-200L LW16 Basic to SX-200-EL |
| NEW 52000082 | \$1,829.00 | Upgrade SX-200D G1002 Basic 144 Port to SX-200ML |
| NEW 52000083 | \$2,099.00 | Upgrade SX-200D 480 Port G1000-5 Basic to SX-200EL |
| ^{NEW} 52000084 | \$1,699.00 | Upgrade SX-200L LW15+1 to SX-200ML |
| ^{NEW} 52000085 | \$1,929.00 | Upgrade SX-200L LW15 MAI & ACD to SX-200EL |
| NEW 52000086 | \$2,299.00 | Upgrade SX-200D 456 Port G1003-5 ACD to SX-200EL |
| NEW 52000087 | \$2,699.00 | Upgrade SX-200D 336 Port LW15 or G1004 MAI to SX-200EL |
| NEW 52000088 | \$2,699.00 | Upgrade SX-200D 336 Port LW15 ACD & MAI to SX-200EL |
| NEW 52000089 | \$2,899.00 | Upgrade SX-200D 672 Port LW15 MAI or G1004 MAI to SX-200EL |
| ^{NEW} 52000090 | \$2,899.00 | Upgrade SX-200D 672 Port LW15 to SX-200EL |
| ^{NEW} 54000070 | \$0.00 | AMERICAN ENGLISH PROMPTS, FIRST SET |
| ^{NEW} 54000071 | \$0.00 | BRITISH ENGLISH PROMPTS, FIRST SET |
| ^{NEW} 54000074 | \$1,483.15 | AMERICAN ENGLISH PROMPTS, SECOND SET |
| ^{NEW} 54000075 | \$1,483.15 | BRITISH ENGLISH PROMPTS, SECOND SET |
| NEW 54000076 | \$1,483.15 | LATIN AMERICAN SPANISH PROMPTS, SECOND SET |
| NEW 6503-IDE-B1 | \$1,265.15 | Upgrade Kit 5.0X AIP70 or AIP120 System to NPM 7.0 System |



| PART NUMBER | DESCRIPTION |
|-------------|-------------|
| | |

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

NEW PART NUMBERS (Continued)

NET PRICE

| NEW 6503-SCSI-B1 | \$1,265.15 | Upgrade Kit from 5.0X VM100 or VMII System to NPM 7.0 System |
|---------------------|-------------|--|
| NEW 6510-SCSI-B1 | \$1,265.07 | Upgrade Kit from 5.0X Rack System to a NPM 7.0 System |
| NEW 9109-542-101-NA | \$882.00 | MITEL EXPRESS MESSENGER PMS SOFTWARE OPTION |
| NEW 9109-542-102-NA | \$661.27 | Mitel Express Messenger Option - Billingual |
| NEW 9148-000-530-NA | \$0.00 | Lightware 30 Image CD |
| NEW 9164-001-001-NA | \$975.26 | 8 Port Voice Card (NMS AG-0) |
| NEW 9164-002-020-NA | \$533.52 | 2 Port Fax Software |
| NEW 9164-002-021-NA | \$960.90 | 4 Port Fax Software |
| NEW 9164-002-022-NA | \$1,921.81 | 8 Port Fax Software |
| NEW 9164-003-002-NA | \$1,067.98 | Client Software License - 25 Users |
| NEW 9164-003-003-NA | \$1,708.59 | Client Software License - 50 Users |
| NEW 9164-003-004-NA | \$2,801.93 | Client Software License - 100 Users |
| NEW 9164-003-005-NA | \$4,288.84 | Client Software License - 200 Users |
| NEW 9164-003-006-NA | \$7,260.79 | Client Software License - 400 Users |
| NEW 9164-003-007-NA | \$8,350.38 | Client Software License - 500 Users |
| NEW 9164-003-008-NA | \$11,523.33 | Client Software License - 750 Users |
| NEW 9164-003-009-NA | \$14,134.59 | Client Software License - 1000 Users |
| NEW 9164-005-001-NA | \$771.17 | Web Browser Access Site Licence |
| NEW 9164-120-001-NA | \$1,483.15 | Baypoint OPM 2.0 SERVER S/W & BRANDING KIt |
| NEW 9164-120-008-NA | \$2,711.14 | 8 Port Voice Card (NMS AG8) |
| NEW 9164-120-009-NA | \$1,483.15 | Mitel OPM 2.0 SERVER S/W & BRANDING KIT |
| NEW 9164-120-010-NA | \$5,693.57 | TS800 Server Package |
| NEW 9164-120-100-NA | \$118.35 | SX-2000 Integration Software |
| NEW 9164-120-101-NA | \$1,030.20 | SX-2000 Integration Hardware |
| NEW 9164-120-200-NA | \$118.35 | SX-200 Integration Software |
| NEW 9164-120-201-NA | \$686.80 | SX-200 Integration Hardware |
| | | |



| PART NUMBER | | DESCRIPTION |
|--------------------------------|-----------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | NEW PART NUMB | · · · · · · · · · · · · · · · · · · · |
| | NET PRICE | |
| ^{NEW} 9164-120-440-NA | \$593.64 | Text to Speech Software License |
| ^{NEW} 9164-120-500-NA | \$889.52 | Centrex SMDI Integration Software |
| ^{NEW} 9164-120-708-NA | \$2,966.31 | 8 Port Voicemail Software |
| NEW 9164-120-709-NA | \$1,779.97 | 4 Port Software Upgrade |
| NEW 9164-120-712-NA | \$4,449.46 | 12 Port Voicemail Software |
| NEW 9164-120-716-NA | \$5,932.62 | 16 Port Voicemail Software |
| ^{NEW} 9164-120-720-NA | \$1,186.34 | 4 Port Software Upgrade (for upgrades above 16 Ports) |
| NEW 9164-500-009-NA | \$3,795.43 | OPM T1 Line - ISA |
| NEW 9169-200-005-NA | \$1,483.15 | VPIM Software Option |
| NEW 9169-200-011-NA | \$0.00 | LATIN AMERICAN SPANISH PROMPTS, FIRST SET |
| NEW 9169-403-010-NA | \$20,132.96 | Client Software License - 1250 Users |
| NEW 9169-403-011-NA | \$22,484.96 | Client Software License - 1500 Users |
| NEW 9169-403-012-NA | \$25,657.92 | Client Software License - 1750 Users |
| NEW 9169-403-013-NA | \$28,270.11 | Client Software License - 2000 Users |
| NEW MK080DA | \$3,287.55 | Lightware 29 To Lightware 30 Upgrade |
| NEW MK080OPS | \$3,287.55 | Lightware 30 Upgrade Via Ops Manager |
| NEW MK082DA | \$5,166.15 | Lightware 28 To Lightware 30 Upgrade |
| NEW MK083DA | \$6,575.10 | Lightware 26/27 To Lightware 30 Upgrade |
| NEW ML010AA | \$1,408.95 | Software Assurance - 1 Future Core Load |
| PRICE DECREASES | | ES . |
| | NEW PRICE / OLD PRICE | |
| DEC 9125-533-002-NA | \$610.54 / \$610.55 | 2nd Digital Link Software |
| | PRICE INCREASES | S |
| | NEW PRICE / OLD PRICE | |
| ^{INC} 9109-100-057-NA | | PKG SW UPG LIGHTWARE 18 REL 1 |
| ^{INC} 9180-500-001-NA | \$198.53 / \$187.86 | DSS/BLF Console Interface Unit |



| PART NUMBER | DESCRIPTION |
|---------------|-----------------------|
| I AN I NUMBEN | DEGUNII IICI v |

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART NUMBERS REMOVED

| 9109-080-008-NA | Mitel Express Messenger 8 port |
|-----------------|---|
| 9109-653-001-NA | SX-200L LW 15 |
| 9109-653-002-NA | SX-200L LW 15 ACD |
| 9109-653-005-NA | SX-200L LW 15 + 1 |
| 9109-653-011-NA | UPG DIG336P LW15 ENH&BSC OR G1001-4 BASIC T |
| 9109-653-013-NA | UPG D336P LW15 MAI OR G1004 MAI TO 200EL |
| 9109-653-022-NA | UPG DIG 672P LW15 ACD OR G1003-4 ACD TO 200E |
| 9109-653-023-NA | UPG DIG 672P LW15 MAI OR G1004 MAI TO 200EL |
| 9109-653-024-NA | UPG DIG 672P LW15 MAI&ACD TO 2 |
| 9109-653-031-NA | SX-200D 456P G1002-5 BASIC UPGRADE TO SX-200 EL, LW17 |
| 9109-653-032-NA | SX-200D 456P G1004 BSC+MAI UPGRADE TO SX-200 EL LW17 |
| 9109-653-041-NA | SX-200D 480P G1000-4 BASIC UPGRADE TO SX-200 LW17 |
| 9109-653-042-NA | SX-200D 480P G1004 BSC+MAI UPGRADE TO SX-200 LW17 |
| 9109-653-061-NA | SX-200 EL w/MCCIII EL to SX-200 EL w/MCCIII ELx, LV R 3.1 |
| 9109-653-062-NA | SX-200 ML to SX-200 EL w/MCCIII ELx, LW 17 R 3.1 |
| 9109-653-101-NA | UPG 200L LW16 BASIC 72P TO ML |
| 9109-653-103-NA | UPG 200L LW16 BASIC 672P TO EL |
| 9109-653-111-NA | UPG 200L LW16 ENH 72P TO ML |
| 9109-653-112-NA | UPG 200L LW16 ENH 144P TO EL |
| 9109-653-113-NA | UPG 200L LW16 ENH 672P TO EL |
| 9109-653-122-NA | UPG 200L LW16 ACD 144P TO EL |
| 9109-653-123-NA | UPG 200L LW16 ACD 672P TO EL |
| 9113-000-900-NA | Superset 401+ TSG |
| 9125-500-301-NA | LIGHTWARE 30 Release 1 Operating System Software |
| | |



| PART NUMBER DESCR | RIPTION |
|-------------------|---------|
|-------------------|---------|

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART NUMBERS REMOVED (Continued)

| 9148-000-512-NA | LW28 Software Image Tape (UNIX) |
|-----------------|---------------------------------------|
| MK080CB | LW26/27-LW28 VS Upgrade |
| MK080CC | LW26/27 - LW28 S-Tape Upgrade |
| MK080CD | LW26/LW27 - LW28 SG Tape Upgrade |
| MK080CG | LW26/27 - LW28 LIGHT CTU Upgrade |
| MK082OPS | LW27 - LW28 LIGHT Y2K via Ops Manager |
| MK085CG | LW26/27 - LW28 LIGHT RSD Upgrade |
| MK101CB | MS2004/2005 - LW28-VS Upgrade |
| MK101CC | MS2004/5 - LW28 S Tape Upgrade |
| MK101CD | MS2004/2005 - LW28-SG Upgrade |
| MK101CE | MS2004/2005 - LW28-S Floppy Upgrade |
| MK101CF | MS2003 - LW28-SG Upgrade |
| MK101CG | MS2003 - LW28-S Floppy Upgrade |
| MK370BA | PKG MicroLIGHT Network DC |
| MS2008-G-NA-00 | LW28 Instream Upgrade SG-Tape |
| MS2008-LZ-NA-00 | LW28 Instream Upgrade LIGHT-RSD |
| MS2008-SF-NA-00 | LW28 Instream Upgrade S-Floppy |
| MS2008-S-NA-00 | LW28 Instream Upgrade S-Tape |
| MS2008-V-NA-00 | LW28 Instream Upgrade VS-Tape |

PART DESCRIPTION CHANGES

| | NEW DESCRIPTION / | OLD DESCRIPTION |
|--------------------------------|---|---|
| ^{сне} 50000196 | IMPRESA Emergency Response Application Kit | IMPRESA EMERGENCY RESPONSE APPLICATION KIT |
| ^{CHG} 50000197 | IMPRESA Emergency Response Pager Notification | IMPRESA EMERGENCY RESPONSE PAGER NOTIFICATION |
| ^{сне} 50000198 | IMPRESA Emergency Response Remote Client | IMPRESA EMERGENCY RESPONSE REMOTE CLIENT |
| ^{CHG} 9109-100-131-NA | SX-200 ML/EL Hotel/Motel Software Pkg. | PKG SX-200 ML/EL H/M SOFTWARE AND DOCS |
| ^{CHG} 9109-100-132-NA | SX-200 ML/EL Hotel/Motel Package w/Messaging Software | PKG SX-200 ML/EL H/M W/VMAIL SOFTKEY S/W & NuPoint S/W |



| PART NUMBER | DESCRIPTION |
|-------------|-------------|
|-------------|-------------|

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART DESCRIPTION CHANGES (Continued)

| | NEW DESCRIPTION | / | OLD DESCRIPTION |
|--------------------------------|---|-------|---|
| ^{сна} 9109-100-133-NA | SX-200 ML/EL Software Pkg. w/PMInterface Option | S | PKG SX-200 ML/EL SW & DOCS W/PMS INTERFACE OPTION |
| ^{сне} 9109-100-134-NA | SX-200 ML/EL Software Pkg. w/PM Messaging Software | S & | PKG SX-200 ML/EL PMS W/VMAIL SOFTKEY S/W & NuPoint S/W |
| ^{сне} 9109-651-004-NA | SX-200 ML Business Pkg. 12X36/SETS/MEM/ST4 | | SX-200 ML BUSINESS PKG 12X36/SETS/MEM/ST4 |
| ^{cHG} 9125-070-002-NA | PRI T1 Card CD-Rom Software | | SW PRI T1 CARD CDROM |
| ^{cHG} 9125-100-269-NA | PRI Euro Hardware Package | | PRI EURO HARDWARE PACKAGE |
| ^{cHG} 9125-100-270-NA | PRI NA Hardware Package | | PRI NA HARDWARE PACKAGE |
| ^{сно} 9125-271-000-NA | R2 Card Application CD-Rom Softw | are | R2 CARD APPLICATION S/W CD-ROM NTA |
| ^{сне} 9145-550-502-NA | 64 MB DIMM RAM | | Memory Upgrade 64MG |
| ^{сне} 9148-000-520-NA | Ops Manager NT Rls. 6.0 to 6.1 Upg | grade | OPS NT REL 6.0 TO 6.1 UPGRADE |
| CHG MC270AA | SX-2000 ISDN PRI Card | | SX-2000 ISDN PRI CARD |
| CHG MW404AA | Cable RJ45 to 2 X BNC | | CABLE RJ45 TO 2 X BNC |

PART NOTE CHANGES

| | NEW NOTE | / | OLD NOTE |
|-------------------------|--|-------------------------------|--|
| ^{сне} 50000196 | INCLUDE(S): 50000271 Impresa Emerg CD 9147-600-404-NA Talk To 9400-700-326-NA Hardwa RJ11 Cable (Qty 1) PRE-REQUISITE(S): Minimum PBX requiremer standalone SX-2000 are; MS2006 M24.2 or greater MC330AA DNIC Revision MSA-A-14 DNI Feature op | CX Card are Dongle arts for a | NOTE(S): KIT INCLUDES; 50000271 Impresa Emergency Response CD 9147-600-404-NA Talk To CX Card 9400-700-326-NA Hardware Dongle RJ11 Cable (Qty 1) PRE REQUISITES; Minimum PBX requirements for a standalone SX-2000 are; MS2006 M24.2 or greater MC330AA DNIC Revision 2.10/3.3 MSA-A-14 DNI Feature option |
| ^{сне} 50000197 | PRE-REQUISITE(S): 50000196 Impresa ER Ap | plication | NOTE(S): PRE-REQUISITES; 50000196 Impresa ER Application |
| ^{сне} 50000198 | PRE-REQUISITE(S): 50000196 Impresa ER Ap Includes 2 remote clients. | plication | NOTE(S): PRE-REQUISITES; 50000196 Impresa ER Application Includes 2 remote clients. |



PART NUMBER DESCRIPTION

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

| 7.4 | KT NOTE OTIANOLO (Gontinaca) | |
|--------------------------------|---|--|
| | NEW NOTE / | OLD NOTE |
| ^{сно} 6530-120S-B1 | INCLUDE(S): 6448-120S-B1 NuPoint Agent / 6975-120S-B1 NP Forms 6946-120S-B1 NP Cut Through Page. | NOTE(S): Includes: 6448-120S-B1 NuPoint Agent / 6975-120S-B1 NP Forms 6946-120S-B1 NP Cut Through Page. |
| ^{сне} 6530-640-В1 | INCLUDE(S): 6448-640-B1 NuPoint Agent / 6975-640-B1 NP Forms 6946-640-B1 NP Cut Through Page. | NOTE(S): Includes: 6448-640-B1 NuPoint Agent / 6975-640-B1 NP Forms 6946-640-B1 NP Cut Through Page. |
| ^{сне} 6531-120R-В1 | INCLUDE(S): 6477-120R-B1 Redundancy Software 6107-120R-B1 Redundant Hard Drive 6012-120R-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. | NOTE(S): Includes: 6477-120R-B1 Redundancy Software 6107-120R-B1 Redundant Hard Drive 6012-120R-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. |
| ^{сне} 6531-120S-B1 | INCLUDE(S): 6477-120S-B1 Redundancy Software 6107-120S-B1 Redundant Hard Drive 6012-120S-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. | NOTE(S): Includes: 6477-120S-B1 Redundancy Software 6107-120S-B1 Redundant Hard Drive 6012-120S-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. |
| ^{сне} 6531-640-В1 | INCLUDE(S): 6477-640-B1 Redundancy Software 6107-640-B1 Redundant Hard Drive 6012-640-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. | NOTE(S): Includes: 6477-640-B1 Redundancy Software 6107-640-B1 Redundant Hard Drive 6012-640-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. |
| ^{сне} 9109-100-057-NA | Includes: 9109-418-234-NA LW 18 RIs 1 s/w 4MB Flash & CD-ROM Tech. Practice (Qty 1) 9109-532-007-NA Superset 4000 Series Sets Option (Qty 1) 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users (Qty 1) 9109-532-023-NA LW 18 Core Features (Qty 1) 9109-532-005-NA Remote Software Download Option (Qty 1) NOTE(S): Customers will be billed NET price initially. Additional REBATED amount will be charged if the old Flash Card is not returned to Mitel within 30 days. | Includes: 9109-418-234-NA LW 18 Release 1 s/w 4MB Flash & CD-ROM Tech. Practice (Qty 9109-532-007-NA Superset 4000 Series Sets Option (Qty 1) 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users (Qty 1) 9109-532-023-NA LW 18 Core Features (Qty 1) 9109-532-005-NA Remote Software Download Option (Qty 1) NOTE(S): Customers will be billed NET price initially. Additional REBATED amount will be charged if the old Flash Card is not returned to Mitel within 30 days. |



PART NUMBER DESCRIPTION

NEW = New Part Number

™ = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Reg Change

PART NOTE CHANGES (Continued)

^{сне} 9109-100-132-NA

NEW NOTE

9109-418-234-NA LW 18 (Rel 1.0) SW 4

Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features

(Qty 1)

Includes:

9109-532-005-NA Remote Software

Download Option (Qty 1)

9109-530-120-NA 120 Maximum User

Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series

Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel

Option (Qty 1)

9109-532-001-NA Automated Attendant

Option (Qtv 1)

9109-532-011-NA Voicemail Softkeys

(Qtv 1)

6470-1-B1 NuPoint English Prompts

(Qty 1)

6925-70-B1 NuPoint Wake-UP (Qty 1)

9400-200-302-NA System ID Module

(Qty 1)

9109-530-048-NA 48 Maximum User

Devices Option (Qty 1)

NOTE(S):

This software is required when ordering

Mitel Inn

Solutions hardware pkg #9109-650-212-NA or

when ordering a Mitel mail system

separately with Mitel

Inn Solutions hardware packages

#9109-651-211-NA or #9109-650-211-NA

PART # 9109-100-132-NA IS MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA.

SX-200 ML/EL can

only operate with one of these options on

the system

Messaging Softkeys for SX-200 Option is

now included

in NuPoint DNIC Power Package(s).

OLD NOTE

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW 4

Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features

(Qty 1)

9109-532-005-NA Remote Software

Download Option (Qty 1)

9109-530-120-NA 120 Maximum User

Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series

Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel

Option (Qty 1)

9109-532-001-NA Automated Attendant

Option (Qtv 1)

9109-532-011-NA Voicemail Softkeys

(Qty 1)

6470-1-B1 NuPoint English Prompts

(Qty 1)

6925-70-B1 NuPoint Wake-UP (Qty 1)

NOTE(S):

This software is required when ordering

Mitel Inn

Solutions hardware pkg

#9109-650-212-NA or

when ordering a Mitel mail system

separately with Mitel

Inn Solutions hardware packages

#9109-651-211-NA or

#9109-650-211-NA

PART # 9109-100-132-NA IS

MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA.

SX-200 ML/EL can

only operate with one of these options on

the system

Messaging Softkeys for SX-200 Option is

now included

in NuPoint DNIC Power Package(s).



PART NUMBER DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

NEW NOTE OLD NOTE ^{сне} 9125-100-263-NA NOTE(S): NOTE(S): MC263BA T1 (DS1) Formatter Card (Qty Includes: MC263BA T1 (DS1) Formatter Card (Qty MA218AA T1 (DS1) Interface Assembly MA218AA T1 (DS1) Interface Assembly (Qty 1) This Hardware Package requires Digital (Qty 1) Link Software Options This Hardware Package requires Digital to enable the links. Link Software Options to enable the links. NOTE(S): ^{сне} 9125-100-264-NA NOTE(S): MC264BA CEPT Interface Card (Qty 1) Includes: MA217AA CEPT Interface Assembly (Qty MC264BA CEPT Interface Card (Qty 1) 1) MA217AA CEPT Interface Assembly (Qty This Hardware Package requires Digital This Hardware Package requires Digital Link Software Options Link Software Options to enable the links. to enable the links. NOTE(S): ^{сне} 9125-100-265-NA NOTE(S): MC263BB E1/T1 Digital Trunk Formatter Includes: MC263BB E1/T1 Digital Trunk Formatter Card (Qty 1) MA218AA T1/DS1 Interface Assembly Card (Qty 1) MA218AA T1/DS1 Interface Assembly (Qty 1) This Hardware Package requires Digital Link Software Options This Hardware Package requires Digital to enable the links. Link Software Options to enable the links. NOTE(S): ^{снб} 9125-271-000-NA Includes: Includes: ^{снб} 9125-300-014-NA 9125-200-161-NA Microlight Basic 9125-200-161-NA Microlight Basic System (120 Volt) (Qty 1) System (120 Volt) (Qty 1) MC269AA ISDN PRI Card (Qty 1) MC269AA ISDN PRI Card (Qty 1) MA225AA Interface Assembly (Qty 1) MA225AA Interface Assembly (Qty 1) MC330AB DNIC Line Card (Qty 2) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LIGHTWARE 30 9125-500-030-NA LIGHTWARE 30 Software Package (Qty 1) Software Package (Qty 1) MFRD-A-44 96 Station Pkg (Qty 1) MFRD-A-44 96 Station Pkg (Qty 1)

MSA-A-15 MSDN Voice 1 (Qty 1)
MSA-A-19 MSDN Public Network
Access (Qty 1)
MSA-A-32 MSDN Voice 5 (Qty 1)
MSA-A-39 SS700 Color (Qty 1)
MSA-A-36 ANI/DNIS (Qty 1)
NOTE(S):
This package includes one (1) Digital
Link in the

LIGHTWARE 30 Software Package. To enable the

second Digital Link you must purchase

9125-533-002-NA.

MSA-A-15 MSDN Voice 1 (Qty 1)

MSA-A-19 MSDN Public Network

MSA-A-32 MSDN Voice 5 (Qty 1)

MSA-A-39 SS700 Color (Qty 1) MSA-A-36 ANI/DNIS (Qty 1)

Access (Qty 1)



PART NUMBER DESCRIPTION

NEW = New Part Number

™ = Price Increase

DEC = Price Decrease

сне = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

NEW NOTE OLD NOTE

^{сне} 9125-300-015-NA Includes:

9125-200-161-BX Microlight Basic

System (240 Volt) (Qty 1)

MC269AA ISDN PRI Card (Qty 1) MA225AA Interface Asembly (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LIGHTWARE 30

Software Package (Qty 1)

MFRD-A-44 96 Station Pkg. (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network

Access (Qty 1)

MSA-A-32 MSDN Voice 5 (Qty 1)

MSA-A-36 ANI/DNIS (Qty 1)

NOTE(S):

This package includes one (1) Digital

Link in the

LIGHTWARE 30 Software Package. To

enable the

second Digital Link you must purchase

9125-533-002-NA.

INCLUDE(S): ^{сне} 9125-300-016-NA

9400-200-161-NA MicroLIGHT Basic

System (AC-120V) (Qty 1) 9125-500-030-NA LightWare 30

Software Package (Qty 1)

MFRD-A-44 Software 96 Station Pkg

(Qty 1)

MSA-A-53 Voicemail Softkeys Option

(Qty 1)

MC340BA LS/GS Trunk Card (8 Circuits)

(Qty 1)

MC320BE ONS Line Card (16 Circuits)

(Qty 1)

MC330AB DNIC Line Card (16 Circuits)

(Qty 3)

9401-000-024-NA Music On Hold Paging

Unit (DNIC) (Qty 1) 9132-025-202-NA Superset 4025 Dark

Grey Backlit (Qty 28)

9132-150-202-NA Superset 4150 Dark

Grey Backlit (Qty 4)

9150-803-073-NA NuPoint DNIC Power

Pkg - 8P 90 Hour (Qty 1)

MC330AB DNIC Line Card (16 Cct) (Qty

1) (Incl. in NuPoint)

Includes:

9125-200-161-BX Microlight Basic

System (240 Volt) (Qty 1)

MC269AA ISDN PRI Card (Qty 1) MA225AA Interface Asembly (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LIGHTWARE 30

Software Package (Qty 1)

MFRD-A-44 96 Station Pkg. (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network

Access (Qty 1)

MSA-A-32 MSDN Voice 5 (Qtv 1) MSA-A-36 ANI/DNIS (Qty 1)

NOTE(S):

Includes:

9400-200-161-NA MicroLIGHT Basic

System (AC-120V) (Qty 1) 9125-500-030-NA LightWare 30

Software Package (Qty 1)

MFRD-A-44 Software 96 Station Pkg

(Qty 1)

MSA-A-53 Voicemail Softkeys Option

(Qty 1)

MC340BA LS/GS Trunk Card (8 Circuits)

(Qty 1)

MC320BE ONS Line Card (16 Circuits)

(Qty 1)

MC330AB DNIC Line Card (16 Circuits)

(Qty 3)

9401-000-024-NA Music On Hold Paging

Unit (DNIC) (Qty 1)

9132-025-202-NA Superset 4025 Dark

Grey Backlit (Qty 28)

9132-150-202-NA Superset 4150 Dark

Grey Backlit (Qty 4)

9150-803-073-NA NuPoint DNIC Power

Pkg - 8P 90 Hour (Qty 1)

MC330AB DNIC Line Card (16 Cct) (Qty

1) (Incl. in NuPoint)

NOTE(S):

For use with Mitel OnePoint Messaging.

^{сне} 9145-550-502-NA



PART NUMBER DESCRIPTION

> NEW = New Part Number INC = Price Increase DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Reg Change

Directory Services Support for:

to Marcel Jacques

Directory Services orders will be directed

PART NOTE CHANGES (Continued)

NEW NOTE OLD NOTE ^{сне} 9148-000-037-NA NOTE(S): NOTE(S):

Directory Services Support for: Directory Services Support for:

Novell NDS Novell NDS Lotus Notes/Domino Lotus Notes/Domino Microsoft Exchange Microsoft Exchange

Directory Services orders will be directed

to Marcel Jacques PRE-REQUISITE(S):

9148-000-034-NA OPS Manager

Network (Qty 1) Directory Services for: 9148-000-038-NA OPS Manager Pre-requisite(s) required:

Network Integrated (Qty 1) 9148-000-034-NA OPS Manager

9148-000-039-NA OPS Manager Network (Qty 1)

System Software (Qty 1) 9148-000-038-NA OPS Manager Network Integrated (Qtv 1) 9148-000-039-NA OPS Manager

System Software (Qty 1)

INCLUDE(S): NOTE(S): ^{сне} 9150-120-002-NA

120 hours/ NP FPSA/ NP Admin/ English Includes:

120 hours/ NP FPSA/ NP Admin/ English Prompts Full Set.

Prompts Full Set.

NOTE(S): INCLUDE(S): ^{CHG} 9150-640-001-NA Includes:

120 hours/ NP FPSA/ NP Admin/ English Prompts Full Set.

120 hours/ NP FPSA/ NP Admin/ English

Prompts Full Set.

^{сне} 9150-640-001NAU INCLUDE(S): NOTE(S):

RIs 7.0 software & Smart Install Includes: Rls 7.0 software & Smart Install

hardware. hardware.

NOTE(S): ^{сне} 9150-6464-05RВ1 INCLUDE(S): NP View User's Guide (5)/ NP View Includes:

Remote Client Licenses (5) NP View User's Guide (5)/ NP View

NP View Remote 1.2 Client Software Remote Client Licenses (5)

Floppy (5). NP View Remote 1.2 Client Software

Floppy (5).

INCLUDE(S): NOTE(S):

NP View User's Guide (50)/ NP View Includes:

Client Licenses (100)/ NP View User's Guide (50)/ NP View

NP View 1.2 Client Software Floppy (10). Client Licenses (100)/

NP View 1.2 Client Software Floppy (10).

^{сне} 9150-6464100RB1 INCLUDE(S): NOTE(S):

Floppy (10).

NP View User's Guide (50)/ NP View Includes:

Remote Client

NP View User's Guide (50)/ NP View

Licenses (100)/ NP View Remote 1.2 Remote Client

Client Software Licenses (100)/ NP View Remote 1.2

> Client Software Floppy (10).

^{сне} 9150-6464-100В1



PART NUMBER DESCRIPTION

> NEW = New Part Number ™ = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

NEW NOTE

^{сне} 9150-6464-25-В1 INCLUDE(S):

NP View User's Guide (25)/ NP View Includes: Client Licenses (25)/

NP View 1.2 Client Software Floppy (5).

INCLUDE(S): NOTE(S): ^{сне} 9150-6464-25RB1

NP View User's Guide (25)/ NP View

Remote Client Licenses (25)/ NP View Remote 1.2

Client Software Floppy (5)

INCLUDE(S): ^{сне} 9400-200-166-NA

9400-200-159-NA Redundant Control

Cabinet 18" (DC-48V) (Qty 1)

MC215AD Main Control Card (Qty 1) MC243BA Circuit Switch II Matrix Card

(Qty 1)

MC606AB Mass Storage Expander Card

(Qty 1)

9400-200-200-NA Redundant Power

Module (Qty 2)

9400-300-306-NA Hard Disk Drive (Qty

9400-300-201-NA DC Power Supply

MK191AA RSD Drive Kit (Qty 1) 9400-300-312-NA Control Resource III

Card (Qty 1)

9400-300-302-NA Quad FIM Carrier

(Qty 3)

OLD NOTE

NOTE(S):

NP View User's Guide (25)/ NP View

Client Licenses (25)/

NP View 1.2 Client Software Floppy (5).

Includes:

NP View User's Guide (25)/ NP View

Remote Client

Licenses (25)/ NP View Remote 1.2

Client Software Floppy (5)

Includes: INCLUDE(S):

9400-200-159-NA Redundant Control

Cabinet 18" (DC-48V) (Qty 1)

MC215AD Main Control Card (Qty 1) MC243BA Circuit Switch II Matrix Card

(Qty 1)

MC606AB Mass Storage Expander Card

(Qty 1)

9400-200-200-NA Redundant Power

Module (Qty 2)

9400-300-306-NA Hard Disk Drive (Qty

9400-300-201-NA DC Power Supply

(Qty 2)

MK191AA RSD Drive Kit (Qty 1)

9400-300-312-NA Control Resource III

Card (Qty 1)

9400-300-302-NA Quad FIM Carrier

(Qty 3)



PART NUMBER DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сне = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

NEW NOTE OLD NOTE ^{сне} 9400-200-167-NA INCLUDE(S): Includes: 9400-200-160-NA Redundant Control INCLUDE(S): Cabinet 18" (AC-120V) (Qty 1) 9400-200-160-NA Redundant Control MC215AD Main Control Card (Qtv 1) Cabinet 18" (AC-120V) (Qty 1) MC243BA Circuit Switch II Matrix Card MC215AD Main Control Card (Qty 1) (Qty 1) MC243BA Circuit Switch II Matrix Card MC606AB Mass Storage Expander Card (Qty 1) MC606AB Mass Storage Expander Card (Qty 1) 9400-200-200-NA Redundant Power (Qty 1) 9400-200-200-NA Redundant Power Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-312-NA Control Resource III 9400-300-302-NA Quad FIM Carrier Card (Qtv 1) 9400-300-302-NA Quad FIM Carrier (Qtv 3) 9400-300-204-NA AC Power Supply (Qty 3) 9400-300-204-NA AC Power Supply (Qty 2) MK191AA RSD Drive Kit (Qty 1) (Qty 2) MK191AA RSD Drive Kit (Qty 1) ^{сне} 9400-200-306-ВА NOTE(S): NOTE(S): 9400-200-304-BA Superset Hub Unit Includes: 9400-200-304-BA Superset Hub Unit (Qty 1) 9400-200-303-NA Peripheral Slot FIM (Qty 1) Carrier Card (Qty 1) 9400-200-303-NA Peripheral Slot FIM 9400-300-301-NA Fiber Interface Module Carrier Card (Qty 1) (FIM) (1KM) (Qty 2) 9400-300-301-NA Fiber Interface Module (FIM) (1KM) (Qty 2) ^{сне} 9400-700-435-NA PRE-REQUISITE(S): NOTE(S): LIGHTWARE 30 Release 1 ISDN Release 6 Pre-requisite(s) required: LIGHTWARE 30 RELEASE 1 **ISDN RELEASE 6** NOTE(S): CHG MC320EA ^{CHG} MK401AA INCLUDE(S): MC264BA CEPT Formatter Card (Qty 1) MC264BA CEPT Formatter Card (Qty 1) INCLUDE(S): MA217AA CEPT Interface (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AA 6 CCT BRI kit (Qty 1) MK400AA 6 CCT BRI kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1)

Prices quoted in Net U.S. Dollars e. and o.e.

Effective: September 10, 2000 Page 2-14

9125-533-002-NA 2nd Digital Link Option

The ISDN Network Gateway SW should

SX-2000 Software should be a minimum

NOTE(S):

be a minimum of 5.2.5

of LW29 Release 2

9125-533-002-NA 2nd Digital Link Option

The ISDN Network Gateway SW should

SX-2000 Software should be a minimum

NOTE(S):

be a minimum of 5.2.5

of LW29 Release 2



PART NUMBER DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PART NOTE CHANGES (Continued)

| | NEW NOTE | / | OLD NOTE |
|--------------------------|---|---|---|
| сна МК401АВ | INCLUDE(S): MC264BA CEPT Format MA217AA CEPT Interfac MK400AB 15 CCT BRI K MSA-A-18 MSDN/DPNS: 9125-533-002-NA 2nd Di NOTE(S): The ISDN Network Gatew be a minimum of 5.2.5 SX-2000 Software should of LW29 Release 2 | te (Qty 1) (it (Qty 1) S Data (Qty 1) gital Link Option vay SW should | Includes: INCLUDE(S): MC264BA CEPT Formatter Card (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AB 15 CCT BRI Kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) 9125-533-002-NA 2nd Digital Link Option NOTE(S): The ISDN Network Gateway SW should be a minimum of 5.2.5 SX-2000 Software should be a minimum of LW29 Release 2 |
| ^{сна} MNRD-A-03 | PRE-REQUISITE(S): MNRD-A-02 MSDN Netw 2 PBXs (Qty 1) | ork Dimension | NOTE(S): Pre-requisite(s) required: MNRD-A-02 MSDN Network Dimension 2 PBXs (Qty 1) |
| ^{CHG} MNRD-A-04 | PRE-REQUISITE(S): MNRD-A-03 (Qty 1) | | NOTE(S): Pre-requisite(s) required: MNRD-A-03 (Qty 1) |
| ^{CHG} MNRD-A-05 | PRE-REQUISITE(S): MNRD-A-04 (Qty 1) | | NOTE(S): Pre-requisite(s) required: MNRD-A-04 (Qty 1) |
| ^{CHG} MNRD-A-10 | PRE-REQUISITE(S): MNRD-A-05 (Qty 1) | | NOTE(S): Pre-requisite(s) required: MNRD-A-05 (Qty 1) |
| ^{снб} MNRD-A-30 | PRE-REQUSITE(S): mnrd-a-10 (Qty 1) | | NOTE(S): Pre-requisite(s) required: mnrd-a-10 (Qty 1) |
| ^{сна} MNRD-A-60 | PRE-REQUSITE(S): MNRD-A-30 (Qty 1) | | NOTE(S): Pre-requisite(s) required: MNRD-A-30 (Qty 1) |
| ^{сне} MW404AA | | | NOTE(S): |



| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------|-----------|-------------|--|

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-2000 LIGHT SYSTEMS - SX-2000 LIGHT

| 9125-300-016-NA | \$14,220.80 | MicroLIGHT 96 Station Package w/Sets & NuPoint Messenger |
|-----------------|-------------|--|
| 9400-200-116-DC | \$2,222.00 | INCLUDE(S): 9400-200-161-NA MicroLIGHT Basic System (AC-120V) (Qty 1) 9125-500-030-NA LightWare 30 Software Package (Qty 1) MFRD-A-44 Software 96 Station Pkg (Qty 1) MSA-A-53 Voicemail Softkeys Option (Qty 1) MC340BA LS/GS Trunk Card (8 Circuits) (Qty 1) MC320BE ONS Line Card (16 Circuits) (Qty 1) MC330AB DNIC Line Card (16 Circuits) (Qty 3) 9401-000-024-NA Music On Hold Paging Unit (DNIC) (Qty 1) 9132-025-202-NA Superset 4025 Dark Grey Backlit (Qty 28) 9132-150-202-NA Superset 4150 Dark Grey Backlit (Qty 4) 9150-803-073-NA NuPoint DNIC Power Pkg - 8P 90 Hour (Qty 1) MC330AB DNIC Line Card (16 Cct) (Qty 1) (Incl. in NuPoint) Peripheral Node II (DC) |
| 9400-200-116-NA | \$2,222.00 | Includes: 9400-200-118-DC Peripheral Cabinet II (DC) (Qty 1) MP912BA DC Power Converter (Qty 1) MC312AB Peripheral Switch Control II Card (Qty 1) 9400-300-301-NA Fiber Interface Module (FIM) (Qty 2) Peripheral Node II (AC) |
| 9400-200-117-DC | \$2,222.00 | Includes: 9400-200-118-NA Peripheral Cabinet II (AC) (Qty 1) MP914AA AC Power Converter (Qty 1) MC312AB Peripheral Switch Control II Card (Qty 1) 9400-300-301-NA Fiber Interface Module (Qty 2) Peripheral Node II Expander (DC) |
| | | Includes: 9400-200-118-DC Peripheral Cabinet II (DC) (Qty 1) MP912BA DC Power Converter (Qty 1) 9400-200-119-NA Peripheral Interconnect Card (Qty 2) 9125-100-106-NA Cabinet Interconnect Cable (15 Ft) (Qty 1) 9125-100-100-NA EMI Filter Kit (Qty 2) NOTE(S): Requires MSA-A-50 for the first Peripheral Expander II Node in the SX-2000 System. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|---|
| | SYSTEMS - SX-200 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change 00 LIGHT (Continued) |
| 9400-200-117-NA | \$2,222.00 | Peripheral Node II Expander (AC) |
| 9400-200-122-NA | \$1,333.20 | Includes: 9400-200-118-NA Peripheral Cabinet II (AC) (Qty 1) MP914AA AC Power Converter (Qty 1) 9400-200-119-NA Peripheral Interconnect Card (Qty 2) 9125-100-106-NA Cabinet Interconnect Cable (15 Ft) (Qty 1) 9125-100-100-NA EMI Filter Kit (Qty 2) NOTE(S): Requires MSA-A-50 for the first Peripheral Expander II Node in the SX-2000 System. DSU Node (DC) |
| 9400-200-124-NA | \$1,333.20 | Includes: 9400-200-123-NA DSU Cabinet (Qty 1) 9400-300-201-NA DC Power Supply (Qty 1) 9400-200-301-NA Peripheral / DSU Resource Card (Qty 2) 9400-300-301-NA Fibre Interface Module (FIM) (Qty 4) DSU Node (AC) |
| 9400-200-161-NA | \$3,555.20 | INCLUDE(S): 9400-200-125-NA DSU Cabinet (Qty 1) 9400-200-301-NA Peripheral/DSU Resource Card (Qty 2) 9400-300-301-NA Fiber Interface Module (Qty 4) 9400-300-204-NA AC Power Supply (Qty 1) MicroLIGHT Basic System with MCIIIE (AC-120V) |
| 9400-200-162-NA | \$3,555.20 | Includes: 9400-200-158-NA MicroLIGHT Control Cabinet (AC) (Qty 1) MP914AA AC Shelf Power Converter (Qty 1) MC215AD Main Control IIIE Card (Qty 1) MC312AB Peripheral Switch Control II Card (Qty 1) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-306-NA Hard Disk Drive (Qty 1) MK191AA RSD Drive Kit (Qty 1) NOTE(S): Requires a DSU Slot FIM Carrier Card (9400-300-308-NA) when adding nodes. MicroLIGHT Basic System with MCIIIE (DC-48V) |
| | | Includes: 9400-200-157-NA MicroLIGHT Control Cabinet (DC) (Qty 1) MP912BA DC Power Converter (Qty 1) MC215AD Main Control IIIE Card (Qty 1) MC312AB Peripheral Switch Control II Card (Qty 1) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-306-NA Hard Disk Drive (Qty 1) MK191AA RSD Drive Kit (Qty 1) NOTE(S): Requires a DSU Slot FIM Carrier Card (9400-300-308-NA) when adding nodes. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|--|
| | SYSTEMS - SX-200 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change OO LIGHT (Continued) |
| 9400-200-163-NA | \$5,332.80 | Redundant Control Node with MCIIIE (AC-120V) |
| 9400-200-164-NA | \$5,332.80 | Includes: 9400-200-160-NA Redundant Control Cabinet 18" (AC-120V) (Qty 1) MC215AD Main Control IIIE Card (Qty 2) MC243BA Circuit Switch Matrix II Card (Qty 2) MC606AB Mass Storage Expander Card (Qty 1) 9400-200-200-NA Redundant Power Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty 2) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-302-NA Quad FIM Carrier (Qty 3) MK191AA RSD Drive Kit (Qty 1) 9400-300-204-NA AC Power Supply (Qty 2) NOTE(S): Redundant Control Node with MCIIIE (DC-48V) |
| 9400-200-165-NA | \$2,222.00 | Includes: 9400-200-159-NA Redundant Control Cabinet 18" (DC-48V) Qty 1) MC215AD Main Control IIIE Card (Qty 2) MC243BA Circuit Switch Matrix II Card (Qty 2) MC606AB Mass Storage Expander Card (Qty 1) 9400-200-200-NA Redundant Power Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty 2) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-201-NA DC Power Supply (Qty 2) 9400-300-302-NA Quad FIM Carrier (Qty 3) MK191AA RSD Drive Kit (Qty 1) Non-Redundant Control Node with MCIIIE 9" (AC-120V) |
| | | Includes: 9400-200-103-NA Non-Redundant Control Cabinet (Qty 1) MC215AD Main Control IIIE Card (Qty 1) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-306-NA Hard Disk Drive (Qty 1) 9400-300-302-NA Quad FIM Carrier (Qty 1) MK191AA RSD Drive Kit (Qty 1) 9400-300-204-NA AC Power Supply (Qty 1) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|--|
| | SYSTEMS - SX-200 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change 00 LIGHT (Continued) |
| 9400-200-166-NA | \$4,888.40 | Non-Redundant Control Node with MCIIIE 18" (DC-48V) |
| 9400-200-167-NA | \$4,888.40 | INCLUDE(S): 9400-200-159-NA Redundant Control Cabinet 18" (DC-48V) (Qty 1) MC215AD Main Control Card (Qty 1) MC243BA Circuit Switch II Matrix Card (Qty 1) MC606AB Mass Storage Expander Card (Qty 1) 9400-200-200-NA Redundant Power Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty 2) 9400-300-201-NA DC Power Supply (Qty 2) MK191AA RSD Drive Kit (Qty 1) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-302-NA Quad FIM Carrier (Qty 3) Non-Redundant Control Node 18" (AC-120V) |
| | | INCLUDE(S): 9400-200-160-NA Redundant Control Cabinet 18" (AC-120V) (Qty 1) MC215AD Main Control Card (Qty 1) MC243BA Circuit Switch II Matrix Card (Qty 1) MC606AB Mass Storage Expander Card (Qty 1) 9400-200-200-NA Redundant Power Module (Qty 2) 9400-300-306-NA Hard Disk Drive (Qty 2) 9400-300-312-NA Control Resource III Card (Qty 1) 9400-300-302-NA Quad FIM Carrier (Qty 3) 9400-300-204-NA AC Power Supply (Qty 2) MK191AA RSD Drive Kit (Qty 1) |
| 9400-200-306-BA | \$1,599.84 | Superset Hub Package NOTE(S): 9400-200-304-BA Superset Hub Unit (Qty 1) 9400-200-303-NA Peripheral Slot FIM Carrier Card (Qty 1) 9400-300-301-NA Fiber Interface Module (FIM) (1KM) (Qty 2) |
| | SYSTEM SOFTWA | RE |
| 50000132 | \$469.65 | LIGHTWARE 30 Release 2 Operating System Software NOTE(S): For Upgrades within LIGHTWARE 30 Systems. |
| | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------------|---------------|--|
| | SYSTEM SOFTWA | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change RE (Continued) |
| 9125-500-030-NA | \$4,696.50 | LIGHTWARE 30 Software Package |
| | | Includes: 9125-500-301-NA LIGHTWARE 30 Rel 1 System Software (Qty 1) MSA-A-03 SMDR (Qty 1) MSA-A-06 T1/D4 (Qty 1) MSA-A-14 Digital Sets (Qty 1) MSA-A-39 SS700 Color (Qty 1) MSA-A-47 Desktop TAPI Support (Qty 1) MTSP-A-10 TAPI Service Provider 1-10 Users (Qty 1) MFRD-A-14 Small Business (Qty 1) MTCL-A-5 Traffic Level Capacity 100 Connections (Qty 1) MLCL-A-16 Maximum 16 Line Appearances (Qty 1) MTP-A-NA NA Tone/Loss Plan (Qty 1) 9400-200-300-NA SX-2000 System ID Module (Qty 1) MD1406-NA-01 Mitel Option Select Report (Qty 1) 9125-030-100-NA LIGHTWARE 30 CD ROM Documentation (Qty 1) |
| 9400-800-500-NA MK074CA | | R2 Node Software upgrade MS2008 Basic System Software Package (S-Floppy System) |
| MK075CA | \$4,696.50 | • • |
| | HARDWARE | |
| 9125-100-263-NA | \$1,066.56 | T1 (DS1) Hardware Package |
| 9125-100-264-NA | \$1,333.20 | NOTE(S): MC263BA T1 (DS1) Formatter Card (Qty 1) MA218AA T1 (DS1) Interface Assembly (Qty 1) This Hardware Package requires Digital Link Software Options to enable the links. CEPT Hardware Package |
| 9125-100-265-NA | \$1,333.20 | NOTE(S): MC264BA CEPT Interface Card (Qty 1) MA217AA CEPT Interface Assembly (Qty 1) This Hardware Package requires Digital Link Software Options to enable the links. T1/E1 Hardware Package |
| | | NOTE(S): MC263BB E1/T1 Digital Trunk Formatter Card (Qty 1) MA218AA T1/DS1 Interface Assembly (Qty 1) This Hardware Package requires Digital Link Software Options to enable the links. |



PART NUMBER NET PRICE DESCRIPTION NEW = New Part Number ™ = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Reg Change HARDWARE (Continued) 9125-300-014-NA \$6,666.00 Euro 96 Station ISDN Microlight Pkg. (120 Volt) 9125-200-161-NA Microlight Basic System (120 Volt) (Qty 1) MC269AA ISDN PRI Card (Qty 1) MA225AA Interface Assembly (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LIGHTWARE 30 Software Package (Qty 1) MFRD-A-44 96 Station Pkg (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-32 MSDN Voice 5 (Qty 1) MSA-A-39 SS700 Color (Qty 1) MSA-A-36 ANI/DNIS (Qty 1) NOTE(S): This package includes one (1) Digital Link in the LIGHTWARE 30 Software Package. To enable the second Digital Link you must purchase 9125-533-002-NA. \$6,666.00 Euro 96 Stn. ISDN Microlight Pkg. (240 Volt) 9125-300-015-NA Includes: 9125-200-161-BX Microlight Basic System (240 Volt) (Qty 1) MC269AA ISDN PRI Card (Qty 1) MA225AA Interface Asembly (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LIGHTWARE 30 Software Package (Qty 1) MFRD-A-44 96 Station Pkg. (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-32 MSDN Voice 5 (Qty 1) MSA-A-36 ANI/DNIS (Qty 1) NOTE(S): This package includes one (1) Digital Link in the LIGHTWARE 30 Software Package. To enable the second Digital Link you must purchase 9125-533-002-NA. SOFTWARE OPTIONS 9125-533-002-NA \$610.54 2nd Digital Link Software NOTE(S): This Software is required for the 2nd link activation on Digital trunks. PRE-REQUISITE(S):

9125-533-001-NA 1st Digital Link Software



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | SOFTWARE OPTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| 9125-533-003-NA | \$704.48 | 3rd Digital Link Software |
| 9125-533-004-NA | \$939.30 | NOTE(S): This Software is required for the 3rd link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-002-NA 2nd Digital Link Software 4th Digital Link Software |
| 9125-533-005-NA | \$704.48 | NOTE(S): This Software is required for the 4th link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-003-NA 3rd Digital Link Software 5th Digital Link Software |
| 9125-533-006-NA | \$939.30 | NOTE(S): This Software is required for the 5th link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-004-NA 4th Digital Link Software 6th Digital Link Software |
| 9125-533-007-NA | \$704.48 | NOTE(S): This Software is required for the 6th link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-005-NA 5th Digital Link Software 7th Digital Link Software |
| 9125-533-008-NA | \$939.30 | NOTE(S): This Software is required for the 7th link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-006-NA 6th Digital Link Software 8th Digital Link Software |
| 9125-533-020-NA | \$3,757.20 | NOTE(S): This Software is required for the 8th link activation on Digital trunks. PRE-REQUISITE(S): 9125-533-007-NA 7th Digital Link Software 9 - 20 Digital Links Software |
| | | NOTE(S): This Software is required for the activation of links 9 to 20 on Digital Trunk Cards. PRE-REQUISITE(S): 9125-533-008-NA 8th Digital Link Software |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------|----------------|---|
| | | NEW = New Part Number |
| | | DEC = Price Decrease |
| | | сно = Part Description/Note/BOM/Pre-Req Change |
| | SOFTWARE OPTIC | ONS (Continued) |
| | | |
| 9125-533-040-NA | \$3,757.20 | 21 - 40 Digital Links Software |
| 9125-533-060-NA | \$3,757.20 | NOTE(S): This Software is required for the activation of links 21 to 40 on Digital Trunk Cards. PRE-REQUISITE(S): 9125-533-020-NA 9 - 20 Digital Links Software 41 - 60 Digital Links Software |
| | | NOTE(S): This Software is required for the activation of links 41 to 60 on Digital Trunk Cards. PRE-REQUISITE(S): 9125-533-040-NA 21 - 40 Digital Links Software |
| MACL-A-07 | \$1,408.95 | 26-50 Agents |
| MACL-A-08 | | 51-100 Agents |
| MACL-A-09 | | 101-150 Agents |
| MACL-A-10 | | 151-200 Agents |
| MACL-A-11 | | 201-350 Agents |
| MFRD-A-07 MFRD-A-12 | • | General Business Large Business |
| MFRD-A-16 | | Medium Business |
| MFRD-A-18 | | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. Large Business |
| | | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. |
| MFRD-A-20 | \$6,575.10 | ONS/OPS Package |
| MFRD-A-21 | \$6,575.10 | Multi-Line Sets |
| MFRD-A-22 | · | Dataset Package |
| MFRD-A-23 | · | Resale/Tandem |
| MFRD-A-24 | | Centralized Attendant |
| MFRD-A-26 | | 32K Telephone Directory |
| MHCL-A-1 | \$1,408.93 | HCI 1 Session/100 Monitors |
| MHCL-A-10 | \$939.30 | NOTE(S): HCI 1 Session/100 Monitors can also be purchased in MSB-A-08 CTI Bundle. PRE-REQUISITE(S): MSA-A-25 HCI Basic Telephony (Qty 1) MSA-A-26 HCI Advanced Telephony (Qty 1) HCI 10 Sessions/1000 Monitors PRE-REQUISITE(S): MHCL-A-5 HCI Sessions/500 Monitors (Qty 1) |
| | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | SOFTWARE OPTIC | · |
| | | |
| MHCL-A-15 | \$939.30 | HCI 15 Sessions/1500 Monitors |
| MHCL-A-2 | \$939.30 | PRE-REQUSITE(S): MHCL-A-10 HCI 10 Sessions/1000 Monitors (Qty 1) HCI 2 Sessions/200 Monitors |
| MHCL-A-20 | \$939.30 | PRE-REQUISITE(S): MHCL-A-1 HCI 1 Session/100 Monitors (Qty 1) HCI 20 Sessions/2000 Monitors |
| MHCL-A-3 | \$939.30 | PRE-REQUISITE(S): MHCL-A-15 HCI 15 Sessions/1500 Monitors (Qty 1) HCl 3 Sessions\300 Monitors |
| MHCL-A-4 | \$939.30 | PRE-REQUISITE(S): MHCL-A-2 HCI 2 Sessions/200 Monitors (Qty 1) HCI 4 Sessions\400 Monitors |
| MHCL-A-5 | \$939.30 | PRE-REQUISITE(S): MHCL-A-3 HCI 3 Sessions/300 Monitors (Qty 1) HCI 5 Sessions\500 Monitors |
| | | PRE-REQUISITE(S): |
| MLCL-A-24 | \$939.30 | MHCL-A-4 HCI 4 Sessions/400 Monitors (Qty 1) 24 Key Line Appearances |
| MLCL-A-32 | | 32 Key Line Appearances |
| MSA-A-01 | | COV Option |
| MSA-A-02 | \$1,878.60 | Advanced ARS |
| MSA-A-04 | \$469.65 | Advanced Data |
| MSA-A-05 | \$2,348.25 | Message Center |
| MSA-A-07 | - | Hotel/Motel |
| MSA-A-08 | \$469.65 | Traffic Reporting |
| MSA-A-09 | | Trunk Busy Status |
| MSA-A-10 | | Attendant Language Select |
| MSA-A-11 | | Advanced Analog Networking |
| MSA-A-12 | | Control Redundancy Software |
| MSA-A-13 | | Peripheral Redundant Software |
| MSA-A-15 | | MSDN Voice I |
| MSA-A-16 | \$704.47 | MSDN Voice II |
| MSA-A-17 | \$704.47 | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 MSDN Voice III |
| | | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------|------------------------|---|
| | SOFTWARE OPTIO | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| MSA-A-18 | \$469.65 | MSDN Data |
| MSA-A-19 | \$0.00 | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 MSDN Public Network Access |
| MSA-A-20 MSA-A-21 | · · | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 Answer Plus MCD MSDN Voice IV |
| MSA-A-23 | \$704.47 | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 Auto-Attendant |
| MSA-A-25 MSA-A-26 | | PRE-REQUISITE(S): MSA-A-20 Answer Plus MCD HCI Basic Telephony HCI Advanced Telephony |
| MSA-A-28 | \$1,408.95 | NOTE(S): HCI Advanced Telephony can also be purchased in MSB-A-08 CTI Bundle. PRE-REQUISITE(S): MSA-A-25 HCI Basic Telephony MSDN Release Link Trunks |
| MSA-A-31 MSA-A-32 | · · | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 MSAN Voice I MSDN Voice V |
| MSA-A-33 MSA-A-34 | \$6,575.10 \$469.65 | PRE-REQUISITE(S): MSA-A-15 MSDN Voice 1 or MSA-A-31 MSAN Voice 1 Autovon Internal SMDR |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------|----------------|---|
| | SOFTWARE OPTIC | NEW = New Part Number NC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| | | |
| MSA-A-35 | \$1,878.60 | Flexible Dimensions |
| MSA-A-36 | \$469.65 | NOTE(S): Improper use of Flexible Dimension software could adversely impact operation. Flexible Dimension software is NOT intended to increase system capacity. Please contact your Mitel AE prior to placing your order for Flexible Dimensions in order to provide them with the desired changes and requirements. PRE-REQUISITES: Minimum of MFRD-A-07 for systems using LIGHTWARE 29 Rls 3 or or greater. Minimum of MFRD-A-16 for systems using LIGHTWARE 30 Rls 1 or or greater. ANI/DNIS |
| MSA-A-37 | · | Fault Management #1 |
| MSA-A-39 MSA-A-40 | | NOTE(S): Used for Alarms Management with Ops Manager. Superset 700 Color Schemes ACD 2000 |
| MSA-A-41 | \$939.30 | PRE-REQUISITE(S): MSA-A-20 Answer Plus MCD MSDN Voice VI |
| MSA-A-43 | \$1,808.15 | NOTE(S): Used for Portable Directory Number Operation. PRE-REQUISITE(S): - MSA-A-15 MSDN Voice I - Minimum of MNRD-A-02 MSDN Network Resource Dimension 2 (2 PBX`s) Networked ACD Option |
| MSA-A-45 | \$469.65 | PRE-REQUISITE(S): MSA-A-41 MSDN Voice VI DSS/BLF |
| MSA-A-46 | \$1,878.60 | NOTE(S): Minimum Software required is LW28 MR2. Network DSS/BLF must be used in conjunction with an OPS Manager platform. PRE-REQUISITE(S): MSA-A-41 MSDN Voice VI is required for Network DSS/BLF, not required for Non-Network DSS/BLF. Skill Based Routing ACD Option NOTE(S): |
| | | NOTE(S): MSB-A-07 ACD 2000 Package 5 Agents and Minimum Software LIGHTWARE 29 Release 1 are required to support this option. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | SOFTWARE OPTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| MSA-A-47 | \$0.00 | Desktop TAPI Support |
| MSA-A-48 | \$1,878.60 | NOTE(S): Min software: LIGHTWARE 29 Rls 3. Order MTSP-A-10 to obtain the first 10 seats at no charge. For use with Superset 4125 & 4150 telephones with TAPI. ACD 2000 Extended Agent Group |
| MSA-A-49 | \$1,408.95 | NOTE(S): Minimum software required is LIGHTWARE 29 Release 3. Software option allows 500 Agent IDs in a single Agent Group. Pre-requisite(s) required: MSA-A-40 ACD 2000 (Qty 1) Emergency Services (E-911) |
| MSA-A-50 | \$1,408.95 | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. Requires a PRI Card or Network Gateway and a minimum of ISDN Release 6 software. Peripheral Node Expansion |
| MSA-A-52 | \$704.47 | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. Required when ordering the first Peripheral Node II Expander (9400-200-117-NA or 9400-200-117-DC) in the SX-2000. Q.SIG |
| MSA-A-53 | \$0.00 | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. Requires a PRI card or Network Gateway and a minimum of ISDN Release 6 software. Voicemail Softkeys |
| | | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. MOSS Option enables softkey integration on Mitel Nupoint Messenger Release 7.0 or greater. To order: Serial number of Mitel NuPoint Messenger MUST be provided or Mitel NuPoint Messenger system MUST appear on the same Purchase Order as SX-2000 Voicemail Softkeys option |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | SOFTWARE OPTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| MSA-A-54 | \$704.47 | ACD Real Time Events |
| MSB-A-05 | | NOTE(S): Minimum software required is LIGHTWARE 30 Release 1. This Software Option is \$0.00 with the purchase or proof of purchase from Mitel of SX-2000 TASKE Rel.7 ACD Agent Toolbox (9146-600-261-NA) or SX-2000 prairieFyre CyberACD (9146-600-401-NA or 9146-600-402-NA or 9146-600-403-NA or 9146-600-404-NA). These parts MUST be purchased directly from Mitel. Pre-requisite(s) required: MSA-A-40 ACD 2000 (Qty 1) Answer Plus ACD Package 25 Agents |
| MSB-A-06 | \$7,044.75 | INCLUDE(S): MSA-A-20 AnswerPlus MCD (Qty 1) MSA-A-23 Auto Attendant (Qty 1) MSA-A-27 AnswerPlus ACD (Qty 1) MACL-A-06 25 ACD Agent Software (Qty 1) NOTE(S): Can only be ordered for use with LW26 Software. ACD 2000 Package 25 Agents |
| MSB-A-07 | \$1,878.60 | INCLUDE(S): MSA-A-20 AnswerPlus MCD (Qty 1) MSA-A-23 Auto Attendant (Qty 1) MSA-A-40 ACD 2000 (Qty 1) MACL-A-06 25 ACD Agent Software (Qty 1) NOTE(S): Can only be ordered for use with LW27 MR0, MR1 and MR2 Software. ACD 2000 Package 5 Agents |
| MSB-A-08 | \$2,817.90 | INCLUDE(S): MSA-A-20 Answer Plus MCD (Qty 1) MSA-A-23 Auto Attendant (Qty 1) MSA-A-40 ACD 2000 (Qty 1) MACL-A-005 ACD Agents (Qty 1) MAIACL-A-02 ACD Agents-2 Groups (Qty 1) NOTE(S): Minimum software required for MSB-A-07 is LIGHTWARE 28 MR3 Minimum software required for MAIACL-A-02 is LIGHTWARE 29 Rel.1 CTI Bundle |
| | | INCLUDE(S): MSA-A-25 HCI Basic Telephony (Qty 1) MSA-A-26 HCI Advanced Telephony (Qty 1) MHCL-A-01 HCI 1 Session (Qty 1) NOTE(S): This CTI Bundle is a cost effective bundled package for CT deployment. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | SOFTWARE OPTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| MTCL-A-10 | \$2,348.25 | Mitel Traffic Capacity Level 10-180 Connections |
| MTCL-A-15 | \$1,878.60 | NOTE(S): 100 Callbacks Mitel Traffic Capacity Level 15-230 Connections |
| MTCL-A-20 | \$4,226.85 | NOTE(S): 128 Callbacks Mitel Traffic Capacity Level 20-640 Connections |
| MTCL-A-30 | \$4,696.50 | NOTE(S): 260 Callbacks Mitel Traffic Capacity Level 30-760 Connections |
| MTCL-A-31 | \$6,575.10 | NOTE(S): 350 Callbacks Mitel Traffic Capacity Level 31-640 Connections |
| MTCL-A-32 | \$6,575.10 | NOTE(S): 260 Callbacks Mitel Traffic Capacity Level 32-860 Connections |
| MTSP-A-10 | \$0.00 | NOTE(S): 240 Callbacks TAPI Service Provider 1-10 Users |
| MTSP-A-20 | \$281.79 | NOTE(S): Min software: LIGHTWARE 29 Rls 3. For use with Superset 4125 & 4150 telephones with TAPI. PRE-REQUISITE(S): MSA-A-47 Desktop TAPI Support (Qty 1) TAPI Server Provider 11-20 Users |
| MTSP-A-40 | \$281.79 | NOTE(S): Min software: LIGHTWARE 29 Rls 3. For use with Superset 4125 & 4150 telephones. PRE-REQUISITE(S): MTSP-A-10 TAPI Service Provider 1-10 Users (Qty 1) TAPI Server Provider 21-40 Users |
| 2 | 4201.17 | NOTE(S): Min software: LIGHTWARE 29 Rls 3. For use with Superset 4125 & 4150 telephones. PRE-REQUISITE(S): MTSP-A-20 TAPI Service Provider 21-40 Users (Qty 1) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | SOFTWARE OPTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DNS (Continued) |
| MTSP-A-50 | \$281.79 | TAPI Server Provider 41-50 Users |
| MTSP-A-60 | \$187.86 | NOTE: Minimum software is LIGHTWARE 29 RIs 2. Need Superset TAPI kit. For use with Superset 4125 & 4150 telephones. Pre-requisite(s) required: Pre-requisite(s) required: MTSP-A-40 TAPI 21-40 users (Qty 1) TAPI Service Provider 41-60 Users |
| MTSP-A-80 | \$187.86 | NOTE(S): Min software: LIGHTWARE 29 Rls 3. For use with Superset 4125 & 4150 telephones with TAPI. PRE-REQUISITE(S): MTSP-A-40 TAPI Service Provider 21-40 Users (Qty 1) TAPI Service Provider 61-80 Users |
| | | NOTE(S): Min software: LIGHTWARE 29 Rls 3. For use with Superset 4125 & 4150 telephones with TAPI. PRE-REQUISITE(S): MTSP-A-60 TAPI Service Provider 41-60 Users (Qty 1) |
| | APPLICATIONS | |
| 50000196 | \$0.00 | IMPRESA Emergency Response Application Kit INCLUDE(S): 50000271 Impresa Emergency Response CD 9147-600-404-NA Talk To CX Card 9400-700-326-NA Hardware Dongle RJ11 Cable (Qty 1) PRE-REQUISITE(S): Minimum PBX requirements for a standalone SX-2000 are; MS2006 M24.2 or greater MC330AA DNIC Revision 2.10/3.3 |
| 50000197 | \$0.00 | MSA-A-14 DNI Feature option IMPRESA Emergency Response Pager Notification PRE-REQUISITE(S): |
| 50000198 | \$0.00 | 50000196 Impresa ER Application |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|---------------|---|
| | | NEW = New Part Number |
| | | mc = Price Increase |
| | | cho = Part Description/Note/BOM/Pre-Req Change |
| | ACD AGENTS | |
| MACL-A-005 | \$1,878.60 | Agents 1-5 |
| MACL-A-010 | \$1,408.95 | Agents 6-10 |
| MACL-A-015 | \$1,408.95 | Agents 11-15 |
| MACL-A-020 | \$939.30 | Agents 16-20 |
| MACL-A-025 | \$939.30 | Agents 21-25 |
| MACL-A-030 | \$704.47 | Agents 26-30 |
| MACL-A-035 | \$704.47 | Agents 31-35 |
| MACL-A-040 | \$704.47 | Agents 36-40 |
| MACL-A-045 | \$704.47 | Agents 41-45 |
| MACL-A-050 | \$704.47 | Agents 46-50 |
| MACL-A-060 | \$704.47 | Agents 51-60 |
| MACL-A-070 | \$704.47 | Agents 61-70 |
| MACL-A-080 | \$704.47 | Agents 71-80 |
| MACL-A-090 | \$704.47 | Agents 81-90 |
| MACL-A-100 | \$704.47 | Agents 91-100 |
| MACL-A-150 | \$939.30 | Agents 101-150 |
| MACL-A-200 | \$939.30 | Agents 151-200 |
| MACL-A-350 | \$2,348.25 | Agents 201-350 |
| MAIACL-A-04 | \$704.47 | ACD Agents - Group of 4 |
| | | NOTE(S): |
| | | MSB-A-07 ACD 2000 Package 5 Agents and Minimum Software LIGHTWARE 29 Release 1 |
| | | are required to support this option. |
| MAIACL-A-08 | \$704.47 | ACD Agents - Group of 8 |
| | | PRE-REQUISITE(S): |
| | | MAIACL-A-04 ACD Agents - Group of 4 |
| | ISDN BRI KITS | |
| MK400AA | \$1,066.56 | 6 CCT BRI Card for Line Side SX-2000 Connectivit |
| | | Includes: |
| | | MC268AA 6 CCT BRI Card |
| | | MW402AA E1 to E1 CEPT Cables |
| | | MW403AA MMI Cable (used to connect PC to BRI Card) |

the BRI card to the MDF)

MW401AA 3 Meter, 25 Pair Cable (used to connect from



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|-------------------|---|
| | ISDN BRI KITS (Co | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| MK400AB | \$2,666.40 | 15 CCT BRI Card for SX-2000 Line Side Connectivity |
| MK401AA | \$3,021.92 | Includes: MC268AB 15 CCT BRI Card MW402AA E1 to E1 CEPT Cables MW403AA MMI Cable (used to connect PC to BRI Card) MW401AA 3 Meter, 25 Pair Cable (used to connect from the BRI Card to the MDF) BRI Kit 6 CCT with CEPT Card |
| MK401AB | \$4.310.68 | INCLUDE(S): MC264BA CEPT Formatter Card (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AA 6 CCT BRI kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) 9125-533-002-NA 2nd Digital Link Option NOTE(S): The ISDN Network Gateway SW should be a minimum of 5.2.5 SX-2000 Software should be a minimum of LW29 Release 2 BRI Kit 15 CCT with CEPT Card |
| MK402AA | | INCLUDE(S): MC264BA CEPT Formatter Card (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AB 15 CCT BRI Kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) 9125-533-002-NA 2nd Digital Link Option NOTE(S): The ISDN Network Gateway SW should be a minimum of 5.2.5 SX-2000 Software should be a minimum of LW29 Release 2 BRI Kit 6 CCT with DSU & CEPT Card |
| | | Includes: MC264BA CEPT Formatter Card (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AA 6 CCT BRI Kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) 9400-200-124-NA DSU Cabinet (Qty 1) 9125-533-002-NA 2nd Digital Link Option NOTE(S): The ISDN Network Gateway SW should be a minimum of 5.2.5 SX-2000 Software should be a minimum of LW29 Release 2 |



| PART NUMBER | NET PRICE | DESCRIPTION | | |
|------------------------------------|-------------------|---|--|--|
| | ISDN BRI KITS (Co | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change | | |
| MK402AB | \$5,599.44 | Includes: MC264BA CEPT Formatter Card (Qty 1) MA217AA CEPT Interface (Qty 1) MK400AB 15 CCT BRI Kit (Qty 1) MSA-A-18 MSDN/DPNSS Data (Qty 1) 9400-200-124-NA DSU Cabinet (Qty 1) 9125-533-002-NA 2nd Digital Link Option NOTE(S): The ISDN Network Gateway SW should be a minimum of 5.2.5 SX-2000 Software should be a minimum of LW29 Release 2 | | |
| ISDN NODES/CARDS | | | | |
| 9125-100-269-NA 9125-100-270-NA | | PRI Euro Hardware Package Includes: MC269AA Euro ISDN PRI card (Qty 1) MA225AA PRI Interface Assembly (Qty 1) NOTE(S): This Hardware Package requires Digital Link Software Options to enable the links Pre-requisite(s) required: SX-2000 S/W must be LW29 Rel 3 or greater | | |
| 9125-100-270-NA 9125-501-101-NA | | PRI NA Hardware Package Includes: MC270AA North American ISDN PRI Card (Qty 1) MA225AA PRI Interface Assembly (Qty 1) NOTE(S): This Hardware Package requires Digital Link Software Options to enable the links Pre-requisite(s) required: SX-2000 S/W must be LW29 Rel 3 or Greater Euro ISDN PRI card with MSDN options | | |
| | | Includes: MC269AA Dual link PRI card (Qty 1) MA225AA PRI interface Assembly (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-32 MSDN Voice 5 (Qty 1) MSA-A-36 ANI/DNIS (Qty 1) NOTE(S): Digital link options must be purchased separately Pre-requisite(s) required: SX-2000 S/W must be LW29 Rel 3 or Greater | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | ISDN NODES/CAR | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DS (Continued) |
| 9125-501-102-NA | \$1,777.60 | ISDN PRI card with MSDN options |
| 9400-700-612-NA | \$2,044.24 | Includes: MC270AA Dual link PRI card (Qty 1) MA225AA PRI interface Assembly (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-17 MSDN Voice 3 (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-32 MSDN Voice 5 (Qty 1) MSA-A-36 ANI/DNIS (Qty 1) NOTE(S): Digital link options must be purchased separately Pre-requisite(s) required: SX-2000 S/W must be LW29 Rel 3 or greater ISDN Release 4 to Release 5 Upgrade Kit |
| 9400-700-622-NA | \$4,888.40 | INCLUDE(S): MB160AAA Dual Link T1 Card (Qty 1) 9147-602-010-NA CD-Rom Drive EID (Qty 1) 9145-500-413-NA 16 Meg Memory Modules (Qty 2) 795000310 Windows NT 4.0 (Qty 1) 9400-700-326-NA ISDN Options Module (Qty 1) 9400-700-414-NA ISDN S/W Package (Qty 1) 9400-700-419-NA Dual Link Access S/W (Qty 1) 9400-700-417-NA Min/Max Software (Qty 1) 9400-700-422-NA NFAS (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) NOTE(S): This Upgrade Kit will only work on a PC LIGHT (Cabinet will be labelled). It will not work on 486 ISDN Nodes. The AFC Card must be upgraded using BC028. Must be LW28 MR2 P17.6.2 for SX-2000 or minimum LW15/16 F57.2 for SX-200. Network Gateway Rel 4 to Rel 5 Upgrade w/4 Link Option |
| | | INCLUDE(S): 9400-700-421-NA Four Link Access Software Option - Rls. 5 (Qty 1) 9400-700-612-NA ISDN Rls. 4 to Rls. 5 Upgrade Kit (Qty 1) MB160AAA Dual Link PRI Card (Qty 1) NOTE(S): The minimum Software required for the SX-2000 is LW28 MR2 Whenever this upgrade is ordered you must order BC028 You must return the old AFC after the upgrade is complete |



PART NUMBER NET PRICE DESCRIPTION NEW = New Part Number ™ = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Reg Change ISDN NODES/CARDS (Continued) 9400-700-623-NA \$3,555.20 ISDN SX-2000 Telecom Server 800 INCLUDE(S): 9400-700-124-NA ISDN Basic System Telecom server 800 (Qty 1) 9400-700-418-NA Single Link SW Option (Network Gateway) (Qty 1) MB160AAA Dual Link PRI card (Qty 1) MSA-A-15 S/W option MSDN/DPNSS Voice 1 (Qty 1) MSA-A-17 S/W MSDN/DPNSS Voice 3 (Qty 1) MSA-A-19 S/W MSDN/DPNSS Public Network Access (Qty 1) MSA-A-32 S/W MSDN/DPNSS Voice 5 (Qty 1) MSA-A-36 S/W ANI/DNIS (Qty 1) 9400-700-414-NA ISDN Software SX-2000 (Qty 1) 9400-700-302-NA AFC Application Fiber Controller w/FIM (Qty 1) 9400-300-301-NA Fiber Interface Module (FIM) (Qty 1) Internal Modem (Qty 1) 9125-533-002-NA 2nd Digital Link Option (SX-2000) (Qty 1) 9125-533-003-NA 3rd Digital Link Option (SX-2000) (Qty 1) This package comes with a Dual Link Card but only one link is activated on the Card. 9400-700-624-NA \$6,399,36 ISDN SX-2000 RLA Telecom Server 800 INCLUDE(S): 9400-700-124-NA ISDN Basic System Telecom server 800 (Qty 1) MB160AAA Edual Link PRA card (Qty 2) 9400-700-416-NA Remote LAN access option (Qty 1) 9400-700-419-NA Dual link software option (Oty 1) MSA-A-15 S/W option MSDN/DPNSS Voice 1 (Qty 1) MSA-A-17 S/W MSDN/DPNSS voice 3 (Qty 1) MSA-A-18 S/W MSDN/DPNSS Data (Qty 1) MSA-A-19 S/W MSDN/DPNSS public network access (Qty 1) MSA-A-32 S/W MSDN/DPNSS Voice 5 (Qty 1) MSA-A-36 S/W ANI/DNIS (Qty 1) 9400-700-414-NA ISDN Software SX-2000 (Qty 1) 9400-700-302-NA AFC Application Fiber Controller w/FIM (Qty 1) 9400-300-301-NA Fiber Interface Module (FIM) (Qty 1) Internal Modem (Oty 1) NOTE(S): For SX-2000 only. MB160AAA \$1,066.56 Dual Link PRI Card NOTE(S): For use with Release 5 and above ISDN Nodes.



| PART NUMBER | NET PRICE | DESCRIPTION | | |
|-----------------------|----------------|--|--|--|
| | ISDN NODES/CAR | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DS (Continued) | | |
| MC269AA | \$2,222.00 | SX-2000 Euro ISDN Dual Link PRI Card | | |
| MC270AA | \$2,222.00 | NOTE(S): The Euro ISDN PRI card is a Digital service card and requires a DSU slot This Dual Link Card DOES NOT include Digital Link options. Digital Link Options MUST be purchased separately. Pre-requisite(s): SX-2000 Light must be at LW29 Rel 3 or Greater SX-2000 ISDN PRI Card | | |
| | | NOTE(S): The ISDN PRI Dual link card is a digital service card and requires a DSU slot This Dual Link Card DOES NOT include Digital Link options. Digital Link Options MUST be purchased separately. Pre-requisite(s): SX-2000 Light S/W must be LW29 Rel 3 or Greater | | |
| ISDN SOFTWARE OPTIONS | | | | |
| 9125-070-002-NA | \$469.65 | PRI T1 Card CD-Rom Software | | |
| 9125-070-011-NA | \$469.65 | NOTE(S): The SX-2000 minimum software LW29 Release 3 This S/W is used for the DSU PRI card only S/W used to upgrade the PRI card to the latest version Euro ISDN PRI Card Release 6 Application Software | | |
| 9125-070-012-NA | \$469.65 | NOTE(S): Euro ISDN Release 6 software is used with the MC269AA PRI Card ISDN PRI Card Release 6 Application Software | | |
| 9125-501-001-NA | \$704.47 | NOTE(S): This ISDN Application Software is used with the MC270AA PRI Card ISDN Min/Max Software Option for the PRI card | | |
| 9125-501-002-NA | | NOTE(S): This SW option can only be used on the SX-2000 PRI card ISDN Auto Min/Max Software Option for the PRI card | | |
| 9125-501-003-NA | \$469.65 | NOTE(S): This SW option can only be used on the SX-2000 PRI card The Min/Max S/W option 9125-501-001-NA is also required ISDN NFAS Software option for PRI card NOTE(S): This SW option can only be used on the SX-2000 PRI card | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|---------------|--|
| | ISDN SOFTWARE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change OPTIONS (Continued) |
| 9125-501-004-NA | \$234.82 | ISDN D-Channel Back up software option for the PRI card |
| 9125-501-005-NA | \$1,690.74 | NOTE(S): This SW option can only be used on the SX-2000 PRI card The NFAS S/W option 9125-501-003-NA is also required ISDN Remote LAN Access software option for PRI card |
| 9125-501-055-NA | \$1,878.60 | NOTE(S): This SW option can only be used on the SX-2000 PRI card The MSDN Data S/W option MSA-A-18 is also required SX-2000 ISDN PRI Card Remote LAN Access Software Kit |
| | | Includes: |
| 9400-700-331-NA | \$140.89 | 9125-501-005-NA Remote LAN Access SW option (Qty 1) MSA-A-18 MSDN Data SW option (Qty 1) NOTE(S): This kit is used on the SX-2000 ISDN PRI card only Pre-requisite(s) required: Requires LW 29 Rel 3 as a Minimum ISDN Auto Min/Max option |
| 9400-700-408-NA | \$469.65 | NOTE(S): The minimum SW required to enable this option is 5.4.14 The Min/Max option PN 9400-700-417-NA must be enabled in conjunction with the Auto Min/Max option ISDN Gateway Software Package - Rls. 4 |
| 9400-700-414-NA | \$469.65 | NOTE(S): Used for ISDN Node Software Upgrades Release 4 and prior only. Requires a Software Application Form. ISDN S/W Upgrade - Release 5 Latest Release |
| | | NOTE(S): Used to upgrade the ISDN Network Gateway Software to the Latest Release 5. This can be used on both the SX-200 and the SX-2000 |
| 9400-700-416-NA | \$1,690.74 | Remote LAN Interface Software Option - RIs. 5 NOTE(S): For SX-2000 only. Requires a separate Dual Link Card (MB160AAA) and #4ESS Connection. PRE-REQUISITE(S): ISDN Node - Release 5 |
| 9400-700-417-NA | \$704.47 | |
| | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|---------------|--|
| | ISDN SOFTWARE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change OPTIONS (Continued) |
| 9400-700-419-NA | \$1,878.60 | Dual Link Access Software Option - Rls. 5 |
| 9400-700-420-NA | \$2,817.90 | NOTE(S): Required for (2nd) Second PRI Link activation. Pre-Requisite(s): ISDN Node Release 5 Three Link Access Software Option - RIs. 5 |
| 9400-700-421-NA | \$4,226.85 | NOTE(S): This Software is required for a 3rd link activation and will also require the Customer to purchase an additional Dual Link PRA Card (MB160AAA). You do not require Two Link Software as a pre-requisite. Pre-Requisite(s): ISDN Node Release 5 Four Link Access Software Option - Rls. 5 |
| 9400-700-422-NA 9400-700-423-NA | \$469.65 | NOTE(S): This Software is required for a 4th Link activation. You do not require Two & Three Link Software as pre-requisites but you may require an MB160AAA Dual Link PRA Card. Pre-Requisite(s): ISDN Node Release 5 Network Facility Assoc. Signaling (NFAS) SftwrRls. 5 ISDN D-Channel Backup SW option |
| 9400-700-430-NA | | NOTE(S): The minimum SW required to enable this option is 5.4.14 The NFAS option PN 9400-700-422-NA must be enabled in conjunction with the D-Channel backup option ISDN Network Gateway Software Package (SX2000) |
| 9400-700-431-NA | \$1,955.36 | Includes: 9400-700-414-NA ISDN SX-2000 Software (Qty 1) MSA-A-17 MSDN Voice 3 (Qty 1) ISDN Network Gateway 2 - 3 link upgrade |
| | | INCLUDE(S): 9400-700-420-NA ISDN 3 link option (Qty 1) MB160AAA EDual link PRA card (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA or 9400-700-623-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA or 9400-700-625-NA Must be purchased prior to ordering upgrade AND 9400-700-419-NA Must be purchased prior to ordering upgrade |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|---------------|---|
| | ISDN SOFTWARE | NEW = New Part Number NC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change OPTIONS (Continued) |
| 9400-700-432-NA | \$3,288.56 | ISDN Network Gateway 2 - 4 link upgrade |
| 9400-700-433-NA | \$1 333 20 | INCLUDE(S): 9400-700-421-NA ISDN 4 link option (Qty 1) MB160AAA EDual link PRA card (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA Must be purchased prior to ordering upgrade AND 9400-700-419-NA Must be purchased prior to ordering upgrade ISDN Network Gateway 3 -4 link upgrade |
| | | INCLUDE(S): 9400-700-421-NA ISDN 4 link option (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA Must be purchased prior to ordering upgrade AND 9400-700-420-NA Must be purchased prior to ordering upgrade |
| 9400-700-434-NA | \$469.65 | ISDN Network Gateway Software Release 6 NOTE(S): Used to upgrade the ISDN Network Gateway Software to the Latest Release 6 |
| 9400-700-435-NA | \$704.48 | SX-2000 ISDN Network Gateway QSIG Software Option |
| | | PRE-REQUISITE(S): LIGHTWARE 30 Release 1 ISDN Release 6 |
| | ISDN SPARES | |
| 9145-500-413-NA 9400-300-310-NA | | Memory Expansion Module 16MB FIM Carrier Card |
| 9400-700-301-NA | \$1,688.72 | NOTE(S): For integrating ISDN nodes to S, VS and SG Systems. Application Fibre Controller W/FIM |
| 9400-700-314-NA 9400-700-318-NA | • | NOTE(S): For use with Release 4 and prior ISDN Nodes. MVIP Cable Single Link PRA Card |
| | | NOTE(S): Used to add 1 link to ISDN Single Link Node. For use with Release 4 and prior ISDN Nodes. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|---|---|--|
| | ISDN SPARES (Co | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change ntinued) |
| 9400-700-319-NA | \$3,199.68 | Dual Link PRA Card |
| 9400-700-322-NA | \$2,461.98 | NOTE(S): For use with Release 4 and prior ISDN Nodes. Classic Motherboard Replacement Kit |
| 9400-700-328-NA MA501AA MC268AA MC268AB MW401AA MW401AB MW402AA | \$213.31 \$933.24 \$2,222.00 \$84.44 \$106.66 | NOTE(S): For use with Release 4 and prior ISDN Nodes. DB9F Nullmodem Cable BRI STUB BRI 6CCT NA SX2K ISDN BRI CARD 15CCT N.A. BRI CABLE (3 METER) BRI CABLE (10 METER) E1 TO E1 CABLE |
| | | |
| 9147-600-403-NA 9400-300-301-NA 9400-300-308-NA | \$222.20 | Talk To Tapi C/S Fiber Interface Module (FIM) DSU Slot FIM Carrier |
| 9400-300-315-NA | \$888.80 | NOTE(S): For use with MicroLIGHT systems only. Multi-Mode Extended FIM |
| 9400-300-316-NA | \$1,066.56 | NOTE(S): Two (2) FIM's are required per link. For use only on SX-200 Peripheral Nodes or SX-2000 Peripheral and DSU Nodes. Single Mode Extended FIM |
| 9401-000-024-NA BC026 | | NOTE(S): Two (2) FIM's required per link. For use only on SX-200 Peripheral Nodes or SX-2000 Peripheral and DSU Nodes. Music on Hold Paging Unit (DNIC) MC606AB MSX Card Upgrade for RSD Upgrade |
| | | NOTE(S): Price if lower revision MSX Card is returned in working order \$133.32 Price if lower revision MSX Card is returned but not in working order \$586.61 Price if lower revision MSX card is not returned \$1,333.20 |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | CARDS (Continued | · · · · · · · · · · · · · · · · · · · |
| BC028 | \$0.00 | Upgrade Spare AFC Card |
| | | NOTE(S): Price if AFC CARD is returned in working order \$177.76 Price if AFC Card returned but not in working order during the warranty \$177.76 Price if AFC Card returned but not in working order and out of warranty \$537.72 Price if AFC Card not returned \$1,688.72 |
| MA217AA | \$177.76 | CEPT Interface Assembly |
| MA218AA | | DS1 Interface Assembly |
| MC260AA | \$1,595.40 | Conference Card (63 Circuit) |
| MC262AA | \$1,595.40 | Tone Detector Card |
| MC263BA | \$1,777.60 | DSI/T1 Formatter Card (2 Links) |
| MC263BB | \$2,222.00 | NOTE(S): This Card is supported on LIGHTWARE 28 (Load P24.9) and a Minimum of LIGHTWARE 29 Release 2 (Load Q23.2.5). This DS1/T1 Dual Link Card DOES NOT include Digital Link options. Digital Link Options MUST be purchased separately. E1/T1 Digital Trunk Formatter Card (2 links) |
| MC264BA | \$2,222.00 | NOTE(S): This card is supported on LIGHTWARE 28 (Load P24.9) and a Minimum of LIGHTWARE 29 Release 2 (Load Q23.2.5). This E1/T1 Dual Link Card DOES NOT include Digital Link options. Digital Link Options MUST be purchased separately. CEPT Interface Card (2 Links) |
| | | NOTE(S): This Card is supported on LIGHTWARE 28 (Load P24.9) and a Minimum of LIGHTWARE 29 Release 2 (Load Q23.2.5). This CEPT Dual Link Card DOES NOT include Digital Link options. Digital Link Options MUST be purchased separately. |
| MC266AA | · | Communications Processor Card |
| MC320BE | | ONS Line Card (16 Circuits) |
| MC320EA | | ONS CLASS Line Card (16 Circuits) |
| MC321AC | \$1,190.99 | , |
| MC323BA | | COV Line Card (12 Circuits) |
| MC330AB | | DNIC Line Card (16 Circuits) |
| MC340BA | | LS/GS Trunk Card (8 Circuits) |
| MC341CA | \$888.80 | DID/Loop Tie Trunk Card (4 Circuits) |
| | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--|---|--|
| | CARDS (Continued | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| MC342BB MC380AA MC606AB | \$1,199.88 | E&M Tie Trunk Card (4 Circuits) DTMF Receiver Card (16 Circuits) Mass Storage Expander Card |
| 9119-000-002-NA | \$711.04 | Superset 7000 (SX-2000) |
| 9119-000-003-NA 9119-000-004-NA 9119-101-001-NA 9119-201-000-NA 9189-000-017-NA 9189-888-001-NA | \$711.04 \$711.04 \$93.93 \$187.86 \$888.80 | INCLUDE(S): Talk-To PC Interface Card Mitel Handset Cords Documentation Superset 7000 DOS Application Software SS7000 Windows 95 Pkg. SS7000 Windows 3.1 Pkg. SS7000 Handset Cradle Superset 7000 Release 3 Upgrade Kit (SX-2000) |
| MT44CDA | ¢1 777 (O | Control that meets Jan1/2000 FCC Part 68 volume control rules. Also adhers to Canada`s Jan1/2000 Volume Control rule |
| MT116BA | \$1,777.60 SPARE COMPONE | • |
| | SPARE COMPONE | INTO |
| 9125-100-101-NA 9125-100-102-NA 9125-100-106-NA 9150-500-399-NA 9180-305-000-NA 9180-EXT-000-NA 9189-048-000-NA 9400-200-103-NA | \$88.88 \$44.44 \$266.64 \$382.18 \$751.44 | CTU Cable for Upgrades SX-2000 Hard Drive Upgrade Kit Peripheral Cabinet Interconnect Cable (15 Ft) RSD Blank Disks (5 Pack) System Fail Transfer Unit (6 Circuit) COV Loop Extender Console Handset (Light Grey)(Qty 10) 9" Control Cabinet (Non-Redundant) (110V) (AC) NOTE(S): Spare Cabinet does not contain a Hard Drive, CTU |
| | | or RSD Drive. To be used as a universal replacement cabinet. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|-------------------|--|
| | SPARE COMPONE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| 0400 000 440 00 | 44.482. 00 | D |
| 9400-200-118-DC | | Peripheral Cabinet II (DC) |
| 9400-200-118-NA | | Peripheral Cabinet II (AC) |
| 9400-200-119-NA 9400-200-123-NA | | Peripheral Interconnect Card |
| | | DSU Cabinet (AC) |
| 9400-200-125-NA 9400-200-144-NA | | DSU Cabinet (AC) |
| 9400-200-144-NA 9400-200-157-NA | | Cabinet Stacking Brackets Micro Light Cabinet (48V) (DC) |
| 9400-200-137-INA | \$2,044.24 | wild begin Cabinet (46V) (DC) |
| | | INCLUDE(S): Spare Cabinet does not contain a Hard Drive, CTU or RSD Drive. To be used as a universal replacement cabinet. NOTE(S): Spare Cabinet does not contain a Hard Drive, CTU or RSD Drive. To be used as a universal replacement cabinet. |
| 9400-200-158-NA | \$2,044.24 | Micro Light Cabinet (110V) (AC) NOTE(S): Spare Cabinet does not contain a Hard Drive, CTU or RSD Drive. |
| 9400-200-159-NA | \$2,310.88 | To be used as a universal replacement cabinet. 18" Control Cabinet (Redundant) (48V) (DC) |
| 9400-200-160-NA | \$2,310.88 | NOTE(S): Spare Cabinet does not contain a Hard Drive, CTU or RSD Drive. To be used as a universal replacement cabinet. 18" Control Cabinet (Redundant) (110V) (AC) |
| 9400-200-200-NA 9400-200-301-NA | · | NOTE(S): Spare Cabinet does not contain a Hard Drive, CTU or RSD Drive. To be used as a universal replacement cabinet. Power Module Redundant Peripheral/DSU Resource Card |
| 9400-200-303-NA | | Peripheral Slot FIM Carrier Card |
| 9400-200-303-NA | \$1,333.20 | NOTE(S): For use with Superset Hub. Superset Hub Unit |
| 9400-300-201-NA | \$444.40 | NOTE(S): Basic Field Replaceable Unit. Includes MC330AB DNIC Line Card (Qty1) and Power Cords. Does NOT include FIMS or Peripheral Slot FIM Carrier Card. Power Supply (DC) Control Node |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--|---|--|
| | SPARE COMPONE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| 9400-300-204-NA 9400-300-302-NA 9400-300-306-NA 9400-300-312-NA 9400-800-201-NA MA209AA MC215AD MC243BA MC312AB MK191AA | \$355.52 \$1,795.38 \$444.40 \$231.09 \$88.88 \$3,555.20 \$1,333.20 \$888.80 | Assembly Power Supply Quad Fim Carrier Hard Disk Drive Control Resources Card III Power Distribution Unit (AC) 3.5" FLOPPY DRIVE Main Control IIIe Card Circuit Switch Matrix II Card Peripheral Switch Control II Card RSD Upgrade Kit |
| MP912BA MP914AA MU171AA MU172BA MU190EA | \$888.80 \$799.92 \$1,422.08 | NOTE(S): Minimum of LW28 MR2 P07.8.2 is required. For Redundant LIGHT Systems an MSX Card at Rev. A.11 or higher is required. Power Converter (DC) Power Converter (AC) SS700 Monitor SS700 Control Unit SS700 Keyboard |
| | NZ NODZOJOANDO | |
| 9125-100-271-NA | \$1,650.00 | E1 R2 Digital Link Hardware Expansion Package Includes: MC271AA E1 R2 Dual link Card (Qty 1) MA225AA Interface Assembly (Qty 1) MW404AA "CABLE" RJ45 TO 2X BNC (Qty 2) 9125-271-000-NA R2 Application Software (Qty 1) NOTE(S): This R2 Hardware Expansion kit does NOT include Digital Link Software options. Additional Links MUST be purchased Pre-requisite(s) required: LIGHTWARE 30 RELEASE 1 UR 1 MINIMUM |



PART NUMBER NET PRICE DESCRIPTION NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change R2 NODES/CARDS (Continued) 9125-502-101-NA \$2,000.00 SX-2000 E1 R2 Single link Package Includes: MC271AA E1 R2 Card (Qty 1) MA225AA Interface Assembly (Qty 1) MW404AA "CABLE" RJ45 TO 2X BNC (Qty 2) 9125-271-000-NA R2 Application software (Qty 1) MSA-A-15 MSDN Voice 1 (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-32 MSDN Voice 5 (Qty 1) MSA-A-36 ANI/DNIS (Qty 1) 9125-533-001-NA 1st Digital Link Option (Qty 1) NOTE(S): This E1 R2 package includes one (1) Digital link to enable the second (2) link you must purchase 9125-533-002 Pre-requisite(s) required: Minimum Software LIGHTWARE 30 RELEASE 1 UR 1 MA225AA \$200.00 Interface Assembly NOTE(S): This interface assembly can be used with either the R2 card or the ISDN PRI card MC271AA \$1,500.00 SX-2000 E1 R2 DUAL LINK CARD Includes: 9125-271-000-NA R2 Application Software (Qty 1) NOTE(S): This R2 Dual Link card DOES NOT include Digital Link options Digital Link Options MUST be purchased separately Pre-requisite(s) required: Minimum Software LIGHTWARE 30 RELEASE 1 UR 1 R2 SPARES 9125-271-000-NA \$500.00 R2 Card Application CD-Rom Software MW404AA \$75.00 Cable RJ45 to 2 X BNC

PROGRAM: SX-2000 NETWORKING PACKAGES



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | PROGRAM: SX-20 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change 2000 NETWORKING PACKAGES (Continued) |
| 9125-300-001-NA | \$5,870.63 | 32 Station Software Network Package Includes: |
| 9125-300-002-NA | \$6,340.28 | 9400-200-161-NA MICROLIGHT Basic Assembly (Qty 1) MA218AA T1 Assembly (Qty 1) MC263BA T1 Trunk Card (Qty 1) MC330AB DNIC Card (Qty 2) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-31 MSAN (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) MFRD-A-40 32 Station Package (Qty 1) 9125-500-030-NA Lightware 30 Software Pkg (Qty 1) 48 Station Software Network Package |
| | | Includes: 9400-200-161-NA MICROLIGHT Basic System (Qty 1) MA218AA T1 Assembly (Qty 1) MC263BA T1 Trunk Card (Qty 1) MC330AB DNIC Card (Qty 2) MFRD-A-42 48 Station Package (Qty 1) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-31 MSAN (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) 9125-500-030-NA Lightware 30 Software Pkg (Qty 1) |
| 9125-300-003-NA | \$6,762.96 | Includes: 9400-200-161-NA MICROLIGHT Basic System (Qty 1) MA218AA T1 Assembly (Qty 1) MC263BA T1 Trunk Card (Qty 1) MC330AB DNIC Card (Qty 2) MFRD-A-44 96 Station Pkg (Qty 1) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-31 MSAN (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) 9125-500-030-NA Lightware 30 Software (Qty 1) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | PROGRAM: SX-20 | NEW = New Part Number NC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DOO NETWORKING PACKAGES (Continued) |
| 9125-300-011-NA | \$5,999.40 | 32 Station Software Network Package |
| 9125-300-012-NA | \$6,443.80 | Includes: 9400-200-161-NA MicroLight Basic System (Qty 1) MA218AA DS1 Assembly (Qty 1) MC263BB E1/T1 Formatter Card (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LW30 Software (Qty 1) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-31 MSAN Voice I (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) MFRD-A-40 MFRD 40 32 Stn S/W (Qty 1) 48 Station Software Network Package |
| | | Includes: 9400-200-161-NA MicroLight Basic System (Qty 1) MA218AA DS1 Assembly (Qty 1) MC263BB E1/T1 Formatter Card (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LW30 Software (Qty 1) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-31 MSAN Voice I (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) MFRD-A-42 MFRD 42 48 Stn S/W (Qty 1) |
| 9125-300-013-NA | \$6,843.76 | Includes: 9400-200-161-NA MicroLight Basic System (Qty 1) MA218AA DS1 Assembly (Qty 1) MC263BB E1/T1 Formatter Card (Qty 1) MC330AB DNIC Line Card (Qty 2) 9125-500-030-NA LW30 Software (Qty 1) MSA-A-15 MSDN Voice I (Qty 1) MSA-A-16 MSDN Voice II (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) MSA-A-19 MSDN Public Network Access (Qty 1) MSA-A-21 MSDN Voice IV (Qty 1) MSA-A-31 MSAN Voice I (Qty 1) MSA-A-32 MSDN Voice V (Qty 1) MFRD-A-44 MFRD 44 96 Stn S/W (Qty 1) |
| MK080CE | \$3,287.55 | LW26/27 - LW28 S-Floppy Upgrade |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | PROGRAM: SX-20 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change DOO NETWORKING PACKAGES (Continued) |
| MS2008-L-NA-00 | \$0.00 | LW28 Instream Upgrade LIGHT |
| | PROGRAM: SX-20 | 000 SOFTWARE MIGRATION |
| 9125-100-110-NA | \$1,000.00 | SX-2000 REMOTE S/W MAKER |
| | | NOTE(S): Used to download SX-2000 In-Stream Software Upgrades from Mitel On Line. |
| 9148-000-530-NA | \$0.00 | Includes: 9145-550-510-NA SCSI Controller 800X/1500S (Qty 1) 9150-500-395-NA RSD Internal Drive (Qty1) 9150-500-399-NA RSD Blank Disks 5 Pack (Qty 1) Remote Copier Software Program/ Cables/ User Guide Lightware 30 Image CD |
| MK080DA | \$3,287.55 | NOTE(S): Will not be sold separately. MUST be purchased with MK080OPS or MR011AA. Order Qty 1 Image CD per Network and Qty 1 MK080OPS or MR011AA per system. Lightware 29 To Lightware 30 Upgrade |
| MK080OPS | \$3,287.55 | NOTE(S): May require a Hard Disk Drive Upgrade (MK192AA) if at LW29 Rls 1 or Rls 2. Software Assurance may be ordered with this part. All software options detailed in the "Dimension & Features" Form attached to this order are re-licensed at no charge. System Documentation is included in this upgrade. A software Application Form and LW30 Certification are required. Lightware 30 Upgrade Via Ops Manager |
| | | NOTE(S): Must be purchased with 9148-000-530-NA (one per Network). Order Qty 1 MK080OPS per switch in Network. All software options detailed in the "Dimension & Features form attached to this order are re-licensed at no charge. System Documentation is included in this upgrade. A Software Application Form and LW30 Certification are required. Can only be used when upgrading from LW29 Rls 3 to LW 30. Pre-requisite(s) required: 9148-000-530-NA Lightware 30 Image CD (Qty 1) |



NET PRICE PART NUMBER DESCRIPTION NEW = New Part Number ™ = Price Increase DEC = Price Decrease сно = Part Description/Note/BOM/Pre-Reg Change PROGRAM: SX-2000 SOFTWARE MIGRATION (Continued) **MK0810PS** \$469.65 LW29 Maintenance Release Upgrade via Ops Manager NOTE(S): For upgrades within LW29 with Ops Manager ONLY. Lightware 29 Release 2 Technical Certification is required. Order Qty 1 per switch in the Network. Order Qty 1 per network of either 9148-000-513-NA LW29 Software Image Tape (UNIX) or 9148-000-514-NA LW29 Software Image CDROM (for Windows NT). Software Assurance for future Core loads may NOT be purchased at the time of this upgrade. MK082BD \$444.40 MCII, MCIIe, MCIII, MCIII **MCIIIE** NOTE(S): For SX-2000 Light and Microlight Systems ONLY To be used with the Software Migration Program. Purchase order should reflect the LIST PRICE. Sales Order Acknowledgement will reflect Price after rebate. A RA# will be issued for the return of the old card. Failure to return the old card will result in a billing to your account for the difference between the LIST Price and the Price after rebate. MK082DA \$5,166.15 Lightware 28 To Lightware 30 Upgrade NOTE(S): May require a Hard Disk Drive Upgrade (MK192AA). May require an RSD Upgrade Kit (MK191AA). If yes/ the Mass Storage Expander Card must be at rev. A.11 for Redundant Systems. Software Assurance may be ordered with this part. All software options detailed in the "Dimension & Features" Form attached to this order are re-licensed at no charge. System Documentation is included in this upgrade. A Software Application Form and LW30 Certification are required.



PART NUMBER NET PRICE DESCRIPTION NEW = New Part Number ™ = Price Increase DEC = Price Decrease сно = Part Description/Note/BOM/Pre-Reg Change PROGRAM: SX-2000 SOFTWARE MIGRATION (Continued) MK083DA \$6,575.10 Lightware 26/27 To Lightware 30 Upgrade May require a Hard Disk Drive Upgrade (MK192AA). Includes an RSD Upgrade Kit (MK191AA). The Mass Storage Expander Card must be at rev. A.11 for Redundant Systems. Software Assurance may be ordered with this part. All software options detailed in the "Dimension & Features" Form attached to this order are re-licensed at no charge. System Documentation is included in this upgrade. A Software Application Form and LW30 Certification are required. MK102CA \$9,393.00 Dark-to-LIGHT LW30 Upgrade (All Software Levels) NOTE(S): Includes System Software, Documentation and System Identification Module. Only valid for purchase if upgrading systems from the DARK platform. All software options detailed in the "Dimension & Features" Form attached to this order are re-licensed at no charge. System Documentation is included in this upgrade. LW30 Certification is required. Refer to Program Bulletin for details regarding required product returns. For Non-redundant DARK to Redundant LIGHT upgrades include MSA-A-12 at no charge on your Purchase Order. When upgrading from DARK to LIGHT, the database must be re-entered manually. MK192AA \$444.40 SX-2000 Hard Disk Drive Upgrade A LIGHTWARE 30 Upgrade MUST be ordered at the same time as the Hard Disk Drive Upgrade in order to be eligible for this Program. 9400-300-306-NA Hard Disk Drive (Qty. 1)



NET PRICE PART NUMBER DESCRIPTION NEW = New Part Number ™ = Price Increase DEC = Price Decrease сно = Part Description/Note/BOM/Pre-Reg Change PROGRAM: SX-2000 SOFTWARE MIGRATION (Continued) ML010AA \$1,408.95 Software Assurance - 1 Future Core Load NOTE(S): Must be purchased with the following part numbers: 9125-500-030-NA/ MK080DA/ MK082DA/ MK083DA/ MK102CA MK370AA/ MK371AA/ MR010AA/ MR011AA/ MR012AA May be ordered up to a maximum of 2 times. MR011AA \$0.00 SW Assurance One Core Load Redemption via OPs Manager NOTE(S): Can only be used by Software Assurance Customers on a LIGHT platform, operating OPS Manager, to redeem one free software load. Reference Software Assurance Plan Number and System ID on the Purchase Order. Order one part number per switch in the Network. Must be ordered with 9148-000-530-NA LW30 OPS CD-Rom. \$0.00 Software Assurance Two Core Load Redemption MR012AA NOTE(S): Can only be used by Software Assurance Customers on a LIGHT platform to redeem two free software loads. Reference Software Assurance Plan Number and System ID on the Purchase Order. Order one part number per switch in the Network. Must be ordered with 9148-000-530-NA LW30 OPS CD-Rom. PROGRAM: SX-2000 HARDWARE UPGRADE MK139AA \$4,888.40 18" Non-Redun Redun INCLUDE(S): MC215AD Main Control IIIE Card (Qty 1) MC243BA Circuit Switch Matrix II Card (Qty 1) MSA-A-12 Main Control Redundancy (Qty 1) NOTE(S): MSA-A-12 Control Redundancy Software option will be added at No Charge.



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PROGRAM: SX-2000 HARDWARE UPGRADE (Continued)

MK140AA \$1,408.95 SX-2000 VS AC Microlight AC

INCLUDE(S):

9400-200-135-NA MICRO LIGHT Control Cabinet (Qty 1)

MP914AA AC Shelf Power Converter (Qty 1) MC215AD Main Control IIIE Card (Qty 1)

MC312AB Peripheral Switch Control II Card (Qty 1)

9400-300-312-NA Control Resource III Card (Qty 1)

9400-300-306-NA Hard Disk Drive (Qty 1) 9150-500-395-NA RSD Drive (Qty 1)

NOTE(S):

Requires a DSU Slot FIM Carrier Card (900-300-308-NA)

when adding Nodes.



SX-2000 SOFTWARE UPGRADES

PART NUMBER NET PRICE UPGRADE FROM UPGRADE TO

NEW = New Part Number

™ = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-2000 SOFTWARE UPGRADES SS7000 CONSOLE FOR SX-2000

9119-201-003-NA

\$187.86 SS7000 Upgrade to Win. 3.1 & Win. 95



OPS MANAGER SYSTEMS

PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

cmo = Part Description/Note/BOM/Pre-Req Change

OPS MANAGER SYSTEMS

NOTE(S):

Dealer must have an MCP (Microsoft Certified Professional) on staff before product can be ordered.

All Software purchases require a completed Software Application Form.

Dealer must put his MCP Number on the Software Application Form.

PRE-REQUISITE(S):

Minimum Switch Software Level: LW29R2 Minimum Hardware Level: CRC3 MC3E All other Hardware requirements as per LW29R2.

OPS MANAGER SOFTWARE

9148-000-034-NA \$5,635.80 OPS Manager for Windows NT Network Software

Includes:

9125-000-025-NA OPS Manager Switch Options (Qty 1) 9148-000-036-NA OPS Manager Basic Software (Qty 1) 9148-000-040-NA OPS System to Network Option (Qty 1)

NOTE(S):

OPS Manager Network Software

Manages 3 or more PBXs

Dealer must have Microsoft Certified Professional

OPS Certification is required

Software Application form is required

9148-000-038-NA \$13,150.20 OPS Manager for Windows NT Full Package

Includes:

9148-000-035-NA NT Server (Qty 1)

9148-000-034-NA OPS Manager Network Software (Qty 1) 9148-000-025-NA OPS Manager Switch Options (Qty 1)

NOTE(S):

OPS Manager Network Software with Server

Monitor and UPS Not Included To Manage 3 or more PBXs

OPS Manager Certification Required Software Application Form Required

Must have a Microsoft Certified Professional (MCP) on staff



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

OPS MANAGER SOFTWARE (Continued)

9148-000-039-NA \$2,348.25 OPS Manager NT System Software

Includes:

9125-000-025-NA OPS Manager Switch Options (Qty 1)

MSA-A-15 Voice 1 (Qty 1)

MSA-A-19 MSDN Public Network Access (Qty 1)

MNRD-A-02 Portable Directory Group for 2 PBXs (Qty 1) 91488-000-036-NA OPS Manager Basic Software (Qty 1)

NOTE(S):

OPS Manager System Software

Supports up to 2 PBX's

Software Application Form is Needed

Dealer must have Microsoft Certified Professional on Staff

OPS Certification is required

OPS MANAGER OPTIONS

9148-000-037-NA \$2,348.25 Directory Services Application Software

NOTE(S):

Directory Services Support for:

Novell NDS

Lotus Notes/Domino Microsoft Exchange

Directory Services orders will be directed to Marcel Jacques

PRE-REQUISITE(S):

9148-000-034-NA OPS Manager Network (Qty 1)

9148-000-038-NA OPS Manager Network Integrated (Qty 1) 9148-000-039-NA OPS Manager System Software (Qty 1)

SX-2000 MANAGEMENT OPTIONS



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | SX-2000 MANAGE | MENT OPTIONS (Continued) |
| 9148-000-025-NA | \$1,408.95 | Network Node Full Management Software Package |
| | | Includes: MSA-A-37 S/W OPS Manager Fault 1 (Qty 1) MSA-A-38 S/W OPS Manager Config. 1 (Qty 1) MSA-A-41 S/W MSDN/DPNSS Voice VI (Qty 1) MSA-A-42 S/W OPS Manager Config. 3 (Qty 1) MSA-A-44 S/W OPS Database Access (Qty 1) MNRD-A-02 MSDN Network Resource Dimension 2 (2 PBX`s) (Qty 1) 9125-100-100-NA EMI Filter Kit (Qty 1) NOTE(S): OPS Manager Switch Options Order 1 for every remote switch PRE-REQUISITE(S): Due to this Package containing MSDN Voice VI (MSA-A-41) you will require MSDN Voice I (MSA-A-15) as a pre-requisite. |
| | MSDN NETWORK | RESOURCE DIMENSIONS |
| MNRD-A-02 | \$0.00 | MSDN Network Resource Dimension 2 (2 PBXS) |
| | | NOTE(S): OPS Manager is the pre-requisite for all MNRD options. Provide PO number of OPS Manager if ordered seperately. PRE-REQUISITE(S): 9148-000-034-NA OPS Manager Network Managment (Qty 1) 9148-000-038-NA OPS Manager Integrated (Qty 1) 9148-000-039-NA OPS Manager System software (Qty 1) |
| MNRD-A-03 | \$234.82 | MSA-A-41 MSDN Voice VI MSDN Network Resource Dimension 3 (3 PBXS) |
| MNRD-A-04 | \$234.82 | PRE-REQUISITE(S): MNRD-A-02 MSDN Network Dimension 2 PBXs (Qty 1) MSDN Network Resource Dimension 4 (4 PBXS) |
| MNRD-A-05 | \$234.82 | PRE-REQUISITE(S): MNRD-A-03 (Qty 1) MSDN Network Resource Dimension 5 (5 PBXS) |
| MNRD-A-10 | \$234.82 | PRE-REQUISITE(S): MNRD-A-04 (Qty 1) MSDN Network Resource Dimension 10 (6-10 PBXS) |
| MNRD-A-30 | \$469.65 | PRE-REQUISITE(S): MNRD-A-05 (Qty 1) MSDN Network Resource Dimension 30 (11-30 PBXS) |
| | | PRE-REQUSITE(S): mnrd-a-10 (Qty 1) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | MSDN NETWORK | RESOURCE DIMENSIONS (Continued) |
| MNRD-A-60 | \$469.65 | MSDN Network Resource Dimension 60 (31-60 PBXS) |
| | | PRE-REQUSITE(S): MNRD-A-30 (Qty 1) |
| | OPS MANAGER U | PGRADES |
| 9148-000-520-NA | \$0.00 | Ops Manager NT Rls. 6.0 to 6.1 Upgrade |
| | | NOTE(S): For Current OPS 6.0 customers |
| | SX-2000 MANAGE | MENT OPTION UPGRADES |
| 9125-100-100-NA | \$133.32 | Dual Ethernet Connectivity Kit |
| | | NOTE(S): This Kit is used for connecting an Port to an MCIIIE Card. |
| | SX-2000 MGMT LA | N CONNECTIVITY KITS FOR UNIX |
| MK340AA | \$1,777.60 | Redundant LIGHT LAN Kit With CRCIII |
| MK342AA | \$1,066.56 | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 2) 9400-300-312-NA Control Resource 3 Card (Qty 1) MA230AA ETHERNET PADDLE Card & Cable (Qty 2) MA233AA RL DUAL 10BASE-T Interface Assembly (Qty 1) MicroLIGHT LAN Kit With CRCIII |
| NAIZO 4O A A | ф1 555 (0) | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 1) 9400-300-312-NA Control Resource 3 Card (Qty 1) MA230AA ETHERNET PADDLE Card & Cable (Qty 1) MA231AA ML AUI Interface Assembly (Qty 1) |
| MK343AA | \$1,///.60 | Redundant SX-2000 S LAN Kit INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 2) MA230AA ETHERNET PADDLE Card & Cable (Qty 2) MA232AA S/SG DUAL AUI Interface Assembly (Qty 1) MW520AA Cable S Maintenance & ALARMS Plane A (Qty 1) MW521AA Cable S Maintenance & ALARMS Plane B (Qty 1) MW522AA Cable S AUI Plane A (Qty 1) MW523AA Cable S AUI Plane B (Qty 1) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | SX-2000 MGMT LA | N CONNECTIVITY KITS FOR UNIX (Continued) |
| MK344AA | \$1,155.44 | Non-Redundant SX-2000 S LAN Kit |
| MK345AA | \$1,777.60 | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 1) MA230AA ETHERNET PADDLE Card & Cable (Qty 1) MA232AA S/SG DUAL AUI Interface Assembly (Qty 1) MW520AA Cable S Maintenance & ALARMS Plane A (Qty 1) MW522AA Cable S AUI Plane A (Qty 1) SX-2000 SG LAN Kit |
| MK346AA | \$1,155.44 | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 2) MA230AA ETHERNET PADDLE Card & Cable (Qty 2) MA232AA S/SG DUAL AUI Interface Assembly (Qty 1) MW510AA Cable SG Maintenance COMM Plane A (Qty 1) MW511AA Cable SG Maintenance COMM Plane B (Qty 1) MW512AA Cable SG Maintenance ACCESS Plane A (Qty 1) MW513AA Cable SG Maintenance ACCESS Plane B (Qty 1) SX-2000 VS LAN Kit |
| MK347AA | \$1,599.84 | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 1) MA230AA ETHERNET PADDLE Card & Cable (Qty 1) MA234AA VS AUI Interface Assembly (Qty 1) MW514AA Cable VS Maintenance COMM (Qty 1) Redundant LIGHT LAN Kit |
| MK349AA | \$888.80 | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 2) MA230AA ETHERNET PADDLE Card & Cable (Qty 2) MA233AA RL DUAL 10BASE-T Interface Assembly (Qty 1) MicroLIGHT LAN Kit |
| | | INCLUDE(S): MC230AA ETHERNET Interface Card (Qty 1) MA230AA ETHERNET PADDLE Card & Cable (Qty 1) MA231AA ML AUI Interface Assembly (Qty 1) |
| | OPS MANAGER SI | PARES FOR WINDOWS NT |
| 9125-100-100-NA | \$133.32 | Dual Ethernet Connectivity Kit |
| | | NOTE(S): This Kit is used for connecting an Port to an MCIIIE Card. |
| | OPS MANAGER SI | PARES FOR UNIX |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|-----------|---------------|
| TARTHOMBER | HETTRIOL | DEGOMII TIGIT |

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

OPS MANAGER SPARES FOR UNIX (Continued)

| 9400-300-312-NA | \$444.40 | Control Resources Card III |
|-----------------|------------|--------------------------------------|
| MA230AA | \$102.21 | ETHERNET Paddle Card & Cable |
| MA231AA | \$97.77 | MicroLIGHT AUI Interface Assembly |
| MA232AA | \$311.08 | S/SG DUAL AUI Interface Assembly |
| MA233AA | \$124.43 | RL DUAL 10BASE-T Interface Assembly |
| MA234AA | \$4,177.76 | VS AUI Interface Assembly |
| MC230AA | \$577.72 | ETHERNET Interface Card |
| MW510AA | \$133.32 | Cable SG Maintenance COMM Plane A |
| MW511AA | \$133.32 | Cable SG Maintenance COMM Plane B |
| MW512AA | \$111.10 | Cable SG Maintenance ACCESS Plane A |
| MW513AA | \$111.10 | Cable SG Maintenance ACCESS Plane B |
| MW520AA | \$88.88 | Cable S Maintenance & ALARMS Plane A |
| MW521AA | \$88.88 | Cable S Maintenance & ALARMS Plane B |
| MW522AA | \$88.88 | Cable S AUI Plane A |
| MW523AA | \$88.88 | Cable S AUI Plane B |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|-----------|-------------|
| FANT NUMBER | NETFRICE | DESCRIF HON |

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200

SX-200 EL STANDARD PACKAGES

| 9109-650-004-NA | \$3,021.92 | SX-200 EL PKG (MCCIII ELx, Triple FIM, Stratum 3 Clock 110V) |
|-----------------|------------|--|
| 9109-650-005-NA | \$2,844.16 | Includes: 9109-610-202-NA Main Control Card III ELx with Stratum 3 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply 110V (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 1) NOTE(S): SX-200 EL PKG (MCCIII ELx, Dual FIM, Stratum 3 Clock 110V) |
| 9109-652-001-NA | \$1,244.32 | Includes: 9109-610-202-NA Main Control Card III Elx with Stratum 3 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-002-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply 110V (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) 9109-611-001-NA Control Dual FIM Carrier (Qty 1) SX-200 Peripheral Node 110V (Rack Mountable) |
| 9109-652-011-NA | \$1,244.32 | INCLUDE(S): 9109-600-001-NA SX-200 Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-612-001-NA Peripheral FIM Carrier II (Qty 1) 9400-300-301-NA FIM Card (Qty 1) SX-200 Peripheral Node 220V (Rack Mountable) |
| | | INCLUDE(S): 9109-600-001-NA SX-200 Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-002-NA Bay Power Supply (Qty 1) 9109-612-001-NA Peripheral FIM Carrier II (Qty 1) 9400-300-301-NA FIM Card (Qty 1) |

SX-200 EL VERTICAL MARKET PACKAGES



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|---|
| | SX-200 EL VERTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change CAL MARKET PACKAGES (Continued) |
| 9109-650-211-NA | \$4,354.23 | SX-200 EL ST3 H/M 6X48X12 PKG |
| 9109-650-212-NA | \$11,997.91 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA Main Control Card III ELx with Stratum 3 Clock (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) 9109-611-001-NA CONTROL DUAL FIM II CARRIER CARD (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package SX-200 EL ST3 H/M 6X48X12 & NuPoint DNIC Pwr Pkg-8P/90Hr |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA Main Control Card III ELx with Stratum 3 clock (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) 9109-611-001-NA CONTROL DUAL FIM II CARRIER CARD (Qty 1) 9150-803-071-NA NuPoint DNIC Power Pkg - 8P 90 Hour (Qty 1) 9109-012-001-NA SX-200 DNIC Line Card (incl. in NuPoint) (Qty 1) 6286 NuPoint 2 Port Serial Interface Card (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package |
| | SX-200 ML STAND | PARD PACKAGES |
| 9109-651-001-NA | \$666.60 | SX-200 ML Package Rls. 2 (Stratum 4 Clock 110V) INCLUDE(S): 9109-610-001-NA Main Control Card III ML w/Stratum 4 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|---|
| | SX-200 ML STAND | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change ARD PACKAGES (Continued) |
| | | |
| 9109-651-002-NA | \$1,111.00 | SX-200 ML Pkg. Rls.2 (MCCIII ML, Stratum 3 Clock 110V) |
| 9109-651-004-NA | \$4,444.00 | INCLUDE(S): 9109-610-002-NA Main Control Card III ML w/ Stratum 3 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) SX-200 ML Business Pkg. 12X36/SETS/MEM/ST4 |
| 9109-651-011-NA | \$666.60 | Includes: 9109-610-001-NA Main Control Card III ML w/Stratum 4 Clock (Qty 1) 9109-600-002-NA SX-200 Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (110V) (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (6 Circuit) (Qty 2) 9401-000-024-NA Music on Hold/Paging Unit (DNIC) (Qty 1) 9109-080-002-NA Mitel Express Messenger 4 Port (Qty 1) 9132-025-202-NA Superset 4025 Dark Grey Backlit (Qty 9) 9132-150-202-NA Superset 4150 Dark Grey Backlit (Qty 1) 9132-200-202-NA Kit Superset PKM 48 Dark Grey (Qty 1) SX-200 ML Pkg. Rls.2 (MCCIII ML, Stratum 4 Clock 220V) |
| 9109-651-012-NA | \$1,111.00 | Includes: 9109-610-001-NA Main Control Card III ML w/ Stratum 4 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-002-NA Bay Power Supply (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) SX-200 ML Pkg. Rls.2 (MCCIII ML, Stratum 3 Clock 220V) |
| | | Includes: 9109-610-002-NA Main Control Card III ML w/ Stratum 3 Clock (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-002-NA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|---|
| | SX-200 ML STAND | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change ARD PACKAGES (Continued) |
| 9109-651-101-NA | \$1,777.60 | SX-200 ML Package of 4 Rls. 2 (Stratum 4 Clock 110V) |
| 0400 050 004 NA | Ø1 044 20 | INCLUDE(S): 9109-651-001-NA SX-200 ML Package Rel. 2 w/ Stratum 4 Clock (Qty 4) |
| 9109-652-001-NA | \$1,244.32 | SX-200 Peripheral Node 110V (Rack Mountable) INCLUDE(S): 9109-600-001-NA SX-200 Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) |
| 9109-652-011-NA | \$1,244.32 | 9109-612-001-NA Peripheral FIM Carrier II (Qty 1) 9400-300-301-NA FIM Card (Qty 1) SX-200 Peripheral Node 220V (Rack Mountable) |
| | | INCLUDE(S): 9109-600-001-NA SX-200 Cabinet (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-002-NA Bay Power Supply (Qty 1) 9109-612-001-NA Peripheral FIM Carrier II (Qty 1) 9400-300-301-NA FIM Card (Qty 1) |
| | SX-200 ML VERTIC | CAL MARKET PACKAGES |
| 9109-651-003-NA | \$2,576.63 | SX-200 ML 4 Port Express Messenger System (110V) |
| 9109-651-211-NA | \$2,754.39 | INCLUDE(S): 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-001-NA MCCIII ML w/ Stratum 4, 110V (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) 9109-080-002-NA 8 Port Express Messenger Card,4 Ports enabled (Qty 1) SX-200 ML ST3 H/M 6X48X12 PKG |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-002-NA Main Control Card III ML Stratum 3 (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package |





| PART NUMBER | NET PRICE | DESCRIPTION |
|--|--|--|
| | SX-200 ML VERTIC | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change CAL MARKET PACKAGES (Continued) |
| 9109-651-212-NA | \$4,664.42 | SX-200 ML H/M ST3 6X48X12 4 Port Express Messenger PKG |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-002-NA Main Control Card III ML Stratum 3 (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) 9109-080-002-NA Mitel Express Messenger - 4 port (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package |
| | CARDS | |
| 9109-005-000-SA 9109-010-002-SA 9109-010-100-NA 9109-011-001-SA 9109-013-000-SA 9109-016-000-SA 9109-018-000-SA 9109-020-000-SA 9109-021-001-NA 9109-021-001-NA 9109-040-000-SA 9109-060-000-SA 9109-610-001-NA 9109-610-002-NA 9109-610-101-NA 9109-610-102-NA 9109-610-202-NA 9109-611-001-NA | \$1,201.90 \$7,726.50 \$1,158.98 \$858.50 \$291.89 \$304.77 \$145.95 \$858.50 \$799.92 \$643.88 \$1,158.98 \$858.50 \$171.70 \$666.60 \$799.92 | Main Control Card III-ML Card (Stratum 3) Main Control III-EL Card (Stratum 4) Main Control III-EL Card (Stratum 3) Main Control III-ELx Card (Stratum 3) Dual FIM Carrier Control Card (EL/ML) |
| | | INCLUDE(S): One imbedded FIM and space for One other optional FIM. |





| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | CARDS (Continued | • |
| 9109-612-001-NA | | Peripheral Card FIM Carrier (EL Cabinet) |
| 9109-613-001-NA | \$688.82 | Triple FIM Carrier Control Card |
| 9400-300-301-NA 9400-300-315-NA | | INCLUDE(S): Two imbedded FIM's and space for One other optional FIM. NOTE(S): Under Bid Control. For low traffic installations only Fiber Interface Module (FIM) Multi-Mode Extended FIM |
| 9400-300-316-NA | \$1,066.56 | NOTE(S): Two (2) FIM's are required per link. For use only on SX-200 Peripheral Nodes or SX-2000 Peripheral and DSU Nodes. Single Mode Extended FIM |
| 9400-300-317-NA | \$444.40 | NOTE(S): Two (2) FIM's required per link. For use only on SX-200 Peripheral Nodes or SX-2000 Peripheral and DSU Nodes. Control FIM Carrier |
| | | NOTE(S): For use only on SX-200 ML Release 1 Systems. |
| 9401-000-004-NA | | SPINE DNIC Module |
| 9401-000-011-NA | | Power Module (Spine) |
| 9401-000-012-NA | | SX-200 SPINE II |
| 9401-000-019-NA | · · | SPINE Control Module |
| 9401-000-020-NA | · | SPINE ONS Module |
| 9401-000-021-NA 9401-000-022-NA | · | SPINE LS/CLASS Module Spine T/R Cable (8 Pin to Amp.) |
| 9401-000-022-NA 9401-000-024-NA | | Music on Hold Paging Unit (DNIC) |
| 9109-613-002-NA | | Control Triple FIM Carrier Card MM 5KM |
| 9109-613-003-NA | | Control Triple FIM Carrier Card SM 14KM |
| 9400-100-301-NA | | Peripheral Fim Carrier |
| | SPARE COMPONE | · |
| 50000404 | | 0\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\ |
| 50000161 | | SX200 ML/EL DOOR (PLASTIC) |
| 9109-002-006-SA | | 4 Meg Memory |
| 9109-008-000-SA | | Bay Power Supply 120 Volt |
| 9109-017-001-SA | | Bay Control Card |
| 9109-034-000-NA | \$207.76 | SP.DISKS G1001 336 PORT |





| PART NUMBER | NET PRICE | DESCRIPTION |
|--|--|--|
| | SPARE COMPONE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | | (11) |
| 9109-034-001-NA 9109-034-301-NA 9109-034-302-NA 9109-034-311-NA 9109-034-312-NA 9109-034-400-NA 9109-034-500-NA | \$207.76 \$207.76 \$207.76 \$207.76 \$207.76 | G1002 Software G1003 Software G1003 ACD Software G1003 (672 Port) Software G1003 (672 Port ACD) Software G1004 Software Lightware 15 Software |
| 9109-034-600-NA 9109-125-000-SA 9109-418-234-NA | \$177.76 | NOTE(S): 9109-034-500-NA Lightware 15 Software Diskettes (Qty 2) Spare Disks LW16 3.5" Floppy Disk Drive (Card Mounted) LW 18 Release 1 (4MB) Flash Card - Spare |
| 9109-600-002-NA 9109-631-001-NA 9180-305-000-NA 9180-EXT-000-NA 9189-048-000-NA 9400-100-304-NA 9400-300-204-NA 9400-300-302-NA 9400-300-305-NA 9400-300-401-NA | \$66.66 \$382.18 \$751.44 \$75.14 \$177.76 \$444.40 \$355.52 \$186.65 | NOTE(S): Includes CD ROM Tech. Practices SX-200 ELx Cabinet SX-200 RM Fan Assembly System Fail Transfer Unit (6 Circuit) COV Loop Extender Console Handset (Light Grey)(Qty 10) Dual T1 Adapter (SX-200 LIGHT) Assembly Power Supply Quad Fim Carrier 3.5" Floppy Disk Drive (SX-200 LIGHT) Cabinet Wall Mount Kit NOTE(S): |
| | | For use only on SX-200 ML Release 1 Systems. |
| | CONSOLES | |
| 9119-000-013-NA 9119-000-014-NA 9119-101-001-NA 9189-000-016-NA 9189-888-001-NA | \$671.60 \$93.93 \$888.80 | SS7000 Windows 95 Pkg. (English) SS7000 Windows 3.1 Pkg. (English) SS7000 Handset Cradle Superconsole 1000 (Grey) Console Handset Amplifier with Volume Control NOTE(S): Used for Superconsole 1000 & Superset 700 consoles installed in the US prior to Jan 1/2000 to provide Volume Control that meets Jan1/2000 FCC Part 68 volume control rules. Also adhers to Canada`s Jan1/2000 Volume Control rule |





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200 VERTICAL MARKET SYSTEM SOFTWARE

9109-100-131-NA \$1,549.85 SX-200 ML/EL Hotel/Motel Software Pkg.

9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn

Solutions hardware pkg #9109-651-211-NA or

#9109-651-212-NA or 9109-650-211-NA

PART # 9109-100-131-NA IS MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA. SX-200 ML/EL can

only operate with one of these options on the system

Express Messenger Hospitality software option

#9109-542-100-NA at an additional charge and

SX-200 Voicemail Softkey Option #9109-532-011-NA at no charge must also be ordered for hardware package

#9109-651-212-NA.





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200 VERTICAL MARKET SYSTEM SOFTWARE (Continued)

9109-100-132-NA

\$1,549.85 SX-200 ML/EL Hotel/Motel Package w/Messaging Software

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

9109-532-011-NA Voicemail Softkeys (Qty 1)

6470-1-B1 NuPoint English Prompts (Qty 1)

6925-70-B1 NuPoint Wake-UP (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn

Solutions hardware pkg #9109-650-212-NA or

when ordering a Mitel mail system separately with Mitel Inn Solutions hardware packages #9109-651-211-NA or

#9109-650-211-NA

PART # 9109-100-132-NA IS MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA. SX-200 ML/EL can

only operate with one of these options on the system

Messaging Softkeys for SX-200 Option is now included

in NuPoint DNIC Power Package(s).





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

™ = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200 VERTICAL MARKET SYSTEM SOFTWARE (Continued)

9109-100-133-NA

\$1,549.85 SX-200 ML/EL Software Pkg. w/PMS Interface Option

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-004-NA PMS Interface Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn

Solutions hardware pkg #9109-651-211-NA or

#9109-651-212-NA or 9109-650-211-NA

PART # 9109-100-133-NA IS MUTUALLY EXCLUSIVE OF

9109-100-131-NA OR 9109-100-132-NA. SX-200 ML/EL can

only operate with one of these options on the system

Express Messenger Hospitality software option

#9109-542-100-NA at an additional charge and

SX-200 Voicemail Softkey Option #9109-532-011-NA at no

charge must also be ordered for hardware package

#9109-651-212-NA.





| PART NUMBER | NET PRICE | DESCRIPTION | | |
|-----------------------------|-----------------|--|--|--|
| | SX-200 VERTICAL | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change MARKET SYSTEM SOFTWARE (Continued) | | |
| 9109-100-134-NA | \$1,549.85 | SX-200 ML/EL Software Pkg. w/PMS & Messaging Software | | |
| | | Includes: 9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices 9109-532-023-NA LW18 Core Features (Qty 1) 9109-532-005-NA Remote Software Download Option (Qty 1) 9400-200-302-NA System ID Module (Qty 1) 9109-530-048-NA 48 Maximum User Devices Option (Qty 1) 9109-530-120-NA 120 Maximum User Devices Option (Qty 1) 9109-532-007-NA Superset 4000 Series Sets Option (Qty 1) 9109-532-004-NA PMS Interface Option (Qty 1) 9109-532-001-NA Automated Attendant Option (Qty 1) 9109-532-001-NA Voicemail Softkeys (Qty 1) 6470-1-B1 NuPoint English Prompts (Qty 1) 6925-70-B1 NuPoint Wake-UP (Qty 1) NOTE(S): This software is required when ordering Mitel Inn Solutions hardware pkg #9109-650-212-NA or when ordering a Mitel mail system separately with Mitel Inn Solutions hardware packages #9109-651-211-NA or #9109-650-211-NA The variant of Mitel Mail PMS software option must be ordered seperately. PART # 9109-100-134-NA IS MUTUALLY EXCLUSIVE OF 9109-100-131-NA OR 9109-100-132-NA. SX-200 ML/EL can only operate with one of these options on the system. Messaging Softkeys for SX-200 Option is now included in NuPoint DNIC Power Package(s). | | |
| SX-200 MAXIMUM USER DEVICES | | | | |
| 9109-530-120-NA | \$469.65 | SX-200 ML/EL 120 Maximum User Devices PRE-REQUISITE(S) 9109-530-048-NA | | |
| 9109-530-216-NA | \$1,455.91 | 9109-530-096-NA 9109-530-072-NA SX-200 ML/EL 216 Maximum User Devices | | |
| 9109-530-336-NA | \$516.61 | PRE-REQUISITE(S): 9109-530-120-NA 9109-530-144-NA SX-200 EL 336 Maximum User Devices PRE-REQUISITE(S): 9109-530-216-NA | | |





| PART NUMBER | NET PRICE | DESCRIPTION |
|---|----------------|--|
| | SX-200 MAXIMUM | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change USER DEVICES (Continued) |
| | | |
| 9109-530-432-NA | \$281.79 | SX-200 EL 432 Maximum User Devices |
| 9109-530-552-NA | \$281.79 | PRE-REQUISITE(S): 9109-530-336-NA SX-200 EL 552 Maximum User Devices |
| 9109-530-672-NA | \$177.76 | PRE-REQUISITE(S): 9109-530-432-NA OR 9109-530-456-NA OR 9109-530-480-NA SX-200 EL 672 Maximum User Devices |
| 9109-530-768-NA | \$187.86 | PRE-REQUISITE(S): 9109-530-552-NA 552 Port software option (Qty 1) SX-200 EL 768 Maximum User Devices |
| 9109-534-001-NA | \$2,489.14 | NOTE(S): Requires LW 17 Release 3.1 This option not available on LW 17 Release 1.1/2.0/ or 3.0 Pre-requisite(s) required: PRE-REQUISITE(S): 9109-530-672-NA SX-200 EL 672 Maximum User Devices (Qty 1) SX-200 ML/EL Options Pkg 120-336 Maximum User Devices |
| | | INCLUDE(S): 9109-530-120-NA 120 Port Software Option 9109-530-216-NA 216 Port Software Option 9109-530-336-NA 336 Port Software Option |
| | SX-200 SOFTWAR | E OPTIONS |
| 9109-532-001-NA 9109-532-002-NA 9109-532-003-NA | \$234.82 | Auto Attendant Option Mitel Application Interface Option Lodging Hotel/Motel Option |
| 9109-532-004-NA | \$0.00 | NOTE(S): Part #`s 9109-532-003-NA and 9109-532-004-NA are mutually exclusive of each other. SX-200 ML/EL can only operate with one of these options on the System. PMS Interface Option |
| 9109-532-006-NA | \$469.65 | NOTE(S): Part #`s 9109-532-003-NA and 9109-532-004-NA are mutually exclusive of each other. SX-200 ML/EL can only operate with one of these options on the System. Centralized Voicemail & Centralized Attendant |
| | | NOTE(S): For use with LW17 only. |





| PART NUMBER | NET PRICE | DESCRIPTION | | |
|---|--|--|--|--|
| | SX-200 SOFTWAR | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change E OPTIONS (Continued) | | |
| 9109-532-007-NA | \$469.65 | Superset 4000 Series Sets Option | | |
| 9109-532-010-NA | \$234.82 | NOTE(S): For use with minimum LW17 only. Fax Tone Detection Option | | |
| 9109-532-011-NA | \$0.00 | NOTE(S): For use with minimum LW17 (ML/EL) only. SX-200 Voicemail Softkey Option | | |
| 9109-532-013-NA | \$46.96 | NOTE(S): For use with LW 17 Rel. 3.1 or later. MOSS Option enables softkey integration on Mitel Express Messenger Rel. 2.1 (MEM) and Mitel NuPoint Messenger Rel. 7.0 or greater. To order: Serial number of MEM or Mitel NP Messenger must be provided OR ensure the MEM / Mitel NP Messenger system appears on the same purchase order as the SX-200 Voicemail Softkey option. ACD Real Time Event Option | | |
| | | NOTE(S): Requires LW 17 Rel 4 or greater This option can only be ordered in conjunction with at least one of the following applications: SX-200 TASKE Rel. 7 ACD Toolbox for 1 to 5 Agents (9146-610-216-NA) or SX-200 TASKE Warranty Renewal (9146-610-362-NA) or SX-200 TASKE Warranty Re-enlist (9146-610-363-NA or or SX-200 prairieFyre CyberACD (9146-610-401-NA or 9146-610-402-NA or 9146-610-403-NA or 9146-610-404-NA). These parts must be purchased directly from Mitel. | | |
| ACD AGENTS (SX-200 ML/EL) | | | | |
| 9109-531-005-NA 9109-531-010-NA 9109-531-015-NA 9109-531-025-NA 9109-531-050-NA 9109-531-075-NA 9109-531-100-NA | \$469.65 \$469.65 \$469.65 \$234.82 | ACD Agents 1-5 ACD Agents 6-10 ACD Agents 11-15 ACD Agents 16-25 ACD Agents 26-50 ACD Agents 51-75 ACD Agents 76-100 | | |
| TAPI SERVICE PROVIDER (SX200 ML/EL) | | | | |





| PART NUMBER | NET PRICE | DESCRIPTION |
|--|--|--|
| | TAPI SERVICE PR | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change OVIDER (SX200 ML/EL) (Continued) |
| 9109-535-005-NA 9109-535-010-NA 9109-535-015-NA 9109-535-020-NA 9109-535-025-NA 9109-535-030-NA 9109-535-040-NA 9109-535-050-NA | \$117.41 \$70.45 \$70.45 \$70.45 \$70.45 | SX-200 TAPI Service Provider 0-5 Users SX-200 TAPI Service Provider 6-10 Users SX-200 TAPI Service Provider 11-15 Users SX-200 TAPI Service Provider 16-20 Users SX-200 TAPI Service Provider 21-25 Users SX-200 TAPI Service Provider 26-30 Users SX-200 TAPI Service Provider 31-40 Users SX-200 TAPI Service Provider 41-50 Users |
| 9109-518-600-NA 9109-518-601-NA 9109-518-602-NA 9109-518-610-NA 9109-518-611-NA 9109-518-612-NA 9109-518-998-NA | \$704.47 \$2,817.90 \$1,174.12 \$2,583.07 \$5,635.80 | LIGHTWARE 16 Enhanced 72 Port LIGHTWARE 16 Enhanced 144 Port LIGHTWARE 16 Enhanced 672 Port LIGHTWARE 16 ACD 72 Ports LIGHTWARE 16 ACD 144 Ports LIGHTWARE 16 ACD 672 Port SX-200 LIGHT LW 15/16 Mitel Mail DNIC Integration SW Option |
| 54000050 9109-100-052-NA | | Includes: 9109-034-500-NA Lightware 15 Software Diskettes (Qty 2) NOTE(S): This option is only available for SX-200 LIGHT systems with LIGHTWARE 15 or LIGHTWARE 16 Serial number from Mitel Mail system must be provided with purchase order for this option. Speak@Ease Option LIGHTWARE 18 Rel. 1 (4MB) Software Package & Docs |
| | | Includes: 9109-418-234-NA LW 18 Release 1 s/w 4MB Flash & CD-ROM Tech. Practice (Qty 9400-200-302-NA System ID Module (Qty 1) 9109-530-048-NA 48 Maximum User Devices Option (Qty 1) 9109-532-007-NA Superset 4000 Series Sets Option (Qty 1) 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users (Qty 1) 9109-532-023-NA LW 18 Core Features (Qty 1) 9109-532-005-NA Remote Software Download Option (Qty 1) |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | SX-200 SOFTWAR | E - LIGHT (Continued) |
| 9109-532-021-NA | \$469.65 | Record A Call Option |
| | | NOTE(S): Serial number from Mitel Express Messenger card must be provided with purchase order for this option. Requires LW 18 Release 1.0 or greater Requires minimum Mitel Express Messenger 3.0 |
| | ISDN NODES/CAR | DS |
| 9109-615-101-NA | \$1,777.60 | SX-200EL/ML PRI Card Single Link Package |
| 9109-615-202-NA | \$1,599.84 | INCLUDE(S): 9109-615-001-NA PRI Card (Qty 1) 9180-510-004-NA Dual link T1/E1 PRI module (Qty 1) 9109-411-001-NA PRI card Application software (Qty 1) 9109-533-201-NA Single Link Option (Qty 1) NOTE(S): This Package includes a Dual link T1/E1 module with one link enabled. To activate Link 2 you require S/W opt 9109-533-202-NA. The PRI T1/E1 module is equipped with a CSU. A stratum 3 clock is required. This package is intended for the Control node, it DOES NOT INCLUDE A FIM II MODULE. PRE-REQUISITE(S): Lightware 17.4 or greater Cabinet (9109-600-002-NA) ISDN PRI card with T1/E1 & FIMII Modules |
| | | Includes: 9109-615-001-NA SX-200 PRI Carrier card (Qty 1) 9180-510-004-NA T1/E1 Module (Qty 1) 9180-510-001-NA FIMII module Multimode (Qty 1) 9109-411-001-NA PRI Card Application software (Qty 1) NOTE(S): This package is intended to be used in a peripheral bay when additional links are required. These link options MUST be purchased seperately to activate this card. If this card is being added to an existing site you will be required to provide the SX-200 System ID to get the additional links activated. Pre-requisite(s): Lightware 17.4 or greater ELx Cabinet (9109-600-002-NA) |
| 9109-632-001-NA | \$0.00 | RS232 Adapter for ELx cabinet and PRI card Pre-requisite(s): Only required with ELX cabinet revision 4.3 or less and only required if the new PRI card is installed |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | JEDN NODES/CAR | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | ISDN NODES/CAR | DS (Continuea) |
| 9109-652-201-NA | \$2,444.20 | SX-200EL/ML ELx Cabinet with 1 PRI link enabled |
| 9109-652-202-NA | \$3,555.20 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-615-001-NA PRI Card (Qty 1) 9180-510-004-NA Dual Link T1/E1 PRI module (Qty 1) 9109-411-001-NA PRI card Application software (Qty 1) 9109-533-201-NA Single Link Option (Qty 1) NOTE(S): This package is intended to replace an existing EL Control Cabinet. It DOES NOT INCLUDE A FIMII CARD. The FIMII card MUST be purchased separately. This Package includes a Dual link T1/E1 module with 1 link enabled. To Activate link 2 you require 9109-533-202-NA The PRI T1/E1 module is equipped with a CSU. A stratum 3 clock is required Pre-requisite(s): LW 17.4 or greater SX-200EL/ML PRI Single Link PKG with ELx PER Node |
| 9400-700-407-NA | \$469.65 | Includes: 9109-612-001-NA Peripherial FIM Carrier II (Qty 1) 9400-300-301-NA FIM Card (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-615-001-NA PRI Card (Qty 1) 9180-510-004-NA Dual Link T1/E1 PRI module (Qty 1) 9180-510-001-NA FIM II (Qty 1) 9109-411-001-NA PRI card Application software (Qty 1) 9109-533-201-NA Single Link Option (Qty 1) NOTE(S): This Package includes a Dual link T1/E1 module with 1 link enabled. To Activate link 2 you require 9109-533-202-NA The ISDN T1/E1 module is equipped with a CSU A stratum 3 clock is required Pre-requisite(s): Lightware 17.4 or greater ISDN Gateway Software Package (SX-200 LIGHT) |
| | | NOTE(S): Used for ISDN Node Software Upgrades Release 4 and prior only. Requires a Software Application Form. For use with 9400-700-103-NA only. |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | | NEW = New Part Number NC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | ISDN NODES/CAR | DS (Continued) |
| 9400-700-612-NA | \$2,044.24 | ISDN Release 4 to Release 5 Upgrade Kit |
| 9400-700-625-NA | \$3,555.20 | INCLUDE(S): MB160AAA Dual Link T1 Card (Qty 1) 9147-602-010-NA CD-Rom Drive EID (Qty 1) 9145-500-413-NA 16 Meg Memory Modules (Qty 2) 795000310 Windows NT 4.0 (Qty 1) 9400-700-326-NA ISDN Options Module (Qty 1) 9400-700-414-NA ISDN S/W Package (Qty 1) 9400-700-419-NA Dual Link Access S/W (Qty 1) 9400-700-417-NA Min/Max Software (Qty 1) 9400-700-422-NA NFAS (Qty 1) MSA-A-17 MSDN Voice III (Qty 1) NOTE(S): This Upgrade Kit will only work on a PC LIGHT (Cabinet will be labelled). It will not work on 486 ISDN Nodes. The AFC Card must be upgraded using BC028. Must be LW28 MR2 P17.6.2 for SX-2000 or minimum LW15/16 F57.2 for SX-200. ISDN SX-200 Telecom Server 800 |
| MB160AAA | \$1,066,56 | INCLUDE(S): 9400-700-124-NA ISDN Basic System Telecom server 800 (Qty 1) MB160AAA Edual link PRA card (Qty 1) 9400-700-418-NA Single Link SW (Qty 1) 9400-700-414-NA ISDN SW SX-200 (Qty 1) 9400-700-302-NA AFC Application Fiber Controller w/FIM (Qty 1) 9400-300-301-NA Fiber Interface Module (FIM) (Qty 1) NOTE(S): This product comes with a Dual Link Card but only one link is activated Dual Link PRI Card |
| | ψ1,000.20 | NOTE(S): |
| | 100N 00FTWARE | For use with Release 5 and above ISDN Nodes. |
| | ISDN SOFTWARE | OPTIONS |
| 9109-411-001-NA | \$469.65 | SX200EL/ML Latest Software Release |
| 9109-532-015-NA | \$704.47 | NOTE(S): This software is used with the SX-200EL/ML PRI card Only SX-200EL/ML Min/Max Software Option (PRI Card) NOTE(S): This S/W option is used with the PRI card only Pre-requisite(s): Lightware 17.4 or later |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|---------------|---|
| | ISDN SOFTWARE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change OPTIONS (Continued) |
| 9109-532-016-NA | \$140.89 | SX-200EL/ML Auto Min/Max Software Option (PRI Card) |
| 9109-532-017-NA | \$469.65 | NOTE(S): This Auto Min/Max S/W option is used with the PRI card only Pre-requisite(s): Lightware 17.4 or later The Min/Max S/W option must be purchased first SX-200EL/ML NFAS Software Option (PRI Card) |
| 9109-532-018-NA | \$234.82 | NOTE(S): This NFAS S/W option is used with the PRI card only Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML D-Channel Software Option (PRI Card) |
| 9109-532-019-NA | \$1,127.16 | NOTE(S): This D-channel Back up S/W option is used with the PRI card Pre-requisite(s): Lightware 17.4 or later The NFAS S/W option (9109-532-017-NA) must be Purchased first. ISDN Remote LAN Access software option for PRI card |
| 9109-532-020-NA | \$704.48 | NOTE(S): This software option can only be used on the ISDN PRI card Pre-requisite(s) required: SX-200ML/EL LW17.4 software ISDN PRI card ISDN Release 6 application software SX-200 QSIG Network Software Option |
| 9109-533-201-NA | \$939.30 | NOTE(S): This option is only supported on the PRI card The minimum software required for QSIG is LIGHTWARE17 Release 4 UR 2/ QSIG outbound calling name requires LIGHTWARE 18 SX-200EL/ML PRI Card link (1) one S/W option |
| 9109-533-202-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (2) two link S/W option |
| 9109-533-203-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (3) three link S/W option NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later |





| PART NUMBER | NET PRICE | DESCRIPTION | |
|--|------------------------|---|--|
| NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change ISDN SOFTWARE OPTIONS (Continued) | | | |
| 9109-533-204-NA | \$939.30 | SX-200EL/ML PRI card (4) four link S/W option | |
| 9109-533-205-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (5) five link S/W option | |
| 9109-533-206-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (6) six link S/W option | |
| 9109-533-207-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (7) seven link S/W option | |
| 9109-533-208-NA | \$939.30 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later SX-200EL/ML PRI card (8) eight link S/W option | |
| 9400-700-407-NA | \$469.65 | NOTE(S): This S/W option is used with the PRI card and T1/E1 Module Pre-requisite(s): Lightware 17.4 or later ISDN Gateway Software Package (SX-200 LIGHT) | |
| 9400-700-417-NA 9400-700-419-NA | \$704.47 \$1.878.60 | NOTE(S): Used for ISDN Node Software Upgrades Release 4 and prior only. Requires a Software Application Form. For use with 9400-700-103-NA only. Min/Max Software Option - Rls. 5 Dual Link Access Software Option - Rls. 5 | |
| 9400-700-420-NA | \$2,817.90 | NOTE(S): Required for (2nd) Second PRI Link activation. Pre-Requisite(s): ISDN Node Release 5 Three Link Access Software Option - Rls. 5 | |
| | | NOTE(S): This Software is required for a 3rd link activation and will also require the Customer to purchase an additional Dual Link PRA Card (MB160AAA). You do not require Two Link Software as a pre-requisite. Pre-Requisite(s): ISDN Node Release 5 | |





| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|---------------|--|
| | ISDN SOFTWARE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change OPTIONS (Continued) |
| 9400-700-421-NA | \$4,226.85 | Four Link Access Software Option - Rls. 5 |
| 9400-700-422-NA 9400-700-431-NA | | NOTE(S): This Software is required for a 4th Link activation. You do not require Two & Three Link Software as pre-requisites but you may require an MB160AAA Dual Link PRA Card. Pre-Requisite(s): ISDN Node Release 5 Network Facility Assoc. Signaling (NFAS) SftwrRls. 5 ISDN Network Gateway 2 - 3 link upgrade |
| 9400-700-432-NA | \$3,288.56 | INCLUDE(S): 9400-700-420-NA ISDN 3 link option (Qty 1) MB160AAA EDual link PRA card (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA or 9400-700-623-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA or 9400-700-625-NA Must be purchased prior to ordering upgrade AND 9400-700-419-NA Must be purchased prior to ordering upgrade ISDN Network Gateway 2 - 4 link upgrade |
| 9400-700-433-NA | ¢1 222 20 | INCLUDE(S): 9400-700-421-NA ISDN 4 link option (Qty 1) MB160AAA EDual link PRA card (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA Must be purchased prior to ordering upgrade AND 9400-700-419-NA Must be purchased prior to ordering upgrade ISDN Notwork Catoway 3-4 link upgrade |
| 9400-700-433-NA | \$1,333.20 | ISDN Network Gateway 3 -4 link upgrade INCLUDE(S): 9400-700-421-NA ISDN 4 link option (Qty 1) PRE-REQUISITE(S): 9400-700-606-NA Must be purchased prior to ordering upgrade OR 9400-700-607-NA Must be purchased prior to ordering upgrade AND 9400-700-420-NA Must be purchased prior to ordering upgrade |
| 9400-700-434-NA | \$469.65 | ISDN Network Gateway Software Release 6 NOTE(S): Used to upgrade the ISDN Network Gateway Software to the Latest Release 6 |





| PART NUMBER | NET PRICE | DESCRIPTION | |
|------------------------------------|-------------|--|--|
| | ISDN SPARES | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change | |
| 9109-615-001-NA | \$1,066.56 | SX-200EL/ML ISDN PRI Card | |
| 9145-500-413-NA 9180-510-001-NA | | NOTE(S): This PRI Card does NOT include a Dual link T1/E1 module The minimum S/W required to support this card is LW 17.4 This card is only supported in the ELx Cabinet Software Link Options are not included and must be ordered separately. Memory Expansion Module 16MB SX-200EL/ML FIM II card | |
| 9180-510-004-NA | | NOTE(S): This FIM II card is used in the PER node and plugs onto the PRI card. An ELx Cabinet is required to support the FIM II A minimum of LW17.4 S/W is required to support the FIM II SX-200EL/ML Dual link T1/E1 PRI Module | |
| 9400-700-301-NA | \$1,688.72 | NOTE(S): This Dual link T1/E1 Module is used with the PRI card The T1/E1 module is equipped with a CSU The minimum S/W requirement is LW17.4 Software Link Options are not included and must be ordered separately. Application Fibre Controller W/FIM | |
| 9400-700-314-NA 9400-700-318-NA | · · | NOTE(S): For use with Release 4 and prior ISDN Nodes. MVIP Cable Single Link PRA Card | |
| 9400-700-319-NA | \$3,199.68 | NOTE(S): Used to add 1 link to ISDN Single Link Node. For use with Release 4 and prior ISDN Nodes. Dual Link PRA Card | |
| 9400-700-323-NA | \$44.44 | NOTE(S): For use with Release 4 and prior ISDN Nodes. ISDN Node to Network Cable | |
| PROGRAM: SX-200 ML/EL UPGRADES | | | |





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000060 | \$2,299.00 | SX-200D 456P G1002-5 SX-200 EL Latest SW BSC |
|----------|------------|---|
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9400-300-301-NA FIM (Qty 1) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 1) 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9109-530-456-NA 456 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| 50000004 | Φ1 COO OO | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000061 | \$1,699.00 | SX-200L LW16 Basic SX-200 ML Latest SW |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-008-000-SA 100V Power Supply (Qty 1) |
| | | 9109-610-002-NA MCC III ML Strat. 3 (Qty 1) |
| | | 9109-530-072-NA 72 User Devices Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000062 | \$1,399.00 | SX-200 ML SX-200 EL w/MCC III ELx |
| | | |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-002-NA MCC III ML Strat. 3 (Qty 1) |
| | | 50000100 LW 18 R 1.0 Software Upgrade (Qty 1) |
| 52000063 | \$2,099.00 | SX-200D 480P G1003-5 SX-200 EL Latest SW ACD |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9109-017-001-SA Bay Control Card (Qty 1) 9109-530-480-NA 480 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| | | 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-531-100-NA 100 ACD Agents Option (Qty 1) |
| F2000064 | \$1,600,00 | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) SX-200L LW16 ENH 72 SX-200 ML Latest SW |
| 52000064 | \$1,699.00 | SX-200L LW16 ENH 72 SX-200 ML Latest SW Port |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-008-000-SA 100V Power Supply (Qty 1) 9109-610-002-NA MCC III ML Strat. 3 (Qty 1) |
| | | 9109-530-072-NA 72 User Devices Option (Qty 1) |
| | | 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |





| | NET DDICE | DECODIDEION |
|-------------|-----------|-------------|
| PART NUMBER | NET PRICE | DESCRIPTION |

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000065 | \$2,099.00 | 200D 480P G1004-5 BSC+MAI | SX-200 EL Latest SW |
|----------|--------------------|--|---------------------|
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx C | abinet (Oty 1) |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple | |
| | | 9109-017-001-SA Bay Control Ca | rd (Qty 1) |
| | | 9109-530-480-NA 480 User Device | |
| | | 9109-532-001-NA Auto Attendant | |
| | | 9109-532-002-NA MAI Software | |
| 5000000 | Φ1 0 2 0 00 | 9109-100-052-NA LW 18 R 1.0 S | |
| 52000066 | \$1,929.00 | SX-200L LW16 ENH 144 Port | SX-200 EL Latest SW |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx C | |
| | | 9109-008-000-SA 100V Power Su | |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple 9109-530-144-NA 144 User Device | |
| | | 9109-532-002-NA MAI Software | |
| | | 9109-532-001-NA Auto Attendant | 1 |
| | | 9109-100-052-NA LW 18 R 1.0 S | |
| 52000067 | \$2,299.00 | 200D 456P G1004-5 | SX-200 EL Latest SW |
| | | BSC+MAI | |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx C | |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple | FIM Carrier (Qty 1) |
| | | 9400-300-301-NA FIM (Qty 1) | (Coming (Ot 1) |
| | | 9400-100-301-NA Peripheral FIM 9109-017-001-SA Bay Control Ca | |
| | | 9109-530-456-NA 456 User Device | |
| | | 9109-532-001-NA Auto Attendant | |
| | | 9109-532-002-NA MAI Software | |
| | | 9109-100-052-NA LW 18 R 1.0 S | |
| 52000068 | \$1,929.00 | SX-200L LW15 | SX-200 EL Latest SW |
| | | | |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx C | |
| | | 9109-008-000-SA 100V Power Su | |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple | |
| | | 9109-530-672-NA 672 User Device 9109-532-001-NA Auto Attendant | |
| | | 9109-100-052-NA LW 18 R 1.0 S | |
| | | 7107-100-032-11A LW 10 K 1.0 D | on marc (Qty 1) |



| | NET DDICE | DECODIDEION |
|-------------|-----------|-------------|
| PART NUMBER | NET PRICE | DESCRIPTION |

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000069 | \$2,899.00 | D672P LW15 or G1003-4 SX-200 EL Latest SW ACD |
|----------|--------------------|--|
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 2) |
| | | 9400-300-301-NA FIM (Qty 3) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 3) 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9109-530-672-NA 672 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| | | 9109-531-100-NA 100 ACD Agents Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000070 | \$2,899.00 | D672P LW15 or G1003-4 SX-200 EL Latest SW BSC |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 2) 9400-300-301-NA FIM (Qty 3) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 3) |
| | | 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9109-530-672-NA 672 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| 5000054 | #2 <00 00 | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000071 | \$2,699.00 | D336P LW15 or G1001-4 SX-200 EL Latest SW BSC |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 2) |
| | | 9400-300-301-NA FIM (Qty 2) |
| | | 9109-530-336-NA 336 User Device Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| 50000070 | Φ1 0 2 0 00 | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000072 | \$1,929.00 | SX-200L LW15 MAI SX-200 EL Latest SW |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-008-000-SA 100V Power Supply (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9109-530-672-NA 672 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| | | 7107 100 002 1111 211 1011 110 001tmate (Qty 1) |





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000073 | \$1,929.00 | SX-200L LW16 ACD 144 Port | SX-200 EL Latest SW |
|----------|-----------------|---|--|
| 52000074 | \$1,929.00 | Includes: 9109-600-002-NA SX-200 ELx Ca 9109-008-000-SA 100V Power Su 9109-610-202-NA MCC III Elx St 9109-613-001-NA Control Triple I 9109-530-144-NA 144 User device 9109-532-001-NA Auto Attendant 9109-532-002-NA MAI Software 0 9109-531-100-NA 100 ACD Agen 9109-100-052-NA LW 18 R 1.0 Sc SX-200L LW16 Basic | pply (Qty 1) rat. 3 (Qty 1) FIM Carrier (Qty 1) es Option (Qty 1) c S/W Option (Qty 1) Option (Qty 1) tts Option (Qty 1) |
| 52000075 | \$1,929.00 | Includes: 9109-600-002-NA SX-200 ELx Ca 9109-008-000-SA 100V Power Su 9109-610-202-NA MCC III Elx St 9109-613-001-NA Control Triple I 9109-530-672-NA 672 User Devic 9109-532-002-NA MAI Software O 9109-100-052-NA LW 18 R 1.0 So SX-200 LW15 ACD | pply (Qty 1) rat. 3 (Qty 1) FIM Carrier (Qty 1) res Option (Qty 1) Option (Qty 1) |
| 52000076 | \$2,600,00 | Includes: 9109-600-002-NA SX-200 ELx Ca 9109-008-000-SA 100V Power Su 9109-610-202-NA MCC III Elx St 9109-613-001-NA Control Triple I 9109-530-672-NA 672 User Devic 9109-532-001-NA Auto Attendant 9109-531-100-NA 100 ACD Agen 9109-100-052-NA LW 18 R 1.0 Sc D336P LW15 or G1003-4 | pply (Qty 1) rat. 3 (Qty 1) FIM Carrier (Qty 1) res Option (Qty 1) r. S/W Option (Qty 1) r. Soption (Qty 1) |
| | <i>\$2,000.</i> | ACD Includes: 9109-600-002-NA SX-200 ELx Ca 9109-610-202-NA MCC III Elx St 9109-613-001-NA Control Triple I 9109-017-001-SA Bay Control Ca 9400-100-301-NA Peripheral FIM 9400-300-301-NA FIM (Qty 2) 9109-530-336-NA 336 User Devic 9109-532-001-NA Auto Attendant 91091-531-100-NA 100 ACD Age 9109-100-052-NA LW 18 R 1.0 Sc | abinet (Qty 1) crat. 3 (Qty 1) FIM Carrier (Qty 1) rd (Qty 1) Carrier (Qty 2) ce Option (Qty 1) cs/W Option (Qty 1) cents Option (Qty 1) |





| PART NUMBER | NFT PRICE | DESCRIPTION |
|-------------|-----------|-------------|

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| F2000077 | ¢1 020 00 | SV 2001 I W/46 FNILL 672 | SX-200 EL Latest SW |
|----------|------------|---|-------------------------|
| 52000077 | \$1,929.00 | SX-200L LW16 ENH 672 Port | SX-200 EL Latest SW |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx Ca | abinet (Oty 1) |
| | | 9109-008-000-SA 100V Power Su | |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple | |
| | | 9109-530-672-NA 672 User Device | |
| | | 9109-532-002-NA MAI Software | |
| | | 9109-532-001-NA Auto Attendant | |
| 52000078 | \$1,200,00 | 9109-100-052-NA LW 18 R 1.0 Se SX-200 EL w/MCC III EL | SX-200 EL w/MCC III ELx |
| 32000076 | \$1,399.00 | 5X-200 EL W/MCC III EL | 3A-200 EL W/MCC III ELX |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx Ca | abinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 50000100 LW18 R 1.0 Software U | |
| 52000079 | \$1,929.00 | SX-200L LW16 ACD 672 | SX-200 EL Latest SW |
| | | Port | |
| | | Includes: | ahinat (Oty. 1) |
| | | 9109-600-002-NA SX-200 ELx Ca 9109-008-000-SA 100V Power Su | |
| | | 9109-610-202-NA MCC III Elx St | |
| | | 9109-613-001-NA Control Triple | |
| | | 9109-530-672-NA 672 User Device | |
| | | 9109-532-002-NA MAI Software | |
| | | 9109-532-001-NA Auto Attendant | |
| | | 9109-531-100-NA 100 ACD Agen | |
| | | 9109-100-052-NA LW 18 R 1.0 Se | |
| 52000080 | \$1,699.00 | SX-200L LW16 ACD 72 Port | SX-200 ML Latest SW |
| | | Includes: | |
| | | 9109-600-002-NA SX-200 ELx Ca | abinet (Qty 1) |
| | | 9109-008-000-SA 100V Power Su | |
| | | 9109-610-002-NA MCC III ML St | |
| | | 9109-530-072-NA 72 User Device | |
| | | 9109-532-002-NA MAI Software 0 | |
| | | 9109-532-001-NA Auto Attendant | |
| | | 9109-531-075-NA 75 ACD Agents 9109-100-052-NA LW 18 R 1.0 Se | |
| | | 7107-100-032-11A LW 10 K 1.0 St | Onware (Qty 1) |





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000081 | \$1,929.00 | SX-200L LW16 Basic SX-200 EL Latest SW |
|----------|------------|--|
| 52000082 | \$1,829.00 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-008-000-SA 100V Power Supply (Qty 1) 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 1) 9109-530-144-NA 144 User Devices Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) SX200D G1002 Basic SX-200 ML Latest SW 144P |
| 52000083 | \$2,099.00 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-002-NA MCC III ML Strat.3 (Qty 1) 9109-611-001-NA Control Dual FIM Carrier (Qty 1) 9109-017-001-SA Bay Control Card (Qty 1) 9109-530-144-NA 144 User Devices Option (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) SX-200D 480P G1000-5 SX-200 EL Latest SW |
| | | BSC Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA MCC III ELx Strat.3 (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 1) 9109-017-001-SA Bay Control Card (Qty 1) 9109-530-480-NA 480 User Devices Option (Qty 1) 9109-532-001-NA Auto Attendant S/W Option (Qty 1) 9109-100-052-NA LW18 R 1.0 Software (Qty 1) |
| 52000084 | \$1,699.00 | SX-200L LW15+1 SX-200 ML Latest SW |
| 52000085 | \$1,929.00 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-008-000-SA 100V Power Supply (Qty 1) 9109-610-002-NA MCC III ML Strat. 3 (Qty 1) 9109-530-096-NA 96 User Devices Option (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) SX-200L LW15 MAI & SX-200 EL Latest SW ACD |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-008-000-SA 100V Power Supply (Qty 1) 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 1) 9109-530-672-NA 672 User Devices Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) 9109-532-001-NA Auto Attendant S/W Option (Qty 1) 9109-531-100-NA 100 ACD Agents (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |





| PART NUMBER | NFT PRICE | DESCRIPTION |
|-------------|-----------|-------------|

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

| 52000086 | \$2,299.00 | SX-200D 456P G1003-5 SX-200 EL Latest SW ACD |
|----------|------------|--|
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9400-300-301-NA FIM (Qty 1) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 1) |
| | | 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9109-530-456-NA 456 User Devices Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| | | 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-531-100-NA 100 ACD Agents Option (Qty 1) |
| 5200007 | ¢2 <00 00 | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000087 | \$2,699.00 | SX-200D 456P G1003-5 SX-200 EL Latest SW ACD |
| | | |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 2) |
| | | 9400-300-301-NA FIM (Qty 2) |
| | | 9109-530-336-NA 336 User Device Option (Qty 1) |
| | | 9109-532-001-NA Auto Attendant S/W Option (Qty 1) |
| | | 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| 52000088 | \$2,699.00 | D336P LW15 ACD & MAI SX-200 EL Latest SW |
| | | Includes: |
| | | 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) |
| | | 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) |
| | | 9109-613-001-NA Control Triple FIM Carrier (Qty 1) |
| | | 9109-017-001-SA Bay Control Card (Qty 1) |
| | | 9400-100-301-NA Peripheral FIM Carrier (Qty 2) |
| | | 9400-300-301-NA FIM (Qty 2) |
| | | 9109-530-336-NA 336 User Device Option (Qty 1) |
| | | 9109-532-002-NA MAI Software Option (Qty 1) |
| | | 9109-531-100-NA 100 ACD Agents Option (Qty 1) |
| | | 9109-100-052-NA LW 18 R 1.0 Software (Qty 1) |
| | | |





| | NET DDICE | DECODIDEION |
|-------------|-----------|-------------|
| PART NUMBER | NET PRICE | DESCRIPTION |

NEW = New Part Number
NC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PROGRAM: SX-200 ML/EL UPGRADES (Continued)

52000089 \$2,899.00 D672P LW15MAI or SX-200 EL Latest SW

G1004MAI

Includes:

9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 2)

9400-300-301-NA FIM (Qty 3)

9400-100-301-NA Peripheral FIM Carrier (Qty 3) 9109-017-001-SA Bay Control Card (Qty 1) 9109-530-672-NA 672 User Devices Option (Qty 1) 9109-532-001-NA Auto Attendant S/W Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1)

52000090 \$2,899.00 \$X-200D 672 Port LW15 \$X-200 EL Latest SW

Includes:

9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-202-NA MCC III Elx Strat. 3 (Qty 1) 9109-613-001-NA Control Triple FIM Carrier (Qty 2)

9400-300-301-NA FIM (Qty 3)

9400-100-301-NA Peripheral FIM Carrier (Qty 3) 9109-017-001-SA Bay Control Card (Qty 1) 9109-530-672-NA 672 User Devices Option (Qty 1) 9109-532-001-NA Auto Attendant S/W Option (Qty 1) 9109-532-002-NA MAI Software Option (Qty 1) 9109-531-100-NA 100 ACD Agents Option (Qty 1) 9109-100-052-NA LW 18 R 1.0 Software (Qty 1)



SX-200 SOFTWARE UPGRADES

| PART NUMBER | NET PRICE UPGRADE FROM | UPGRADE TO |
|--------------|------------------------|------------|
| PAR I NUMBER | NET PRICE UPGRADE PROW | UPGRADE TO |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200 SOFTWARE UPGRADES

SX-200 LIGHT

| 9109-519-615-NA | \$413.29 | Upgrade from LW15 Ba | sic to LW16 Enhanced 672 |
|---|--|--|---|
| 9109-519-617-NA 9109-519-619-NA | | | sic to Lw16 ACD 672 Port LW16 Enh. 672 Port |
| 9109-519-621-NA | \$2,066.46 | Upgrade from LW15 En | hanced to LW16 ACD 672 |
| 9109-519-622-NA | \$375.72 | LW15 ACD | LW16 ACD 672 Port |
| 9109-519-638-NA | \$469.95 | LW16 Enh. 72 Port | LW16 Enh. 144 Port |
| 9109-519-639-NA | \$2,583.08 | LW16 Enh. 72 Port | LW16 Enh. 672 Port |
| 9109-519-642-NA | \$5,400.98 | LW16 Enh. 72 Port | LW16 ACD 672 Port |
| 9109-519-643-NA | \$2,113.42 | LW16 Enh. 144 Port | LW16 Enh. 672 Port |
| | | | 1 |
| 9109-519-645-NA | \$4,666.20 | Upgrade from LW16 En | hanced 144 Port to LW16 |
| 9109-519-645-NA 9109-519-646-NA | | Upgrade from LW16 En ACD 672 Port LW16 Enh. 672 Port | LW16 ACD 672 Port |
| | \$2,817.90 | ACD 672 Port | |
| 9109-519-646-NA | \$2,817.90 \$1,408.95 | ACD 672 Port LW16 Enh. 672 Port | LW16 ACD 672 Port |
| 9109-519-646-NA 9109-519-647-NA | \$2,817.90 \$1,408.95 \$4,461.68 | ACD 672 Port LW16 Enh. 672 Port LW16 ACD 72 Port | LW16 ACD 672 Port LW16 ACD 144 Port |
| 9109-519-646-NA 9109-519-647-NA 9109-519-648-NA | \$2,817.90 \$1,408.95 \$4,461.68 \$3,052.73 | ACD 672 Port LW16 Enh. 672 Port LW16 ACD 72 Port LW16 ACD 72 Port | LW16 ACD 672 Port LW16 ACD 144 Port LW16 ACD 672 Port |
| 9109-519-646-NA 9109-519-647-NA 9109-519-648-NA 9109-519-649-NA | \$2,817.90 \$1,408.95 \$4,461.68 \$3,052.73 | ACD 672 Port LW16 Enh. 672 Port LW16 ACD 72 Port LW16 ACD 72 Port LW16 ACD 144 Port LW15 +1 | LW16 ACD 672 Port LW16 ACD 144 Port LW16 ACD 672 Port LW16 ACD 672 Port |
| 9109-519-646-NA 9109-519-647-NA 9109-519-648-NA 9109-519-649-NA 9109-519-651-NA | \$2,817.90 \$1,408.95 \$4,461.68 \$3,052.73 \$2,348.24 \$5,166.15 | ACD 672 Port LW16 Enh. 672 Port LW16 ACD 72 Port LW16 ACD 72 Port LW16 ACD 144 Port LW15 +1 | LW16 ACD 672 Port LW16 ACD 144 Port LW16 ACD 672 Port LW16 ACD 672 Port LW16 ACD 672 Port |

SS7000 CONSOLE FOR SX-200

9119-201-002-NA \$169.07 SS7000 Upgrade to Win. 3.1 & Win. 95

SX-200 ML/EL



SX-200 SOFTWARE UPGRADES (Continued)

PART NUMBER NET PRICE UPGRADE FROM UPGRADE TO

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-200 ML/EL (Continued)

9109-100-057-NA \$352.24 LW16 ML and LW17 LW 18 Release 1

Includes:

9109-418-234-NA $\,$ LW 18 Rls 1 s/w 4MB Flash & CD-ROM Tech.

Practice (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users (Qty 1)

9109-532-023-NA LW 18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

NOTE(S):

Customers will be billed NET price initially.

Additional REBATED amount will be charged if the old

Flash Card is not returned to Mitel within 30 days.



MITEL INN SOLUTIONS

| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------|-----------|-------------|
| PAK I NUIVIDEK | NEI PRICE | DESCRIPTION |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Req Change

MITEL INN SOLUTIONS **HARDWARE**

9109-650-211-NA \$4.354.23 SX-200 EL ST3 H/M 6X48X12 PKG

Includes:

9109-600-002-NA SX-200 ELx Cabinet (Oty 1)

9109-610-202-NA Main Control Card III ELx with Stratum 3 Clock (Qty

9109-017-001-SA Bay Control Card II (Qty 1)

9109-008-000-SA Bay Power Supply (Qty 1)

9109-010-003-NA BONS Card (Qty 4)

9109-012-002-NA BNIC Card (Qty 1)

9109-011-001-SA LS/GS Trunk Card (Qty 1)

9109-611-001-NA CONTROL DUAL FIM II CARRIER CARD (Qty 1)

NOTE(S):

Please reference Mitel Inn Solutions SX-200 ML/EL

software packages for the required software to operate

this hardware package

9109-650-212-NA \$11,997.91 SX-200 EL ST3 H/M 6X48X12 & NuPoint DNIC Pwr

Pkg-8P/90Hr

Includes:

9109-600-002-NA SX-200 ELx Cabinet (Qty 1)

9109-610-202-NA Main Control Card III ELx with Stratum 3 clock (Qty

9109-017-001-SA Bay Control Card II (Qty 1)

9109-008-000-SA Bay Power Supply (Qty 1)

9109-010-003-NA BONS Card (Qty 4)

9109-012-002-NA BNIC Card (Qty 1)

9109-011-001-SA LS/GS Trunk Card (Qty 1)

9109-611-001-NA CONTROL DUAL FIM II CARRIER CARD (Oty 1)

9150-803-071-NA NuPoint DNIC Power Pkg - 8P 90 Hour (Qty 1)

9109-012-001-NA SX-200 DNIC Line Card (incl. in NuPoint) (Qty 1)

6286 NuPoint 2 Port Serial Interface Card (Otv 1)

NOTE(S):

Please reference Mitel Inn Solutions SX-200 ML/EL

software packages for the required software to operate

this hardware package



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | HARDWARE (Cont | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| 9109-651-211-NA | \$2,754.39 | SX-200 ML ST3 H/M 6X48X12 PKG |
| 9109-651-212-NA | \$4,664.42 | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-002-NA Main Control Card III ML Stratum 3 (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package SX-200 ML H/M ST3 6X48X12 4 Port Express Messenger PKG |
| | | Includes: 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-002-NA Main Control Card III ML Stratum 3 (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-010-003-NA BONS Card (Qty 4) 9109-012-002-NA BNIC Card (Qty 1) 9109-011-001-SA LS/GS Trunk Card (Qty 1) 9109-080-002-NA Mitel Express Messenger - 4 port (Qty 1) NOTE(S): Please reference Mitel Inn Solutions SX-200 ML/EL software packages for the required software to operate this hardware package |
| | SOFTWARE | |

Prices quoted in Net U.S. Dollars e. and o.e.



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

cно = Part Description/Note/BOM/Pre-Reg Change

SOFTWARE (Continued)

9109-100-131-NA \$1,549.85 SX-200 ML/EL Hotel/Motel Software Pkg.

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn

Solutions hardware pkg #9109-651-211-NA or

#9109-651-212-NA or 9109-650-211-NA

PART # 9109-100-131-NA IS MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA. SX-200 ML/EL can

only operate with one of these options on the system

Express Messenger Hospitality software option

#9109-542-100-NA at an additional charge and

SX-200 Voicemail Softkey Option #9109-532-011-NA at no

charge must also be ordered for hardware package

#9109-651-212-NA.



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Req Change

SOFTWARE (Continued)

9109-100-132-NA

\$1,549.85 SX-200 ML/EL Hotel/Motel Package w/Messaging Software

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-003-NA Lodging Hotel/Motel Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

9109-532-011-NA Voicemail Softkeys (Qty 1)

6470-1-B1 NuPoint English Prompts (Qty 1)

6925-70-B1 NuPoint Wake-UP (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn

Solutions hardware pkg #9109-650-212-NA or

when ordering a Mitel mail system separately with Mitel Inn Solutions hardware packages #9109-651-211-NA or

#9109-650-211-NA

PART # 9109-100-132-NA IS MUTUALLY EXCLUSIVE OF

9109-100-133-NA OR 9109-100-134-NA. SX-200 ML/EL can

only operate with one of these options on the system

Messaging Softkeys for SX-200 Option is now included

in NuPoint DNIC Power Package(s).



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SOFTWARE (Continued)

9109-100-133-NA

\$1,549.85 SX-200 ML/EL Software Pkg. w/PMS Interface Option

Includes:

9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices

9109-532-023-NA LW18 Core Features (Qty 1)

9109-532-005-NA Remote Software Download Option (Qty 1)

9400-200-302-NA System ID Module (Qty 1)

9109-530-048-NA 48 Maximum User Devices Option (Qty 1)

9109-530-120-NA 120 Maximum User Devices Option (Qty 1)

9109-532-007-NA Superset 4000 Series Sets Option (Qty 1)

9109-532-004-NA PMS Interface Option (Qty 1)

9109-532-001-NA Automated Attendant Option (Qty 1)

NOTE(S):

This software is required when ordering Mitel Inn Solutions hardware pkg #9109-651-211-NA or

#9109-651-212-NA or 9109-650-211-NA

PART # 9109-100-133-NA IS MUTUALLY EXCLUSIVE OF 9109-100-131-NA OR 9109-100-132-NA. SX-200 ML/EL can

only operate with one of these options on the system

Express Messenger Hospitality software option

#9109-542-100-NA at an additional charge and

SX-200 Voicemail Softkey Option #9109-532-011-NA at no

charge must also be ordered for hardware package

#9109-651-212-NA.



PART NUMBER NET PRICE DESCRIPTION NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Reg Change SOFTWARE (Continued) 9109-100-134-NA \$1,549.85 SX-200 ML/EL Software Pkg. w/PMS & Messaging Software Includes: 9109-418-234-NA LW 18 (Rel 1.0) SW, 4 Mb Flash & Tech Practices 9109-532-023-NA LW18 Core Features (Qty 1) 9109-532-005-NA Remote Software Download Option (Qty 1) 9400-200-302-NA System ID Module (Qty 1) 9109-530-048-NA 48 Maximum User Devices Option (Qty 1) 9109-530-120-NA 120 Maximum User Devices Option (Qty 1) 9109-532-007-NA Superset 4000 Series Sets Option (Qty 1) 9109-532-004-NA PMS Interface Option (Qty 1) 9109-532-001-NA Automated Attendant Option (Qty 1) 9109-532-011-NA Voicemail Softkeys (Qty 1) 6470-1-B1 NuPoint English Prompts (Qty 1) 6925-70-B1 NuPoint Wake-UP (Qty 1) NOTE(S): This software is required when ordering Mitel Inn Solutions hardware pkg #9109-650-212-NA or when ordering a Mitel mail system separately with Mitel Inn Solutions hardware packages #9109-651-211-NA or #9109-650-211-NA The variant of Mitel Mail PMS software option must be ordered seperately.

9109-542-102-NA

\$661.27 Mitel Express Messenger Option - Billingual

in NuPoint DNIC Power Package(s).

only operate with one of these options on the system. Messaging Softkeys for SX-200 Option is now included

PART # 9109-100-134-NA IS MUTUALLY EXCLUSIVE OF 9109-100-131-NA OR 9109-100-132-NA. SX-200 ML/EL can



MITEL MESSAGING SOLUTIONS

| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------|-----------|-------------|--|

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

MITEL MESSAGING SOLUTIONS

NOTE(S):

1. For parts and pricing pertaining to Professional Services please refer to the separate Professional Services Section within this Price List.

2. For parts and pricing pertaining to Mitel Mail 6.1B please refer to the separate Mitel Mail 6.1B Sub-Section within this Mitel Messaging Solutions Section.

MITEL EXPRESS MESSENGER

| 9109-080-002-NA | \$1,998.91 | Mitel Express Messenger 4 Port |
|------------------------------------|--------------------------|--|
| 9109-080-009-NA 9109-080-001-NA | \$3,244.12 \$1,776.71 | NOTE(S): Systems include: 8 Port Express Messenger Card with 4 Ports enabled Mitel Express Manager application Documentation softcopy on floppy disk Systems do not include serial cable for local management Mitel Express Messenger 6 port Mitel Express Messenger 2 Port |
| 9109-532-011-NA | \$0.00 | NOTE(S): Systems include: 8 Port Express Messenger Card with 2 Ports enabled Mitel Express Manager application Documentation softcopy on floppy disk Systems do not include serial cable for local management SX-200 Voicemail Softkey Option |
| | | NOTE(S): For use with LW 17 Rel. 3.1 or later. MOSS Option enables softkey integration on Mitel Express Messenger Rel. 2.1 (MEM) and Mitel NuPoint Messenger Rel. 7.0 or greater. To order: Serial number of MEM or Mitel NP Messenger must be provided OR ensure the MEM / Mitel NP Messenger system appears on the same purchase order as the SX-200 Voicemail Softkey option. |
| 9109-542-102-NA | \$661.27 | Mitel Express Messenger Option - Billingual |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | MITEL EXPRESS N | MESSENGER (Continued) |
| 9109-651-003-NA | \$2,576.63 | SX-200 ML 4 Port Express Messenger System (110V) |
| | | INCLUDE(S): 9109-600-002-NA SX-200 ELx Cabinet (Qty 1) 9109-610-001-NA MCCIII ML w/ Stratum 4, 110V (Qty 1) 9109-017-001-SA Bay Control Card II (Qty 1) 9109-008-000-SA Bay Power Supply (Qty 1) 9109-012-002-NA BNIC Card (Qty 2) 9109-010-003-NA BONS Card (Qty 1) 9109-080-002-NA 8 Port Express Messenger Card,4 Ports enabled (Qty 1) |
| | MITEL EXPRESS N | MESSENGER SOFTWARE |
| 9109-080-007-NA | \$46.96 | Mitel Express Manager Software |
| 9109-542-000-NA | \$374.78 | NOTE(S): This software is included with Express Messenger Systems Mitel Express Messenger 2-4 Port Software Upgrade |
| 9109-542-001-NA | \$1,418.34 | NOTE(S): Serial Number of Express Messenger Required with order Mitel Express Messenger Software Upgrade 2-6 Ports |
| 9109-542-002-NA | \$2,113.42 | NOTE(S): The serial number of the Express Messenger card is required. Mitel Express Messenger Upgrade 2-8 Ports |
| 9109-542-003-NA | \$1,210.76 | NOTE(S): Serial number of Mitel Express Messenger is required Mitel Express Messenger Software Upgrade 4-6 Ports |
| 9109-542-004-NA | \$1,892.69 | NOTE(S): The serial number of the Mitel Express Messenger is required Mitel Express Messenger Upgrade 4-8 Ports |
| 9109-542-005-NA | \$694.14 | NOTE(S): The serial number of the Mitel Express Messenger is required Mitel Express Messenger Software Upgrade 6-8 Ports |
| 9109-542-101-NA | \$882.00 | NOTE(S): The serial number of the Mitel Express Messenger is required MITEL EXPRESS MESSENGER PMS SOFTWARE OPTION |
| | | NOTE(S): |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--|---------------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) SYSTEMS (Continued) |
| 9150-803-022-NA 9150-803-052-NA 9150-803-063-NA 9150-803-070-NA | \$9,031.42 \$16,976.84 | Mitel NuPoint Messenger 70: 8 Port/90 hr, LS Mitel NuPoint Messenger 70: 8 Port/90 hr, E&M Mitel NuPoint Messenger 70: 24 Port/90 hr, T1 Mitel NuPoint Messenger 70 Power Pkg: 8 Port/210 hr, SX-200 |
| 9150-803-071-NA | \$6,825.07 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 8 Port/90 hr, SX-200 |
| 9150-803-072-NA | \$7,254.32 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 8 Port/210 hr, SX-2000 |
| 9150-803-073-NA | \$6,825.07 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 8 Port/90 hr, SX-2000 |
| 9150-803-074-NA | \$13,092.12 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 16 Port/210 hr, SX-200 |
| 9150-803-075-NA | \$12,233.62 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg: 16 Port/90 hr, SX-200 |
| 9150-803-076-NA | \$13,092.12 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg:16 Port/210 hr, SX-2000 |
| 9150-803-077-NA | \$12,233.62 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 16 Port/90 hr, SX-2000 |
| 9150-803-078-NA | \$19,960.12 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 1) Mitel NuPoint Messenger 70 Power Pkg: 24 Port/210 hr, SX-200 |
| | | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 2) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) SYSTEMS (Continued) |
| 9150-803-079-NA | \$18,886.14 | Mitel NuPoint Messenger 70 Power Pkg: 24 Port/90 hr, SX-200 |
| 9150-803-080-NA | \$19,960.12 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg:24 Port/210 hr, SX-2000 |
| 9150-803-081-NA | \$18,886.14 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg:24 Port/90 hr, SX-2000 |
| 9150-803-082-NA | \$24,252.62 | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg: 32 Port/210 hr, SX-200 |
| 9150-803-083-NA | \$23,394.12 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 3) Mitel NuPoint Messenger 70 Power Pkg: 32 Port/90 hr, SX-200 |
| 9150-803-084-NA | \$24,252.62 | Includes: 9109-012-001-NA SX-200 DNIC Line Card (Qty 3) Mitel NuPoint Messenger 70 Power Pkg:32 Port/210 hr, SX-2000 |
| 9150-803-085-NA | \$23,394.12 | Includes: MC330W5 SX-2000 DNIC Line card (Qty 2) Mitel NuPoint Messenger 70 Power Pkg: 32 Port/90 hr, SX-2000 |
| | | Includes: MC330W5 SX-2000 DNIC Line Card (Qty 2) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|-----------|-------------|
| | | |
| | | |

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

NUPOINT MESSENGER (70) SYSTEMS (Continued)

9150-262-072-NA \$3,661.50 Mitel NuPoint Messenger 70 Lite ENG: 4 Port/30 hr,

SX-200

NOTE(S): Includes:

4 Loop Start Ports (LS Ports) 30 Hours Message Storage Mitel NP Receptionist Software

English Prompts

Mitel PBX Enhanced Inband Integration

The only options that can be installed on a Mitel NuPoint Messenger system are PMS Integrations/ Hotel prompts/ and CTI (Serial) cards. These options must be ordered separately direct from Mitel after the system has been received and a System Information Report is printed. Any other hardware or software options will require the system to be upgraded to a Mitel NuPoint Messenger system.

NUPOINT MESSENGER (70) BASE SOFTWARE

9150-431-700-NA \$0.00 Mitel NuPoint Messenger Softkeys

NOTE(S):

Must also order 9109-532-011-NA to enable SX-200 softkey option (no charge) or MSA-A-53 to enable SX-2000 softkey option (no charge).

For Models 120R/120S/640, for all System Sales, this part must be ordered directly from Mitel.

In the U.S. Channels only: For Model 70 New System Sales this part must be

ordered from Wholesale Distribution.

NUPOINT MESSENGER (70) SW INTEGRATION KITS

6904-70-B1 \$231.07 Logistics/PMS Integration - Model 70

NOTE(S):

May require a serial port card.

9150-420-154-NA \$153.67 PTI Telcom Link Kit

NOTE(S):

You must also order a 2-port Serial Card (MVIP)

6286 from wholesale distribution.

Provides connectivity with Protocol Technologies Telcom Link



| PART NUMBER | NET PRICE | DESCRIPTION |
|---|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) OPTIONAL SOFTWARE |
| 9150-431-704-BA 9150-431-704-NA 9150-6464-05RB1 | \$923.33 | NuPoint Agent British English NuPoint Agent American English - Model 70 NP View Additional Remote Client Licenses (5) |
| 9150-6464-25RB1 | \$1,291.54 | INCLUDE(S): NP View User`s Guide (5)/ NP View Remote Client Licenses (5) NP View Remote 1.2 Client Software Floppy (5). NuPoint View Additional Remote Client Licenses (25) |
| 9150-6464100RB1 | \$3,875.55 | INCLUDE(S): NP View User`s Guide (25)/ NP View Remote Client Licenses (25)/ NP View Remote 1.2 Client Software Floppy (5) NP View Additional Remote Client Licenses (100) |
| 9150-6465-05RB1 | \$92.05 | INCLUDE(S): NP View User's Guide (50)/ NP View Remote Client Licenses (100)/ NP View Remote 1.2 Client Software Floppy (10). NP View Remote Client Spare Diskettes (5) |
| 9150-6464-25-B1 | | NOTE(S): Can be used for either local or remote users. NP View Additional Local Client Licenses (25) |
| 9150-6464-100B1 | \$2,768.11 | INCLUDE(S): NP View User's Guide (25)/ NP View Client Licenses (25)/ NP View 1.2 Client Software Floppy (5). NP View Additional Local Client Licenses (100) |
| 9150-6465-05-B1 9150-6488-02B1X | | INCLUDE(S): NP View User's Guide (50)/ NP View Client Licenses (100)/ NP View 1.2 Client Software Floppy (10). NP View Client Session Spare Diskettes (5) NP Net Asynchronous Kit 2-Link Expansion - Model 70 NOTE(S): |
| | | Requires NP Net/ VPIM Hardware. |
| | NUPOINT MESSEN | IGER (70) HARDWARE |
| 9150-5610TX | \$2,176.30 | DSE 8 Port Line Card - Model 70 - Nortel |
| 9150-5610T | \$2,176.30 | NOTE(S): Use for Nortel In-Channel Integration. DSE 8 Port Line Card - Nortel - Model 70 NOTE(S): |
| | | Use for Nortel In-Channel Integration. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) HARDWARE (Continued) |
| 9150-6215 | \$5,060.86 | NuPoint Fax Card - Shared Resource 4 Port - Model 70 |
| 9150-6217 | \$10,120.86 | NuPoint Fax Card - Shared Resource 8 Port - Model 70 |
| 9150-6222 | \$2,530.00 | NuPoint Fax Card - Shared Resource 2 Port - Model 70 |
| 9150-6232T | \$6,232.71 | Dual T1 Card - Model 70 |
| 9150-6283 | \$505.65 | NOTE(S): Digital Telephony Card only. Requires DSP24 Line Card to complete set. 2 Port Serial Interface Card - Model 70 |
| 9150-6284 | \$910.87 | NOTE(S): Includes: Card and Cabledigiboard manufactured card. 4 Port Serial Interface Card - Model 70 |
| 9150-6285 | \$1,007.88 | NOTE(S): Includes: Card and Cabledigiboard manufactured card. 8 Port Serial Interface Card - Model 70 |
| 9150-5607 | \$3,289.77 | NOTE(S): Includes: Card and Cabledigiboard manufactured card. Voicebridge Box for AT&T Integration - Model 70 |
| 9150-5608TX | \$2,176.30 | NOTE(S): Requires Centrex 1AESS Integration Software. 8 Port DSE Line Card Expansion - Model 70 - Lucent |
| 9150-5609TX | \$2,176.30 | NOTE(S): Use for Lucent In-Channel Integration. 8 Port DSE Line Card Expansion - Model 70 - Mitel |
| 9150-6249TX 9150-6229TX | · | NOTE(S): Use for Mitel DNIC Integration. DSP8 Line Card Expansion - Model 70 DSP24 Line Card Expansion - Model 70 |
| 9150-6247TX | | NOTE(S): To add ports to a system. Shipped in an expansion module. DSP Card only. Requires a Dual T1 to complete the set. Addition of this card to an existing Dual T1 24 Port Line Card Set will add 24 additional ports to total 48. Dual T1 8 Port/DSP8 Set Expansion - Model 70 |
| 9150-6268TX | \$5,060.86 | Dual T1 16 Port/DSP8 Set Expansion Model 70 |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--------------------------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) HARDWARE (Continued) |
| 9150-6208TX | \$9,109.54 | Dual T1 24 Port Line Card Set Expansion Model 70 |
| 9150-6223LX | \$1,316.08 | NOTE(S): To add ports to a system. Shipped in an expansion module. 4 Port Loop Start Line Card Expansion - Model 70 |
| 9150-6205LX | \$2,528.28 | NOTE(S): To add ports to a system. Shipped in an expansion module. 8 Port Loop Start Line Card Expansion - Model 70 |
| 9150-6223EX | \$1,568.48 | NOTE(S): To add ports to a system. Shipped in an expansion module. 4 Port E&M Line Card Expansion - Model 70 |
| 9150-6205DX | \$2,809.01 | NOTE(S): To add ports to a system. Shipped in an expansion module. 8 Port DID Line Card Expansion - Model 70 |
| 9150-6205EX | \$2,809.01 | NOTE(S): To add ports to a system. Shipped in an expansion module. 8 Port E&M Line Card Expansion - Model 70 |
| 9150-6272-01 9150-6258 | \$505.66 | NOTE(S): To add ports to a system. Shipped in an expansion module. Ethernet 16 Card 1 - Model 70 Serial 16 Kit Expansion - Model 70 |
| 9150-6226DU | \$1.265.42 | NOTE(S): Used for adding a kit to an existing system. Provides additional 16 port increments for RS-232 Integrations. 4 to 8 Port Line Card Upgrade - DID/E&M - Model 70 |
| 9150-6226LU 9150-6012-70-B1 | \$1,265.43 | 4 to 8 Port Line Card Opgrade - DID/EdiM - Model 70 4 to 8 Port Line Card Upgrade - LS - Model 70 Zip Drive 100 MB - Model 70 |
| 9150-6242 | \$101.30 | NOTE(S): Includes: Zip Drive/ Software/ 2 Zip Cartridges/ Parallel Cable/ Power Supply. For all Model 70 System Sales, this part must be ordered direct from Mitel. Telephony Octopus Cables 6-Conn RJ61 - Model 70 |
| 9150-6243 | \$84.13 | NOTE(S): Use on E&M/ DID/ Loop Start/ (12 Port). Telephony Octopus Cables 12-Conn RJ61 - Model 70 |
| | | NOTE(S): Use on DID/ Loop Start/ (24 Port). |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--|---------------------|---|
| | | NEW = New Part Number IMC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) HARDWARE (Continued) |
| 9150-6244 | \$253.26 | Adaptor - 1 RJ61 to 2 RJ11 - Model 70 |
| 9150-6245 | \$98.73 | NOTE(S): Includes 8 adaptors. Universal RJ61 to RJ61 Cable Kit - Model 70 |
| | · | NOTE(S): Includes 4 each of 1 ft/ 2 ft/ 14 ft cables. |
| 6107-70-B1 | \$897.99 | Drive Kit, Insystem Model 70 |
| | | NOTE(S): For NEW SYSTEMS ONLY. In the US order from Wholesale Distribution (except for MCS US). To add redundancy. This drive is shipped in conjunction with a new system order. Needs 6477-70-B1 software. |
| | NUPOINT MESSEN | IGER (70) HARDWARE SPARES |
| 4431-70 | \$106.45 | Mital NuPaint Massanger 70: Spara Dawer Supply |
| 9150-4363-70S | | Mitel NuPoint Messenger 70: Spare Power Supply Spare - System Modem - Model 70 |
| 9150-5147 | | Spare - Memory Expansion Kit (116 Meg SIMM) - Model 70 |
| 9150-5828 | \$463.59 | Spare - 16 Cable Kit - Model 70 |
| 9150-5829 | | Spare - Serial 16 16 Port Spare Module - Model 70 |
| 9150-5830 | | Spare - Serial 16 Spare 1 1/2" Cable - Model 70 |
| 9150-6013 | | Spare - Zip Drive Cartridge 100Mb - Model 70 |
| 9150-6014 9150-6143 | | Spare - Zip Drive 100MB - Model 70 Spare - 48V Telephony Configuration Card - Model 70 |
| | , | NOTE(S): |
| 9150-6146 | \$388.04 | Includes cables. Spare - 48V External Telephony Power Supply - Model 70 |
| 9150-6147-64 | \$3,235.69 | Spare - Model 70 Chassis (64 Mb Memory) |
| 9150-6282 9150-6290 9150-6800-70 9150-6977-B1-S | \$60.95 \$141.65 | NOTE(S): Includes: Power Supply/ Motherboard/ Chassis/ Floppy Drive. Spare - Serial 16 Kit Model 70 Spare - 4 Port Serial Interface Card Cable - Model 70 Spare - MVIP Cable Kit - Model 70 Spare - Switch Box - Model 70 |
| | | NOTE(S): Must be included with Zip Drives for Release 7.0. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (70) UPGRADES |
| 9150-6901-210B1 | \$3,599.40 | 210 Hour Diskette Upgrade - New Systems Model 70 |
| 9150-070-001NAU | \$1,291.54 | NOTE(S): Order with new system purchase. Expands 90 Hours to 210 Hours. Cannot be used with Mitel Power Packages. NuPoint Messenger RIs 6.1B to 7.0 SW Upgrade Model 70 |
| | | NOTE(S): Includes: Rls 7.0 software & Smart Install hardware. |
| | NUPOINT MESSEN | IGER (70) BUNDLED APPLICATIONS |
| 50000268 50000269 | | Enhanced Desktop Messaging w/out Fax, Model 70 Enhanced Desktop Messaging With 2 Port Fax, Model 70 |
| 6530-70-B1 | \$1,126.22 | NuPoint Messenger Enhanced Messaging Model 70 |
| 6531-70-B1 | \$2,059.54 | INCLUDE(S): 9150-431-704-NA NP Agent 6975-70-B1 NP Forms 6946-70-B1 NP Cut Thourgh Page ENHANCED RELIABILITY PKG, MODEL 70 |
| | | NOTE(S): Includes: 6477-70-B1 Redundancy Software 6107-70-B1 Redundant Hard Drive 6012-70-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. |
| | NUPOINT MESSEN | IGER (120R) BASE SOFTWARE |
| 9150-120-001-NA | \$885.76 | Mitel NuPoint Messenger 120R Base SW: Branding Kit-ENG NOTE(S): Includes: 120 hours/ NP Receptionist/ NuPoint Fax/ NP FPSA/ NP Admin/ English Prompts Full Set. Base Software and Smart Install must be purchased for each Base Model ordered. |
| | | |



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Req Change

NUPOINT MESSENGER (120R) BASE SOFTWARE (Continued)

9150-431-700-NA \$0.00 Mitel NuPoint Messenger Softkeys

NOTE(S):

Must also order 9109-532-011-NA to enable SX-200 softkey option (no charge) or MSA-A-53 to enable SX-2000 softkey

option (no charge).

For Models 120R/120S/640, for all System Sales, this part must be ordered directly from Mitel.

In the U.S. Channels only: For Model 70 New System Sales this part

must be

ordered from Wholesale Distribution.

NUPOINT MESSENGER(120R) SW INTEGRATION KITS

9150-420-154-NA \$153.67 PTI Telcom Link Kit

NOTE(S):

You must also order a 2-port Serial Card (MVIP)

6286 from wholesale distribution.

Provides connectivity with Protocol Technologies Telcom Link

NUPOINT MESSENGER (120R) HARDWARE

6107-120R-B1 \$3,289.40 Drive Kit In-System Model 120R

NOTE(S):

To add redundancy. This drive is shipped in conjunction with a new system order. Needs 6477-120R-B1 software.

NUPOINT MESSENGER (120R) UPGRADES

9150-120R001NAU \$1,291.54 NuPoint Messenger Rls 6.1B to 7.0 SW Upgrade

Model 120R

NOTE(S):

Includes: Rls 7.0 software & Smart Install hardware.

NUPOINT MESSENGER (120R) BUNDLED APPLICATIONS



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| PARTNUMBER | NETFRICE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (120R) BUNDLED APPLICATIONS (Continued) |
| 6530-120R-B1 | \$2,253.38 | NuPoint Messenger Enhanced Messaging Model 120R |
| 6531-120R-B1 | \$3,197.91 | INCLUDE(S): 6448-120R-B1 NP Agent 6975-120R-B1 NP Forms 6946-120R-B1 Cut Through Page NuPoint Messenger Enhanced Reliability Pkg, Model 120R |
| 6534-B1 | \$3,648.62 | INCLUDE(S): 6477-120R-B1 Redundancy Software 6107-120R-B1 Redundant Hard Drive 6012-120R-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. Enhanced Desktop Msg With 2PT Fax Card - Model 120/640 |
| 6535-B1 | \$1,416.52 | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG StarterKit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack 6221 2 Port Shared Resource Fax Card Enhanced Desktop Msg W/O Fax - Model 120/640 |
| | | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG Starter Kit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack |
| | NUPOINT MESSEN | IGER (120S) BASE SOFTWARE |
| 9150-120-002-NA | \$2,768.12 | Mitel NuPoint Messenger 120S Base SW: Branding Kit-ENG |
| 9150-431-700-NA | \$0.00 | INCLUDE(S): 120 hours/ NP FPSA/ NP Admin/ English Prompts Full Set. Mitel NuPoint Messenger Softkeys |
| | | NOTE(S): Must also order 9109-532-011-NA to enable SX-200 softkey option (no charge) or MSA-A-53 to enable SX-2000 softkey option (no charge). For Models 120R/120S/640, for all System Sales, this part must be ordered directly from Mitel. In the U.S. Channels only: For Model 70 New System Sales this part must be ordered from Wholesale Distribution. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|---------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (120S) SW INTEGRATION KITS |
| 9150-420-154-NA | \$153.67 | PTI Telcom Link Kit |
| | | NOTE(S): You must also order a 2-port Serial Card (MVIP) 6286 from wholesale distribution. |
| | | Provides connectivity with Protocol Technologies Telcom Link |
| | NUPOINT MESSEN | IGER (120S) HARDWARE |
| 6107-120S-B1 | \$5,904.23 | Redundant Drive Kit New-System Model 120S |
| | | NOTE(S): To add redundancy. This drive is shipped in conjunction with a new system order. Needs 6477-120S-B1 software. |
| | NUPOINT MESSEN | IGER (120S) UPGRADES |
| | | |
| 9150-120S002NAU | \$2,306.92 | NuPoint Messenger RIs 6.1B to 7.0 SW Upgrade Model 120S |
| | | NOTE(S): Includes: Rls 7.0 software & Smart Install hardware. |
| | NUPOINT MESSEN | IGER (120S) BUNDLED APPLICATIONS |
| 6530-120S-B1 | \$4,208.06 | NuPoint Messenger Enhanced Messaging Model 120S |
| | ţ 1, 2 00100 | INCLUDE(S): |
| 0504 4000 54 | \$5.004.40 | 6448-120S-B1 NuPoint Agent / 6975-120S-B1 NP Forms 6946-120S-B1 NP Cut Through Page. |
| 6531-120S-B1 | \$6,224.12 | NuPoint Messenger Enhanced Reliability Pkg, Model 120S |
| 6534-B1 | \$3,648.62 | INCLUDE(S): 6477-120S-B1 Redundancy Software 6107-120S-B1 Redundant Hard Drive 6012-120S-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. Enhanced Desktop Msg With 2PT Fax Card - Model |
| | | 120/640 |
| | | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG StarterKit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack 6221 2 Port Shared Resource Fax Card |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | NUPOINT MESSEN | IGER (120S) BUNDLED APPLICATIONS (Continued) |
| 6535-B1 | \$1,416.52 | Enhanced Desktop Msg W/O Fax - Model 120/640 |
| | | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG Starter Kit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack |
| | NUPOINT MESSEN | NGER (640) BASE SOFTWARE |
| 9150-431-700-NA | \$0.00 | Mitel NuPoint Messenger Softkeys |
| | | NOTE(S): Must also order 9109-532-011-NA to enable SX-200 softkey option (no charge) or MSA-A-53 to enable SX-2000 softkey option (no charge). For Models 120R/120S/640, for all System Sales, this part must be ordered directly from Mitel. In the U.S. Channels only: For Model 70 New System Sales this part must be ordered from Wholesale Distribution. |
| 9150-640-001-NA | \$4,429.74 | Mitel NuPoint Messenger 640 Base SW: Branding Kit (ENG) |
| | | INCLUDE(S): 120 hours/ NP FPSA/ NP Admin/ English Prompts Full Set. |
| | NUPOINT MESSEN | IGER (640) SW INTEGRATION KITS |
| 9150-420-154-NA | \$153.67 | PTI Telcom Link Kit |
| | | NOTE(S): You must also order a 2-port Serial Card (MVIP) 6286 from wholesale distribution. |
| | | Provides connectivity with Protocol Technologies Telcom Link |
| | NUPOINT MESSEN | NGER (640) HARDWARE |
| 6107-640-B1 | \$5,904.23 | Redundant Drive Kit New-System Model 640 |
| | | NOTE(S): To add redundancy. This drive is shipped in conjunction with a new system order. Needs 6477-640-B1 software. |
| | NUPOINT MESSEN | IGER (640) UPGRADES |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| N | UPOINT MESSEN | IGER (640) UPGRADES (Continued) |
| 9150-640-001NAU | \$3,229.31 | NuPoint Messenger RIs 6.1B to 7.0 SW Upgrade Model 640 |
| | | INCLUDE(S): Rls 7.0 software & Smart Install hardware. |
| N | UPOINT MESSEN | IGER (640) BUNDLED APPLICATIONS |
| 6530-640-B1 | \$4,771.64 | NuPoint Messenger Enhanced Messaging Model 640 |
| 6531-640-B1 | \$7,104.09 | INCLUDE(S): 6448-640-B1 NuPoint Agent / 6975-640-B1 NP Forms 6946-640-B1 NP Cut Through Page. NuPoint Messenger Enhanced Reliability Pkg Model 640 |
| 6534-B1 | \$3,648.62 | INCLUDE(S): 6477-640-B1 Redundancy Software 6107-640-B1 Redundant Hard Drive 6012-640-B1 Zip Drive Kit 6976-B1 Smart Install Switch Box. Enhanced Desktop Msg With 2PT Fax Card - Model 120/640 |
| 6535-B1 | \$1,416.52 | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG StarterKit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack 6221 2 Port Shared Resource Fax Card Enhanced Desktop Msg W/O Fax - Model 120/640 |
| | | INCLUDE(S): 6445-25-XXX-B1 NP View Desktop MSG Starter Kit 6262-01 Ethernet Card 6490-XXX-B1 TCP/IP Stack |
| M | IITEL MAIL 6.1B | |
| 9109-518-998-NA | \$0.00 | SX-200 LIGHT LW 15/16 Mitel Mail DNIC Integration SW Option |
| | | Includes: 9109-034-500-NA Lightware 15 Software Diskettes (Qty 2) NOTE(S): This option is only available for SX-200 LIGHT systems with LIGHTWARE 15 or LIGHTWARE 16 Serial number from Mitel Mail system must be provided with purchase order for this option. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|---------------|-----------|--------------|
| I AK I NOMBEK | METTRICE | DECOKII IIOI |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

MITEL MAIL 6.1B (Continued)

| 9150-430-101-NA | \$510.81 | MM 6.1 ENGLISH Hotel Prompts |
|------------------------------------|------------|--|
| | | NOTE(S): |
| | | These prompts are no charge when ordered |
| 9150-430-130-NA | ¢057.61 | with a Mitel Mail system. MM Power Prompts Server |
| 9150-430-150-NA 9150-430-450-NA | | MM 6.1 NUMERIC Prompts |
| 9150-430-451-NA | | MM 6.1 NUMERIC OVERLAY Prompts |
| 9150-430-131-NA | | MM Powerpoints GUI Client for Windows |
| 9150-430-150-NA | | MM 6.1 PMS: STD ENCORE |
| 9150-430-151-NA | · · | MM 6.1 PMS: EECO |
| 9150-430-152-NA | | MM 6.1 PMS: LOGISTIX |
| 9150-430-153-NA | · · | MM 6.1 PMS: HIS |
| 9150-430-300-NA | · | MM 6.1 AMIS |
| 9150-430-301-NA | | MM 6.1 Mesa-Net Async |
| 9150-430-303-NA | | MM 6.1 Cut Through Paging |
| 9150-430-304-NA | | MM 6.1 Mesaform |
| 9150-430-305-NA | • | MM 6.1 Mesa-Net (TCP/IP) |
| 9150-430-309-NA | | MM 6.1 Mesa-Net TCP/IP 2-4 Upgrade |
| 9150-430-310-NA | \$849.06 | MM 6.1 Mesa-Net TCP/IP 4-6 Upgrade |
| 9150-430-311-NA | | MM 6.1 Mesa-Net TCP/IP 6-8 Upgrade |
| 9150-430-734-NA | \$428.39 | MM One Net Config Client Software |
| 9150-430-736-NA | \$2,145.39 | MM One Net SNMP Server Software |
| 9150-430-401-NA | \$857.64 | MM 6.1 Call Agent - English |
| 9150-430-406-NA | \$257.55 | MM 6.1 Enhanced Inband Signalling |
| 9150-430-503-NA | \$287.59 | MM 6.1 SMDI |
| 9150-430-504-NA | | MM 6.1 Meridian Integration |
| 9150-430-507-NA | | MM 6.1 Call Detail Recording |
| 9150-430-509-NA | | MM 6.1 Toll Saver |
| 9150-430-510-NA | | MM 6.1 Enhanced SMDI |
| 9150-430-511-NA | · · | MM 6.1 TCP/IP |
| 9150-430-601-NA | \$1,458.59 | MM 6.1 One View Kit for 25 Clients |
| | | INCLUDE(S): |
| | | OneView Software (Qty 1) |
| | | OneView Network Sessions (Qty 6) OneView Client Licenses (Qty 25) |
| | | OneView User Guides (Qty 25) |
| | | OneView Client Server (Qty 1) |
| | | Fax & Voice Memo Messaging Support Software (Qty 1) Pre-requisite(s) required: |
| | | Ethernet Card |
| | | TCP/IP Software |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|-------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease |
| | | сно = Part Description/Note/BOM/Pre-Req Change |
| | MITEL MAIL 6.1B (| Continued) |
| | | |
| 9150-430-602-NA | \$2,918.04 | MM 6.1 One View Kit for 100 Clients |
| | | INCLUDE(S): OneView Software (Qty 1) |
| | | OneView Network Sessions (Qty 6) |
| | | OneView Client Licenses (Qty 100) OneView User Guides (Qty 25) |
| | | One View Client Server (Qty 1) |
| | | Fax & Voice Memo Messaging Support Software (Qty 1) Pre-requisite(s) required: |
| | | Ethernet Card TCP/IP Software |
| 9150-430-603-NA | \$1.154.68 | MM 6.1 One View 25 Clients |
| 9150-430-604-NA | · | MM 6.1 One View 100 Clients |
| 9150-430-720-NA | \$279.01 | MM Enhanced Auto Wake-up |
| 9150-430-750-NA | | MM Upgrade 6.0X to 6.1 |
| 9150-430-751-NA | · · | MM Crare Drive Co. Hours |
| 9150-430-752-NA 9150-6291 | | MM Spare Drive - 90 Hours MM Spare - 8 Port Serial Interface Card Cable - Model |
| 9130-0291 | \$109.03 | 70 |
| 9150-702-154-NA | \$158.82 | MM Memory Expansion - 16 Meg Simm |
| | MITEL MAIL 6.1B | HARDWARE |
| 0450 420 754 NA | \$200.62 | MM Drive Conversion Kit |
| 9150-430-751-NA 9150-430-752-NA | | MM Spare Drive - 90 Hours |
| 9150-702-071-NA | | MM 6.0x Redundancy Kit |
| | | INCLUDE(S): |
| | | Redundancy Software (Qty 1) |
| 9150-702-101-NA | \$2,360.87 | Redundant Hard Drive (M155) (Qty 1) MM 4 Port LS Line Card (MVIP) |
| 9150-702-102-NA | | MM 8 Port LS Line Card (MVIP) |
| 9150-702-112-NA | | MM 2 Port Fax Card (MVIP) |
| 9150-702-113-NA | | MM 4 Port Fax Card (MVIP) |
| 9150-702-114-NA | | MM 8 Port Fax Card (MVIP) |
| 9150-702-118-NA 9150-702-119-NA | | MM 2 Port CTI (MVIP) Card 4 Port CTI (MVIP) Card |
| 9150-702-119-NA 9150-702-120-NA | | 8 Port CTI (MVIP) Card |
| 9150-702-121-NA | | Ethernet NIC Card |
| | | NOTE(S): |
| | | Required for optional MESA-Net (TCP/IP) & One View Software. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|-------------------|--|
| | | NEW = New Part Number |
| | | mc = Price Increase pec = Price Decrease |
| | | оно = Part Description/Note/BOM/Pre-Req Change |
| | MITTI MAIL CADI | · · · · · · · · · · · · · · · · · · · |
| | WITEL WAIL 6.16 F | HARDWARE (Continued) |
| 9150-702-131-NA | \$2,760.08 | 4 to 8 Port Line Card Upg/LS |
| 9150-702-132-NA | | 4 to 8 Port Line Card Upg/E&M |
| 9150-702-135-NA | | 6.1B 8 Port DSE Line Card - DNIC |
| 9150-702-136-NA | \$3,476.07 | 6.1B 8 Port DSP Line CARD - DNIC |
| 9150-702-137-NA | \$8,841.69 | 24 Port DSP DNIC Card |
| 9150-702-144-NA | \$3,923.34 | MM Chassis |
| 9150-702-145-NA | | Power/Configuration Card |
| 9150-702-146-NA | \$532.27 | Tel. VDC Power Supply |
| 9150-702-147-NA | \$364.86 | MM2 Power/Config Card & Power Supply Kit |
| | | INCLUDE(S): 9150-702-145-NA Power/Config Card (Qty 1) |
| | | Power Supply (Qty 1) |
| 9150-702-152-NA | | RJ61 to RJ11 Adapter Cable |
| 9150-702-154-NA | \$158.82 | MM Memory Expansion - 16 Meg Simm |
| | MITEL ONEPOINT | MESSENGER SYSTEM HARDWARE |
| 9164-001-001-NA | \$975.26 | 8 Port Voice Card (NMS AG-0) |
| 9164-120-008-NA | | 8 Port Voice Card (NMS AG8) |
| 9164-120-010-NA | | TS800 Server Package |
| 9164-500-009-NA | | OPM T1 Line - ISA |
| 3104-300-003-1 1 /A | | |
| | MITEL ONEPOINT | MESSENGER INTEGRATION |
| 9164-120-100-NA | \$118.35 | SX-2000 Integration Software |
| 9164-120-101-NA | \$1,030.20 | SX-2000 Integration Hardware |
| 9164-120-200-NA | \$118.35 | SX-200 Integration Software |
| 9164-120-201-NA | \$686.80 | SX-200 Integration Hardware |
| 9164-120-500-NA | \$889.52 | Centrex SMDI Integration Software |
| | MITEL ONEPOINT | MESSENGER SYSTEM SOFTWARE |
| 9164-002-020-NA | \$522.52 | 2 Port Fax Software |
| 9164-002-020-NA 9164-002-021-NA | | 4 Port Fax Software |
| 9164-002-021-NA 9164-002-022-NA | · · | 8 Port Fax Software |
| 9164-002-022-NA 9164-003-002-NA | | Client Software License - 25 Users |
| 9164-003-002-NA 9164-003-003-NA | | Client Software License - 25 Users Client Software License - 50 Users |
| 9104-003-003-NA | \$1,708.39 | Cheff Software License - 50 Users |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | MITEL ONEPOINT | MESSENGER SYSTEM SOFTWARE (Continued) |
| | | |
| 9164-003-004-NA | ' ' | Client Software License - 100 Users |
| 9164-003-005-NA | \$4,288.84 | Client Software License - 200 Users |
| 9164-003-006-NA | \$7,260.79 | Client Software License - 400 Users |
| 9164-003-007-NA | | Client Software License - 500 Users |
| 9164-003-008-NA | \$11,523.33 | Client Software License - 750 Users |
| 9164-003-009-NA | | Client Software License - 1000 Users |
| 9164-005-001-NA | \$771.17 | Web Browser Access Site Licence |
| 9164-120-001-NA | \$1,483.15 | Baypoint OPM 2.0 SERVER S/W & BRANDING KI |
| 9164-120-009-NA | \$1,483.15 | NOTE(S): Baypoint OPM 2.0 server software plus branding kit Includes: Getting Started Guide (9164-120-114-NA) - Qty 1 Quick Reference Cards (9164-953-014-NA) - Qty 25 Documentation Set - Mitel (9164-120-101-NA) - Qty 1 Software - OPM 2.0 CD - Baypoint Branding Branding Items - Front panel sticker etc. (Baypoint) PC Anywhere software - (9164-120-050-NA) North American English Prompts MS Windows NT Server O/S Mitel OPM 2.0 SERVER S/W & BRANDING KIT |
| | | NOTE(S): Mitel OPM 2.0 server software plus branding kit Includes: Getting Started Guide (9164-120-114-NA) - Qty 1 Quick Reference Cards (9164-953-014-NA) - Qty 25 Documentation Set - Mitel (9164-120-101-NA) - Qty 1 Software - OPM 2.0 CD - Mitel Branding Branding Items - Front panel sticker etc. (Mitel) PC Anywhere software - (9164-120-050-NA) North American English Prompts MS Windows NT Server O/S |
| 9164-120-440-NA | \$593.64 | Text to Speech Software License |
| 9164-120-708-NA | | 8 Port Voicemail Software |
| 9164-120-709-NA | • | 4 Port Software Upgrade |
| 9164-120-712-NA | | 12 Port Voicemail Software |
| 9164-120-716-NA | • • | 16 Port Voicemail Software |
| 9164-120-720-NA | \$1,186.34 | 4 Port Software Upgrade (for upgrades above 16 Ports) |
| 9169-200-005-NA | \$1,483.15 | VPIM Software Option |
| 9169-403-010-NA | \$20,132.96 | Client Software License - 1250 Users |
| 9169-403-011-NA | \$22,484.96 | Client Software License - 1500 Users |
| | 025 - 55 - 22 | 0" (0 % 1" 4750 11 |

9169-403-012-NA

\$25,657.92 Client Software License - 1750 Users



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | MITEL ONEPOINT | MESSENGER SYSTEM SOFTWARE (Continued) |
| 9169-403-013-NA | \$28,270.11 | Client Software License - 2000 Users |
| | PROGRAM: NUPC | DINT MESSENGER PRICE PROMOTION |
| | | |
| 50000180 | \$2,116.20 | NPM 90HR Upgrade from 6.0 to 7.0 System - Model 70 |
| 50000181 | \$5,104.90 | NPM 210HR Upgrade from 6.0 to 7.0 System - Model |
| 6503-IDE-B1 | \$1,265.15 | 70 Upgrade Kit 5.0X AIP70 or AIP120 System to NPM 7.0 System |
| 6503-SCSI-B1 | \$1,265.15 | NOTE(S): This upgrade kit is used to convert speech and data directly from an AIP70 or an AIP120 System to a NPM 7.0 System (new 7.0 Systems must be ordered separately). This product is fully refundable upon return ot Mitel. Upgrade Kit from 5.0X VM100 or VMII System to NPM 7.0 System |
| 6510-SCSI-B1 | \$1,265.07 | NOTE(S): This upgrade kit is used ot convert speech and data directly from a VM100 or a VMII System to a NPM Release 7.0 System (new 7.0 Systems must be ordered separately). This product is fully refundable upon return to Mitel. Upgrade Kit from 5.0X Rack System to a NPM 7.0 System |
| | | NOTE(S): This upgrade kit is used to convert speech and data from a Rack System to a NPM 7.0 System (new 7.0 System must be ordered separately). This product is fully refundable upon return to Mitel. |





| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-------------------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | Services please refer t | pertaining to Professional |
| | XPRESSOFFICE B | UNDLES |
| 9168-500-003-NA | \$1,167.55 | XO5232I w/ Single POTS, NTL EXT. REM NA ISDN U i/f |
| 9168-500-004-NA | \$711.99 | XpressOffice 5232i with remote Nortel PBX Ext and Single Voice Port. Has U interface for use outside of North America with NA ISDN. Business Pack. No Encryption. XO5232I with business pack and Dual POTS - NA ISDN U i/f |
| 9168-500-005-NA | \$1,069.86 | XpressOffice 5232i with Business Pack and Dual Voice Port. Has U interface for use outside of North America. Business Pack. No Encryption. XO5232I w/ NTL EXT. REM NA ISDN U i/f |
| 9168-500-006-NA | \$1,069.86 | XpressOffice 5232i with remote Nortel PBX Ext. Has U interface for use outside of North America. Business Pack. No Encryption. XO5232I w/, NTL EXT. Central - NA ISDN U i/f |
| 9180-300-001-NA | \$1,127.16 | XpressOffice 5232i with central Nortel PBX Ext. Has U interface for use outside of North America. Business Pack. No Encryption. XpressOffice Teleworker DNIC Unit |
| 9180-300-002-NA | \$1,221.09 | NOTE(S): Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Provides up to 8:1 data compression Supports multiple LAN devices with optional Hub Pack 9180-300-008-NA Delivers remote extension from Mitel's SX-200 or SX-200 PBX Provides full access to head office PBX and Data networks XpressOffice Teleworker DNIC/POTs Unit |
| | | NOTE(S): Includes a Single POTS port for analog phone or fax. Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Provides up to 8:1 data compression Supports multiple LAN devices with optional Hub Pack 9180-300-008-NA Delivers remote extension from Mitel's SX-200 or SX-200 PBX Provides full access to head office PBX and Data networks |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSOFFICE B | UNDLES (Continued) |
| 9180-300-003-NA | \$1,221.09 | XpressOffice Teleworker DNIC/Hub Unit |
| 9180-300-004-NA | \$2,207.35 | NOTE(S): Includes a 4 port 10BaseT Ethernet hub for connecting LAN Devices. Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Provides up to 8:1 data compression Delivers remote extension from Mitel's SX-200 or SX-200 PBX Provides full access to head office PBX and Data networks XpressOffice Teleworker DNIC/DNIC Package |
| 9180-300-005-NA | | NOTE(S): Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Package includes: XpressOffice Teleworker DNIC Units (Qty.2) XpressOffice Teleworker DNIC Package with POTS Option |
| 9180-300-006-NA | \$2,348.25 | NOTE(S): Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Package includes: XpressOffice Teleworker DNIC Unit (Qty.1) XpressOffice Teleworker DNIC/POTs Unit (Qty.1) XpressOffice Teleworker Call Center Agent Package |
| 9180-300-012-NA | \$13,807.71 | NOTE(S): Minimum System Software required is LIGHTWARE 29 Release 2 or LIGHTWARE 17 Release 2. Package includes: XpressOffice Teleworker DNIC Units (Qty.2) Superset 4025 Dark Grey (Qty.1) Xpressway RLAN/XpressOffice 5232i 6 USER Bundle |
| MKT10880Z1 | \$711.99 | NOTE(S): Includes Xpressway 11 slot chassis/ RSC9002 system controller/ Dual PRI 9346 module/ Voice Resouce Module/ Voice Interface Module with 6 DNIC extenders AND 6 XpressOffice 5232i`s with DNIC extenders and Single POTS port. Central site operates over ISDN PRI and remotes work on BRI Due to size order ships in 2 boxes. X.Connect 5232i Edge Router, Bus. Pack and 2 POTS |
| | | NOTE(S): Includes XpressOffice 5232i,Business Pack,dual POTS interface. Supports up to 70 devices on the LAN. Routes IP. Supports PPP and ML/PPP. PAP/CHAP CLID Security. Connects to ISDN BRI "U" interface. Comes with ISDN and Ethernet cables, manuals and software. |



| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------------------|----------------|--|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change | |
| | XPRESSOFFICE B | UNDLES (Continued) | |
| MKT10880Z3 | \$1,069.86 | XpressOffice 5232i BP and Ntl PBX Ext - Remote | |
| MKT10880Z4 | \$1,167.55 | NOTE(S): XpressOffice 5232i with Business Pack and PBX Extension for Nortel Meridian. Connects up to ISDN BRI U and 10baseT. Comes with ISDN & Ethernet cables/ software and manuals. XpressOffice 5232i w/BP, Ntl. PBX ext. and SVP | |
| MKT10880Z12 | \$1,069.86 | NOTE(S): Includes: XpressOffice 5232i, with Business Pack, and Meridian PBX extender pack - Central Site as well as Single POTS port. Comes with all s/w, power supply, LAN cable, ISDN cable and manuals. XO5232I w/ NTL EXT. REM EURO ISDN S/T i/f | |
| MKT10880Z14 | \$711.99 | NOTE(S): XpressOffice 5232i with remote Nortel PBX Extender. Has ST interface with Euro ISDN. No Encryption. Business Pack. XO5232I w/ DUAL POTS, BP - EURO ISDN S/T i/f | |
| MKT10880Z22 | \$1,069.86 | NOTE(S): XpressOffice 5232i with Business Pack and Dual Voice Port. Has S/T interface with support for Euro ISDN. Business Pack. No Encryption. X.Connect 5232i Edge Router, Bus. Pack, PBX Ext-Central Site | |
| MKT10880Z24 | \$1,069.86 | NOTE(S): Includes: XpressOffice 5232i, with Business Pack, and Meridian PBX extender pack - Central Site. Comes with all software, power supply, LAN cable, ISDN cable and manuals. XO5232I W/ NTL EXT. CENTRAL - EURO ISDN S/T i/f 40B | |
| | | NOTE(S): XpressOffice 5232i with central Nortel PBX Ext - Euro S/T. Has S/T interface with euro ISDN. 40 bit Encryption. Business Pack. | |
| XPRESSOFFICE COMPONENTS | | | |

XPRESSOFFICE COMPONENTS



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSOFFICE C | OMPONENTS (Continued) |
| 10439Z1 | \$452.74 | XpressConnect 5232i - Base ER U-Intf UTP |
| 10439Z6 | \$452.74 | NOTE(S): Supports up to four devices on Ethernet LAN. Features IP static routing bandwidth-on-demand and STAC 4:1 data compression. Supports BCP, IPCP, Multi-link PPP, BACP, PAP, CHAP and CCP. North American ISDN and U interface. XpressConnect 5232i - Base ER S-Intf UTP |
| 10440A1 | | NOTE(S): Supports up to 4 devices on an Ethernet LAN. Features IP static routing, bandwidth-on-demand and STAC 4:1 data compression. Supports BCP, IPCP, Multi-link PPP, BACP, PAP, CHAP and CCP. North American ISND with an S/T interface XpressConnect 5232i - Voice Pack 2 Port |
| 10441Z1 | \$192.56 | NOTE(S): A card which comes with 2 analog POTS ports for connection of multiple analog devices such as telephones, fax machines, answering machines and stand-alone modems. Voice Features include: Distinctive Ringing Three-Way Calling Call Forwarding Call Waiting Message Display Calling Line Identification (CLID) XpressConnect 5232i - Business Pack |
| | | NOTE(S): Increases support up to 70 devices on an LAN Features IP static routing, bandwidth-on-demand, STAC 4:1 data compression/ Mitel 8:1 data compression, IPX spoofing, SNMP management, Telnet, and Mitel 256 bit Encryption. Supports PPP (including PAP and CHAP), Multi-link PPP, BACP AND MP+. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSOFFICE C | OMPONENTS (Continued) |
| 10773R1 | \$517.55 | XpressConnect 5232i Meridian PBX Extender - Remote |
| 10774R1 | \$517.55 | NOTE(S): For use when connected to a Nortel Meridian PBX Digital PHONE Set. Unit resides in the XpressOffice 5232i. The XpressConnect 5232i PBX Extender pack is an off premise link extender which allows a PBX line to be extended to a remote location via ISDN. With XpressConnect 5232i PBX extender technology, access to corporate LAN and the corporate PBX facilities can be delivered through the same device! XpressOffice 5232i Meridian PBX Extender - Central |
| 10885Z1 | \$517.55 | NOTE(S): For use at the central site when connected to a PBX and using a remote PBX extended 5232i. The XpressConnect 5232i PBX Extender pack, is an off premise link extender which allows a PBX line to be extended to a remote location via ISDN. With XpressConnect 5232i PBX extender technology, access to corporate LAN and the corporate PBX facilities can be delivered through the same device! Resides on VIM9606 module (10771Z3) DNIC EXTENDER UPGRADE KIT |
| 9168-500-020-NA | \$100.00 | NOTE(S): DNIC extender card for use at the central or remote site. Can be used in conjunction with both the SX-200 and SX-2000. To be installed in either an XpressOffice 5232i or on a Xpressway Voice Interface Module 9612. XO5232I S/W UPGRADE 3.1 - NO ENC |
| 9168-500-021-NA | \$100.00 | NOTE(S): Upgrades XpressOffice 5232i to the latest release of software/ version 3.1. See bulletin for details on features. No encryption. XO5232I S/W UPGRADE 3.1 - 256 ENC |
| 9168-500-022-NA | \$100.00 | NOTE(S): Upgrades XpressOffice 5232i to the latest release of software/ version 3.1. See bulletin for details on features. 256 bit encryption. XO5232I S/W UPGRADE 3.1 - 40 ENC NOTE(S): Upgrades XpressOffice 5232i to the latest release |
| | | of software/ version 3.1. See bulletin for details on features. 40 bit encryption. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSOFFICE C | OMPONENTS (Continued) |
| 9180-300-007-NA | \$140.89 | XpressOffice Teleworker POTS Upgrade Module |
| 9180-300-008-NA | \$93.93 | NOTE(S): Module used to upgrade XpressOffice Teleworker DNIC Units to allow analog capability for Remote FAX or Modem use. NOTE: POTs upgrade cannot be used when the 4-port Hub Module is installed in the Remote XpressOffice DNIC Unit. XpressOffice Teleworker HUB Upgrade Module |
| | , ,,,,,, | NOTE(S): Module used to upgrade XpressOffice Teleworker DNIC Units to allow 4 port ethernet connection for remote LAN devices. NOTE: Hub upgrade cannot be used when the POTs Module is installed in the Remote XpressOffice DNIC Unit. |
| | XPRESSWAY RLA | N BUNDLES |
| 9180-300-012-NA | \$13,807.71 | Xpressway RLAN/XpressOffice 5232i 6 USER Bundle |
| MKT10790Z1 | \$5,858.41 | NOTE(S): Includes Xpressway 11 slot chassis/ RSC9002 system controller/ Dual PRI 9346 module/ Voice Resouce Module/ Voice Interface Module with 6 DNIC extenders AND 6 XpressOffice 5232i`s with DNIC extenders and Single POTS port. Central site operates over ISDN PRI and remotes work on BRI Due to size order ships in 2 boxes. Xway 4 RLAN RSC9002 Bundle w/ RAC s/w & Compression |
| MKT10791Z1 | \$6,510.29 | NOTE(S): Includes Xpressway 4 slot chassis,4 slot backplane,RSC9002 RAC software,cables,manuals. RAC software has 256 bit encryption and upto 8:1 compression Xway 11 RLAN RSC9002 Bundle w/RAC s/w & Compression |
| | | NOTE(S): Includes Xpressway 11 slot chassis,5 slot backplane,RSC9002 RAC software,cables,manuals. RAC software has 256 bit encryption and up to 8:1 compression |
| | XPRESSWAY RLA | N CHASSIS COMPONENTS |
| 10155K1 | \$1,628.75 | RAC S/W Kit Version 4.x |
| | | RAC Software Version 4.x for Xpressway RLAN or XpressStack Software is included in Xpressway RLAN RSC9002 Bundles |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|---------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSWAY RLA | N CHASSIS COMPONENTS (Continued) |
| 6756K1 | \$55.42 | Xpressway 11 Wallmount Kit |
| 6913K1 | \$18.79 | NOTE(S): Wallmount kit for the Xpressway 11 slot chassis. Xpressway 4 Rackmount Kit |
| 7474A1 | \$91.11 | NOTE(S): Mounting kit which recesses the Xpressway 4 slot chassis in a rack or cabinet. Splitter Kit for the XC11 Chassis |
| 7840A1 | \$25.36 | NOTE(S): Kit allows a non-segmented Xpressway backplane 11 to be changed into a segmented unit. De Splitter Kit for the XC 11 Chassis |
| 7841A1 | \$586.12 | NOTE(S): Kit allows a segmented Xpressway 11 backplane to be changed into a non-segmented unit. Xc11 Redundant PS 120/230 VAC 600W |
| 8213K1 | \$46.03 | NOTE(S): Redundant Power Supply for Xpressway 11 slot chassis. Supplies power at 120/230V, 600W. Xway Central Front Mount Kit |
| | | NOTE(S): Xpressway 11 slot chassis front mount kit. Adds "ears" to the front of the chassis to allow for mounting flush or recessed in a rack or cabinet. |
| | XPRESSWAY RLA | N MODULES |
| 10196Z1 | \$1,689.80 | BRI 9308 (U) 8 Port Basic Rate Interface Module |
| | | Supports 8 ISDN BRI U i/f Connections (16B Channels) Includes: 9308U Module BRI9308 Software Kit Integrated NT1 Installation Manual 8 BRI Cables |
| | XPRESSWAY RLA | N PBX EXTENSION PRODUCTS |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|---------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSWAY RLA | N PBX EXTENSION PRODUCTS (Continued) |
| 10771Z1 | \$3,383.36 | VIM 9606 with 6 Switch Side PBX Packs - Nortel |
| 10771Z2 | \$3,383.36 | The Voice Interface Module (VIM9606) hosts the PBX extender Packs for the Nortel Meridian SL1 allowing them to reside within the Xpressway chassis. Each VIM9606 supports up to 6 users. The 9606 can support connection into a Meridian at the central site or sets at a remote site. Connect to the VRM9630 via DB25 cable. NOTE: With the Nortel version there are seperate packs for switch or phone connection. VIM 9606 WITH 6 Phone Side PBX Packs - Nortel |
| 10773R1 | \$517.55 | The Voice Interface Module (VIM9606) hosts the PBX extender Packs for the Nortel Meridian SL1 allowing them to reside within the Xpressway chassis. Each VIM9606 supports up to 6 users. The 9606 can support connection into a Meridian at the central site or sets at a remote site. Connect to the VRM9630 via DB25 cable. NOTE: With the Nortel version there are seperate packs for switch or phone connection. XpressConnect 5232i Meridian PBX Extender - Remote |
| 10774R1 | \$517.55 | NOTE(S): For use when connected to a Nortel Meridian PBX Digital PHONE Set. Unit resides in the XpressOffice 5232i. The XpressConnect 5232i PBX Extender pack is an off premise link extender which allows a PBX line to be extended to a remote location via ISDN. With XpressConnect 5232i PBX extender technology, access to corporate LAN and the corporate PBX facilities can be delivered through the same device! XpressOffice 5232i Meridian PBX Extender - Central |
| | | NOTE(S): For use at the central site when connected to a PBX and using a remote PBX extended 5232i. The XpressConnect 5232i PBX Extender pack, is an off premise link extender which allows a PBX line to be extended to a remote location via ISDN. With XpressConnect 5232i PBX extender technology, access to corporate LAN and the corporate PBX facilities can be delivered through the same device! Resides on VIM9606 module (10771Z3) |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|---------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSWAY RLA | N PBX EXTENSION PRODUCTS (Continued) |
| 10885Z1 | \$517.55 | DNIC EXTENDER UPGRADE KIT |
| 10901Z1 | \$3,383.36 | NOTE(S): DNIC extender card for use at the central or remote site. Can be used in conjunction with both the SX-200 and SX-2000. To be installed in either an XpressOffice 5232i or on a Xpressway Voice Interface Module 9612. VIM 9612 W/6 DNIC Modules - Mitel |
| 10901Z2 | \$727.96 | The Voice Interface Module (VIM9612) hosts the PBX extender Packs for the Mitel SX-2000/SX-200 allowing them to reside within the Xpressway chassis. Each VIM9612 supports up to 6 users. The 9612 can support connection into a DNIC card at the central site or sets at a remote site. Connect to VRM9630 via DB25 cable. VIM 9612 W/NO DNIC Modules - Mitel |
| MKT10772Z1 | \$2,537.05 | The Voice Interface Module (VIM9612) hosts the PBX extender Packs for the Mitel SX-2000/SX-200 allowing them to reside within the Xpressway chassis. Each VIM9612 supports up to 6 users. The 9612 can support connection into a DNIC card at the central site or sets at a remote site. Connect to VRM9630 via DB25 cable. VRM 9630 with no Backplane |
| MKT10772Z2 | \$2,601.86 | NOTE(S): VRM communicates to the RLAN over the P1 backplane. Support for up to 30 channels. Each RLAN supports a max of 2 VRM's for a total of 60 channels per RLAN system. Connects via DB25 cable to VIM cards. ASSY VRM 9630 C/W 4 SLOT |
| MKT10772Z3 | \$2,601.86 | NOTE(S): VRM communicates to the RLAN over the P1 backplane. Support for up to 30 channels. Each RLAN supports a max of 2 VRM's for a total of 60 channels per RLAN system. Connects via DB25 cable to VIM cards. VRM 9630 with 5 slot Backplane |
| | | NOTE(S): VRM communicates to the RLAN over the P1 backplane. Support for up to 30 channels. Each RLAN supports a max of 2 VRM's for a total of 60 channels per RLAN system. Connects via DB25 cable to VIM cards. |
| | XPRESSWAY RLA | N SYSTEM CONTROLLERS |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--------------------|----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | XPRESSWAY RLA | N SYSTEM CONTROLLERS (Continued) |
| 10444Z2 | \$5,532.48 | RSC9002 System Controller, 5 Slot Backplane, RAC S/W |
| 10444Z1 | \$5,532.48 | RSC9002 System Controller card with Compression. 5 slot backplane and RAC software. RSC9002 System Controller 4 Slot Backplane, RAC S/W |
| 9168-500-024-NA | \$250.00 | RSC9002 System Controller card with Compression. 4 slot backplane and RAC software. RLAN S/W UPGRADE 5.0 - 256 ENC |
| 9168-500-026-NA | \$250.00 | NOTE(S): Upgrades Xpressway RLAN to the latest release of software/ version 5.0. See bulletin for details on features. 256 bit encryption. RLAN S/W UPGRADE 5.0 - 40 BIT ENC |
| 9168-500-025-NA | \$250.00 | NOTE(S): Upgrades Xpressway RLAN to the latest release of software/ version 5.0. See bulletin for details on features. 40 bit encryption. RLAN S/W UPGRADE 5.0 - NO ENC |
| | | NOTE(S): Upgrades Xpressway RLAN to the latest release of software/ version 5.0. See bulletin for details on features. No encryption. |
| | XPRESSSTACK PR | RODUCTS |
| 10078Z10 | \$6,510.29 | XpressStack PRIe - Dual PRI/T1 |
| 40404144 | \$10.50 | Comes with 2 PRI/TI, and 1 10Base-T port. Supports an analog connection passing MSDN from the PBX to remote locations that utilize the XpressOffice 5232i with Dual Analog Voice Port option(9180-300-007-NA) Comes with manuals, RAC software, and cables. |
| 10131K1 10131K2 | | XpressStack Flush Rackmount Kit XpressStack Inset Rackmount Kit |
| | HARDWARE | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-------------|----------------|--|
| | HARDWARE (Cont | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| 10439Z3 | \$644.36 | XpressConnect 5232i - Base TB U-Intf UTP |
| MKT10880Z2 | \$711.99 | NOTE(S): Includes: XpressConnect 5232i base unit with Teleworker Bridge software (Mitel Single Link/Mulitlink Protocol) BRI U interface/ 10 base T port/ Bandwidth on demand/ Configuration is done locally or through telnet into a VT100 compatible console. Supports Mitel's up to 8:1 compression and 256 bit encryption. Can also prioritze and filter specific protocols. Also supports up to 10 different destinations and 10 MAC addresses on the local network. Please note: Mitel Single Link/Multilink protocol will only communicate with another XpressOffice 5232i running Teleworker Bridge software or an Xpressway RLAN. XpressConnect 5232i - Teleworker Bridge, Business Pack and 2 |
| | | NOTE(S): Includes: XpressConnect 5232i base unit with Teleworker Bridge software (Mitel Single Link/Mulitlink Protocol) BRI U interface/ 10 base T port/ Bandwidth on demand/ Configuration is done locally or through telnet into a VT100 compatible console. Supports Mitel`s up to 8:1 compression and 256 bit encryption. Can also prioritze and filter specific protocols. Also supports up to 10 different destinations and 10 MAC addresses on the local network. Please note: Mitel Single Link/Multilink protocol will only communicate with another XpressOffice 5232i running Teleworker Bridge software or an Xpressway RLAN. Also includes 2 analog voice ports that support call waiting/ 3-way calling/ voice message indication/ distinctive ring and Caller ID. |
| | MISCELLANEOUS | CABLES AND ACCESSORIES |
| BS05EU | \$38.51 | 5332 Power Supply - For Sparing Only NOTE(S): |
| H45886 | \$12.21 | For the XpressOffice 5232i and XpressOffice Teleworker. |
| J06988 | \$16.91 | NOTE(S): For the XpressOffice 5232i and XpressOffice Teleworker. DB25 TO RJ45 adapter NOTE(S): |
| | | For use with the Xpressway RLAN console. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | CV EO | |
| | SX-50 | |
| | SYSTEMS | |
| 9104-500-002-SA | \$472.17 | Basic System (MCII) (110V) |
| 9104-500-300-NA | \$1,837.19 | INCLUDE(S): Cabinet Assembly and Cover Power Supply with Power Cord and Main Control Card (contains RS-232 and Console Interfaces). SX-50 4x16 Configured System |
| | | INCLUDE(S): 9104-500-002-SA Basic System (Qty 1) 9104-060-102-SA Console (Qty 1) 9104-511-055-NA MS55 Software (Qty 1) 9104-020-001-SA ONS Line Card (16 Circuit) (Qty 1) 9104-030-100-SA LS/GS Trunk Card (4 Circuit) (Qty 1) |
| | HARDWARE | |
| | | |
| 9104-020-001-SA | | ONS Line Card (16 Circuit) |
| 9104-020-003-SA 9104-020-100-SA | | ONS Line Card (4 Circuit) |
| 9104-020-100-SA 9104-020-101-SA | | OPS Line Card (4 Circuit) OPS Line Card (8 Circuit) |
| 9104-021-001-SA | | COV Line Card (8 Circuit) |
| 9104-024-001-NA | | DNIC Line Card (8 Circuit) |
| | | NOTE(S): Maximum 4 per System. |
| 9104-030-100-SA | \$330.52 | Supports SS410 & SS420 only. LS/GS Trunk Card (4 Circuit) |
| 9104-030-101-SA | | LS/GS Trunk Card (8 Circuit) |
| 9104-030-110-SA | | DID Trunk Card (4 Circuit) |
| 9104-030-111-SA | | DID Trunk Card (8 Circuit) |
| 9104-040-000-SA | | Universal Card |
| 9104-041-001-SA | \$321.08 | E&M Module |
| 9104-042-001-SA | \$279.01 | MOH/Paging Module |
| 9104-060-102-SA | \$635.29 | Console (Grey) |
| | SOFTWARE | |
| 9104-511-055-NA | \$516.62 | MS55 Software |





| DARTAUMRER | NET DDICE | DECCRIPTION | |
|-------------|-----------|-------------|--|
| PART NUMBER | NET PRICE | DESCRIPTION | |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SPARE COMPONENTS

| 9104-001-000-SA | \$437.83 | Power Supply 110V |
|-----------------|----------|---------------------------|
| 9104-010-100-SA | \$927.18 | Main Control Card II |
| 9104-044-001-SA | \$270.43 | RMATS Module |
| 9104-071-003-SA | \$171.70 | Cabinet Cover (Grey) |
| 9104-072-001-SA | \$85.85 | Wall Mounting Plate |
| 9104-080-001-NA | \$17.17 | Power Cord |
| 9104-081-101-NA | \$38.63 | Lithium Batteries (Qty 5) |
| 9104-083-001-NA | \$21.46 | Fuse Kit |



SX-50 SOFTWARE UPGRADES

| PART NUMBER | NET PRICE UPGRADE FROM | UPGRADE TO |
|--------------|-------------------------|-------------|
| I ART HOMBER | HETT KIDE OF CHAPET KOM | OI ONABE IO |

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-50 SOFTWARE UPGRADES

SX-50

| 9104-520-051-NA | \$375.72 | MS50 | MS55 |
|-----------------|----------|------|------|
| 9104-520-151-NA | \$375.72 | MS51 | MS55 |
| 9104-520-251-NA | \$375.72 | MS52 | MS55 |
| 9104-520-351-NA | \$375.72 | MS53 | MS55 |
| 9104-520-451-NA | \$375.72 | MS54 | MS55 |

DESKTOP DEVICES



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|-----------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | DESKTOP DEVIC | ES |
| | SUPERSET 4000 S | SERIES |
| 9132-250-101-NA | \$56.36 | SIM2 (Analog Interface) |
| 9132-800-500-NA 9132-800-501-NA | | NOTE(S): Provides an analog interface on Superset 4025 & 4150 phones. Min. Software: LIGHTWARE 29 Rls 3 or LIGHTWARE 17 Rls 3. Power adapter 9132-800-210-NA sold separately. Headset with Feature Control Switch Deluxe Over-The-Ear Headset (with Feature Control Switch) |
| 9132-800-600-NA | \$511.92 | NOTE(S): Supported by Superset 4015/4025/4125 and 4150 telephones. North American Digital Line Monitor |
| | | NOTE(S): For Use on SX-200 or SX-2000 |
| | SUPERSET 4000 S | ERIES - SPARE PARTS |
| 0400 000 400 111 | | D0000 0 |
| 9132-000-100-NA 9132-201-200-NA | | RS232 Spare Cable (Qty 10) Universal Handset Light Grey (Qty 25) |
| 9132-800-105-NA | \$46.96 | NOTE(S): Without handset cord. For use with light grey Superset 4000 Series telephones. Handset Cord 9 ft/3.0 m Light Grey (Qty 25) |
| 9132-800-107-NA | \$28.18 | NOTE(S): Spare Stand Light Grey Pkg of 10 |
| 9132-800-200-NA | \$272.40 | NOTE(S): For use with light grey Superset 4000 Series telephones. Universal Handset Dark Grey (Qty 25) |
| 9132-800-207-NA | \$28.18 | NOTE(S): Without handset cord. For use with dark grey Superset 4000 Series telephones. Spare Stand Dark Grey Pkg of 10 |
| 9132-800-208-NA | \$46.96 | NOTE(S): For use with dark grey Superset 4000 Series telephones. Handset Cord 9ft/3.0m Dark Grey (Qty 25) |
| | | NOTE (G) |

NOTE(S):



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|----------------|--|
| s | UPERSET 4000 S | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change SERIES - SPARE PARTS (Continued) |
| 0400 000 000 NA | фод од | Object Designed (Display for DKM40 (Display of 5) |
| 9132-800-209-NA | \$93.93 | Short Bracket (Black) for PKM48 (Pkg of 5) |
| 9132-800-601-NA | \$4.70 | NOTE(S): Use for securing 1 PKM48 next to a phone. Wall Mounting Hardware Kit (Qty 25) |
| | | NOTE(S): Needed if wall mounting Superset 4025 or 4150 telephones. Wall mounting hardware included with Superset 4001 & 4015. Consists of a screw and plastic spacer per telephone. |
| s | UPERSET 400 SE | ERIES |
| 9112-100-000-NA | \$140.89 | Milink Data Module |
| | | NOTE(S): |
| 9112-200-000-NA | ¢107 06 | Connects to Superset 410,420 and 430, for 19.2 KBS Async Data. Milink PKM (Light Grey) |
| 9112-502-000-NA | | Milink PKM (Dark Grey) |
| 9115-000-000-NA | | Superset 420 Light Grey |
| 9115-000-900-NA | | Superset 420 TSG |
| 9115-502-000-NA | | Superset 420 Dark Grey |
| s | UPERSET 400 SE | ERIES - SPARE PARTS |
| 9112-080-001-NA | \$46.96 | Milink Cables (0.3m) (Qty 25) |
| 9112-080-002-NA | \$46.96 | Milink Cables (1m) (Qty 25) |
| 9112-080-003-NA | | Milink Cables (3.0m) (Qty 25) |
| 9112-200-001-NA | | PKM Power Adaptor |
| 9112-200-008-NA | | PKM Connector Strip |
| 9113-200-001-NA | \$56.36 | SS401+ Stand Light Grey NOTE(S): |
| 0442 200 000 NA | \$56.36 | Cannot be used on SX-50. |
| 9113-200-002-NA | \$56.36 | SS401+ Stand Dark Grey NOTE(S): |
| | | Cannot be used on SX-50. |
| 9115-007-001-NA | | Mitel Handsets Light Grey (Qty 25) |
| 9115-007-003-NA | | Mitel Handsets Dark Grey (Qty 25) |
| 9115-008-001-NA | | 8` Handset Cords Light Grey (Qty 25) |
| 9115-200-001-NA 9115-200-002-NA | | SS420 Stand Dark Grov |
| 3113-200-002-NA | φ30.30 | SS420 Stand Dark Grey |
| | | |



| PART NUMBER | NET PRICE | DESCRIPTION |
|--|--|--|
| | SUPERSET 400 SE | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change ERIES - SPARE PARTS (Continued) |
| 9115-501-003-NA | \$23.48 | 8` Handset Cords Dark Grey (Qty 10) |
| | SUPERSET 400/40 | 00 SERIES - SPARE PARTS |
| 9115-009-001-NA 9115-010-001-NA | | Line Cords (Qty 25) 12` Handset Cords Light Grey (Qty 25) |
| | SUPERSET 4001 | |
| 9132-001-100-NA 9132-001-106-NA 9132-001-200-NA 9132-001-206-NA | \$403.90 \$140.89 | Superset 4001 Light Grey Superset 4001 Light Grey (Qty 6) Superset 4001 Dark Grey Superset 4001 Dark Grey (Qty 6) |
| | SUPERSET 4015 | |
| 9132-015-100-NA 9132-015-200-NA 50000285 50000286 | \$131.50 \$1,263.36 | Superset 4015 Light Grey Superset 4015 Dark Grey Superset 4015 Dark Grey (Qty 12) Superset 4015 Light Grey (Qty 12) |
| | SUPERSET 4025 | |
| 9132-025-100-NA 9132-025-102-NA 9132-025-200-NA 9132-025-202-NA 50000287 50000288 50000402 50000403 | \$206.65 \$187.86 \$206.65 \$2,047.67 \$2,047.67 \$1,916.17 | Superset 4025 Light Grey Superset 4025 Light Grey Backlit Superset 4025 Dark Grey Superset 4025 Dark Grey Backlit Superset 4025 Dark Grey Backlit (Qty 12) Superset 4025 Light Grey Backlit (Qty 12) SUPERSET 4025 DK GREY - 12 PACK SUPERSET 4025 LT GREY - 12 PACK |
| | SUPERSET 4090 | |
| 9132-090-801-NA | \$14.09 | Superset 4090 A/C Adapter for Charger NOTE(S): Use only with the Superset 4090 Charger. Do not use with the Superset 4090 Base Unit. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|------------------|---|
| | SUPERSET 4090 (0 | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change Continued) |
| 9132-090-802-NA 9132-090-803-NA | | SS4090 Belt Clip (qty 5) Superset 4090 Headset |
| 9132-090-804-NA | \$32.88 | NOTE(S): For use with Superset 4090 only. Superset 4090 Leather Carrying Case |
| 9132-090-805-NA 9132-090-806-NA | | NOTE(S): For use with Superset 4090 handset. SS4090 Charging Unit (with AC Adaptor) Superset 4090 Wall Mount Plate (Qty 5) |
| 9132-090-807-NA 9132-090-808-NA | | NOTE(S): To wall mount base station. SS4090 Spare Battery (qty 4) Superset 4090 A/C Adapter for Base Unit |
| | | NOTE(S): Use only with the Superset 4090 Base Station. Do not use with the Superset 4090 Charger. |
| | SUPERSET 4125 | |
| 9132-125-102-NA | \$328.75 | Superset 4125 Light Grey, Backlit with TAPI NOTE(S): For SX-2000 the Minimum Software required is LIGHTWARE 29 Rls. 3. PRE-REQUISITE(S) on SX-2000: MSA-A-47 Desktop TAPI Support and MTSP-A-10 TAPI Service Provider 1-10 Users or MSB-A-08 CTI Bundle that includes HCI Basic/Advanced Telephony. PRE-REQUISITE(S) on SX-200: Minimum Software required is LIGHTWARE 17 Rls. 4. and 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users INCLUDE(S): Telephone/RS232 Cable/TAPI Software |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|----------------------|---|
| | SUPERSET 4125 (C | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change Continued) |
| 9132-125-202-NA | \$328.75 | Superset 4125 Dark Grey, Backlit with TAPI |
| 50000289 50000290 | \$2,841.38 | NOTE(S): For SX-2000 the Minimum Software required is LIGHTWARE 29 Rls. 3. PRE-REQUISITE(S) on SX-2000: MSA-A-47 Desktop TAPI Support and MTSP-A-10 TAPI Service Provider 1-10 Users or MSB-A-08 CTI Bundle that includes HCI Basic/Advanced Telephony. PRE-REQUISITE(S) on SX-200: Minimum Software required is LIGHTWARE 17 Rls. 4. and 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users INCLUDE(S): Telephone/RS232 Cable/TAPI Software Superset 4125 Dark Grey, Backlit with TAPI (Qty 12) Superset 4125 Light Grey, Backlit with TAPI (Qty 12) |
| | SUPERSET 4150 | |
| 9132-000-200-NA | \$93.93 | Mitel TAPI Desktop Software NOTE(S): SX-2000 ONLY. Minimum software: LW29 Rls 3 Used with Superset 4125 & 4150 telephones. Add-on purchase for Superset 4150 telephones without TAPI |
| 9132-150-102-NA | \$309.97 | or as a spare. Superset 4150 Light Grey Backlit |
| 9132-150-202-NA 9132-150-302-NA | \$309.97 \$403.90 | Superset 4150 Dark Grey Backlit Superset 4150 Light Grey Backlit with TAPI |
| | | NOTE(S): For SX-2000 the Minimum Software required is LIGHTWARE 29 Rls. 3. PRE-REQUISITE(S) on SX-2000: MSA-A-47 Desktop TAPI Support and MTSP-A-10 TAPI Service Provider 1-10 Users or MSB-A-08 CTI Bundle that includes HCI Basic/Advanced Telephony. PRE-REQUISITE(S) on SX-200: Minimum Software required is LIGHTWARE 17 Rls. 4. and 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users INCLUDE(S): Telephone/RS232 Cable/TAPI Software |



| PART NUMBER | NET PRICE | DESCRIPTION |
|----------------------|-----------------|---|
| | SUPERSET 4150 (| NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change Continued) |
| 9132-150-402-NA | \$403.90 | Superset 4150 Dark Grey Backlit with TAPI |
| 50000282 50000283 | \$3,146.66 | NOTE(S): For SX-2000 the Minimum Software required is LIGHTWARE 29 Rls. 3. PRE-REQUISITE(S) on SX-2000: MSA-A-47 Desktop TAPI Support and MTSP-A-10 TAPI Service Provider 1-10 Users or MSB-A-08 CTI Bundle that includes HCI Basic/Advanced Telephony. PRE-REQUISITE(S) on SX-200: Minimum Software required is LIGHTWARE 17 Rls. 4. and 9109-535-005-NA SX-200 TAPI Service Provider 0-5 Users INCLUDE(S): Telephone/RS232 Cable/TAPI Software Superset 4150 Light Grey Backlit (Qty 12) Superset 4150 Dark Grey Backlit (Qty 12) |
| | PERIPHERALS - H | EADSETS |
| 9132-800-500-NA | \$93.93 | Headset with Feature Control Switch |
| | PERIPHERALS - P | KM MODULES |
| 9132-200-100-NA | \$117.41 | Superset PKM48 Light Grey (no SIM 1, no bracket) |
| 9132-200-102-NA | \$178.47 | NOTE(S): Min software: LIGHTWARE 29 Rls 2 or LIGHTWARE 17 Rls 3. Excludes SIM1 (PKM IF) and bracket. For use as a second PKM on a telephone (SX-200 only) or for use as a spare (SX-200 or SX-2000). Power adapter 9132-800-210-NA ordered separately. Kit Superset PKM48 Light Grey |
| 9132-200-200-NA | \$117.41 | NOTE(S): Min software: LIGHTWARE 29 RIs 2 or LIGHTWARE 17 RIs 3. Includes: PKM/ SIM1 (PKM IF)/ short bracket/ PKM cable/ desi card/ lens/ and documentation. Power adapter 9132-800-210-NA sold separately. Superset PKM48 Dark Grey (no SIM1, no bracket) |
| | | NOTE(S): Min software: LIGHTWARE 29 Rls2 or LW17 Rls 3. Excludes SIM1 (PKM IF) and bracket. For use as a second PKM on a telephone (SX-200 only) or for use as a spare (SX-200 or SX-2000). Power adapter 9132-800-210-NA sold separately. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|------------------|--|
| | PERIPHERALS - P | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change KM MODULES (Continued) |
| 9132-200-202-NA | \$178.47 | Kit Superset PKM48 Dark Grey |
| 9132-250-100-NA | \$42.27 | NOTE(S): Min software: LIGHTWARE 29 Rls 2 or LIGHTWARE 17 Rls 3. Includes: PKM/ SIM1 (PKM IF)/ short bracket/ PKM cable/ desi card/ lens/ and documentation. Power adapter 9132-800-210-NA sold separately. SIM1 (PKM Interface) |
| 9132-800-210-NA | \$9.39 | NOTE(S): Use for connecting a Superset PKM48 to a compatible phone. Power Adapter (North America) |
| 9132-800-299-NA | \$18.79 | NOTE(S): Order separately for use on a Superset PKM 48. Order separately for use on a SIM 2. Long Bracket (Black) for PKM48 (single) |
| | | NOTE(S): Use for securing 2 PKM48s to a phone (SX-200 only). |
| | PERIPHERALS - E. | XPANSION MODULES |
| 9132-250-100-NA | ¢42.27 | CIMA (DIAM Interfere) |
| 9132-800-210-NA | \$9.39 | SIM1 (PKM Interface) NOTE(S): Use for connecting a Superset PKM48 to a compatible phone. Power Adapter (North America) |
| 9141-110-200-NA | ¢224.92 | NOTE(S): Order separately for use on a Superset PKM 48. Order separately for use on a SIM 2. Dataset 1102 |
| 9141-110-200-NA | | NOTE(S): For use on SX-200 or SX-2000. Dataset 1103 |
| 9141-210-200-NA | \$234.82 | NOTE(S): For use on SX-200 or SX-2000. Dataset 2102 |
| 9141-210-300-NA | \$234.82 | NOTE(S): For use on either SX-200 or SX-2000. Dataset 2103 |
| | | NOTE(S): For use on either SX-200 or SX-2000. |



| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|------------------|--|
| | PERIPHERALS - E. | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change XPANSION MODULES (Continued) |
| 9141-220-300-NA | \$469.65 | Dataset 2203 |
| 9141-300-001-NA | \$18.79 | NOTE(S): For use on SX-2000 only. Dataset Power Supply |
| | SPARE COMPONE | ENTS |
| 9132-000-100-NA 9132-201-200-NA | | RS232 Spare Cable (Qty 10) Universal Handset Light Grey (Qty 25) NOTE(S): |
| 9132-800-107-NA | \$28.18 | Without handset cord. For use with light grey Superset 4000 Series telephones. Spare Stand Light Grey Pkg of 10 |
| 9132-800-200-NA | \$272.40 | NOTE(S): For use with light grey Superset 4000 Series telephones. Universal Handset Dark Grey (Qty 25) |
| 9132-800-207-NA | \$28.18 | NOTE(S): Without handset cord. For use with dark grey Superset 4000 Series telephones. Spare Stand Dark Grey Pkg of 10 |
| 9132-800-209-NA | \$93.93 | NOTE(S): For use with dark grey Superset 4000 Series telephones. Short Bracket (Black) for PKM48 (Pkg of 5) |
| 9180-500-001-NA | \$198.53 | NOTE(S): Use for securing 1 PKM48 next to a phone. DSS/BLF Console Interface Unit |
| | | INCLUDE(S): PKM Interface (Qty 1) AC Power Adapter (Qty 1) 5 Meter Cable (Qty 1) Wall Mounting Bracket (Qty 2) NOTE(S): Minimum Software: LightWare 17 Release 3.1 or LightWare 29 Release 2. On SX-200 provides DSS/BLF Functionality. On SX-2000 provides BLF only. Used with Superset PKM 48. |

PROGRAM: SUPERSET 4090 PRICE PROMOTION



PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number
INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PROGRAM: SUPERSET 4090 PRICE PROMOTION (Continued)

9132-090-000-NA \$342.84 Superset 4090 Cordless Black

NOTE(S): SX-200 ONLY.

Minimum Software: LW17 Rls 3.1





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SPEAK@EASE SOFTWARE

54000050

\$0.00 Speak@Ease Option



IMPRESA APPLICATIONS

PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

CHG = Part Description/Note/BOM/Pre-Reg Change

IMPRESA APPLICATIONS

CUSTOMER INTERACTION SERVERS

9185-000-100-NA \$4,464.20 Impresa Customer Interaction Server - Non Redundant

(800S)

NOTE(S): INCLUDES:

TS800 PIII 550 MHz Server w/ 384 M RAM

IDE Controller w/ 9.0 GB Hard Drive

Application Fiber Controller (AFC) Card (installed)

Windows NT Operating System

Oracle Database Software

Impresa CIS System Software / MiTAI Runtime Software /

TAPI Software / PC Anywhere Software Fiber Interface Module (FIM) Card and Cable

SAM Module

Impresa CIS Documentation

PRE-REQUISITE(S):

MSB-A-08 CTI Bundle must be included on your purchase order

 $\ensuremath{\mathsf{MSB}\text{-}A\text{-}08}$ CTI Bundle is No Charge when purchased with

this Server Package.

8 or 24 Port NMS DSP Cards (9164-001-001-NA or

9164-120-024-NA) are sold separately and are pre-installed

in this Server Package.

9185-000-200-NA \$7,726.50 Impresa Customer Interaction Server - Redundant

(1500SR)

NOTE(S):

Includes:

TS1500SR PIII 550 MHz Server w/ 384 M RAM

RAID Controller with SCSI (9.0 GB Hard Drive)

14 Slot Riser Card (4 PCI/ 10 ISA)

Hot Swappable Redundant Power Supplies (2)

Hot Swappable Drive Casing (3 Drives)

Application Fiber Controller (AFC) Card (installed)

Windows NT Operating System

Oracle Database Software

Impresa CIS System Software / MiTAI Runtime Software /

TAPI Software / PC Anywhere Software

Fiber Interface Module (FIM) Card and Cable

SAM Module

Impresa CIS Documentation

PRE-REQUISITE(S):

MSB-A-08 CTI Bundle must be included on your purchase order

MSB-A-08 CTI Bundle is No Charge when purchased with

this Server Package.

8 or 24 Port NMS DSP Cards (9164-001-001-NA or

9164-120-024-NA) are sold separately and are pre-installed

in this Server Package.

Prices quoted in Net U.S. Dollars e. and o.e.

Effective: September 10, 2000 Page 3-126



IMPRESA APPLICATIONS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | IMPRESA CUSTON | MER INTERACTION SUITES |
| 9185-300-100-NA | \$9,111.21 | Impresa Customer Interaction Suite - Basic |
| 9185-300-200-NA | \$11,929.11 | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) 9164-001-001-NA 8 Port NMS DSP Card OR 9164-120-024-NA 24 Port NMS DSP Card INCLUDE(S): Impresa Intelligent Media Router (IMR) Server Lic (Qty 1) Impresa Agent Desktop/Screen Pop Server License (Qty 1) 9185-201-004-NA Impresa IMR 4 Port License (Qty 1) 9185-201-400-NA Impresa IMR App. Gen. License (Qty 1) 9185-101-105-NA Impresa Basic AD License - 5 Seats (Qty 1) 9185-101-400-NA Impresa Desktop Manager License (Qty 1) Impresa Customer Interaction Suite - Enhanced |
| | | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) 9164-001-001-NA 8 Port NMS DSP Card OR 9164-120-024-NA 24 Port NMS DSP Card INCLUDE(S): Impresa Intelligent Media Router (IMR) Server Lic. (Qty 1) Impresa Agent Desktop/Screen Pop Server License (Qty 1) 9185-201-004-NA Impresa IMR 4 Port License (Qty 1) 9185-201-400-NA Impresa IMR App. Gen. License (Qty 1) 9185-101-105-NA Impresa Enhanced AD License- 5 Seats (Qty 1) 9185-101-400-NA Impresa Desktop Manager License (Qty 1) 9185-201-200-NA Impresa Data Coll. w Crystal Reports (Qty 1) 9185-201-401-NA Impresa IMR Busy Queuing License (Qty 1) |
| | IMPRESA INTELLI | GENT MEDIA ROUTER |
| 9185-200-100-NA | \$6,387.24 | Impresa Intelligent Media Router - Basic |
| | | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) 9164-001-001-NA 8 Port NMS DSP Card OR 9164-120-024-NA 24 Port NMS DSP Card INCLUDE(S): Impresa Intelligent Media Router (IMR) Server Lic (Qty 1) 9185-201-004-NA Impresa IMR 4 Port License (Qty 1) 9185-201-400-NA Impresa IMR App. Gen. License (Qty 1) |



IMPRESA APPLICATIONS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|-----------------|---|
| | IMPRESA INTELLI | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change GENT MEDIA ROUTER (Continued) |
| 9185-200-200-NA | \$9,017.28 | Impresa Intelligent Media Router - Enhanced |
| | IMPRESA AGENT | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) 9164-001-001-NA 8 Port NMS DSP Card OR 9164-120-024-NA 24 Port NMS DSP Card INCLUDE(S): Impresa Intelligent Media Router (IMR) Server Lic. (Qty 1) 9185-201-004-NA Impresa IMR 4 Port License (Qty 1) 9185-201-400-NA Impresa IMR App. Gen. License (Qty 1) 9185-201-200-NA Impresa Data Coll. w Crystal Reports (Qty 1) 9185-201-401-NA Impresa IMR Busy Queuing License (Qty 1) |
| 9185-100-100-NA | \$4,038.99 | Impresa Agent Desktop - Basic |
| 9185-100-200-NA | \$4,508.64 | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) INCLUDE(S): Impresa Agent Desktop/Screen Pop Server License (Qty 1) 9185-101-105-NA Impresa Basic AD License - 5 Seats (Qty 1) 9185-101-400-NA Impresa Desktop Manager License (Qty 1) Impresa Agent Desktop - Enhanced |
| | | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) INCLUDE(S): Impresa Agent Desktop/Screen Pop Server License (Qty 1) 9185-101-105-NA Impresa Enhanced AD License- 5 Seats (Qty 1) 9185-101-400-NA Impresa Desktop Manager License (Qty 1) |

IMPRESA SCREEN POP



IMPRESA APPLICATIONS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|---|
| | IMPRESA SCREEN | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change N POP (Continued) |
| 9185-400-100-NA | \$4,226.85 | Impresa Screen Pop |
| | | NOTE(S): PRE-REQUISITE(S): 9185-000-100-NA Impresa CIS Server (800S) OR 9185-000-200-NA Impresa CIS Server (1500SR) INCLUDE(S): Impresa Agent Desktop/Screen Pop Server License (Qty 1) 9185-401-105-NA Impresa Scrn Pop Client Lic- 5 Seats (Qty 1) 9185-401-400-NA Impresa Screen Pop Admin License (Qty 1) |
| | IMPRESA AGENT | DESKTOP LICENSES |
| | | |
| 9185-101-105-NA | \$657.51 | Impresa Basic Agent Desktop - 5 Seat License |
| 9185-101-110-NA | \$1,221.09 | Impresa Basic Agent Desktop - 10 Seat License |
| 9185-101-125-NA | \$2,817.90 | Impresa Basic Agent Desktop - 25 Seat License |
| 9185-101-150-NA | \$5,166.15 | Impresa Basic Agent Desktop - 50 Seat License |
| 9185-101-199-NA | \$9,862.65 | Impresa Basic Agent Desktop - 100 Seat License |
| 9185-101-205-NA | \$939.30 | Impresa Enhanced Agent Desktop - 5 Seat License |
| 9185-101-210-NA | \$1,784.67 | Impresa Enhanced Agent Desktop - 10 Seat License |
| 9185-101-225-NA | \$4,226.85 | Impresa Enhanced Agent Desktop - 25 Seat License |
| 9185-101-250-NA | \$7,984.05 | Impresa Enhanced Agent Desktop - 50 Seat License |
| 9185-101-299-NA | \$15,028.80 | Impresa Enhanced Agent Desktop - 100 Seat License |
| 9185-101-305-NA | \$563.58 | Impresa Agent Desktop Enhanced Upgrade - 5 Seat Upgrade |
| 9185-101-310-NA | \$1,033.23 | Impresa Agent Desktop Enhanced Upgrade - 10 Seat Upgrade |
| 9185-101-325-NA | \$1,878.60 | Impresa Agent Desktop Enhanced Upgrade - 25 Seat Upgrade |
| 9185-101-350-NA | \$3,569.34 | Impresa Agent Desktop Enhanced Upgrade - 50 Seat Upgrade |
| 9185-101-399-NA | \$5,635.80 | Impresa Agent Desktop Enhanced Upgrade - 100 Seat Upgrade |
| 9185-101-400-NA | \$399.20 | Impresa Desktop Manager - 1 Seat License |
| 9185-101-401-NA | | Impresa SP Admin to Desktop Manager Upgrade - 1 Seat Upgrade |
| | IMPRESA SCREEN | POP CLIENT LICENSES |
| 9185-401-105-NA | \$798.41 | Impresa Screen Pop Client - 5 Seat License |
| 9185-401-110-NA | | Impresa Screen Pop Client - 10 Seat License |
| | | • |



IMPRESA APPLICATIONS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------|--------------------|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease |
| | ##PDE04 00DEE4 | CHO = Part Description/Note/BOM/Pre-Req Change |
| | IMPRESA SCREEN | I POP CLIENT LICENSES (Continued) |
| | | |
| 9185-401-125-NA | \$3,522.38 | Impresa Screen Pop Client - 25 Seat License |
| 9185-401-150-NA | | Impresa Screen Pop Client - 50 Seat License |
| 9185-401-199-NA | \$12,492.69 | Impresa Screen Pop Client - 100 Seat License |
| 9185-401-305-NA | | Impresa SP to AD Upgrade - 5 Seat Upgrade License |
| 9185-401-310-NA | \$516.62 | Impresa SP to AD Upgrade - 10 Seat Upgrade License |
| 9185-401-325-NA | \$939.30 | Impresa SP to AD Upgrade - 25 Seat Upgrade License |
| 9185-401-350-NA | \$1,596.81 | Impresa SP to AD Upgrade - 50 Seat Upgrade License |
| 9185-401-399-NA | \$2,442.18 | Impresa SP to AD Upgrade - 100 Seat Upgrade License |
| 9185-401-400-NA | \$328.76 | Impresa Screen Pop Administration - 1 Seat License |
| | IMPRESA INTELLI | GENT MEDIA ROUTER LICENSES |
| | mii Klom in i Llei | SENT MESIX NOOTEN EIGENGEG |
| | | |
| 9185-201-004-NA | | Impresa Intelligent Media Router 4 Port License |
| 9185-201-008-NA | | Impresa Intelligent Media Router 8 Port License |
| 9185-201-016-NA | \$5,447.94 | Impresa Intelligent Media Router 16 Port License |
| 9185-201-032-NA | \$10,144.44 | Impresa Intelligent Media Router 32 Port License |
| 9185-201-100-NA | \$1,972.53 | Impresa Basic Data Collector License |
| 9185-201-200-NA | \$2,254.32 | Impresa Enh. Data Collector Lic. (includes Crystal Reports) |
| 9185-201-400-NA | \$751.44 | Impresa IMR Application Generator - 1 Seat License |
| 9185-201-401-NA | | Impresa IMR Busy Queuing License |
| | IMPRESA SPARES | i |
| | | |
| 9185-201-300-NA | ¢201.70 | Crystal Reports Professional Version |
| 9100-201-300-INA | \$201.79 | Crystal Nepulis Fluiessional Version |

CTI APPLICATIONS



| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------|-----------|-------------|--|

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Reg Change

CTI APPLICATIONS

NOTE(S):

For parts and pricing pertaining to Professional

Services please refer to the separate

Professional Services Section within this Price

List.

FASTCALL

INCLUDE(S):

Talk-To PC Card (Qty 1)

Mitel Service Provider Software Disk (Qty 1) Fastcall Lite Application Disk (Qty 1) Fastcall Trigger Library Disk (Qty 1)

Fastcall User Guide (covers Lite and Pro) (Qty 1)

RJ11 Telephone Cable (Qty 1)

Handset (Qty 1) Handset Cord (Qty 1)

NOTE(S):

Requires site qualification prior to purchase.

9191-201-000-NA \$164.38 Fastcall Pro for TAPI (SX-2000)

INCLUDE(S):

Fastcall Pro Application Disk (Qty 1)

NOTE(S):

Requires site qualification prior to purchase.

9191-206-100-NA \$281.79 Fastcall Lite for TAPI (SX-200)

INCLUDE(S):

Talk-To PC Card (Qty 1)

Mitel Service Provider Software Disk (Qty 1) Fastcall Lite Application Disk (Qty 1) Fastcall Trigger Library Disk (Qty 1)

Fastcall User Guide (covers Lite and Pro) (Qty 1)

RJ11 Telephone Cable (Qty 1)

Handset (Qty 1) Handset Cord (Qty 1)

NOTE(S):

Requires site qualification prior to purchase.

9191-207-100-NA \$136.20 Fastcall Pro for TAPI (SX-200)

INCLUDE(S):

Fastcall Pro Application Disk (Qty 1)

NOTE(S):

Requires site qualification prior to purchase.

PHONEWARE NT



CTI APPLICATIONS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|-----------------|----------------|--|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change |
| | PHONEWARE NT (| Continued) |
| 9191-600-002-NA | \$884.36 | PhoneWare NT SX-2000 Connectivity Kit |
| 9191-600-033-NA | \$439.96 | NOTE(S): Package contains: AFC Card, CTI Bundle and software needed to interface PC to PBX. PhoneWare NT SX-200 Connectivity Kit |
| | | NOTE(S): Kit necessary to connect the NT PhoneWare Server to SX-200 |



ENABLING TECHNOLOGIES

| PART NUMBER | NET PRICE | DESCRIPTION |
|---|--|---|
| | | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHO = Part Description/Note/BOM/Pre-Req Change |
| | Services please refer to | ertaining to Professional |
| | TALK TO TAPI | |
| 9147-400-105-NA 9147-600-401-NA 9147-600-403-NA | \$439.96 | SX-2000/Server Connectivity Kit-100 Sessions TALK TO TAPI Tool Kit (for SX-200) Talk To Tapi C/S |
| 9147-400-105-NA 9147-402-005-NA 9147-402-006-NA 9147-403-106-NA 9147-600-402-NA | \$3,110.80 \$3,110.80 \$3,110.80 | SX-2000/Server Connectivity Kit-100 Sessions MiTAI Local Runtime (SX-200) MiTAI Runtime 7.3.1 (SX-2000) MiTAI Tool Kit 7.3.1 (SX-2000) MiTAI Tool Kit 7.3.1 NT (SX-200) |



PRAIRIEFYRE ACD REPORTING SYSTEMS

| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------|--------------------|---|
| | | NEW = New Part Number |
| | | mc = Price Increase |
| | | cho = Part Description/Note/BOM/Pre-Req Change |
| | | |
| | PRAIRIEFYRE AC | D REPORTING SYSTEMS |
| | SX-200 prairieFyre | CyberACD |
| 9146-610-401-NA | \$2.583.07 | SX200 prairieFyre CyberACD 1-10 Agts |
| 9146-610-402-NA | | SX200 prairieFyre CyberACD 1-25 Agts |
| 9146-610-403-NA | | SX200 prairieFyre CyberACD 1-100 Agts |
| 9146-610-404-NA | | SX200 prairieFyre CyberACD Unlimited Agts |
| 9146-610-405-NA | | SX200 prairieFyre CyberACD 1-25 Upgd |
| 9146-610-406-NA | \$2,301.28 | SX200 prairieFyre CyberACD 1-100 Upgd |
| 9146-610-407-NA | \$2,113.42 | SX200 pFyre CybACD Unlimited Upgd |
| 51000572 | \$2,817.90 | SX200 pFyre Adaptiv WorkFORCE Agent Scheduling SW |
| 51000573 | \$2,583.08 | SX200 prairieFyre CyberACD Enterprise Node S/W |
| | SX-200 prairieFyre | CyberACD VT-100 |
| 9146-610-421-NA | \$92.99 | SX200 prairieFyre VT100 RT Server |
| 9146-610-422-NA | | SX200 prairieFyre VT100 RT Client |
| | SX-200 prairieFyre | CyberACD SQL |
| 9146-610-411-NA | ¢146.52 | SX200 pFyre SQL Client Access |
| 9146-610-412-NA | | SX200 pr yre SQL Client Access SX200 prairieFyre SQL Adv Server |
| 3140-010-412-11A | | • |
| | SX-2000 prairieFyr | re CyberACD |
| 9146-600-401-NA | | SX2K prairieFyre CyberACD 1-10 Agts |
| 9146-600-402-NA | | SX2K prairieFyre CyberACD 1-25 Agts |
| 9146-600-403-NA | · | SX2K prairieFyre CyberACD 1-100 Agts |
| 9146-600-404-NA | | SX2K prairieFyre CyberACD Unlimited Agts |
| 9146-600-405-NA | | SX2K prairieFyre CyberACD 1-25 Upgd |
| 9146-600-406-NA | | SX2K prairieFyre CyberACD 1-100 Upgd |
| 9146-600-407-NA | \$2,113.42 | SX2K prairieFyre CyberACD Unlimited Upgd |

SX-2000 prairieFyre CyberACD SQL

51000574

51000575

Scheduling SW

\$2,817.90 SX2000 pFyre Adaptiv WorkFORCE Agent

\$2,583.08 SX2000 prairieFyre CyberACD Enterprise Node



PRAIRIEFYRE ACD REPORTING SYSTEMS (Continued)

| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|--------------------|--|
| | SX-2000 prairieFyr | NEW = New Part Number INC = Price Increase DEC = Price Decrease CHG = Part Description/Note/BOM/Pre-Req Change Te CyberACD SQL (Continued) |
| 9146-600-411-NA 9146-600-412-NA | | SX2K prairieFyre SQL Client Access SX2K prairieFyre SQL Adv Server |
| | SX-200 & SX-2000 | prairieFyre HARDWARE |
| 9146-600-223-NA 9146-600-224-NA | | Digi Board 2 Ports Digi Board 4 Ports |



TASKE REL.7 ACD REPORTING SYSTEMS

| PART NUMBER | NET PRICE | DESCRIPTION |
|------------------------------------|-----------------------------------|--|
| | | MEW = New Part Number |
| | | мс = Price Increase |
| | | cно = Part Description/Note/BOM/Pre-Req Change |
| | | |
| | | D REPORTING SYSTEMS |
| | NOTE(S): For software designat | ed as upgrades or options (i.e. Voice |
| | Toolbox, Call Costing, | Agent Provisioning, Desktop Sign), |
| | | initial installation, the Customer`s er must be provided with the Purchase |
| | Order. | or made so provided man and randomade |
| | SX-2000 TASKE R | EL.7 ACD AGENT TOOLBOX |
| 04.40.000.004.NA | Φ2 170 14 | OV 0000 Table Dal 7 AOD Table at 4 40 America |
| 9146-600-261-NA | \$3,1/0.14 | SX-2000 Taske Rel.7 ACD Toolbox 1-10 Agents |
| | | This part number includes one Taske Rel. 7 Supervisor Client position. |
| 9146-600-262-NA | \$2,817.90 | SX-2000 Taske Rel.7 ACD Toolbox 11-25 Agents |
| 9146-600-263-NA | | SX-2000 Taske Rel.7 ACD Toolbox 26-50 Agents |
| 9146-600-264-NA | \$1,761.19 | SX-2000 Taske Rel.7 ACD Toolbox 51-70 Agents |
| 9146-600-265-NA | \$1,761.19 | SX-2000 Taske Rel.7 ACD Toolbox 71-100 Agents |
| 9146-600-266-NA | | SX-2000 Taske Rel.7 ACD Toolbox 101-150 Agents |
| 9146-600-267-NA | \$1,761.19 | SX-2000 Taske Rel.7 ACD Toolbox 151-350 Agents |
| | SX-2000 TASKE R | EL.7 SUPERVISOR CLIENT |
| 0440 000 074 NA | Φ0.65.60 | OV 0000 Teele Del 7 Our en de en Olient |
| 9146-600-271-NA 9146-600-272-NA | | SX-2000 Taske Rel.7 Supervisor Client SX-2000 Taske Rel.7 Supervisor Client (3 Clients) |
| 9146-600-273-NA | | SX-2000 Taske Rel. 7 Supervisor Client (5 clients) |
| 9146-600-274-NA | | SX-2000 Taske Rel. 7 Supervisor Client (10 clients) |
| 9146-600-280-NA | | SX-2000 Taske Rel.7 Enterprise Supervisor Client |
| | | EL.7 VOICE TOOLBOX |
| | | |
| 9146-600-330-NA | \$3,522.37 | SX-2000 Taske Rel.7 Voice Toolbox (for 4 channels) |
| | | NOTE(S): |
| | | This is a licence for 4 Ports only For additional licences customer must purchase sufficient |
| | | quantity of this part (i.e. for a 16 port licence the |
| | | customer must purchase a quantity of 4) Limit of 64 ports per server. Requires a 16 port |
| | | Dialogic Card which is not supplied by Mitel. |
| | SX-2000 TASKE R | EL.7 CALL CENTER COSTING |
| | | |
| 9146-600-340-NA | \$1,056.71 | SX-2000 Taske Rel.7 Call Center Costing Utility |
| | | |



TASKE REL.7 ACD REPORTING SYSTEMS (Continued)

PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

SX-2000 TASKE REL.7 DESKTOP SIGN

9146-600-370-NA \$394.51 SX-2000 Taske Rel.7 Agent Desktop Sign (5 seats)

SX-200 & SX-2000 TASKE HARDWARE

9146-600-223-NA \$511.92 Digi Board 2 Ports 9146-600-224-NA \$1,080.19 Digi Board 4 Ports



TASKE REL.5 ACD REPORTING SYSTEMS

PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

TASKE REL.5 ACD REPORTING SYSTEMS

NOTE(S):

For software designated as upgrades or options (i.e. Voice Toolbox, Call Costing, Agent Provisioning, Desktop Sign), being purchased after initial installation, the Customer's Hardware Lock Number must be provided with the Purchase Order.

SX-200 REL.5 STANDALONE

9146-610-203-NA \$5.682.76 SX-200 TASKE Advanced Standalone

SX-200 & SX-2000 TASKE HARDWARE

9146-600-223-NA \$511.92 Digi Board 2 Ports 9146-600-224-NA \$1,080.19 Digi Board 4 Ports



PROFESSIONAL SERVICES

| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------|-----------|-------------|--|
| TANTHOMBEN | METTATOL | DECOMM TICH | |

NEW = New Part Number
NC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PROFESSIONAL SERVICES

BILLING SERVICES

| 9178-001-001-NA 9178-002-001-NA | | Professional Services - General |
|------------------------------------|-------------|---|
| 9176-002-001-NA | \$795.00 | Professional Services - Project Management |
| | | NOTE(S): |
| 9178-003-001-NA | \$795.00 | Professional Services - Application Engineering |
| | | NOTE(S): |
| 9178-004-001-NA | \$795.00 | Professional Services - Programmer/Analyst |
| 9178-005-001-NA | | Professional Services - System Engineer |
| 9178-006-001-NA | | Professional Services - Analysis Services |
| 9178-007-001-NA | | Professional Services - Implementation Services |
| 9178-010-001-NA | | Professional Services - On-Site Charge |
| 9178-010-002-NA | | Professional Services - Travel |
| 9178-020-001-NA | | Professional Services - Custom |
| 9178-050-001-NA | | Call Center Health Check <15 agents |
| 3170 000 001 1470 | Ψ1,500.00 | |
| | | NOTE(S): Prof. Services - Call Center Health Check up to 15 agents |
| 9178-050-002-NA | \$10,000,00 | Call Center Health Check >15 Agents |
| 3170 000 002 1470 | φ10,000.00 | • |
| | | NOTE(S): Prof. Services - CC Health Check greater than 15 agents - Si |
| 9178-050-003-NA | \$12,500,00 | Call Center Health Check - Multi site |
| 3170 000 000 147 | Ψ12,300.00 | |
| | | NOTE(S): Prof. Services - Call Center Health Check Multi-site |
| 9178-051-001-NA | \$10,000,00 | Call Center Health Check - Annual |
| 33 33. 33. 14. | Ψ10,000.00 | |
| | | NOTE(S): Prof. Services - Call Center yearly health check-up |
| | | 1 101. Del vices can center yearry nearth encek-up |





PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

 $_{\text{INC}}$ = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

MISCELLANEOUS

NOTE(S):

All equipment listed in this Miscellaneous section is subject to change without notice. In the event of unavailability or price changes, Mitel will make every attempt to substitute an equivalent product.

"MITEL ASSUMES NO LIABILITY FOR THIS EQUIPMENT"

MISCELLANEOUS INSTALLATION

9180-FIB-003-XX \$88.88 Fiber Cable 3 metres 9180-RACK-23-01 \$177.76 23"x7` Rack, Welded, Tapped

9180-RAK-SHF-02 \$53.32 Shelf 23"x22" Grey



PRODUCT SUPPORT

| | NET DDICE | DECODIDEION |
|-------------|-----------|-------------|
| PART NUMBER | NET PRICE | DESCRIPTION |

NEW = New Part Number

INC = Price Increase
DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

PRODUCT SUPPORT TECHNICAL CREDITS

9109-964-001-NA \$454.50 5 TC credits only 9109-964-005-NA \$858.50 10 TC credits only 9109-964-009-NA \$2,014.95 25 TC credits only



LITERATURE PRODUCTS

PART NUMBER NET PRICE DESCRIPTION

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

LITERATURE PRODUCTS VOICE PROCESSING LITERATURE

9164-953-014-NA

\$2.50 TUI REFERENCE CARD - 25 PACK

NOTE(S):

Mitel One Point Messenger Client Quick Reference Guide

Issue 3





| PART NUMBER | NET PRICE | DESCRIPTION | |
|-------------|-----------|-------------|--|

NEW = New Part Number

INC = Price Increase

DEC = Price Decrease

сно = Part Description/Note/BOM/Pre-Req Change

OTHER

OTHER

| - |
|-----|
| |
| ۱D |
| |
| |
| SET |
| ND |





| 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000198 \$ 0.00 3-15 54000071 \$ 0.00 50000268 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 | PAGE | T PRICE | NE | PART NUMBER | PAGE | ET PRICE | N | PART NUMBER |
|---|-----------|---------------------------------------|----|-------------|-------|---------------------------------------|----|-------------|
| 10131K1 | 3-67 | 2,299.00 | \$ | 52000067 | 3-111 | 6,510.29 | \$ | 10078Z10 |
| 10155K1 | 3-67 | 1,929.00 | \$ | 52000068 | 3-111 | 18.79 | \$ | 10131K1 |
| 10196Z1 | 3-68 | 2,899.00 | \$ | 52000069 | 3-111 | 18.79 | \$ | 10131K2 |
| 10196Z1 | 3-68 | 2,899.00 | \$ | 52000070 | | 1,628.75 | \$ | 10155K1 |
| 10439Z1 | 3-68 | 2,699.00 | \$ | 52000071 | | 1,689.80 | \$ | 10196Z1 |
| 10439Z3 | 3-68 | 1,929.00 | \$ | 52000072 | | 452.74 | \$ | 10439Z1 |
| 10439Z6 | 3-69 | 1,929.00 | \$ | 52000073 | | 644.36 | \$ | 10439Z3 |
| 10441Z1 | 3-69 | 1,929.00 | \$ | 52000074 | | 452.74 | \$ | 10439Z6 |
| 10444Z1 | 3-69 | 1,929.00 | \$ | 52000075 | 3-105 | 126.81 | \$ | 10440A1 |
| 10444Z1 | 3-69 | 2,699.00 | \$ | 52000076 | 3-105 | 192.56 | \$ | 10441Z1 |
| 10444Z2 | 3-70 | 1,929.00 | \$ | 52000077 | | 5,532.48 | \$ | 10444Z1 |
| 10771Z1 \$ 3,383.36 3-109 \$2000079 \$ 1,929.00 10771Z2 \$ 3,383.36 3-109 \$2000080 \$ 1,699.00 10773R1 \$ 517.55 3-106,3-1 \$2000081 \$ 1,929.00 10774R1 \$ 517.55 3-106,3-1 \$2000082 \$ 1,829.00 10885Z1 \$ 517.55 3-106,3-1 \$2000083 \$ 2,099.00 10901Z1 \$ 3,383.36 3-110 \$2000084 \$ 1,699.00 10901Z2 \$ 727.96 3-110 \$2000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 \$2000086 \$ 2,299.00 50000132 \$ 469.65 3-4 \$2000087 \$ 2,699.00 50000161 \$ 44.44 3-50 \$2000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 \$2000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 50000198 \$ 1,416.52 3-91 \$4000070 | 3-70 | | | 52000078 | | | | 10444Z2 |
| 10771Z2 \$ 3,383.36 3-109 \$2000080 \$ 1,699.00 10773R1 \$ 517.55 3-106, 3-1 \$2000081 \$ 1,929.00 1074R1 \$ 517.55 3-106, 3-1 \$2000082 \$ 1,829.00 10885Z1 \$ 517.55 3-106, 3-1 \$2000083 \$ 2,099.00 10901Z1 \$ 3,383.36 3-110 \$2000084 \$ 1,6699.00 10901Z2 \$ 727.96 3-110 \$2000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 \$2000086 \$ 2,299.00 50000132 \$ 469.65 3-4 \$2000087 \$ 2,699.00 50000161 \$ 44.44 3-50 \$2000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 \$2000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000196 \$ 0.00 3-15 \$4000070 \$ 0.00 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 50000288 \$ 1,416.52 3-91 \$4000076 | 3-70 | | | | | | | 10771Z1 |
| 10773R1 \$ 517.55 3-106, 3-1 52000081 \$ 1,929.00 10774R1 \$ 517.55 3-106, 3-1 52000082 \$ 1,829.00 10885Z1 \$ 517.55 3-106, 3-1 52000083 \$ 2,099.00 10901Z1 \$ 3,383.36 3-110 52000084 \$ 1,699.00 10901Z2 \$ 727.96 3-110 52000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 52000086 \$ 2,299.00 50000132 \$ 469.65 3-4 52000087 \$ 2,699.00 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000089 \$ 2,899.00 50000196 \$ 0.00 3-15 54000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 54000070 \$ 0.00 3-5 50000268 \$ 1,416.52 3-91 54000071 \$ 0.00 3-5 50000282 \$ 3,648.62 3-91 54000075 \$ 1,483.15 5000028 \$ 1,483.15 500002 | 3-70 | | | | | | | · |
| 10774R1 \$ 517.55 3-106, 3-1 52000082 \$ 1,829.00 10885Z1 \$ 517.55 3-106, 3-1 52000083 \$ 2,099.00 10901Z1 \$ 3,383.36 3-110 52000084 \$ 1,699.00 10901Z2 \$ 727.96 3-110 52000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 52000086 \$ 2,299.00 50000132 \$ 469.65 3-4 52000087 \$ 2,699.00 50000161 \$ 44.44 3-50 52000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000099 \$ 2,899.00 50000196 \$ 0.00 3-15 54000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 54000070 \$ 0.00 3-5 50000288 \$ 1,416.52 3-91 54000071 \$ 0.00 3-5 50000289 \$ 3,648.62 3-91 54000074 \$ 1,483.15 5000028 \$ 1,483.15 5000028 | 3-71 | <u> </u> | | | | | | |
| 10885Z1 \$ 517.55 3-106, 3-1 52000083 \$ 2,099.00 10901Z1 \$ 3,383.36 3-110 52000084 \$ 1,699.00 10901Z2 \$ 727.96 3-110 52000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 \$2000086 \$ 2,299.00 50000132 \$ 469.65 3-4 52000088 \$ 2,699.00 50000161 \$ 44.44 3-50 52000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000090 \$ 2,899.00 50000196 \$ 0.00 3-15 54000070 \$ 0.00 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000198 \$ 0.00 3-15 54000071 \$ 0.00 50000280 \$ 1,416.52 3-91 54000071 \$ 0.00 50000281 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000282 \$ 3,648.62 3-91 54000075 \$ 1,483.15 | 3-71 | · · · · · · · · · · · · · · · · · · · | | | | | | 10774R1 |
| 10901Z1 \$ 3,383.36 3-110 52000084 \$ 1,699.00 10901Z2 \$ 727.96 3-110 52000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 \$2000086 \$ 2,299.00 50000132 \$ 469.65 3-4 \$2000087 \$ 2,699.00 50000180 \$ 2,116.20 3-101 \$2000088 \$ 2,699.00 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000196 \$ 0.00 3-15 \$4000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 \$ 0.00 50000268 \$ 1,416.52 3-91 \$4000071 \$ 0.00 \$ 0.00 50000269 \$ 3,648.62 3-91 \$4000075 \$ 1,483.15 \$ 0000269 \$ 3,648.62 3-91 \$54000075 \$ 1,483.15 \$ 0000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 \$ 0000282 \$ 3,146.66 3-121 \$600074 \$ 1,483.15 \$ 0000283 \$ 3,446.66 3-121 \$6107-120R-B1 \$ 3,2 | 3-71 | | | | | | | |
| 10901Z2 \$ 727.96 3-110 52000085 \$ 1,929.00 4431-70 \$ 106.45 3-90 52000086 \$ 2,299.00 50000132 \$ 469.65 3-4 52000087 \$ 2,699.00 50000161 \$ 44.44 3-50 52000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000090 \$ 2,899.00 50000196 \$ 0.00 3-15 54000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000268 \$ 1,448.15 3-91 54000071 \$ 0.00 50000268 \$ 1,483.15 50000269 \$ 3,648.62 3-91 54000074 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 1,483.15 50000280 \$ 2,841.38 3-121 6107-120R-B1 <td>3-71</td> <td>· · · · · · · · · · · · · · · · · · ·</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>10901Z1</td> | 3-71 | · · · · · · · · · · · · · · · · · · · | | | | | | 10901Z1 |
| 4431-70 \$ 106.45 3-90 \$2000086 \$ 2,299.00 50000132 \$ 469.65 3-4 \$2000087 \$ 2,699.00 50000161 \$ 44.44 3-50 \$2000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 \$2000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000196 \$ 0.00 3-15 \$4000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 3-5 50000288 \$ 1,416.52 3-91 \$4000071 \$ 0.00 50000289 \$ 3,648.62 3-91 \$4000074 \$ 1,483.15 50000281 \$ 3,146.66 3-121 \$4000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000284 \$ 1,263.36 3-118 \$107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 <td>3-71</td> <td>· · · · · · · · · · · · · · · · · · ·</td> <td></td> <td></td> <td></td> <td>· · · · · · · · · · · · · · · · · · ·</td> <td></td> <td></td> | 3-71 | · · · · · · · · · · · · · · · · · · · | | | | · · · · · · · · · · · · · · · · · · · | | |
| 50000132 \$ 469.65 3.4 52000087 \$ 2,699.00 50000161 \$ 44.44 3-50 52000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000090 \$ 2,899.00 50000196 \$ 0.00 3-15 54000050 \$ 0.00 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000198 \$ 0.00 3-15 54000071 \$ 0.00 50000268 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000289 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000281 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000285 \$ 1,263.36 3-118 6107-120R-B1 \$ 3,289.40 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-60-B1 <t< td=""><td>3-72</td><td><u> </u></td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | 3-72 | <u> </u> | | | | | | |
| 50000161 \$ 44.44 3-50 \$2000088 \$ 2,699.00 50000180 \$ 2,116.20 3-101 \$2000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000196 \$ 0.00 3-15 \$4000050 \$ 0.00 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 50000268 \$ 1,416.52 3-91 \$4000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 \$4000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000285 \$ 1,263.36 3-118 \$6107-120R-B1 \$ 3,289.40 50000286 \$ 1,263.36 3-118 \$6107-120R-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 \$6107-640-B1 \$ 5,904.23 50000288 \$ 2,047.67 3-118 \$6107-70-B1 \$ 897.99 50000289 \$ 2,841.38 3-120 \$6503 | 3-72 | | | | | | | |
| 50000180 \$ 2,116.20 3-101 52000089 \$ 2,899.00 50000181 \$ 5,104.90 3-101 52000090 \$ 2,899.00 50000196 \$ 0.00 3-15 54000050 \$ 0.00 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000268 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120R-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 <t< td=""><td>3-72</td><td>· ·</td><td></td><td></td><td></td><td></td><td></td><td></td></t<> | 3-72 | · · | | | | | | |
| 50000181 \$ 5,104.90 3-101 \$2000090 \$ 2,899.00 50000196 \$ 0.00 3-15 \$4000050 \$ 0.00 3-5 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 \$000 50000198 \$ 0.00 3-15 \$4000071 \$ 0.00 \$000 50000268 \$ 1,416.52 3-91 \$4000074 \$ 1,483.15 \$0000269 \$ 3,648.62 3-91 \$4000075 \$ 1,483.15 \$0000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 \$0000283 \$ 3,146.66 3-121 \$6107-120R-B1 \$ 3,289.40 \$0000283 \$ 3,146.66 3-121 \$6107-120R-B1 \$ 3,289.40 \$0000285 \$ 1,263.36 3-118 \$6107-120R-B1 \$ 5,904.23 \$0000286 \$ 1,263.36 3-118 \$6107-640-B1 \$ 5,904.23 \$0000287 \$ 2,047.67 3-118 \$6107-70-B1 \$ 897.99 \$0000288 \$ 2,441.38 3-120 \$6503-SCSI-B1 \$ 1,265.15 \$0000289 \$ 2,841.38 3-120 \$6503-SCSI-B1 \$ 1,265.15 \$0000402 \$ 1,916.17 | 3-73 | | | | | | | |
| 50000196 \$ 0.00 3-15 54000050 \$ 0.00 3-25 50000197 \$ 0.00 3-15 54000070 \$ 0.00 50000198 \$ 0.00 3-15 54000071 \$ 0.00 50000268 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-11 | 3-73 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| 50000197 \$ 0.00 3-15 \$4000070 \$ 0.00 50000198 \$ 0.00 3-15 \$4000071 \$ 0.00 50000268 \$ 1,416.52 3-91 \$4000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 \$4000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 \$6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 \$6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 \$6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 \$6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 \$6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 \$6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 \$6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 \$6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 | -58, 3-12 | · · · · · · · · · · · · · · · · · · · | | | | | | |
| 50000198 \$ 0.00 3-15 \$4000071 \$ 0.00 50000268 \$ 1,416.52 3-91 \$4000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 \$4000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 \$4000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 \$6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 \$6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 \$6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 \$6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 \$6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 \$6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 \$6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 \$6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 \$6530-20R-B1 \$ 4,771.64 51000572 \$ 2,817.90 | 3-143 | | | | | | | |
| 50000268 \$ 1,416.52 3-91 54000074 \$ 1,483.15 50000269 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000574 \$ 2,817.90 | 3-143 | | | | | | | |
| 50000269 \$ 3,648.62 3-91 54000075 \$ 1,483.15 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 </td <td>3-143</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | 3-143 | | | | | | | |
| 50000282 \$ 3,146.66 3-121 54000076 \$ 1,483.15 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,29 | 3-143 | | | | | | | |
| 50000283 \$ 3,146.66 3-121 6107-120R-B1 \$ 3,289.40 50000286 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-640-B1 \$ 5,904.23 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-640-B1 \$ 4,771.64 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6531-120R-B1 \$ 3,197.91 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 7,104.09 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-143 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| 50000285 \$ 1,263.36 3-118 6107-120S-B1 \$ 5,904.23 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6531-120R-B1 \$ 3,197.91 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-640-B1 \$ 7,104.09 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,6 | 3-92 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| 50000286 \$ 1,263.36 3-118 6107-640-B1 \$ 5,904.23 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6531-120R-B1 \$ 3,197.91 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-640-B1 \$ 7,104.09 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-94 | | | | | | | |
| 50000287 \$ 2,047.67 3-118 6107-70-B1 \$ 897.99 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6531-120R-B1 \$ 3,197.91 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-95 | · · · · · · · · · · · · · · · · · · · | | | | · · · · · · · · · · · · · · · · · · · | | |
| 50000288 \$ 2,047.67 3-118 6503-IDE-B1 \$ 1,265.15 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6531-120R-B1 \$ 3,197.91 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-90 | | | | | | | |
| 50000289 \$ 2,841.38 3-120 6503-SCSI-B1 \$ 1,265.15 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-101 | | | | | | | |
| 50000290 \$ 2,841.38 3-120 6510-SCSI-B1 \$ 1,265.07 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-101 | | | | | | | |
| 50000402 \$ 1,916.17 3-118 6530-120R-B1 \$ 2,253.38 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-101 | | | | | | | |
| 50000403 \$ 1,916.17 3-118 6530-120S-B1 \$ 4,208.06 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-93 | | | | | | | |
| 51000572 \$ 2,817.90 3-134 6530-640-B1 \$ 4,771.64 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-94 | · · · · · · · · · · · · · · · · · · · | | | | · · · · · · · · · · · · · · · · · · · | | |
| 51000573 \$ 2,583.08 3-134 6530-70-B1 \$ 1,126.22 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-96 | | | | | | | |
| 51000574 \$ 2,817.90 3-134 6531-120R-B1 \$ 3,197.91 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-91 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| 51000575 \$ 2,583.08 3-134 6531-120S-B1 \$ 6,224.12 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-93 | | | | | | | |
| 52000060 \$ 2,299.00 3-66 6531-640-B1 \$ 7,104.09 52000061 \$ 1,699.00 3-66 6531-70-B1 \$ 2,059.54 | 3-93 | | | | | | | |
| \$ 1,699.00 \$ 3-66 6531-70-B1 \$ 2,059.54 | 3-94 | | | | | | | |
| | 3-96 | · · · · · · · · · · · · · · · · · · · | | | | · · · · · · · · · · · · · · · · · · · | | |
| 52000062 \$ 1,399.00 3-66 6534-B1 \$ 3,648.62 3-9 | | <u> </u> | | | | · · · · · · · · · · · · · · · · · · · | | |
| | 94, 3-96 | | | | | | | |
| | -93, 3-95 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| | 3-108 | | | | | · · · · · · · · · · · · · · · · · · · | | |
| 52000065 \$ 2,099.00 3-67 6904-70-B1 \$ 231.07 | 3-86 | | | | | | | |
| 52000066 \$ 1,929.00 3-67 6913K1 \$ 18.79 | 3-108 | 18.79 | \$ | 6913K1 | 3-67 | 1,929.00 | \$ | 52000066 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NE | T PRICE | PAGE |
|-----------------|----|----------|-------|-------------------|----|----------|------------|
| 7474A1 | \$ | 91.11 | 3-108 | 9109-034-001-NA | \$ | 207.76 | 3-51 |
| 7840A1 | \$ | 25.36 | 3-108 | 9109-034-301-NA | \$ | 207.76 | 3-51 |
| 7841A1 | \$ | 586.12 | 3-108 | 9109-034-302-NA | \$ | 207.76 | 3-51 |
| 8213K1 | \$ | 46.03 | 3-108 | 9109-034-311-NA | \$ | 207.76 | 3-51 |
| 9104-001-000-SA | \$ | 437.83 | 3-114 | 9109-034-312-NA | \$ | 207.76 | 3-51 |
| 9104-010-100-SA | \$ | 927.18 | 3-114 | 9109-034-400-NA | \$ | 207.76 | 3-51 |
| 9104-020-001-SA | \$ | 729.72 | 3-113 | 9109-034-500-NA | \$ | 207.76 | 3-51 |
| 9104-020-003-SA | \$ | 377.74 | 3-113 | 9109-034-600-NA | \$ | 188.87 | 3-51 |
| 9104-020-100-SA | \$ | 558.02 | 3-113 | 9109-040-000-SA | \$ | 1,158.98 | 3-49 |
| 9104-020-101-SA | \$ | 1,116.05 | 3-113 | 9109-060-000-SA | \$ | 858.50 | 3-49 |
| 9104-021-001-SA | \$ | 772.65 | 3-113 | 9109-061-000-SA | \$ | 171.70 | 3-49 |
| 9104-024-001-NA | \$ | 686.80 | 3-113 | 9109-080-001-NA | \$ | 1,776.71 | 3-82 |
| 9104-030-100-SA | \$ | 330.52 | 3-113 | 9109-080-002-NA | \$ | 1,998.91 | 3-82 |
| 9104-030-101-SA | \$ | 643.87 | 3-113 | 9109-080-007-NA | \$ | 46.96 | 3-83 |
| 9104-030-110-SA | \$ | 558.02 | 3-113 | 9109-080-009-NA | \$ | 3,244.12 | 3-82 |
| 9104-030-111-SA | \$ | 1,116.05 | 3-113 | 9109-100-052-NA | \$ | 704.48 | 3-58 |
| 9104-040-000-SA | \$ | 188.87 | 3-113 | 9109-100-057-NA | \$ | 352.24 | 3-75 |
| 9104-041-001-SA | \$ | 321.08 | 3-113 | 9109-100-131-NA | \$ | 1,549.85 | 3-52, 3-77 |
| 9104-042-001-SA | \$ | 279.01 | 3-113 | 9109-100-132-NA | \$ | 1,549.85 | 3-53, 3-78 |
| 9104-044-001-SA | \$ | 270.43 | 3-114 | 9109-100-133-NA | \$ | 1,549.85 | 3-54, 3-79 |
| 9104-060-102-SA | \$ | 635.29 | 3-113 | 9109-100-134-NA | \$ | 1,549.85 | 3-55, 3-80 |
| 9104-071-003-SA | \$ | 171.70 | 3-114 | 9109-125-000-SA | \$ | 177.76 | 3-51 |
| 9104-072-001-SA | \$ | 85.85 | 3-114 | 9109-411-001-NA | \$ | 469.65 | 3-61 |
| 9104-080-001-NA | \$ | 17.17 | 3-114 | 9109-418-234-NA | \$ | 211.34 | 3-51 |
| 9104-081-101-NA | \$ | 38.63 | 3-114 | 9109-518-600-NA | \$ | 234.82 | 3-58 |
| 9104-083-001-NA | \$ | 21.46 | 3-114 | 9109-518-601-NA | \$ | 704.47 | 3-58 |
| 9104-500-002-SA | \$ | 472.17 | 3-113 | 9109-518-602-NA | \$ | 2,817.90 | 3-58 |
| 9104-500-300-NA | \$ | 1,837.19 | 3-113 | 9109-518-610-NA | \$ | 1,174.12 | 3-58 |
| 9104-511-055-NA | \$ | 516.62 | 3-113 | 9109-518-611-NA | \$ | 2,583.07 | 3-58 |
| 9104-520-051-NA | \$ | 375.72 | 3-115 | 9109-518-612-NA | \$ | 5,635.80 | 3-58 |
| 9104-520-151-NA | \$ | 375.72 | 3-115 | 9109-518-998-NA | \$ | 0.00 | 3-58, 3-96 |
| 9104-520-251-NA | \$ | 375.72 | 3-115 | 9109-519-615-NA | \$ | 413.29 | 3-74 |
| 9104-520-351-NA | \$ | 375.72 | 3-115 | 9109-519-617-NA | \$ | 3,616.31 | 3-74 |
| 9104-520-451-NA | \$ | 375.72 | 3-115 | 9109-519-619-NA | \$ | 375.72 | 3-74 |
| 9109-002-006-SA | \$ | 1,433.70 | 3-50 | 9109-519-621-NA | \$ | 2,066.46 | 3-74 |
| 9109-005-000-SA | \$ | 394.91 | 3-49 | 9109-519-622-NA | \$ | 375.72 | 3-74 |
| 9109-008-000-SA | \$ | 429.25 | 3-50 | 9109-519-638-NA | \$ | 469.95 | 3-74 |
| 9109-010-002-SA | \$ | 1,201.90 | 3-49 | 9109-519-639-NA | \$ | 2,583.08 | 3-74 |
| 9109-010-100-NA | \$ | 7,726.50 | 3-49 | 9109-519-642-NA | \$ | 5,400.98 | 3-74 |
| 9109-011-001-SA | \$ | 1,158.98 | 3-49 | 9109-519-643-NA | \$ | 2,113.42 | 3-74 |
| 9109-012-001-NA | \$ | 858.50 | 3-49 | 9109-519-645-NA | \$ | 4,666.20 | 3-74 |
| 9109-013-000-SA | \$ | 291.89 | 3-49 | 9109-519-646-NA | \$ | 2,817.90 | 3-74 |
| 9109-016-000-SA | \$ | 304.77 | 3-49 | 9109-519-647-NA | \$ | 1,408.95 | 3-74 |
| 9109-017-001-SA | \$ | 666.60 | 3-50 | 9109-519-648-NA | \$ | 4,461.68 | 3-74 |
| 9109-018-000-SA | \$ | 145.95 | 3-49 | 9109-519-649-NA | \$ | 3,052.73 | 3-74 |
| 9109-020-000-SA | \$ | 858.50 | 3-49 | 9109-519-651-NA | \$ | 2,348.24 | 3-74 |
| 9109-021-000-SA | \$ | 858.50 | 3-49 | 9109-519-652-NA | \$ | 5,166.15 | 3-74 |
| 9109-021-001-NA | \$ | 799.92 | 3-49 | 9109-519-653-NA | \$ | 375.72 | 3-74 |
| 9109-031-000-SA | \$ | 643.88 | 3-49 | 9109-530-120-NA | \$ | 469.65 | 3-74 |
| 9109-034-000-NA | \$ | 207.76 | 3-47 | 7107 330 120 1111 | Ψ | 107.00 | 3-33 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | N | ET PRICE | PAGE |
|------------------------------------|---------------|----------|------------|------------------------------------|-------------|-----------|------------|
| 9109-530-336-NA | \$ | 516.61 | 3-55 | 9109-542-005-NA | \$ | 694.14 | 3-83 |
| 9109-530-432-NA | \$ | 281.79 | 3-56 | 9109-542-101-NA | \$ | 882.00 | 3-83 |
| 9109-530-552-NA | \$ | 281.79 | 3-56 | 9109-542-102-NA | \$ | 661.27 | 3-82 |
| 9109-530-672-NA | \$ | 177.76 | 3-56 | 9109-600-002-NA | \$ | 666.60 | 3-51 |
| 9109-530-768-NA | \$ | 187.86 | 3-56 | 9109-610-001-NA | \$ | 666.60 | 3-49 |
| 9109-531-005-NA | \$ | 704.47 | 3-57 | 9109-610-002-NA | \$ | 799.92 | 3-49 |
| 9109-531-010-NA | \$ | 469.65 | 3-57 | 9109-610-101-NA | \$ | 1,955.36 | 3-49 |
| 9109-531-015-NA | \$ | 469.65 | 3-57 | 9109-610-102-NA | \$ | 2,399.76 | 3-49 |
| 9109-531-025-NA | \$ | 469.65 | 3-57 | 9109-610-202-NA | \$ | 2,577.52 | 3-49 |
| 9109-531-050-NA | \$ | 469.65 | 3-57 | 9109-611-001-NA | \$ | 444.40 | 3-49 |
| 9109-531-075-NA | \$ | 234.82 | 3-57 | 9109-612-001-NA | \$ | 888.80 | 3-50 |
| 9109-531-100-NA | \$ | 234.82 | 3-57 | 9109-613-001-NA | \$ | 688.82 | 3-50 |
| 9109-532-001-NA | \$ | 0.00 | 3-56 | 9109-613-002-NA | \$ | 1,777.60 | 3-50 |
| 9109-532-002-NA | \$ | 234.82 | 3-56 | 9109-613-003-NA | \$ | 2,133.12 | 3-50 |
| 9109-532-002-NA | \$ | 0.00 | 3-56 | 9109-615-001-NA | \$ | 1,066.56 | 3-50 |
| 9109-532-003-NA 9109-532-004-NA | \$ | 0.00 | 3-56 | 9109-615-101-NA | | 1,777.60 | 3-59 |
| 9109-532-004-NA | \$ | 469.65 | | 9109-615-202-NA | \$ | 1,599.84 | |
| 9109-532-000-NA 9109-532-007-NA | \$ \$ | 469.65 | 3-56 | 9109-631-001-NA | \$ | 66.66 | 3-59 |
| | <u> </u> | | 3-57 | 9109-632-001-NA 9109-632-001-NA | <u> </u> | 0.00 | 3-51 |
| 9109-532-010-NA | | 234.82 | 3-57 | | | | 3-59 |
| 9109-532-011-NA | \$ | 0.00 | 3-57, 3-82 | 9109-650-004-NA | \$ | 3,021.92 | 3-45 |
| 9109-532-013-NA | \$ | 46.96 | 3-57 | 9109-650-005-NA | \$ | 2,844.16 | 3-45 |
| 9109-532-015-NA | \$ | 704.47 | 3-61 | 9109-650-211-NA | \$ | 4,354.23 | 3-46, 3-76 |
| 9109-532-016-NA | \$ | 140.89 | 3-62 | 9109-650-212-NA | \$ | 11,997.91 | 3-46, 3-76 |
| 9109-532-017-NA | \$ | 469.65 | 3-62 | 9109-651-001-NA | \$ | 666.60 | 3-46 |
| 9109-532-018-NA | \$ | 234.82 | 3-62 | 9109-651-002-NA | \$ | 1,111.00 | 3-47 |
| 9109-532-019-NA | \$ | 1,127.16 | 3-62 | 9109-651-003-NA | \$ | 2,576.63 | 3-48, 3-82 |
| 9109-532-020-NA | \$ | 704.48 | 3-62 | 9109-651-004-NA | \$ | 4,444.00 | 3-47 |
| 9109-532-021-NA | \$ | 469.65 | 3-59 | 9109-651-011-NA | \$ | 666.60 | 3-47 |
| 9109-533-201-NA | \$ | 939.30 | 3-62 | 9109-651-012-NA | \$ | 1,111.00 | 3-47 |
| 9109-533-202-NA | \$ | 939.30 | 3-62 | 9109-651-101-NA | \$ | 1,777.60 | 3-48 |
| 9109-533-203-NA | \$ | 939.30 | 3-62 | 9109-651-211-NA | \$ | 2,754.39 | 3-48, 3-76 |
| 9109-533-204-NA | \$ | 939.30 | 3-63 | 9109-651-212-NA | \$ | 4,664.42 | 3-49, 3-77 |
| 9109-533-205-NA | \$ | 939.30 | 3-63 | 9109-652-001-NA | \$ | 1,244.32 | 3-45, 3-48 |
| 9109-533-206-NA | \$ | 939.30 | 3-63 | 9109-652-011-NA | \$ | 1,244.32 | 3-45, 3-48 |
| 9109-533-207-NA | \$ | 939.30 | 3-63 | 9109-652-201-NA | \$ | 2,444.20 | 3-60 |
| 9109-533-208-NA | \$ | 939.30 | 3-63 | 9109-652-202-NA | \$ | 3,555.20 | 3-60 |
| 9109-534-001-NA | \$ | 2,489.14 | 3-56 | 9109-964-001-NA | \$ | 454.50 | 3-141 |
| 9109-535-005-NA | \$ | 0.00 | 3-58 | 9109-964-005-NA | \$ | 858.50 | 3-141 |
| 9109-535-010-NA | \$ | 117.41 | 3-58 | 9109-964-009-NA | \$ | 2,014.95 | 3-141 |
| 9109-535-015-NA | \$ | 70.45 | 3-58 | 9112-080-001-NA | \$ | 46.96 | 3-117 |
| 9109-535-020-NA | \$ | 70.45 | 3-58 | 9112-080-002-NA | \$ | 46.96 | 3-117 |
| 9109-535-025-NA | \$ | 70.45 | 3-58 | 9112-080-003-NA | \$ | 46.96 | 3-117 |
| 9109-535-030-NA | \$ | 70.45 | 3-58 | 9112-100-000-NA | \$ | 140.89 | 3-117 |
| 9109-535-040-NA | \$ | 70.45 | 3-58 | 9112-200-000-NA | \$ | 187.86 | 3-117 |
| 9109-535-050-NA | \$ | 70.45 | 3-58 | 9112-200-001-NA | \$ | 18.79 | 3-117 |
| 9109-542-000-NA | \$ | 374.78 | 3-83 | 9112-200-008-NA | \$ | 4.70 | 3-117 |
| 9109-542-001-NA | \$ | 1,418.34 | 3-83 | 9112-502-000-NA | \$ | 187.86 | 3-117 |
| 9109-542-002-NA | \$ | 2,113.42 | 3-83 | 9113-200-001-NA | \$ | 56.36 | 3-117 |
| 9109-542-003-NA | \$ | 1,210.76 | 3-83 | 9113-200-002-NA | \$ | 56.36 | 3-117 |
| 9109-542-004-NA | \$ | 1,892.69 | 3-83 | 9115-000-000-NA | \$ | 187.86 | 3-117 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NE | T PRICE | PAGE |
|-----------------|----|-----------|------------|----------------------------|----|----------|------------|
| 9115-000-900-NA | \$ | 369.01 | 3-117 | 9125-501-101-NA | \$ | 1,777.60 | 3-18 |
| 9115-007-001-NA | \$ | 187.86 | 3-117 | 9125-501-102-NA | \$ | 1,777.60 | 3-19 |
| 9115-007-003-NA | \$ | 187.86 | 3-117 | 9125-502-101-NA | \$ | 2,000.00 | 3-30 |
| 9115-008-001-NA | \$ | 37.57 | 3-117 | 9125-533-002-NA | \$ | 610.54 | 3-6 |
| 9115-009-001-NA | \$ | 117.41 | 3-118 | 9125-533-003-NA | \$ | 704.48 | 3-7 |
| 9115-010-001-NA | \$ | 46.96 | 3-118 | 9125-533-004-NA | \$ | 939.30 | 3-7 |
| 9115-200-001-NA | \$ | 56.36 | 3-117 | 9125-533-005-NA | \$ | 704.48 | 3-7 |
| 9115-200-002-NA | \$ | 56.36 | 3-117 | 9125-533-006-NA | \$ | 939.30 | 3-7 |
| 9115-501-003-NA | \$ | 23.48 | 3-118 | 9125-533-007-NA | \$ | 704.48 | 3-7 |
| 9115-502-000-NA | \$ | 187.86 | 3-117 | 9125-533-008-NA | \$ | 939.30 | 3-7 |
| 9119-000-002-NA | \$ | 711.04 | 3-27 | 9125-533-020-NA | \$ | 3,757.20 | 3-7 |
| 9119-000-003-NA | \$ | 711.04 | 3-27 | 9125-533-040-NA | \$ | 3,757.20 | 3-8 |
| 9119-000-004-NA | \$ | 711.04 | 3-27 | 9125-533-060-NA | \$ | 3,757.20 | 3-8 |
| 9119-000-013-NA | \$ | 671.60 | 3-51 | 9132-000-100-NA | \$ | 66.66 | 3-116, 3-1 |
| 9119-000-014-NA | \$ | 671.60 | 3-51 | 9132-000-200-NA | \$ | 93.93 | 3-120 |
| 9119-101-001-NA | \$ | 93.93 | 3-27, 3-51 | 9132-001-100-NA | \$ | 140.89 | 3-118 |
| 9119-201-000-NA | \$ | 187.86 | 3-27 | 9132-001-106-NA | \$ | 403.90 | 3-118 |
| 9119-201-002-NA | \$ | 169.07 | 3-74 | 9132-001-200-NA | \$ | 140.89 | 3-118 |
| 9119-201-003-NA | \$ | 187.86 | 3-38 | 9132-001-206-NA | \$ | 403.90 | 3-118 |
| 9125-070-002-NA | \$ | 469.65 | 3-21 | 9132-015-100-NA | \$ | 131.50 | 3-118 |
| 9125-070-011-NA | \$ | 469.65 | 3-21 | 9132-015-200-NA | \$ | 131.50 | 3-118 |
| 9125-070-012-NA | \$ | 469.65 | 3-21 | 9132-025-100-NA | \$ | 187.86 | 3-118 |
| 9125-100-100-NA | \$ | 133.32 | 3-43 | 9132-025-102-NA | \$ | 206.65 | 3-118 |
| 9125-100-101-NA | \$ | 31.11 | 3-27 | 9132-025-200-NA | \$ | 187.86 | 3-118 |
| 9125-100-102-NA | \$ | 88.88 | 3-27 | 9132-025-202-NA | \$ | 206.65 | 3-118 |
| 9125-100-106-NA | \$ | 44.44 | 3-27 | 9132-090-000-NA | \$ | 342.84 | 3-124 |
| 9125-100-110-NA | \$ | 1,000.00 | 3-33 | 9132-090-801-NA | \$ | 14.09 | 3-118 |
| 9125-100-263-NA | \$ | 1,066.56 | 3-5 | 9132-090-802-NA | \$ | 70.45 | 3-119 |
| 9125-100-264-NA | \$ | 1,333.20 | 3-5 | 9132-090-803-NA | \$ | 84.54 | 3-119 |
| 9125-100-265-NA | \$ | 1,333.20 | 3-5 | 9132-090-804-NA | \$ | 32.88 | 3-119 |
| 9125-100-269-NA | \$ | 1,333.20 | 3-18 | 9132-090-805-NA | \$ | 56.36 | 3-119 |
| 9125-100-270-NA | \$ | 1,333.20 | 3-18 | 9132-090-806-NA | \$ | 56.36 | 3-119 |
| 9125-100-271-NA | \$ | 1,650.00 | 3-29 | 9132-090-807-NA | \$ | 63.87 | 3-119 |
| 9125-271-000-NA | \$ | 500.00 | 3-30 | 9132-090-808-NA | \$ | 14.09 | 3-119 |
| 9125-300-001-NA | \$ | 5,870.63 | 3-31 | 9132-125-102-NA | \$ | 328.75 | 3-119 |
| 9125-300-002-NA | \$ | 6,340.28 | 3-31 | 9132-125-202-NA | \$ | 328.75 | 3-120 |
| 9125-300-003-NA | \$ | 6,762.96 | 3-31 | 9132-150-102-NA | \$ | 309.97 | 3-120 |
| 9125-300-011-NA | \$ | 5,999.40 | 3-32 | 9132-150-202-NA | \$ | 309.97 | 3-120 |
| 9125-300-012-NA | \$ | 6,443.80 | 3-32 | 9132-150-302-NA | \$ | 403.90 | 3-120 |
| 9125-300-013-NA | \$ | 6,843.76 | 3-32 | 9132-150-402-NA | \$ | 403.90 | 3-121 |
| 9125-300-014-NA | \$ | 6,666.00 | 3-6 | 9132-200-100-NA | \$ | 117.41 | 3-121 |
| 9125-300-015-NA | \$ | 6,666.00 | 3-6 | 9132-200-102-NA | \$ | 178.47 | 3-121 |
| 9125-300-016-NA | \$ | 14,220.80 | 3-1 | 9132-200-200-NA | \$ | 117.41 | 3-121 |
| 9125-500-030-NA | \$ | 4,696.50 | 3-5 | 9132-200-202-NA | \$ | 178.47 | 3-122 |
| 9125-501-001-NA | \$ | 704.47 | 3-21 | 9132-201-200-NA | \$ | 272.40 | 3-116, 3-1 |
| 9125-501-002-NA | \$ | 140.89 | 3-21 | 9132-250-100-NA | \$ | 42.27 | 3-110, 3-1 |
| 9125-501-003-NA | \$ | 469.65 | 3-21 | 9132-250-101-NA | \$ | 56.36 | 3-116 |
| 9125-501-004-NA | \$ | 234.82 | 3-21 | 9132-800-105-NA | \$ | 46.96 | 3-116 |
| 9125-501-005-NA | \$ | 1,690.74 | 3-22 | 9132-800-107-NA | \$ | 28.18 | 3-116, 3-1 |
| , | Ψ | -,070.71 | 3-44 | , 10 2 000 107 1111 | Ψ | 20.10 | 5 110, 5-1 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | N | ET PRICE | PAGE |
|-----------------|---------------|----------|------------|-----------------|-----------|-----------|------------|
| 9132-800-207-NA | \$ | 28.18 | 3-116, 3-1 | 9146-610-407-NA | \$ | 2,113.42 | 3-134 |
| 9132-800-208-NA | \$ | 46.96 | 3-116 | 9146-610-411-NA | \$ | 146.53 | 3-134 |
| 9132-800-209-NA | \$ | 93.93 | 3-117, 3-1 | 9146-610-412-NA | \$ | 443.35 | 3-134 |
| 9132-800-210-NA | \$ | 9.39 | 3-122 | 9146-610-421-NA | \$ | 92.99 | 3-134 |
| 9132-800-299-NA | \$ | 18.79 | 3-122 | 9146-610-422-NA | \$ | 149.35 | 3-134 |
| 9132-800-500-NA | \$ | 93.93 | 3-116, 3-1 | 9147-400-105-NA | \$ | 1,777.60 | 3-133 |
| 9132-800-501-NA | \$ | 131.50 | 3-116 | 9147-402-005-NA | \$ | 3,110.80 | 3-133 |
| 9132-800-600-NA | \$ | 511.92 | 3-116 | 9147-402-006-NA | \$ | 3,110.80 | 3-133 |
| 9132-800-601-NA | \$ | 4.70 | 3-117 | 9147-403-106-NA | \$ | 3,110.80 | 3-133 |
| 9141-110-200-NA | \$ | 234.82 | 3-122 | 9147-600-401-NA | \$ | 439.96 | 3-133 |
| 9141-110-300-NA | \$ | 187.86 | 3-122 | 9147-600-402-NA | \$ | 3,110.80 | 3-133 |
| 9141-210-200-NA | \$ | 234.82 | 3-122 | 9147-600-403-NA | \$ | 3,110.80 | 3-25, 3-13 |
| 9141-210-300-NA | \$ | 234.82 | 3-122 | 9148-000-025-NA | \$ | 1,408.95 | 3-41 |
| 9141-220-300-NA | \$ | 469.65 | 3-123 | 9148-000-034-NA | \$ | 5,635.80 | 3-39 |
| 9141-300-001-NA | \$ | 18.79 | 3-123 | 9148-000-037-NA | \$ | 2,348.25 | 3-40 |
| 9145-500-413-NA | \$ | 262.20 | 3-24, 3-65 | 9148-000-038-NA | \$ | 13,150.20 | 3-39 |
| 9145-550-502-NA | \$ | 295.08 | 3-143 | 9148-000-039-NA | \$ | 2,348.25 | 3-40 |
| 9146-600-223-NA | \$ | 511.92 | 3-135, 3-1 | 9148-000-520-NA | \$ | 0.00 | 3-42 |
| 9146-600-224-NA | \$ | 1,080.19 | 3-135, 3-1 | 9148-000-530-NA | \$ | 0.00 | 3-33 |
| 9146-600-261-NA | \$ | 3,170.14 | 3-136 | 9150-070-001NAU | \$ | 1,291.54 | 3-91 |
| 9146-600-262-NA | \$ | 2,817.90 | 3-136 | 9150-120-001-NA | \$ | 885.76 | 3-91 |
| 9146-600-263-NA | \$ | 2,113.42 | 3-136 | 9150-120-002-NA | \$ | 2,768.12 | 3-93 |
| 9146-600-264-NA | \$ | 1,761.19 | 3-136 | 9150-120R001NAU | \$ | 1,291.54 | 3-92 |
| 9146-600-265-NA | \$ | 1,761.19 | 3-136 | 9150-120S002NAU | \$ | 2,306.92 | 3-94 |
| 9146-600-266-NA | \$ | 1,761.19 | 3-136 | 9150-262-072-NA | \$ | 3,661.50 | 3-86 |
| 9146-600-267-NA | \$ | 1,761.19 | 3-136 | 9150-420-154-NA | \$ | 153.67 | 3-86, 3-92 |
| 9146-600-271-NA | \$ | 965.60 | 3-136 | 9150-430-101-NA | \$ | 510.81 | 3-97 |
| 9146-600-272-NA | \$ | 1,930.26 | 3-136 | 9150-430-130-NA | \$ | 857.64 | 3-97 |
| 9146-600-273-NA | \$ | 2,895.86 | 3-136 | 9150-430-131-NA | \$ | 4,291.64 | 3-97 |
| 9146-600-274-NA | \$ | 4,825.18 | 3-136 | 9150-430-150-NA | \$ | 213.77 | 3-97 |
| 9146-600-280-NA | \$ | 2,413.06 | 3-136 | 9150-430-151-NA | \$ | 213.77 | 3-97 |
| 9146-600-330-NA | \$ | 3,522.37 | 3-136 | 9150-430-152-NA | \$ | 213.77 | 3-97 |
| 9146-600-340-NA | \$ | 1,056.71 | 3-136 | 9150-430-153-NA | \$ | 213.77 | 3-97 |
| 9146-600-370-NA | \$ | 394.51 | 3-137 | 9150-430-300-NA | \$ | 1,111.76 | 3-97 |
| 9146-600-401-NA | \$ | 2,583.07 | 3-134 | 9150-430-301-NA | \$ | 1,197.61 | 3-97 |
| 9146-600-402-NA | \$ | 5,447.94 | 3-134 | 9150-430-303-NA | \$ | 1,292.04 | 3-97 |
| 9146-600-403-NA | \$ | 7,514.40 | 3-134 | 9150-430-304-NA | \$ | 1,768.96 | 3-97 |
| 9146-600-404-NA | \$ | 9,393.00 | 3-134 | 9150-430-305-NA | \$ | 1,768.96 | 3-97 |
| 9146-600-405-NA | \$ | 3,099.69 | 3-134 | 9150-430-309-NA | \$ | 849.06 | 3-97 |
| 9146-600-406-NA | \$ | 2,301.28 | 3-134 | 9150-430-310-NA | \$ | 849.06 | 3-97 |
| 9146-600-407-NA | \$ | 2,113.42 | 3-134 | 9150-430-311-NA | \$ | 849.06 | 3-97 |
| 9146-600-411-NA | \$ | 146.53 | 3-135 | 9150-430-401-NA | \$ | 857.64 | 3-97 |
| 9146-600-412-NA | \$ | 443.35 | 3-135 | 9150-430-406-NA | \$ | 257.55 | 3-97 |
| 9146-610-203-NA | \$ | 5,682.76 | 3-138 | 9150-430-450-NA | \$ | 257.55 | 3-97 |
| 9146-610-401-NA | \$ | 2,583.07 | 3-134 | 9150-430-451-NA | \$ | 257.55 | 3-97 |
| 9146-610-402-NA | \$ | 5,447.94 | 3-134 | 9150-430-503-NA | \$ | 287.59 | 3-97 |
| 9146-610-403-NA | \$ | 7,514.40 | 3-134 | 9150-430-504-NA | \$ | 287.59 | 3-97 |
| 9146-610-404-NA | <u> </u> | 9,393.00 | | 9150-430-507-NA | <u> </u> | 8,211.55 | |
| 9146-610-405-NA | <u> </u> | 3,099.69 | 3-134 | 9150-430-509-NA | <u>\$</u> | 862.79 | 3-97 |
| | | | 3-134 | | | | 3-97 |
| 9146-610-406-NA | \$ | 2,301.28 | 3-134 | 9150-430-510-NA | \$ | 6,318.56 | 3-97 |





| 9150-430-511-NA \$ 9150-430-601-NA \$ 9150-430-602-NA \$ 9150-430-603-NA \$ 9150-430-604-NA \$ 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5607 \$ 9150-5607 \$ 9150-5608TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 | 673.92 1,458.59 2,918.04 1,154.68 3,446.87 279.01 428.39 2,145.39 | 3-97 3-97 3-98 3-98 3-98 3-98 | 9150-6258 9150-6268TX 9150-6272-01 9150-6282 9150-6283 | \$ \$ \$ | 2,108.48 5,060.86 | 3-89 |
|--|--|--|--|----------------|----------------------|--------------|
| 9150-430-602-NA \$ 9150-430-603-NA \$ 9150-430-603-NA \$ 9150-430-604-NA \$ 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-751-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5607 \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ | 2,918.04 1,154.68 3,446.87 279.01 428.39 | 3-97 3-98 3-98 3-98 3-98 | 9150-6272-01 9150-6282 | | 5,060.86 | |
| 9150-430-603-NA \$ 9150-430-604-NA \$ 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5607 \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 | 2,918.04 1,154.68 3,446.87 279.01 428.39 | 3-98 3-98 3-98 3-98 | 9150-6282 | \$ | | 3-88 |
| 9150-430-604-NA \$ 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 | 3,446.87 279.01 428.39 | 3-98 3-98 3-98 | | | 505.66 | 3-89 |
| 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-6012-70-B1 \$ 9150-6014 \$ 9150-6143 \$ | 279.01 428.39 | 3-98 3-98 | 9150-6283 | \$ | 2,108.48 | 3-90 |
| 9150-430-720-NA \$ 9150-430-734-NA \$ 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-6012-70-B1 \$ 9150-6014 \$ 9150-6143 \$ | 279.01 428.39 | 3-98 | | \$ | 505.65 | 3-88 |
| 9150-430-736-NA \$ 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-430-752-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6143 \$ | | | 9150-6284 | \$ | 910.87 | 3-88 |
| 9150-430-750-NA \$ 9150-430-751-NA \$ 9150-430-751-NA \$ 9150-431-700-NA \$ 9150-431-704-NA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6143 \$ | 2,145.39 | 3-97 | 9150-6285 | \$ | 1,007.88 | 3-88 |
| 9150-430-751-NA \$ 9150-430-752-NA \$ 9150-431-700-NA \$ 9150-431-704-BA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6143 \$ | | 3-97 | 9150-6290 | \$ | 60.95 | 3-90 |
| 9150-430-751-NA \$ 9150-430-752-NA \$ 9150-431-700-NA \$ 9150-431-704-BA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6143 \$ | 854.21 | 3-98 | 9150-6291 | \$ | 109.03 | 3-98 |
| 9150-431-700-NA \$ 9150-431-704-BA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ | 299.62 | 3-98 | 9150-640-001-NA | \$ | 4,429.74 | 3-95 |
| 9150-431-700-NA \$ 9150-431-704-BA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610T \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ | 857.64 | 3-98 | 9150-640-001NAU | \$ | 3,229.31 | 3-96 |
| 9150-431-704-BA \$ 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 0.00 | 3-86, 3-91 | 9150-6464-05RB1 | \$ | 344.72 | 3-87 |
| 9150-431-704-NA \$ 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5147 \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 923.33 | 3-87 | 9150-6464-100B1 | \$ | 2,768.11 | 3-87 |
| 9150-4363-70S \$ 9150-500-399-NA \$ 9150-5147 \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 923.33 | 3-87 | 9150-6464100RB1 | \$ | 3,875.55 | 3-87 |
| 9150-500-399-NA \$ 9150-5147 \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 442.99 | 3-90 | 9150-6464-25-B1 | \$ | 923.33 | 3-87 |
| 9150-5147 \$ 9150-5607 \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 266.64 | 3-27 | 9150-6464-25RB1 | \$ | 1,291.54 | 3-87 |
| 9150-5607 \$ 9150-5608TX \$ 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 215.48 | 3-90 | 9150-6465-05-B1 | \$ | 92.05 | 3-87 |
| 9150-5608TX \$ 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 3,289.77 | 3-88 | 9150-6465-05RB1 | \$ | 92.05 | 3-87 |
| 9150-5609TX \$ 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 2,176.30 | 3-88 | 9150-6488-02B1X | \$ | 923.33 | 3-87 |
| 9150-5610T \$ 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 2,176.30 | 3-88 | 9150-6800-70 | \$ | 141.65 | 3-90 |
| 9150-5610TX \$ 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 2,176.30 | 3-87 | 9150-6901-210B1 | \$ | 3,599.40 | 3-91 |
| 9150-5828 \$ 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 2,176.30 | 3-87 | 9150-6977-B1-S | \$ | 151.95 | 3-90 |
| 9150-5829 \$ 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 463.59 | 3-90 | 9150-702-071-NA | \$ | 1,746.92 | 3-98 |
| 9150-5830 \$ 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 1,940.21 | 3-90 | 9150-702-101-NA | \$ | 2,360.87 | 3-98 |
| 9150-6012-70-B1 \$ 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 151.95 | 3-90 | 9150-702-102-NA | \$ | 5,580.25 | 3-98 |
| 9150-6013 \$ 9150-6014 \$ 9150-6143 \$ | 1,771.09 | 3-89 | 9150-702-112-NA | \$ | 2,832.19 | 3-98 |
| 9150-6014 \$ 9150-6143 \$ | 66.96 | 3-90 | 9150-702-113-NA | \$ | 6,133.98 | 3-98 |
| 9150-6143 \$ | 788.10 | 3-90 | 9150-702-114-NA | \$ | 12,263.67 | 3-98 |
| | 315.93 | 3-90 | 9150-702-118-NA | \$ | 616.40 | 3-98 |
| 9150-6146 \$ | 388.04 | 3-90 | 9150-702-119-NA | \$ | 871.38 | 3-98 |
| 9150-6147-64 \$ | 3,235.69 | 3-90 | 9150-702-120-NA | \$ | 1,227.65 | 3-98 |
| 9150-6205DX \$ | 2,809.01 | 3-89 | 9150-702-121-NA | \$ | 691.09 | 3-98 |
| 9150-6205EX \$ | 2,809.01 | 3-89 | 9150-702-131-NA | \$ | 2,760.08 | 3-99 |
| 9150-6205LX \$ | 2,528.28 | 3-89 | 9150-702-132-NA | \$ | 3,099.18 | 3-99 |
| 9150-6208TX \$ | 9,109.54 | 3-89 | 9150-702-135-NA | \$ | 3,305.22 | 3-99 |
| 9150-6215 \$ | 5,060.86 | 3-88 | 9150-702-136-NA | \$ | 3,476.07 | 3-99 |
| 9150-6217 \$ | 10,120.86 | 3-88 | 9150-702-137-NA | \$ | 8,841.69 | 3-99 |
| 9150-6222 \$ | 2,530.00 | 3-88 | 9150-702-144-NA | \$ | 3,923.34 | 3-99 |
| 9150-6223EX \$ | 1,568.48 | 3-89 | 9150-702-145-NA | \$ | 364.86 | 3-99 |
| 9150-6223LX \$ | 1,316.08 | 3-89 | 9150-702-146-NA | \$ | 532.27 | 3-99 |
| 9150-6226DU \$ | 1,265.43 | 3-89 | 9150-702-147-NA | \$ | 364.86 | 3-99 |
| 9150-6226LU \$ | 1,265.43 | 3-89 | 9150-702-152-NA | \$ | 279.01 | 3-99 |
| 9150-6229TX \$ | 3,542.17 | 3-88 | 9150-702-154-NA | \$ | 158.82 | 3-99 |
| 9150-6232T \$ | 6,232.71 | 3-88 | 9150-803-022-NA | \$ | 7,468.95 | 3-84 |
| 9150-6242 \$ | 101.30 | 3-89 | 9150-803-052-NA | \$ | 9,031.42 | 3-84 |
| 9150-6243 \$ | 84.13 | 3-89 | 9150-803-063-NA | \$ | 16,976.84 | 3-84 |
| 9150-6244 \$ | 253.26 | 3-89 | 9150-803-070-NA | \$ | 7,254.32 | 3-84 |
| 9150-6245 | 98.73 | 3-90 | 9150-803-070-NA 9150-803-071-NA | \$ | 6,825.07 | 3-84 |
| 9150-6247TX \$ | 3,264.02 | | 9150-803-071-NA 9150-803-072-NA | \$ | 7,254.32 | |
| 9150-6247TX \$ 9150-6249TX \$ | 1,012.17 | 3-88 3-88 | 9150-803-072-NA 9150-803-073-NA | <u> </u> | 6,825.07 | 3-84 3-84 |





| PART NUMBER | NET PRICE | PAGE | PART NUMBER | N | ET PRICE | PAGE |
|-----------------|--------------|-------|-----------------|----|-----------|------------|
| 9150-803-074-NA | \$ 13,092.12 | 3-84 | 9168-500-025-NA | \$ | 250.00 | 3-111 |
| 9150-803-075-NA | \$ 12,233.62 | 3-84 | 9168-500-026-NA | \$ | 250.00 | 3-111 |
| 9150-803-076-NA | \$ 13,092.12 | 3-84 | 9169-200-005-NA | \$ | 1,483.15 | 3-100 |
| 9150-803-077-NA | \$ 12,233.62 | 3-84 | 9169-200-011-NA | \$ | 0.00 | 3-143 |
| 9150-803-078-NA | \$ 19,960.12 | 3-84 | 9169-403-010-NA | \$ | 20,132.96 | 3-100 |
| 9150-803-079-NA | \$ 18,886.14 | 3-85 | 9169-403-011-NA | \$ | 22,484.96 | 3-100 |
| 9150-803-080-NA | \$ 19,960.12 | 3-85 | 9169-403-012-NA | \$ | 25,657.92 | 3-100 |
| 9150-803-081-NA | \$ 18,886.14 | 3-85 | 9169-403-013-NA | \$ | 28,270.11 | 3-101 |
| 9150-803-082-NA | \$ 24,252.62 | 3-85 | 9178-001-001-NA | \$ | 795.00 | 3-139 |
| 9150-803-083-NA | \$ 23,394.12 | 3-85 | 9178-002-001-NA | \$ | 795.00 | 3-139 |
| 9150-803-084-NA | \$ 24,252.62 | 3-85 | 9178-003-001-NA | \$ | 795.00 | 3-139 |
| 9150-803-085-NA | \$ 23,394.12 | 3-85 | 9178-004-001-NA | \$ | 795.00 | 3-139 |
| 9164-001-001-NA | \$ 975.26 | 3-99 | 9178-005-001-NA | \$ | 795.00 | 3-139 |
| 9164-002-020-NA | \$ 533.52 | 3-99 | 9178-006-001-NA | \$ | 795.00 | 3-139 |
| 9164-002-021-NA | \$ 960.90 | 3-99 | 9178-007-001-NA | \$ | 795.00 | 3-139 |
| 9164-002-022-NA | \$ 1,921.81 | 3-99 | 9178-010-001-NA | \$ | 200.00 | 3-139 |
| 9164-003-002-NA | \$ 1,067.98 | 3-99 | 9178-010-002-NA | \$ | 1.00 | 3-139 |
| 9164-003-003-NA | \$ 1,708.59 | 3-99 | 9178-020-001-NA | \$ | 1.00 | 3-139 |
| 9164-003-004-NA | \$ 2,801.93 | 3-100 | 9178-050-001-NA | \$ | 7,500.00 | 3-139 |
| 9164-003-005-NA | \$ 4,288.84 | 3-100 | 9178-050-002-NA | \$ | 10,000.00 | 3-139 |
| 9164-003-006-NA | \$ 7,260.79 | 3-100 | 9178-050-003-NA | \$ | 12,500.00 | 3-139 |
| 9164-003-007-NA | \$ 8,350.38 | 3-100 | 9178-051-001-NA | \$ | 10,000.00 | 3-139 |
| 9164-003-008-NA | \$ 11,523.33 | 3-100 | 9180-300-001-NA | \$ | 1,127.16 | 3-102 |
| 9164-003-009-NA | \$ 14,134.59 | 3-100 | 9180-300-002-NA | \$ | 1,221.09 | 3-102 |
| 9164-005-001-NA | \$ 771.17 | 3-100 | 9180-300-003-NA | \$ | 1,221.09 | 3-103 |
| 9164-120-001-NA | \$ 1,483.15 | 3-100 | 9180-300-004-NA | \$ | 2,207.35 | 3-103 |
| 9164-120-008-NA | \$ 2,711.14 | 3-99 | 9180-300-005-NA | \$ | 2,301.28 | 3-103 |
| 9164-120-009-NA | \$ 1,483.15 | 3-100 | 9180-300-006-NA | \$ | 2,348.25 | 3-103 |
| 9164-120-010-NA | \$ 5,693.57 | 3-99 | 9180-300-007-NA | \$ | 140.89 | 3-107 |
| 9164-120-100-NA | \$ 118.35 | 3-99 | 9180-300-008-NA | \$ | 93.93 | 3-107 |
| 9164-120-101-NA | \$ 1,030.20 | 3-99 | 9180-300-012-NA | \$ | 13,807.71 | 3-103, 3-1 |
| 9164-120-200-NA | \$ 118.35 | 3-99 | 9180-305-000-NA | \$ | 382.18 | 3-27, 3-51 |
| 9164-120-201-NA | \$ 686.80 | 3-99 | 9180-500-001-NA | \$ | 198.53 | 3-123 |
| 9164-120-440-NA | \$ 593.64 | 3-100 | 9180-510-001-NA | \$ | 666.60 | 3-65 |
| 9164-120-500-NA | \$ 889.52 | 3-99 | 9180-510-004-NA | \$ | 444.40 | 3-65 |
| 9164-120-708-NA | \$ 2,966.31 | 3-100 | 9180-EXT-000-NA | \$ | 751.44 | 3-27, 3-51 |
| 9164-120-709-NA | \$ 1,779.97 | 3-100 | 9180-FIB-003-XX | \$ | 88.88 | 3-140 |
| 9164-120-712-NA | \$ 4,449.46 | 3-100 | 9180-RACK-23-01 | \$ | 177.76 | 3-140 |
| 9164-120-716-NA | \$ 5,932.62 | 3-100 | 9180-RAK-SHF-02 | \$ | 53.32 | 3-140 |
| 9164-120-720-NA | \$ 1,186.34 | 3-100 | 9185-000-100-NA | \$ | 4,464.20 | 3-126 |
| 9164-500-009-NA | \$ 3,795.43 | 3-99 | 9185-000-200-NA | \$ | 7,726.50 | 3-126 |
| 9164-953-014-NA | \$ 2.50 | 3-142 | 9185-100-100-NA | \$ | 4,038.99 | 3-128 |
| 9168-500-003-NA | \$ 1,167.55 | 3-102 | 9185-100-200-NA | \$ | 4,508.64 | 3-128 |
| 9168-500-004-NA | \$ 711.99 | 3-102 | 9185-101-105-NA | \$ | 657.51 | 3-129 |
| 9168-500-005-NA | \$ 1,069.86 | 3-102 | 9185-101-110-NA | \$ | 1,221.09 | 3-129 |
| 9168-500-006-NA | \$ 1,069.86 | 3-102 | 9185-101-125-NA | \$ | 2,817.90 | 3-129 |
| 9168-500-020-NA | \$ 100.00 | 3-106 | 9185-101-150-NA | \$ | 5,166.15 | 3-129 |
| 9168-500-021-NA | \$ 100.00 | 3-106 | 9185-101-199-NA | \$ | 9,862.65 | 3-129 |
| 9168-500-022-NA | \$ 100.00 | 3-106 | 9185-101-205-NA | \$ | 939.30 | 3-129 |
| 9168-500-024-NA | \$ 250.00 | 3-100 | 9185-101-210-NA | \$ | 1,784.67 | 3-129 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NE | T PRICE | PAGE |
|---------------------------------------|----------------|-----------|------------|------------------------------------|---------------|----------|------------|
| 9185-101-225-NA | \$ | 4,226.85 | 3-129 | 9400-200-117-DC | \$ | 2,222.00 | 3-1 |
| 9185-101-250-NA | \$ | 7,984.05 | 3-129 | 9400-200-117-NA | \$ | 2,222.00 | 3-2 |
| 9185-101-299-NA | \$ | 15,028.80 | 3-129 | 9400-200-118-DC | \$ | 1,422.08 | 3-28 |
| 9185-101-305-NA | \$ | 563.58 | 3-129 | 9400-200-118-NA | \$ | 1,422.08 | 3-28 |
| 9185-101-310-NA | \$ | 1,033.23 | 3-129 | 9400-200-119-NA | \$ | 444.40 | 3-28 |
| 9185-101-325-NA | \$ | 1,878.60 | 3-129 | 9400-200-122-NA | \$ | 1,333.20 | 3-2 |
| 9185-101-350-NA | \$ | 3,569.34 | 3-129 | 9400-200-123-NA | \$ | 939.30 | 3-28 |
| 9185-101-399-NA | \$ | 5,635.80 | 3-129 | 9400-200-124-NA | \$ | 1,333.20 | 3-2 |
| 9185-101-400-NA | \$ | 399.20 | 3-129 | 9400-200-125-NA | \$ | 799.92 | 3-28 |
| 9185-101-401-NA | \$ | 140.90 | 3-129 | 9400-200-144-NA | \$ | 222.20 | 3-28 |
| 9185-200-100-NA | \$ | 6,387.24 | 3-127 | 9400-200-157-NA | \$ | 2,044.24 | 3-28 |
| 9185-200-200-NA | \$ | 9,017.28 | 3-128 | 9400-200-158-NA | \$ | 2,044.24 | 3-28 |
| 9185-201-004-NA | \$ | 1,643.78 | 3-130 | 9400-200-159-NA | \$ | 2,310.88 | 3-28 |
| 9185-201-008-NA | \$ | 3,005.76 | 3-130 | 9400-200-160-NA | \$ | 2,310.88 | 3-28 |
| 9185-201-016-NA | \$ | 5,447.94 | 3-130 | 9400-200-161-NA | \$ | 3,555.20 | 3-2 |
| 9185-201-032-NA | \$ | 10,144.44 | 3-130 | 9400-200-162-NA | \$ | 3,555.20 | 3-2 |
| 9185-201-100-NA | \$ | 1,972.53 | 3-130 | 9400-200-163-NA | \$ | 5,332.80 | 3-3 |
| 9185-201-200-NA | \$ | 2,254.32 | 3-130 | 9400-200-164-NA | \$ | 5,332.80 | 3-3 |
| 9185-201-300-NA | \$ | 281.79 | 3-130 | 9400-200-165-NA | \$ | 2,222.00 | 3-3 |
| 9185-201-400-NA | \$ | 751.44 | 3-130 | 9400-200-166-NA | \$ | 4,888.40 | 3-4 |
| 9185-201-401-NA | \$ | 657.51 | 3-130 | 9400-200-167-NA | \$ | 4,888.40 | 3-4 |
| 9185-300-100-NA | \$ | 9,111.21 | 3-127 | 9400-200-200-NA | \$ | 888.80 | 3-28 |
| 9185-300-200-NA | \$ | 11,929.11 | 3-127 | 9400-200-301-NA | \$ | 711.04 | 3-28 |
| 9185-400-100-NA | \$ | 4,226.85 | 3-129 | 9400-200-303-NA | \$ | 444.40 | 3-28 |
| 9185-401-105-NA | \$ | 798.41 | 3-129 | 9400-200-304-BA | \$ | 1,333.20 | 3-28 |
| 9185-401-110-NA | \$ | 1,502.88 | 3-129 | 9400-200-306-BA | \$ | 1,599.84 | 3-4 |
| 9185-401-125-NA | \$ | 3,522.38 | 3-130 | 9400-300-201-NA | \$ | 444.40 | 3-28 |
| 9185-401-150-NA | \$ | 6,669.03 | 3-130 | 9400-300-204-NA | \$ | 444.40 | 3-29, 3-51 |
| 9185-401-199-NA | \$ | 12,492.69 | 3-130 | 9400-300-301-NA | \$ | 222.20 | 3-25, 3-50 |
| 9185-401-305-NA | \$ | 328.76 | 3-130 | 9400-300-302-NA | \$ | 355.52 | 3-29, 3-51 |
| 9185-401-310-NA | \$ | 516.62 | 3-130 | 9400-300-305-NA | \$ | 186.65 | 3-51 |
| 9185-401-325-NA | \$ | 939.30 | 3-130 | 9400-300-306-NA | \$ | 1,795.38 | 3-29 |
| 9185-401-350-NA | \$ | 1,596.81 | 3-130 | 9400-300-308-NA | \$ | 444.40 | 3-25 |
| 9185-401-399-NA | \$ | 2,442.18 | 3-130 | 9400-300-310-NA | \$ | 533.28 | 3-24 |
| 9185-401-400-NA | \$ | 328.76 | 3-130 | 9400-300-312-NA | \$ | 444.40 | 3-29, 3-43 |
| 9189-000-016-NA | \$ | 888.80 | 3-51 | 9400-300-315-NA | \$ | 888.80 | 3-25, 3-50 |
| 9189-000-017-NA | \$ | 888.80 | 3-27 | 9400-300-316-NA | \$ | 1,066.56 | 3-25, 3-50 |
| 9189-048-000-NA | \$ | 75.14 | 3-27, 3-51 | 9400-300-317-NA | \$ | 444.40 | 3-50 |
| 9189-888-001-NA | \$ | 44.44 | 3-27, 3-51 | 9400-300-401-NA | \$ | 96.88 | 3-51 |
| 9191-200-100-NA | \$ | 324.06 | 3-131 | 9400-700-301-NA | \$ | 1,688.72 | 3-24, 3-65 |
| 9191-201-000-NA | \$ | 164.38 | 3-131 | 9400-700-314-NA | \$ | 71.10 | 3-24, 3-65 |
| 9191-206-100-NA | \$ | 281.79 | 3-131 | 9400-700-318-NA | \$ | 1,999.80 | 3-24, 3-65 |
| 9191-207-100-NA | \$ | 136.20 | 3-131 | 9400-700-319-NA | \$ | 3,199.68 | 3-25, 3-65 |
| 9191-600-002-NA | \$ | 884.36 | 3-131 | 9400-700-322-NA | \$ | 2,461.98 | 3-25, 3-05 |
| 9191-600-033-NA | \$ | 439.96 | 3-132 | 9400-700-323-NA | \$ | 44.44 | 3-65 |
| 9400-100-301-NA | \$ | 444.40 | 3-50 | 9400-700-328-NA | \$ | 31.11 | 3-05 |
| 9400-100-301-NA 9400-100-304-NA | \$ | 177.76 | 3-50 | 9400-700-331-NA | \$ | 140.89 | 3-23 |
| 9400-100-304-NA 9400-200-103-NA | \$ | 1,777.60 | 3-31 | 9400-700-407-NA | \$ | 469.65 | 3-60, 3-63 |
| 9400-200-103-NA 9400-200-116-DC | \$ | 2,222.00 | | 9400-700-407-NA 9400-700-408-NA | <u> </u> | 469.65 | |
| フ + ∪U-∠UU-11U- D し | Ф | ∠,∠∠∠.∪∪ | 3-1 | 7400-100-408-INA | Ф | 407.03 | 3-22 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NI | ET PRICE | PAGE |
|-----------------|----|----------|------------|-------------|----|-----------|------------|
| 9400-700-416-NA | \$ | 1,690.74 | 3-22 | MACL-A-040 | \$ | 704.47 | 3-16 |
| 9400-700-417-NA | \$ | 704.47 | 3-22, 3-63 | MACL-A-045 | \$ | 704.47 | 3-16 |
| 9400-700-419-NA | \$ | 1,878.60 | 3-23, 3-63 | MACL-A-050 | \$ | 704.47 | 3-16 |
| 9400-700-420-NA | \$ | 2,817.90 | 3-23, 3-63 | MACL-A-060 | \$ | 704.47 | 3-16 |
| 9400-700-421-NA | \$ | 4,226.85 | 3-23, 3-63 | MACL-A-07 | \$ | 1,408.95 | 3-8 |
| 9400-700-422-NA | \$ | 469.65 | 3-23, 3-64 | MACL-A-070 | \$ | 704.47 | 3-16 |
| 9400-700-423-NA | \$ | 234.82 | 3-23 | MACL-A-08 | \$ | 3,052.72 | 3-8 |
| 9400-700-430-NA | \$ | 469.65 | 3-23 | MACL-A-080 | \$ | 704.47 | 3-16 |
| 9400-700-431-NA | \$ | 1,955.36 | 3-23, 3-64 | MACL-A-09 | \$ | 3,522.37 | 3-8 |
| 9400-700-432-NA | \$ | 3,288.56 | 3-24, 3-64 | MACL-A-090 | \$ | 704.47 | 3-16 |
| 9400-700-433-NA | \$ | 1,333.20 | 3-24, 3-64 | MACL-A-10 | \$ | 3,757.20 | 3-8 |
| 9400-700-434-NA | \$ | 469.65 | 3-24, 3-64 | MACL-A-100 | \$ | 704.47 | 3-16 |
| 9400-700-435-NA | \$ | 704.48 | 3-24 | MACL-A-11 | \$ | 11,976.07 | 3-8 |
| 9400-700-612-NA | \$ | 2,044.24 | 3-19, 3-60 | MACL-A-150 | \$ | 939.30 | 3-16 |
| 9400-700-622-NA | \$ | 4,888.40 | 3-19 | MACL-A-200 | \$ | 939.30 | 3-16 |
| 9400-700-623-NA | \$ | 3,555.20 | 3-20 | MACL-A-350 | \$ | 2,348.25 | 3-16 |
| 9400-700-624-NA | \$ | 6,399.36 | 3-20 | MAIACL-A-04 | \$ | 704.47 | 3-16 |
| 9400-700-625-NA | \$ | 3,555.20 | 3-61 | MAIACL-A-08 | \$ | 704.47 | 3-16 |
| 9400-800-201-NA | \$ | 231.09 | 3-29 | MB160AAA | \$ | 1,066.56 | 3-20, 3-61 |
| 9400-800-500-NA | \$ | 469.65 | 3-5 | MC215AD | \$ | 3,555.20 | 3-29 |
| 9401-000-004-NA | \$ | 219.53 | 3-50 | MC230AA | \$ | 577.72 | 3-44 |
| 9401-000-011-NA | \$ | 133.32 | 3-50 | MC243BA | \$ | 1,333.20 | 3-29 |
| 9401-000-012-NA | \$ | 219.53 | 3-50 | MC260AA | \$ | 1,595.40 | 3-26 |
| 9401-000-019-NA | \$ | 88.88 | 3-50 | MC262AA | \$ | 1,595.40 | 3-26 |
| 9401-000-020-NA | \$ | 488.84 | 3-50 | MC263BA | \$ | 1,777.60 | 3-26 |
| 9401-000-021-NA | \$ | 399.96 | 3-50 | MC263BB | \$ | 2,222.00 | 3-26 |
| 9401-000-022-NA | \$ | 30.22 | 3-50 | MC264BA | \$ | 2,222.00 | 3-26 |
| 9401-000-024-NA | \$ | 133.32 | 3-25, 3-50 | MC266AA | \$ | 1,066.56 | 3-26 |
| BC026 | \$ | 0.00 | 3-25 | MC268AA | \$ | 933.24 | 3-25 |
| BC028 | \$ | 0.00 | 3-26 | MC268AB | \$ | 2,222.00 | 3-25 |
| BS05EU | \$ | 38.51 | 3-112 | MC269AA | \$ | 2,222.00 | 3-21 |
| H45886 | \$ | 12.21 | 3-112 | MC270AA | \$ | 2,222.00 | 3-21 |
| J06988 | \$ | 16.91 | 3-112 | MC271AA | \$ | 1,500.00 | 3-30 |
| MA209AA | \$ | 88.88 | 3-29 | MC312AB | \$ | 888.80 | 3-29 |
| MA217AA | \$ | 177.76 | 3-26 | MC320BE | \$ | 1,057.67 | 3-26 |
| MA218AA | \$ | 177.76 | 3-26 | MC320EA | \$ | 1,057.67 | 3-26 |
| MA225AA | \$ | 200.00 | 3-30 | MC321AC | \$ | 1,190.99 | 3-26 |
| MA230AA | \$ | 102.21 | 3-44 | MC323BA | \$ | 1,590.95 | 3-26 |
| MA231AA | \$ | 97.77 | 3-44 | MC330AB | \$ | 799.92 | 3-26 |
| MA232AA | \$ | 311.08 | 3-44 | MC340BA | \$ | 1,155.44 | 3-26 |
| MA233AA | \$ | 124.43 | 3-44 | MC341CA | \$ | 888.80 | 3-26 |
| MA234AA | \$ | 4,177.76 | 3-44 | MC342BB | \$ | 791.03 | 3-27 |
| MA501AA | \$ | 213.31 | 3-25 | MC380AA | \$ | 1,199.88 | 3-27 |
| MACL-A-005 | \$ | 1,878.60 | 3-16 | MC606AB | \$ | 1,333.20 | 3-27 |
| MACL-A-010 | \$ | 1,408.95 | 3-16 | MFRD-A-07 | \$ | 2,348.25 | 3-8 |
| MACL-A-015 | \$ | 1,408.95 | 3-16 | MFRD-A-12 | \$ | 4,226.85 | 3-8 |
| MACL-A-020 | \$ | 939.30 | 3-16 | MFRD-A-16 | \$ | 2,348.25 | 3-8 |
| MACL-A-025 | \$ | 939.30 | 3-16 | MFRD-A-18 | \$ | 4,226.85 | 3-8 |
| MACL-A-030 | \$ | 704.47 | 3-16 | MFRD-A-20 | \$ | 6,575.10 | 3-8 |
| MACL-A-035 | \$ | 704.47 | 3-16 | MFRD-A-21 | \$ | 6,575.10 | 3-8 |
| MIUCT-U-033 | φ | / 04.4 / | 3-10 | WII KD-A-21 | φ | 0,575.10 | 3-8 |





| PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NE | T PRICE | PAGE |
|---------------------------|----|----------|-------|----------------|----|----------|-------|
| MFRD-A-22 | \$ | 7,514.40 | 3-8 | MKT10880Z24 | \$ | 1,069.86 | 3-104 |
| MFRD-A-23 | \$ | 7,514.40 | 3-8 | MKT10880Z3 | \$ | 1,069.86 | 3-104 |
| MFRD-A-24 | \$ | 7,514.40 | 3-8 | MKT10880Z4 | \$ | 1,167.55 | 3-104 |
| MFRD-A-26 | \$ | 6,575.10 | 3-8 | ML010AA | \$ | 1,408.95 | 3-36 |
| MHCL-A-1 | \$ | 1,408.95 | 3-8 | MLCL-A-24 | \$ | 939.30 | 3-9 |
| MHCL-A-10 | \$ | 939.30 | 3-8 | MLCL-A-32 | \$ | 1,878.60 | 3-9 |
| MHCL-A-15 | \$ | 939.30 | 3-9 | MNRD-A-02 | \$ | 0.00 | 3-41 |
| MHCL-A-2 | \$ | 939.30 | 3-9 | MNRD-A-03 | \$ | 234.82 | 3-41 |
| MHCL-A-20 | \$ | 939.30 | 3-9 | MNRD-A-04 | \$ | 234.82 | 3-41 |
| MHCL-A-3 | \$ | 939.30 | 3-9 | MNRD-A-05 | \$ | 234.82 | 3-41 |
| MHCL-A-4 | \$ | 939.30 | 3-9 | MNRD-A-10 | \$ | 234.82 | 3-41 |
| MHCL-A-5 | \$ | 939.30 | 3-9 | MNRD-A-30 | \$ | 469.65 | 3-41 |
| MK074CA | \$ | 4,696.50 | 3-5 | MNRD-A-60 | \$ | 469.65 | 3-42 |
| MK075CA | \$ | 4,696.50 | 3-5 | MP912BA | \$ | 888.80 | 3-29 |
| MK080CE | \$ | 3,287.55 | 3-32 | MP914AA | \$ | 888.80 | 3-29 |
| MK080DA | \$ | 3,287.55 | 3-33 | MR011AA | \$ | 0.00 | 3-36 |
| MK080OPS | \$ | 3,287.55 | 3-33 | MR012AA | \$ | 0.00 | 3-36 |
| MK081OPS | \$ | 469.65 | 3-34 | MS2008-L-NA-00 | \$ | 0.00 | 3-33 |
| MK082BD | \$ | 444.40 | 3-34 | MSA-A-01 | \$ | 1,291.54 | 3-9 |
| MK082DA | \$ | 5,166.15 | 3-34 | MSA-A-02 | \$ | 1,878.60 | 3-9 |
| MK083DA | \$ | 6,575.10 | 3-35 | MSA-A-04 | \$ | 469.65 | 3-9 |
| MK102CA | \$ | 9,393.00 | 3-35 | MSA-A-05 | \$ | 2,348.25 | 3-9 |
| MK139AA | \$ | 4,888.40 | 3-36 | MSA-A-07 | \$ | 1,408.95 | 3-9 |
| MK140AA | \$ | 1,408.95 | 3-37 | MSA-A-08 | \$ | 469.65 | 3-9 |
| MK191AA | \$ | 666.60 | 3-29 | MSA-A-09 | \$ | 469.65 | 3-9 |
| MK192AA | \$ | 444.40 | 3-35 | MSA-A-10 | \$ | 0.00 | 3-9 |
| MK340AA | \$ | 1,777.60 | 3-42 | MSA-A-11 | \$ | 939.30 | 3-9 |
| MK342AA | \$ | 1,066.56 | 3-42 | MSA-A-12 | \$ | 1,878.60 | 3-9 |
| MK343AA | \$ | 1,777.60 | 3-42 | MSA-A-13 | \$ | 939.30 | 3-9 |
| MK344AA | \$ | 1,155.44 | 3-43 | MSA-A-15 | \$ | 939.30 | 3-9 |
| MK345AA | \$ | 1,777.60 | 3-43 | MSA-A-16 | \$ | 704.47 | 3-9 |
| MK346AA | \$ | 1,155.44 | 3-43 | MSA-A-17 | \$ | 704.47 | 3-9 |
| MK347AA | \$ | 1,599.84 | 3-43 | MSA-A-18 | \$ | 469.65 | 3-10 |
| MK349AA | \$ | 888.80 | 3-43 | MSA-A-19 | \$ | 0.00 | 3-10 |
| MK400AA | \$ | 1,066.56 | 3-16 | MSA-A-20 | \$ | 704.47 | 3-10 |
| MK400AB | \$ | 2,666.40 | 3-17 | MSA-A-21 | \$ | 1,408.95 | 3-10 |
| MK401AA | \$ | 3,021.92 | 3-17 | MSA-A-23 | \$ | 704.47 | 3-10 |
| MK401AB | \$ | 4,310.68 | 3-17 | MSA-A-25 | \$ | 1,408.95 | 3-10 |
| MK402AA | \$ | 4,310.68 | 3-17 | MSA-A-26 | \$ | 1,878.60 | 3-10 |
| MK402AB | \$ | 5,599.44 | 3-18 | MSA-A-28 | \$ | 1,408.95 | 3-10 |
| MKT10772Z1 | \$ | 2,537.05 | 3-110 | MSA-A-31 | \$ | 939.30 | 3-10 |
| MKT10772Z2 | \$ | 2,601.86 | 3-110 | MSA-A-32 | \$ | 704.47 | 3-10 |
| MKT10772Z3 | \$ | 2,601.86 | 3-110 | MSA-A-33 | \$ | 6,575.10 | 3-10 |
| MKT10772Z3 MKT10790Z1 | \$ | 5,858.41 | 3-110 | MSA-A-34 | \$ | 469.65 | 3-10 |
| MKT10790Z1 MKT10791Z1 | \$ | 6,510.29 | 3-107 | MSA-A-35 | \$ | 1,878.60 | 3-10 |
| MKT1079121 MKT10880Z1 | \$ | 711.99 | 3-107 | MSA-A-36 | \$ | 469.65 | 3-11 |
| MKT10880Z12 | \$ | 1,069.86 | 3-103 | MSA-A-37 | \$ | 469.65 | 3-11 |
| MKT10880Z14 | \$ | 711.99 | 3-104 | MSA-A-39 | \$ | 0.00 | 3-11 |
| MKT10880Z14 MKT10880Z2 | \$ | 711.99 | 3-104 | MSA-A-40 | \$ | 1,878.60 | 3-11 |
| WIX 1 10000L2 | Ψ | 111.22 | 3-112 | 141012-12-40 | Ψ | 1,070.00 | 3-11 |





| MSA-A-43 \$ 1,808.15 3-11 MSA-A-45 \$ 460.65 3-11 MSA-A-46 \$ 1,878.60 3-11 MSA-A-47 \$ 0.00 3-12 MSA-A-48 \$ 1,878.60 3-12 MSA-A-49 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-53 \$ 1,000 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 1,777.60 3-227 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-14 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU401AA \$ 344.44 3-25 MW401AA \$ 353.33 3-25 MW401AA \$ 353.33 3-25 MW401AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW512AA \$ 88.88 3-44 MW512AA \$ 88.88 3-44 MW523AA \$ 88.88 3-44 MW523AA \$ 88.88 3-44 | PART NUMBER | N | ET PRICE | PAGE | PART NUMBER | NET PRICE | PAGE |
|--|-------------|----|----------|------|-------------|-----------|------|
| MSA-A-45 \$ 499.65 3-11 MSA-A-46 \$ 1,878.60 3-11 MSA-A-47 \$ 0.00 3-12 MSA-A-48 \$ 1,408.95 3-12 MSA-A-49 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 2,248.25 3-14 MTCL-A-10 \$ 2,2348.25 3-14 MTCL-A-10 \$ 2,2348.25 3-14 MTCL-A-30 \$ 4,296.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 <td>MSA-A-43</td> <td>\$</td> <td>1,808.15</td> <td>3-11</td> <td></td> <td></td> <td></td> | MSA-A-43 | \$ | 1,808.15 | 3-11 | | | |
| MSA-A-46 \$ 1,878.60 3-11 MSA-A-47 \$ 0.00 3-12 MSA-A-48 \$ 1,878.60 3-12 MSA-A-49 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-51 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-09 \$ 1,878.60 3-14 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 <td>-</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | - | | | | | | |
| MSA-A-47 \$ 0.00 3-12 MSA-A-48 \$ 1.878.60 3-12 MSA-A-49 \$ 1.408.95 3-12 MSA-A-50 \$ 1.408.95 3-12 MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4.226.85 3-13 MSB-A-06 \$ 7.044.75 3-13 MSB-A-07 \$ 1.878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 2,817.90 3-14 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1.878.60 3-14 MTCL-A-30 \$ 4,226.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-50 \$ 281.79 3-14 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 | MSA-A-46 | | 1,878.60 | | | | |
| MSA-A-48 \$ 1,878.60 3-12 MSA-A-49 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-30 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-14 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 <td>MSA-A-47</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | MSA-A-47 | | | | | | |
| MSA-A-49 \$ 1,408.95 3-12 MSA-A-50 \$ 1,408.95 3-12 MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-08 \$ 2,817.90 3-13 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-30 \$ 1,878.60 3-14 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 <td>MSA-A-48</td> <td>\$</td> <td>1,878.60</td> <td></td> <td></td> <td></td> <td></td> | MSA-A-48 | \$ | 1,878.60 | | | | |
| MSA-A-52 \$ 704.47 3-12 MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MSB-A-09 \$ 1,878.60 3-14 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-30 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU190EA \$ 355.52 | MSA-A-49 | \$ | 1,408.95 | | | | |
| MSA-A-53 \$ 0.00 3-12 MSA-A-54 \$ 704.47 3-13 MSB-A-06 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-60 \$ 187.86 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU171BA \$ 1,422.08 3-29 MU401AB \$ 106.66 3-25 MW401AA \$ 75.00 <td< td=""><td>MSA-A-50</td><td>\$</td><td>1,408.95</td><td>3-12</td><td></td><td></td><td></td></td<> | MSA-A-50 | \$ | 1,408.95 | 3-12 | | | |
| MSA-A-54 \$ 704.47 3-13 MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-40 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW401AA \$ 75.00 | MSA-A-52 | \$ | 704.47 | 3-12 | | | |
| MSB-A-05 \$ 4,226.85 3-13 MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU190EA \$ 355.52 3-29 MU401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW401AA \$ 33.32 3-44 MW510AA \$ 133.32 3-44 | MSA-A-53 | \$ | 0.00 | 3-12 | | | |
| MSB-A-06 \$ 7,044.75 3-13 MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW401AA \$ 75.00 3-30 MW510AA \$ 133.32 | MSA-A-54 | \$ | 704.47 | 3-13 | | | |
| MSB-A-07 \$ 1,878.60 3-13 MSB-A-08 \$ 2,817.90 3-13 MTI16BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW401AA \$ 75.00 3-30 MW510AA \$ 133.32 <td< td=""><td>MSB-A-05</td><td>\$</td><td>4,226.85</td><td>3-13</td><td></td><td></td><td></td></td<> | MSB-A-05 | \$ | 4,226.85 | 3-13 | | | |
| MSB-A-08 \$ 2,817.90 3-13 MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW510AA \$ 133.32 3- | MSB-A-06 | \$ | 7,044.75 | 3-13 | | | |
| MT116BA \$ 1,777.60 3-27 MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW51AA \$ 111.10 3-44 MW51AA \$ 88.88 3-44 MW52AA \$ 88.88 3-44 | MSB-A-07 | \$ | 1,878.60 | 3-13 | | | |
| MTCL-A-10 \$ 2,348.25 3-14 MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW51AA \$ 111.10 3-44 MW52AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 | MSB-A-08 | \$ | 2,817.90 | 3-13 | | | |
| MTCL-A-15 \$ 1,878.60 3-14 MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW401AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW51AA \$ 88.88 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 </td <td>MT116BA</td> <td>\$</td> <td>1,777.60</td> <td>3-27</td> <td></td> <td></td> <td></td> | MT116BA | \$ | 1,777.60 | 3-27 | | | |
| MTCL-A-20 \$ 4,226.85 3-14 MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MUT71AA \$ 799.92 3-29 MU171BA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW51AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW520AA \$ 88.88 3-44 | MTCL-A-10 | \$ | 2,348.25 | 3-14 | | | |
| MTCL-A-30 \$ 4,696.50 3-14 MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW510AA \$ 133.32 3-44 MW510AA \$ 133.32 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 | MTCL-A-15 | \$ | 1,878.60 | 3-14 | | | |
| MTCL-A-31 \$ 6,575.10 3-14 MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-15 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 | MTCL-A-20 | \$ | 4,226.85 | 3-14 | | | |
| MTCL-A-32 \$ 6,575.10 3-14 MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MW401AA \$ 355.52 3-29 MW401AB \$ 106.66 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 | MTCL-A-30 | \$ | 4,696.50 | 3-14 | | | |
| MTSP-A-10 \$ 0.00 3-14 MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 | MTCL-A-31 | \$ | 6,575.10 | 3-14 | | | |
| MTSP-A-20 \$ 281.79 3-14 MTSP-A-40 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTCL-A-32 | \$ | 6,575.10 | 3-14 | | | |
| MTSP-A-40 \$ 281.79 3-14 MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-10 | \$ | 0.00 | 3-14 | | | |
| MTSP-A-50 \$ 281.79 3-15 MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-20 | | 281.79 | 3-14 | | | |
| MTSP-A-60 \$ 187.86 3-15 MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-40 | | 281.79 | 3-14 | | | |
| MTSP-A-80 \$ 187.86 3-15 MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-50 | \$ | 281.79 | 3-15 | | | |
| MU171AA \$ 799.92 3-29 MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-60 | \$ | 187.86 | 3-15 | | | |
| MU172BA \$ 1,422.08 3-29 MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MTSP-A-80 | | 187.86 | 3-15 | | | |
| MU190EA \$ 355.52 3-29 MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | MU171AA | | 799.92 | 3-29 | | | |
| MW401AA \$ 84.44 3-25 MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | 3-29 | | | |
| MW401AB \$ 106.66 3-25 MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW402AA \$ 53.33 3-25 MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | 84.44 | 3-25 | | | |
| MW404AA \$ 75.00 3-30 MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW510AA \$ 133.32 3-44 MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | 3-25 | | | |
| MW511AA \$ 133.32 3-44 MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW512AA \$ 111.10 3-44 MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW513AA \$ 111.10 3-44 MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW520AA \$ 88.88 3-44 MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW521AA \$ 88.88 3-44 MW522AA \$ 88.88 3-44 | | | | | | | |
| MW522AA \$ 88.88 3-44 | | | | | | | |
| | | | | | | | |
| MW523AA \$ 88.88 3-44 | | | | | | | |
| | MW523AA | \$ | 88.88 | 3-44 | | | |